

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 595Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FENDER L/H FRT (CONSISTENT)	DENTED	488.75	488.75
1	FENDER INNER SHIELD L/H FRT (CONSISTENT)	NOT NECESSARY	145.00	-
1	HEAD LAMP L/H (CONSISTENT)	NOT NECESSARY	630.00	-
1	BUMPER FRT (CONSISTENT)	DEFORMED	1,112.50	1,112.50
1	BUMPER SIDE RETAINER FRT (CONSISTENT)	NECESSARY	85.00	85.00
1	SHOCK ABSORBER L/H FRT (CONSISTENT)	NOT NECESSARY	380.00	-
1	LOWER ARM L/H FRT (CONSISTENT)	NOT NECESSARY	341.25	-
1	KNUCKLE ARM L/H FRT (CONSISTENT)	NOT NECESSARY	603.75	-
1	WHEEL BEARING HUP L/H FRT (CONSISTENT)	NOT NECESSARY	470.00	-
	LESS 10% DISCOUNT		-	-168.62
			4,256.25	1,517.63
	SPECIAL NETT ITEMS			
1	SPORT RIM L/H FRT (SN) (CONSISTENT)	сит	900.00	650.00
			900.00	650.00
	LABOUR			
	REMOVE & REPLACE ACCIDENT DAMAGED PARTS.		700.00	300.00
	SPRAY PAINTING ACCIDENT EFFECT PARTS.		650.00	400.00
	REMOVE AND REFIX UNDERCARRIAGE.	NOT NECESSARY	180.00	-
	COMPUTERIZED WHEEL ALIGNMENT.		80.00	80.00
	CHECKING WIRING.		60.00	30.00
	UNDERCOAT.	NOT NECESSARY	80.00	-
			1,750.00	810.00
	GRAND TOTAL		6,906.25	2,977.63
			•	

RECOMMENDED COST OF LUMP SUM REPAIRS		2,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM18018225/Aba3s2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.