

(08711/13)

Surveyor: Kelvin

REF:

C13/TMLI 8018234/K1162

Mugman

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: GW 6744HPolicy No. MCDM0015Claims No. M1805029

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 1054 C Yr Regn: 29 Dec 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 240 C.C. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 29.9 J36 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHLD814444 097728Gen. Cond: Good / 0 / Poor / BurntSteering: 0 / Jammed / Leaked / Burnt orBrake: 0 / Jammed / Leaked / Burnt orModi: Nil / S/Rim / 0 / STD/Rim orTyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Markk

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 6/10/18 D.O.I. 8/10/18Survey held at CDHE (Loyang)Des. of Damages: Frt / Rear / 0 / S / N / S / UIC / Rooftop orRear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 1054 C - C13/FCL 8001272 / Dred302
	GW 6744H - NA/INC 13021087/r
10/10/18	Continues PIP \$4235.92 / 3 Op. (Red. 3349.84, 442)

RECEIVED 22 OCT 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

250

Transportation:

\$ + RS. \$

Photos

Others

TOTAL


10Report Format: TPLump Sum / (B.) (\$) 4,235.92Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Team: ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305222975
CUSTOMER	REGN NO.: SHC1054C	MILEAGE	
MS	MAKE: HYUNDAI	FUEL	
CUSTOMER NO. 7010045	MODEL I-40	DATE/TIME IN 06.10.2018 14:30	
ADDRESS 383 SIN MING DRIVE	YR OF MANU 29.12.2016	TARGET DATE	
Singapore SINGAPORE 575717	CHASSIS CODE RMHLB41UMHU097724	COMPLETION DATE/TIME:	
65508755 (R) (P)			
COUNT CARD NO.			

Accident Date: 06.10.2018  
NATURE: 3P 06.10.2018

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION	FRONT
		tokio - taxi rear Right	
		LRR/Kdm -	



CHECKED & PASSED OUT BY:			
SERVICE ADVISOR		CUSTOMER'S SIGNATURE	
Acknowledgement Slip		Exit Pass	
Vehicle No.: SHC1054C LARRY		Vehicle No.: SHC1054C	
Signature/Date		Name of Service Advisor Date	
To be returned to Service Reception upon collection		To be kept by Security Guard	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/10/2018 09:21
Date Of Accident	06/10/2018 12:40
Exact Location Of Accident	WOODLANDS AVE 5 TWDS AVE 9
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1054C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	ONG HUEY CHEE
NRIC No	S1357695E
Date Of Birth	08/07/1959
Occupation	OUTDOOR
Date Of Driving Pass	16/06/1980
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98327965
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 12 MARSILING LANE #10-27
Postcode	730012
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW6274H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NEO SWEE SOON
NRIC/Passport Number	S0684888E
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

## IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 192203321R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON. 6 OCT 2018 @ 1240 hr I VEH-

I was driving along the above location

Straight Suddenly a unknown vehicle

Stop at the lane I veh A slow down

at stop suddenly veh B from rear

hit veh A rear.. at the point

of accident veh A no PAC.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199203321R

Policyholder's Signature

Date & Time:

Driver's Signature




(If driver is not the policyholder)




Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)  
 59 Loyang Drive  
 Singapore 508969  
 Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**COMFORT TRANSPORTATION PTE LTD**

Singapore

**Claimant Insurer:** India International Insurance Pte Ltd

**PARTICULARS OF CLAIM**

<b>Claim Type:</b>	THIRD PARTY	<b>Ref. No:</b>	
<b>Policy No:</b>		<b>Date of Loss:</b>	06/10/2018
<b>Vehicle Reg. No.:</b>	SHC1054C	<b>Driveable?</b>	YES
<b>Party At Fault:</b>	UNKNOWN		
<b>Driver (TP):</b>	ONG HUEY CHEE		
<b>Make/Model:</b>	HYUNDAI I40, 1.7 D CRDI (A)	<b>Vehicle Reg. Date:</b>	29/12/2016
<b>Vehicle Colour:</b>	BLUE	<b>Gen Condition:</b>	GOOD
<b>Engine No:</b>	D4FDGU700034	<b>Chassis No:</b>	KMHLB41UMHU097724
<b>Odometer:</b>	299336 KM		
<b>Paint Type:</b>			
<b>List Item Discount:</b>	20.00 %		
<b>Total Loss?</b>	NO		
<b>Est. Duration of Repair (day)</b>	5		
<b>Description of Accident/Loss</b>	PLS REFER TO ATTACHED		
<b>Present Location:</b>	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	5,925.76
Miscellaneous Items	10.00
Labour	1,650.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>7,585.76</b>
<b>+ GST 7.00% (S\$)</b>	<b>531.00</b>
<b>Nett Amount (S\$)</b>	<b>8,116.76</b>

**This claim is handled by: NG NYUK PHIN**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2018)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	<b>ComfortDelGro Engineering Pte Ltd/SHC1054C/08/10/2018 13:00</b>	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT LID <i>X GNL</i>	20.00	0.00	*1,681.40 FL
2	1		*BOOT LID GARNISH <i>X rpr-Adm</i>	20.00	0.00	*398.00 FL
3	1		*REAR BUMPER <i>X su</i>	20.00	0.00	*544.50 FL
4	1		*REAR BUMPER SPONGE <i>X su</i>	20.00	0.00	*103.50 FL
5	1		*REAR BUMPER REINFORCEMENT <i>X su</i>	20.00	0.00	*428.40 FL
6	2		*REAR BUMPER BRACKET - RH/LH <i>X su</i>	20.00	0.00	*160.60 FL
7	1		*REAR BUMPER SIDE BARCKET - RH <i>X su</i>	20.00	0.00	*35.60 FL
8	1		*REAR BUMPER UNDERCOVER <i>cut</i>	20.00	0.00	*228.00 FL
9	1		*REAR BUMPER REFLECTOR - RH <i>cut</i>	20.00	0.00	*27.40 FL
10	1		*TAIL LAMP - RH <i>horizontal</i>	20.00	0.00	*697.80 FL
11	1		*TAIL LAMP (BOOTLID) - RH <i>horizontal</i>	20.00	0.00	*417.40 FL
12	1		*REAR PANEL <i>X rpr</i>	20.00	0.00	*592.30 FL
13	1		*BOOT LID I40 <i>no</i>	20.00	0.00	*41.00 FL
14	1		*BOOT LID CRDI <i>no</i>	20.00	0.00	*41.00 FL
15	1		*EXAHUST SILENCER - RH <i>Bent</i>	20.00	0.00	*967.70 FL
16	1		*EXAHUST CENTRE PIPE <i>Bent</i>	20.00	0.00	*730.10 FL
17	1		*ADVERTISEMENT - REAR BUMPER <i>no</i>	0	0.00	*50.00 FS
18	2		*ADVERTISEMENT - REAR FENDER - RH/LH <i>no</i>	0	0.00	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,344.70
- List Item Discount on L Items (\$\$)	1,418.94
<b>Total Parts (\$\$)</b>	<b>5,925.76</b>

ComfortDelGro Engineering Pte Ltd/SHC1054C/08/10/2018 13:00. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (S\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	<del>800.00</del> <sup>400</sup>
2	SPRAY PAINTING	New	<del>700.00</del> <sup>600</sup>
3	TUFF KOTE	New	<del>100.00</del> <sup>xs</sup>
4	WIRING CHARGE	New	<del>50.00</del> <sup>20</sup>
Gross Labour Cost (S\$)			1,650.00

ComfortDelGro Engineering Pte Ltd/SHC1054C/08/10/2018 13:00. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Kala 10Kk

✓ 8/10/18 1405 hrs.

3 Days

P/P

Before Paint y foto

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before attempting repairs
- To display damaged part against resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# COMFORTDELGRO ENGINEERING

Our Job Ref No . 305222975

Date : 10. Oct. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC1054C

Date of Accident: 6. Oct. 2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO GW6274H

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$2,955.92

(b) Labour Charges

\$1280.00

**Total for Part-By-Part Repair Cost**

\$4235.92

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Calvin

Name : Calvin

Date : 10/10/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305222975  
 REGN NO : SHC1054C  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 29.12.2016  
 DATE/TIME IN : 06.10.2018 14:30  
 ACCIDENT DATE : 06.10.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	544.50	20.00	435.60
0002	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40
0003	04-01-0103-0852-G	I40VC REFLECTOR/REFLEX AS	1	27.40	20.00	21.92
0004	04-01-0103-0585-A	I40VC LAMP ASSY-RR COMB O	1	697.80	20.00	558.24
0005	04-01-0103-0583-G	I40V2 LAMP ASSY-RR COMB I	1	417.40	20.00	333.92
0006	04-01-0103-0786-G	I40VC EMBLEM-CRDI	1	41.00	20.00	32.80
0007	04-01-0103-0787-G	I40VC EMBLEM-I40	1	41.00	20.00	32.80
0008	02-01-0103-0054-G	I40VC MUFFLER ASSY-RH	1	967.70	20.00	774.16
0009	02-01-0103-0086-G	I40VC PIPE-EXHAUST FR	1	730.10	20.00	584.08

SUB-TOTAL : 2,955.92

## JOB NATURE

0000 L	MERIMEN FEE	10.00
0001 L	PANEL BEATING	400.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305222975  
REGN NO : SHC1054C  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 29.12.2016  
DATE/TIME IN : 06.10.2018 14:30  
ACCIDENT DATE : 06.10.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 23-502	SPRAYPAINT ON AFFECTED AREA			600.00		
0003 17-01	CHECK ALL LIGHTING			20.00		
SUB-TOTAL						: 1,030.00
TOTAL						: 3,985.92

\_\_\_\_\_  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

### ...CLAIM SUBFOLDER...(Pending for Survey Report)































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2018 <a href="#">Sendback Est</a>	08 Oct 2018 13:00 <b>\$7,585.76</b>	09 Oct 2018 10:27 <a href="#">Edit Adj Rpt</a>	<b>\$4,235.92</b> <a href="#">Edit Estimates</a>	<b>\$4,235.92</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>DIAN HUANG ENTERPRISE PTE LTD</b> , Co. Reg. No.: 201015681D								
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	<b>SHC1054C</b>	Date of Loss:	06/10/2018 12:00 - :59 [21 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / M1805029</b>	Policy/Cover Note No.:	MV007330 Coverage: 05/09/2018 - 04/09/2019						
Vehicle Reg. No. (Insured):	<b>GW6274H</b>	Policy No. (Claimant):	MCOM0015						
		Excess:	\$0.00						
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Zheng Hanyang</b> - 65926416]								
Claimant's Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 18/10/2018]								
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE. THKS								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents


**SHC1054C (M1805029)**  
**[GW6274H]**  
**TP**  
**COMFORT TRANSPORTATION PTE LTD**  
**Oct 6 2018 12:00PM**  
**[DIAN HUANG ENTERPRISE PTE LTD]**  
**ComfortDelGro Engineering Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		
1	08/10/18 09:33	<b>Accident Statement</b>	 Load HTM	<input checked="" type="checkbox"/>
2	08/10/18 13:00	<b>Repairer Estimates</b>	 Load HTM	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		
1	09/10/18 10:27	<b>Accident Statement</b> From: SC - Reg. No: GW6274H, Claimant: DIAN HUANG ENTERPRISE PTE LTD	 Load HTM	<input checked="" type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		
1	08/10/18 09:25	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	08/10/18 09:25	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	08/10/18 09:25	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	08/10/18 09:25	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	08/10/18 09:25	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	08/10/18 09:26	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	08/10/18 09:26	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	08/10/18 09:26	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	08/10/18 09:26	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	08/10/18 09:26	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	09/10/18 18:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
				<input checked="" type="checkbox"/>
18	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
21	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
22	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
23	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
24	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
25	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
26	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
27	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
28	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
29	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
30	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
31	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
32	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
33	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
34	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
35	09/10/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
36	10/10/18 17:43	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	10/10/18 17:43	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	10/10/18 17:43	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	19/10/18 12:10	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	08/10/18 09:28	Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	24/10/18 13:00	Letter of Demand from Third Party	Load TIF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	08/10/18 09:33	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	08/10/18 09:25	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	08/10/18 09:25	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	08/10/18 09:25	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	08/10/18 09:25	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	08/10/18 09:25	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	08/10/18 09:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	08/10/18 09:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	08/10/18 09:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	08/10/18 09:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	08/10/18 09:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	08/10/18 09:28	Sketch Plan		Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18018234/K1RBE2

Date: 02/11/2018

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MV007330

Claimant Vehicle No: SHC1054C

Insured Vehicle No: GW6274H

Date of Loss: 06/10/2018

Nature of Claim: TP

Claim No: M1805029

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC1054C

Make &amp; Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDGU700034

Reg. Date: 29/12/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU097724

Colour: Blue

Odometer: 299336 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,925.76	3,205.92	2,719.84	45.90
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,650.00	1,020.00	630.00	38.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,585.76</b>	<b>4,235.92</b>	<b>3,349.84</b>	<b>44.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>531.00</b>	<b>296.51</b>	<b>234.49</b>	<b>44.16</b>
<b>Nett Amount (S\$)</b>	<b>8,116.76</b>	<b>4,532.43</b>	<b>3,584.33</b>	<b>44.16</b>

### INSPECTION

Date of Assignment:	09/10/2018 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	08/10/2018 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2018)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC1054C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Serviceable	1,681.40 FL	*- FL
2	1		*BOOT LID GARNISH	Repair	398.00 FL	*- FL
3	1		*REAR BUMPER	Deformed	544.50 FL	*544.50 FL
4	1		*REAR BUMPER SPONGE	Serviceable	103.50 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Serviceable	428.40 FL	*- FL
6	2		*REAR BUMPER BRACKET - RH/LH	Serviceable	160.60 FL	*- FL
7	1	0	*REAR BUMPER SIDE BARCKET - RH	Serviceable	35.60 FL	*- FL
8	1		*REAR BUMPER UNDERCOVER	Cut	228.00 FL	*228.00 FL
9	1		*REAR BUMPER REFLECTOR - RH	Cut	27.40 FL	*27.40 FL
10	1		*TAIL LAMP - RH	Grazed	697.80 FL	*697.80 FL
11	1		*TAIL LAMP (BOOTLID) - RH	Grazed	417.40 FL	*417.40 FL
12	1		*REAR PANEL	Repair	592.30 FL	*- FL
13	1		*BOOT LID I40	Necessary	41.00 FL	*41.00 FL
14	1		*BOOT LID CRDI	Necessary	41.00 FL	*41.00 FL
15	1		*EXAHUST SILENCER - RH	Bent	967.70 FL	*967.70 FL
16	1		*EXAHUST CENTRE PIPE	Bent	730.10 FL	*730.10 FL
17	1		*ADVERTISEMENT - REAR BUMPER	Necessary	50.00 FS	*50.00 FS
18	2		*ADVERTISEMENT - REAR FENDER - RH/LH	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,344.70</b>	<b>3,944.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,418.94</b>	<b>738.98</b>
<b>Total Parts (\$\$)</b>	<b>5,925.76</b>	<b>3,205.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (\$\$)			10.00	10.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	700.00	600.00
3	TUFF KOTE	New	100.00	0.00
4	WIRING CHARGE	New	50.00	20.00
Gross Labour Cost (\$\$)			1,650.00	1,020.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;