



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00001781-01	Date of Loss:	05/10/2018
Vehicle Reg. No.:	SJD2265A	Driveable?	
Driver Age/Info:	46 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GWEE LAY HIONG	Contact No:	+6597844895
Driver:	GWEE LAY HIONG		
Make/Model:	HONDA STREAM, 1.8 (A)	Vehicle Reg. Date:	13/03/2008
Vehicle Colour:	SILVER	Chassis No:	RN61058149
Engine No:	R18A1765316		
Odometer:	298620 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Remarks:	VEHICLE IN WORKSHOP!		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

NOT ALLOCATED
EXCESS 4?
Whiplash before pa. day - 6 Day.

COST OF CLAIMS

Parts
 Miscellaneous Items
 Labour
 Paintwork Labour
 Towing

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Amount

8,099.00

1,520.00

4,100.00

0.00

0.00

Gross Total (\$\$)**13,719.00****+ GST 7.00% (\$\$)****960.33****Nett Amount (\$\$)****14,679.33**

This claim is handled by: JIMMY GOH - 9040 4688

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Oct 2018)

Parts: M1-MPV HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJD2265A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BUMPER <i>Deep cut</i>	0.00	0.00	*680.00 F	✓
2	1		*REAR BUMPER SIDE RETAINER LH <i>11</i>	0.00	0.00	*48.00 F	X
3	10		*REAR BUMPER CLIPS <i>rec</i>	0.00	0.00	*40.00 F	✓
4	1		*REAR FENDER LH <i>R</i>	0.00	0.00	*900.00 F	X
5	1		*REAR FENDER QUARTER GLASS MOULDING LH <i>11</i>	0.00	0.00	*90.00 F	X
6	1		*REAR DOOR LH <i>300500</i>	0.00	0.00	*850.00 F	✓
7	1		*REAR DOOR UPPER HINGE LH <i>11</i>	0.00	0.00	*65.00 F	X
8	1		*REAR DOOR LOWER HINGE LH	0.00	0.00	*65.00 F	?
9	1		*REAR DOOR WEATHER STRIP LH <i>rec</i>	0.00	0.00	*160.00 F	✓
10	1		*REAR DOOR INNER LOCK LH <i>11</i>	0.00	0.00	*230.00 F	X
11	1		*REAR DOOR FRAME STICKER LH <i>rec</i>	0.00	0.00	*60.00 F	✓
12	1		*ROCKER PANEL LH <i>R</i>	0.00	0.00	*350.00 F	X
13	1		*CENTRE DOOR PILLAR LH <i>R</i>	0.00	0.00	-	X
			REPAIR				
14	1		*FRONT DOOR LH <i>300500</i>	0.00	0.00	*900.00 F	✓
15	1		*FRONT DOOR UPPER HINGE LH	0.00	0.00	*65.00 F	?
16	1		*FRONT DOOR LOWER HINGE LH	0.00	0.00	*65.00 F	?
17	1		*FRONT DOOR WEATHER STRIP LH <i>rec</i>	0.00	0.00	*160.00 F	✓
18	1		*FRONT DOOR INNER LOCK LH <i>11</i>	0.00	0.00	*230.00 F	X
19	1		*FRONT DOOR FRAME STICKER LH <i>rec</i>	0.00	0.00	*75.00 F	✓
20	1		*FRONT FENDER LH <i>300500</i>	0.00	0.00	*550.00 F	✓
21	1		*FRONT FENDER SIGNAL LAMP LH <i>one</i>	0.00	0.00	*38.00 F	✓
22	1		*FRONT FENDER INNER SHIELD LH <i>Two</i>	0.00	0.00	*138.00 F	✓
23	10		*FRONT FENDER INNER SHIELD CLIPS <i>rec</i>	0.00	0.00	*40.00 F	✓
24	1		*FRONT BUMPER <i>De/negat</i>	0.00	0.00	*750.00 F	✓
25	1		*FRONT BUMPER SIDE RETAINER LH <i>set</i>	0.00	0.00	*55.00 F	✓
26	10		*FRONT BUMPER CLIPS <i>rec</i>	0.00	0.00	*40.00 F	✓
27	1		*FRONT SHOCK ABSORBER LH	0.00	0.00	*330.00 F	?
28	1		*FRONT KNUCKLE ARM LH	0.00	0.00	*300.00 F	?
29	1		*FRONT KNUCKLE BEARING LH	0.00	0.00	*95.00 F	?
30	1		*FRONT WHEEL HUB LH	0.00	0.00	*185.00 F	?
31	1		*FRONT LOWER ARM LH	0.00	0.00	*350.00 F	?
32	1		*FRONT STABILIZER LINK LH	0.00	0.00	*105.00 F	?
33	1		*FRONT TIE ROD END LH	0.00	0.00	*90.00 F	?

F=Franchise part.

Total Parts (S\$)

8,099.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT SPORT RIM LH 15 <i>10/ser</i>	550.00
2	1	FRONT TYRE LH (FALKEN) 205/65R15 <i>800</i>	180.00 X
3	1	REAR QUARTER GLASS SEALANT LH <i>11</i>	60.00
4	1	REAR SPORT RIM LH 15 <i>400</i>	550.00
5	1	REAR TYRE LH (FALKEN) 205/65R15 <i>800</i>	180.00 X
Sub Total (S\$)			1,520.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILITATE REPAIR	New <i>1100</i>	1,500.00
2	TO REMOVE & INSTALL LHR FENDER QUARTER GLASS	New <i>11</i>	100.00 X
3	TO REMOVE & INSTALL SEATS,CAPETS & TRIMS TO FACILITATE REPAIR	New <i>60</i>	200.00
4	TO REMOVE & INSTALL LHR DOOR COMPONENTS	New <i>60</i>	80.00
5	TO REMOVE & INSTALL LHF DOOR COMPONENTS	New <i>60</i>	80.00
6	TO REMOVE & INSTALL LHR SPORT RIM INCLUDING TYRE BALANCING	New <i>11</i>	20.00 <i>q</i>
7	TO REMOVE & INSTALL LHF SPORT RIM INCLUDING TYRE BALANCING	New <i>11</i>	20.00 <i>q</i>
8	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	70.00 ✓
9	TO REMOVE & INSTALL LHF UNDERCARRIAGE PARTS	New <i>150?</i>	200.00 ?
10	TO CONDUCT ANTI RUST COATING ON AFFECTED AREAS	New <i>2N</i>	100.00 X
11	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00 ✓
12	TO SPRAY PAINT ON AFFECTED AREAS	New <i>1300</i>	1,700.00
Gross Labour Cost (S\$)			4,100.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

Company Registration No. 199005791M