



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDD 5288K

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	FRONT EMBOSS NUMBER PLATE (SN)	BENT	83.00	83.00
1	FRT BUMPER TOP CARRIER (SN)	NOT NECESSARY	397.45	-
1	FRT LH BOTTOM MOUNTING SIDE PANEL (SN)	NOT NECESSARY	18.00	-
1	FRT RH BOTTOM MOUNTING SIDE PANEL (SN)	NOT NECESSARY	18.00	-
1	FRT LH TOP MOUNTING SIDE PANEL (SN)	NOT NECESSARY	18.00	-
1	FRONT RH TOP MOUNTING SIDE PANEL (SN)	NOT NECESSARY	18.00	-
1	MOUNTING SUPPORT (SN)	NOT NECESSARY	13.25	-
1	INSERT AIR INLET MIDDLE (M) (SN)	NOT NECESSARY	88.80	-
1	SUPPORT FOG LAMP LH (M) (SN)	NOT NECESSARY	41.85	-
1	SUPPORT FOG LAMP RH (M) (SN)	NOT NECESSARY	41.85	-
1	SHOCK ABSORBER FRONT (M) (SN)	NOT NECESSARY	52.15	-
1	FRT BUMPER M PANEL PRIMED (PDC/SRA) (SN)	DEFORMED	1,238.25	1,238.25
1	FLAP TOWING EYE PRIMED (M) (SN)	NOT NECESSARY	42.20	-
1	REPAIR KIT HOLDER BUMPER FRT (M) (SN)	NOT NECESSARY	84.10	-
1	LICENCE PLATE BASE ECE (M) (SN)	SCRATCHED	81.10	81.10
1	M PERFORMANCE FRT ATTACHMENT CARBON (SN) (CRACKED)	NOT CONSISTENT WITH THE IMPACT	3,084.00	-
1	FRONT PANEL V STRUT (SN)	NOT NECESSARY	110.00	-
1	FRT BUMPER BOTTOM CARRIER (M) (SN)	NOT NECESSARY	225.05	-
1	M PERFORMANCE FRONT GRILLE LH BLK (SN)	CRACKED	145.25	145.25
1	M PERFORMANCE FRONT GRILLE RH BLK (SN)	CRACKED	145.25	145.25
1	AIR DUCT RADIATOR (SN)	NOT NECESSARY	51.50	-
1	AIR DUCT BOTTOM (M) (SN)	NOT NECESSARY	51.50	-
1	PLAQUE 82MM (SN)	NECESSARY	69.50	69.50
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	20.20	-
4	PDC SENSOR ALPINWEISS (300) (SN)	NOT NECESSARY	1,475.20	-
1	(DG/SL) ADHESIVE GLUE 1K 50ML (SN)	NOT NECESSARY	57.95	-
			7,821.40	1,842.35



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
	<b>LABOUR</b> REPLACE FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDE REPAIR ON NECESSARY DAMAGE AREA. SPRAY PAINTING FRONT BUMPER. TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		2,550.00	850.00
			1,038.00	934.00
			177.00	150.00
			3,765.00	1,934.00
	<b>GRAND TOTAL</b>		<b>11,586.40</b>	<b>3,776.35</b>
	<b>RECOMMENDED COST OF REPAIRS</b>		<b>0.00</b>	<b>3,776.35</b>
	<b>LESS EXCESS</b>		<b>0.00</b>	<b>-1,000.00</b>
	<b>NETT LIABILITY</b>		<b>0.00</b>	<b>2,776.35</b>

Report Ref No. CS/AWA18018253/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.