

REF: CSI/CTI18018264/ B rd3er

Special Instruction:

L/S: \$15,700.00

From Person: catherine thia CTI Date/Time: 9/10/18
 Estimated Cost: Bill no:

Third Parties:

Claimant:

Surveyor: PAR Automotive consultantsWorkshop: N-SI AutomotiveOD/TP Re-inspection EvaluationTo Inspect Vehicle No: SLA 1844C Insured: GBD 394at Workshop m/s: N-SI Automotive Tel: 68420051of: 2 kaki Bukit Ave 2 #01-17/18Policy No: Claim No: SNM17D06487C02Sum Insured: Excess:Make of Veh: D.O.A. 9/11/2017
(Client's Record)

H.O.D. Endorsement Date:

Date/Time: Person Contacted: Vehicle IN/OUTDate/Time: Confirmed with Final Fig days (Red \$ / %; Original 13 days)Date/Time: 22/10/18 Submit Final Fig L/S \$8600, 8 days (Red \$ 7100 / 45 %; Original 13 days)

Date/Time	Action/Instruction
	SLA 1844C - NA IAGI 702/2/15/13
	GBD 394 - NA IAGI 702/4/15/13
	DoA: 9/11/17
	DoA: 9/11/17
	Repair days 8
	TTCOM
	12/10/18

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 22 OCT 2018

Para(3) : Nett Value

Market Value : Salvage Value : Nett Value : Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

100

100

1) Date/Time: 22/10/18 File Pass to: typist3) Date/Time: File Pass to: 5) Date/Time: File Pass to: 2) Date/Time: File Return to: 4) Date/Time: File Return to: 6) Date/Time: File Return to:

Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Monday, 8 October 2018 5:35 PM
To: assignments
Subject: our ref: SNM17D06487C02 (assignment to do paper survey)
Attachments: TP survey report.pdf

Dear Sir/ Mdm

We refer to the above.

Please assist to do the paper survey on this vehicle.

We will send you the OI and TP GIA report on separate email.

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0441-18-N51

01 August 2018

ACCIDENT VEHICLE SURVEY REPORT

Kan Chong Ho
10 Martaban Road #02-01
Singapore 328668

VEHICLE INFORMATION:

Vehicle Reg No.:	SLA1844C	Odometer:	010277km
Make & Model:	Honda City 1.5 CVT	Colour:	Red
Chassis number:	MRHGM6660GP000448	Date of accident:	09/11/2017
Year of Regn.:	24/02/2016	Date inspected:	13/11/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	23/11/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Bridgestone	6mm/Bridgestone	185/55R16
Rear:	6mm/Bridgestone	6mm/Bridgestone	185/55R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment	
AIRCON CONDENSER	1	bent	386.00	386.00	ETV
AIRCON CONDENSER FAN BLADE	1	warped	49.20	49.20	} NAX
AIRCON CONDENSER FAN COWLING	1	distorted	41.20	41.20	
AIRCON CONDENSER FAN MOTOR	1	shorted	190.10	190.10	
AIRCON CONDENSER LH AIR GUIDE	1	warped	18.60	18.60	} BTV
AIRCON CONDENSER RH AIR GUIDE	1	warped	18.60	18.60	
AIRCON CONDENSER UPPER BRACKET L/R	2	bent	23.00	23.00	
AIRCON CONDENSER UPPER BRACKET RUBBER BUSH L/R	2	deformed	17.00	17.00	NNX
AIRCON DISCHARGE HOSE	1	bent	135.60	135.60	} BTV
AIRCON LIQUID PIPE	1	bent	93.10	93.10	
AIRCON SUCTION HOSE	1	bent	89.60	89.60	
BATTERY TRAY GARNISH	1	deformed	15.50	15.50	NNX
BATTERY UPPER BRACKET	1	repair	15.10	0.00	
FRONT BONNET	1	buckled	397.10	397.10	BTV
FRONT BONNET CENTER WEATHERSTRIP SEAL L/R	2	deformed	21.60	21.60	NNX
FRONT BONNET HINGES L/R	2	bent	62.00	62.00	NNX
FRONT BONNET INSULATOR MAT	1	deformed	39.60	39.60	NNX
FRONT BONNET MECHANISM LOCK	1	bent	87.70	87.70	BTV
FRONT BONNET MECHANISM LOCK CABLE	1	reuse	9.40	0.00	
FRONT BONNET MECHANISM LOCK COVER	1	warped	15.50	15.50	CUTV
FRONT BONNET RUBBER GUIDE STOPPER L/R	2	deformed	33.00	33.00	NNX
FRONT BONNET SIDE WEATHERSTRIP SEAL L/R	2	deformed	21.60	21.60	NNX
FRONT BONNET STAND CLIPS HOLDER	1	reuse	6.50	0.00	
FRONT BUMPER	1	squashed	459.80	459.80	DDV
FRONT BUMPER FOGLAMP COVER L/R	2	fractured	47.20	47.20	BRV
FRONT BUMPER FOGLAMP L/R	2	fractured	555.80	555.80	CUTV
FRONT BUMPER LOWER GRILLE	1	fractured	88.00	88.00	CRAV
FRONT BUMPER LOWER WEATHERSTRIP SEAL	1	deformed	18.50	18.50	CUTV
FRONT BUMPER REINFORCEMENT	1	bent	230.70	230.70	BTV
FRONT BUMPER SIDE RETAINER L/R	2	necessary	42.00	42.00	NECV
FRONT BUMPER TOW HOOK COVER	1	reuse	14.80	0.00	
FRONT FENDER L/R	2	buckled	541.20	541.20	DDV
FRONT FENDER QUARTER GARNISH L/R	2	warped	32.80	32.80	CUTV
FRONT GRILLE	1	fractured	86.90	86.90	BRV
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	23.40	23.40	NECV
FRONT GRILLE BASE	1	fractured	165.10	165.10	BRV
FRONT GRILLE CHROME MOULDING	1	fractured	180.70	180.70	CUTV
FRONT GRILLE INNER BRACKET	1	bent	14.30	14.30	BTV
FRONT GRILLE LH UPPER COVER	1	deformed	24.30	24.30	} CUTV
FRONT GRILLE LOWER MOULDING	1	fractured	24.80	24.80	
FRONT GRILLE RH UPPER COVER	1	deformed	32.30	32.30	
FRONT HEADLAMP L/R	2	fractured	648.20	648.20	CRAV

FRONT HEADLAMP LOWER BRACKET L/R	2	bent	55.00	55.00	BT✓
FRONT HORN	1	distortion	48.50	48.50	NNX
FRONT OUTSIDE TEMPERATURE SENSOR	1	shorted	42.60	42.60	NNX
FRONT SUPPORT PANEL	1	bent	337.80	337.80	BT✓
RADIATOR (AUTO)	1	bent	1,100.50	1,100.50	NNX
RADIATOR FAN BLADE	1	warped	30.30	30.30	NNX
RADIATOR FAN COWLING	1	distorted	54.80	54.80	NNX
RADIATOR FAN MOTOR	1	shorted	200.40	200.40	NNX
RADIATOR LOWER RUBBER BUSH L/R	2	deformed	20.00	20.00	NNX
RADIATOR SPARE TYRE	1	fractured	19.70	19.70	HCX
RADIATOR UPPER BRACKET L/R	2	repair	26.20	0.00	
RADIATOR UPPER BRACKET RUBBER BUSH L/R	2	deformed	21.00	21.00	NNX
REAR BOOTLID	1	buckled	475.00	475.00	DD✓
REAR BOOTLID 'CITY' EMBLEM	1	necessary	15.70	15.70	
REAR BOOTLID 'H' LOGO EMBLEM	1	necessary	15.70	15.70	NEC✓
REAR BOOTLID 'I-VTEC' EMBLEM	1	necessary	16.60	16.60	
REAR BOOTLID CHROME MOULDING	1	fractured	98.50	98.50	CRA✓
REAR BOOTLID CHROME MOULDING CLIPS HOLDER	4	necessary	26.00	26.00	NEC
REAR BOOTLID HINGES L/R	2	bent	132.80	132.80	BT✓
REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	1	deformed	48.50	48.50	NNX
REAR BOOTLID MECHANISM LOCK	1	bent	87.90	87.90	BT✓
REAR BOOTLID OPENER SENSOR BUTTON	1	shorted	132.00	132.00	CUT✓
REAR BOOTLID REFLECTOR BACK RUBBER GASKET L/R	2	necessary	27.00	27.00	NEC✓
REAR BOOTLID REFLECTOR L/R	2	fractured	220.00	220.00	CRA✓
REAR BOOTLID RUBBER GUIDE STOPPER L/R	2	deformed	14.60	14.60	NNX
REAR BOOTLID RUBBER PROTECTOR L/R	2	deformed	16.80	16.80	NNX
REAR BOOTLID WEATHERSTRIP	1	deformed	70.00	70.00	NNX
REAR BUMPER	1	squashed	463.70	463.70	DD✓
REAR BUMPER CENTER REVERSE SENSOR L/R	2	shorted	270.00	270.00	CUT✓
REAR BUMPER LOWER SEAL COVER L/R	2	deformed	50.00	50.00	CUT✓
REAR BUMPER REFLECTOR L/R	2	fractured	60.00	60.00	CUT✓
REAR BUMPER SIDE RETAINER L/R	2	necessary	23.00	23.00	NEC✓
REAR BUMPER SIDE REVERSE SENSOR L/R	1-2	shorted	330.00	165.00	CUT
REAR END PANEL	1	buckled	316.70	316.70	DD✓
REAR END PANEL ANTENNA SENSOR	1	shorted	85.00	85.00	CUT✓
REAR END PANEL BUZZLE SENSOR	1	shorted	80.00	80.00	CUT✓
REAR END PANEL INNER TOP GARNISH	1	fractured	316.70	316.70	BT✓
REAR EXHAUST GASKET	1	necessary	43.20	43.20	
REAR EXHAUST RUBBER MOUNTING	2	distorted	33.00	33.00	NNX
REAR EXHAUST SILENCER BOX	1	bent	380.00	380.00	
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	2	deformed	151.80	151.80	NNX
REAR FENDER L/R	2	repair	2,218.80	0.00	
REAR NUMBER PLATE LAMP L/R	2	fractured	24.00	24.00	NNX
REAR SPARE TYRE INNER TOP CARDBOARD COVER	1	fractured	89.00	89.00	NNX
REAR SPARE TYRE PANEL	1	buckled	399.70	399.70	NNX
REAR TAILLAMP BACK RUBBER GASKET L/R	2	necessary	27.00	27.00	NEC✓

REAR TAILLAMP INNER PANEL L/R	2	buckled	137.60	137.60	R X
REAR TAILLAMP L/R	2	fractured	450.00	450.00	CRA X NA
Subtotal before discount			S\$ 14,320.50	S\$ 12,029.70	
Percentage discount 20% and 20%			S\$ 2,864.10	S\$ 2,405.94	
Sub-total 1			S\$ 11,456.40	S\$ 9,623.76	
AIRCON CONDENSER LH AIR GUIDE CLIPS - SET	1	necessary	30.00	30.00	} NEC V
AIRCON CONDENSER RH AIR GUIDE CLIPS - SET	1	necessary	30.00	30.00	
BATTERY	1	dented	280.00	280.00	NNX
FRONT BONNET INSULATOR MAT CLIPS - SET	1	necessary	30.00	30.00	NNX
FRONT BUMPER CLIPS - SET	1	necessary	50.00	50.00	NEC V
FRONT FENDER INNER SHIELD CLIPS L/R - SET	2	necessary	100.00	100.00	NNX
FRONT FENDER QUARTER GARNISH CLIPS L/R - SET	2	necessary	60.00	50.00	NEC V
FRONT GRILLE CLIPS - SET	1	necessary	50.00	50.00	} NEC V
FRONT NUMBER PLATE	1	bent	25.00	25.00	
FRONT NUMBER PLATE HOLDER	1	bent	50.00	50.00	
REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	1	necessary	40.00	40.00	NNX
REAR BOOTLID REVERSE CAMERA	1	shorted	800.00	800.00	NNX
REAR BUMPER CLIPS - SET	1	necessary	30.00	30.00	} NEC V
REAR BUMPER LOWER SEAL COVER CLIPS L/R - SET	2	necessary	60.00	60.00	
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	30.00	30.00	
REAR FENDER INNER SHIELD CLIPS L/R - SET	2	necessary	60.00	60.00	NNX
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	necessary	60.00	60.00	NNX
REAR FENDER QUARTER GARNISH CLIPS L/R - SET	2	reuse	60.00	0.00	
REAR NUMBER PLATE	1	bent	25.00	25.00	} NNX
REAR NUMBER PLATE HOLDER	1	bent	50.00	50.00	
REAR SPARE TYRE PANEL INSULATOR MAT	1	necessary	250.00	250.00	
REAR TAILLAMP CLIPS L/R - SET	2	necessary	60.00	60.00	NEC V
Subtotal before discount			S\$ 2,230.00	S\$ 2,160.00	
Sub-total 2			S\$ 2,230.00	S\$ 2,160.00	
Parts-total			S\$ 13,686.40	S\$ 11,783.76	

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	180.00	120.00 150.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	200.00	60.00 140.00
To remove and refit rear windscreen(to FR)	150.00	0.00
To remove, reinstall rear suspension and undercarriage part. (to FR)	600.00	0.00
To road test driving, check and resetting wheel alignments system.	180.00	0.00
To remove, reinstall petrol tank. (to FR)	80.00	0.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	150.00	60.00 NNX
To send vehicle for cleaning, shampoo, upholstery and cushion seat.	200.00	0.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare-tyre panel and rear bumper.	2,000.00	1,000.00 1,320.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R), front doors (L/R), and engine bay area.	2,300.00	1,100.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	180.00	50.00 120.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	4,500.00	1,600.00 3,250.00
To mount vehicle on to Car 'O' Liner.	400.00	400.00 NNX
To apply anti-rust chemical on repaired and replaced panel.	150.00	60.00 150.00
Labour Total	SS 11,270.00	SS 6,690.00
Parts & Labour Total	SS 24,956.40	SS 18,473.76

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 15,700.00
and the recommended number of working days for the repairs is within 13 day(s).


B J Loi (I Eng., MIM, AIRTE)
Automotive Appraiser

Repair days 8

Trim

lin

12/10/18

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0441-18-N51

01 August 2018

ACCIDENT VEHICLE SURVEY REPORT

Kan Chong Ho
10 Martaban Road #02-01
Singapore 328668

VEHICLE INFORMATION:

Vehicle Reg No.:	SLA1844C	Odometer:	010277km
Make & Model:	Honda City 1.5 CVT	Colour:	Red
Chassis number:	MRHGM6660GP000448	Date of accident:	09/11/2017
Year of Regn.:	24/02/2016	Date inspected:	13/11/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	23/11/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/11/2017 14:26
Date Of Accident	09/11/2017 10:30
Exact Location Of Accident	BKE TWDS JURONG B4 PIE CHANGI EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLA1844C
Insured/Policyholder	
Name Of Registered Owner	KAN CHONG HO
NRIC No	S2030186D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83494707
Alternative Phone No	OTHERS-81215820
Vehicle Particulars	
Manufacturer	HONDA
Model	CITY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100500776-00000
Cover Note Number	
Driver	
Name of Driver	KAN CHONG HO
NRIC No	S2030186D
Date Of Birth	22/11/1948
Occupation	INDOOR
Date Of Driving Pass	12/06/1973
Driving Experience	44 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83494707
Fax Number	
Contact Number	OTHERS-81215820
Email Address	NOEMAIL

Address	10 MARTABAN ROAD #02-01
Postcode	328668
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD39U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKW6217B
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLE7682S
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name KAN CHONG HO
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SLA1844C
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


Driver's Signature
(if driver is not the policyholder)
Date & Time

Report Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

VEHICLE 01 - SUBARU
 VEHICLE 02 - GSD 344
 VEHICLE 03 - NEW 60743
 VEHICLE 04 - GSD 344



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. VEHICLE 01 (SUBARU) WAS TRAVELLING ALONG THE ROAD AND WAS IN THE RIGHT HAND LANE.
2. VEHICLE 02 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
3. VEHICLE 03 (NEW 60743) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
4. VEHICLE 04 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
5. VEHICLE 01 (SUBARU) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
6. VEHICLE 02 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
7. VEHICLE 03 (NEW 60743) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
8. VEHICLE 04 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
9. VEHICLE 01 (SUBARU) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
10. VEHICLE 02 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
11. VEHICLE 03 (NEW 60743) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
12. VEHICLE 04 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
13. VEHICLE 01 (SUBARU) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
14. VEHICLE 02 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
15. VEHICLE 03 (NEW 60743) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
16. VEHICLE 04 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
17. VEHICLE 01 (SUBARU) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
18. VEHICLE 02 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
19. VEHICLE 03 (NEW 60743) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.
20. VEHICLE 04 (GSD 344) WAS TRAVELLING STRAIGHT AHEAD AND APPROXIMATELY IN THE MIDDLE OF THE ROAD.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
 Date & Time

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature
 Name
 ID Card No.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Your Ref: SNM17D06487C02

Date: 25th Oct 2018

Our Ref: CS1/CTI18018264/Brd3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLA 1844C
INSURED VEHICLE: GBD 39U
ACCIDENT DATE: 09/11/2017**

We thank you for your instruction on 09/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLA 1844C from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SLA 1844C.
- c) Colour damaged vehicle photographs of SLA 1844C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLA 1844C
Make & Model	: Honda City 1.5 CVT
Year of Registration	: 2016
Chassis Number	: MRHGM6660GP000448
Engine Capacity	: 1497 cc
2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1844C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	AIRCON CONDENSER	BENT	386.00	386.00
1	AIRCON CONDENSER FAN BLADE	NOT NECESSARY	49.20	-
1	AIRCON CONDENSER FAN COWLING	NOT NECESSARY	41.20	-
1	AIRCON CONDENSER FAN MOTOR	NOT NECESSARY	190.10	-
1	AIRCON CONDENSER LH AIR GUIDE	BENT	18.60	18.60
1	AIRCON CONDENSER RH AIR GUIDE	BENT	18.60	18.60
2	AIRCON CONDENSER UPPER BRACKET L/R	BENT	23.00	23.00
2	AIRCON CONDENSER UPPER BRACKET RUBBER BUSH L/R	NOT NECESSARY	17.00	-
1	AIRCON DISCHARGE HOSE	BENT	135.60	135.60
1	AIRCON LIQUID PIPE	BENT	93.10	93.10
1	AIRCON SUCTION HOSE	BENT	89.60	89.60
1	BATTERY TRAY GARNISH	NOT NECESSARY	15.50	-
1	BATTERY UPPER BRACKET	TO REPAIR SEE LABOUR	15.10	-
1	FRONT BONNET	BENT	397.10	397.10
2	FRONT BONNET CENTER WEATHERSTRIP SEAL L/R	NOT NECESSARY	21.60	-
2	FRONT BONNET HINGES L/R	NOT NECESSARY	62.00	-
1	FRONT BONNET INSULATOR MAT	NOT NECESSARY	39.60	-
1	FRONT BONNET MECHANISM LOCK	BENT	87.70	87.70
1	FRONT BONNET MECHANISM LOCK CABLE	REUSE	9.40	-
1	FRONT BONNET MECHANISM LOCK COVER	CUT	15.50	15.50
2	FRONT BONNET RUBBER GUIDE STOPPER L/R	NOT NECESSARY	33.00	-
2	FRONT BONNET SIDE WEATHERSTRIP SEAL L/R	NOT NECESSARY	21.60	-
1	FRONT BONNET STAND CLIPS HOLDER	REUSE	6.50	-
1	FRONT BUMPER	DENTED	459.80	459.80
2	FRONT BUMPER FOGLAMP COVER L/R	BROKEN	47.20	47.20
2	FRONT BUMPER FOGLAMP L/R	CUT	555.80	555.80
1	FRONT BUMPER LOWER GRILLE	CRACKED	88.00	88.00
1	FRONT BUMPER LOWER WEATHERSTRIP SEAL	CUT	18.50	18.50
1	FRONT BUMPER REINFORCEMENT	BENT	230.70	230.70

Report Ref No. CS1/CT118018264/Brd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT BUMPER SIDE RETAINER L/R	NECESSARY	42.00	42.00
1	FRONT BUMPER TOW HOOK COVER	REUSE	14.80	-
2	FRONT FENDER L/R	DENTED	541.20	541.20
2	FRONT FENDER QUARTER GARNISH L/R	CUT	32.80	32.80
1	FRONT GRILLE	BROKEN	86.90	86.90
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	23.40	23.40
1	FRONT GRILLE BASE	BROKEN	165.10	165.10
1	FRONT GRILLE CHROME MOULDING	CUT	180.70	180.70
1	FRONT GRILLE INNER BRACKET	BENT	14.30	14.30
1	FRONT GRILLE LH UPPER COVER	CUT	24.30	24.30
1	FRONT GRILLE LOWER MOULDING	CUT	24.80	24.80
1	FRONT GRILLE RH UPPER COVER	CUT	32.30	32.30
2	FRONT HEADLAMP L/R	CRACKED	648.20	648.20
2	FRONT HEADLAMP LOWER BRACKET L/R	BENT	55.00	55.00
1	FRONT HORN	NOT NECESSARY	48.50	-
1	FRONT OUTSIDE TEMPERATURE SENSOR	NOT NECESSARY	42.60	-
1	FRONT SUPPORT PANEL	BENT	337.80	337.80
1	RADIATOR (AUTO)	NOT NECESSARY	1,100.50	-
1	RADIATOR FAN BLADE	NOT NECESSARY	30.30	-
1	RADIATOR FAN COWLING	NOT NECESSARY	54.80	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	200.40	-
2	RADIATOR LOWER RUBBER BUSH L/R	NOT NECESSARY	20.00	-
1	RADIATOR SPARE TYRE (FRACTURED)	NOT CONSISTENT WITH THE IMPACT	19.70	-
2	RADIATOR UPPER BRACKET L/R	TO REPAIR SEE LABOUR	26.20	-
2	RADIATOR UPPER BRACKET RUBBER BUSH L/R	NOT NECESSARY	21.00	-
1	REAR BOOTLID	DENTED	475.00	475.00
1	REAR BOOTLID 'CITY' EMBLEM	NECESSARY	15.70	15.70
1	REAR BOOTLID 'H' LOGO EMBLEM	NECESSARY	15.70	15.70
1	REAR BOOTLID 'I-VTEC' EMBLEM	NECESSARY	16.60	16.60
1	REAR BOOTLID CHROME MOULDING	CRACKED	98.50	98.50
4	REAR BOOTLID CHROME MOULDING CLIPS HOLDER	NECESSARY	26.00	26.00
2	REAR BOOTLID HINGES L/R	BENT	132.80	132.80

Report Ref No. CS1/CTI18018264/Brd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	NOT NECESSARY	48.50	-
1	REAR BOOTLID MECHANISM LOCK	BENT	87.90	87.90
1	REAR BOOTLID OPENER SENSOR BUTTON	CUT	132.00	132.00
2	REAR BOOTLID REFLECTOR BACK RUBBER GASKET L/R	NECESSARY	27.00	27.00
2	REAR BOOTLID REFLECTOR L/R	CRACKED	220.00	220.00
2	REAR BOOTLID RUBBER GUIDE STOPPER L/R	NOT NECESSARY	14.60	-
2	REAR BOOTLID RUBBER PROTECTOR L/R	NOT NECESSARY	16.80	-
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	70.00	-
1	REAR BUMPER	DENTED	463.70	463.70
2	REAR BUMPER CENTER REVERSE SENSOR L/R	CUT	270.00	270.00
2	REAR BUMPER LOWER SEAL COVER L/R	CUT	50.00	50.00
2	REAR BUMPER REFLECTOR L/R	CUT	60.00	60.00
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	23.00	23.00
2	REAR BUMPER SIDE REVERSE SENSOR L/R	CUT-1PC ONLY	330.00	165.00
1	REAR END PANEL	DENTED	316.70	316.70
1	REAR END PANEL ANTENNA SENSOR	CUT	85.00	85.00
1	REAR END PANEL BUZZLE SENSOR	CUT	80.00	80.00
1	REAR END PANEL INNER TOP GARNISH	BENT	316.70	316.70
1	REAR EXHAUST GASKET	NOT NECESSARY	43.20	-
2	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	33.00	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	380.00	-
2	REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	NOT NECESSARY	151.80	-
2	REAR FENDER L/R	TO REPAIR SEE LABOUR	2,218.80	-
2	REAR NUMBER PLATE LAMP L/R	NOT NECESSARY	24.00	-
1	REAR SPARE TYRE INNER TOP CARDBOARD COVER	NOT NECESSARY	89.00	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	399.70	-
2	REAR TAILLAMP BACK RUBBER GASKET L/R	NECESSARY	27.00	27.00
2	REAR TAILLAMP INNER PANEL L/R	TO REPAIR SEE LABOUR	137.60	-
2	REAR TAILLAMP L/R	NOT NECESSARY	450.00	-
	LESS 20% DISCOUNT		-2,864.10	-1,595.58
			11,456.40	6,382.32

Report Ref No. CS1/CTI18018264/Brd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
1	SET AIRCON CONDENSER LH AIR GUIDE CLIPS (SN)	NECESSARY	30.00	30.00
1	SET AIRCON CONDENSER RH AIR GUIDE CLIPS (SN)	NECESSARY	30.00	30.00
1	BATTERY (SN)	NOT NECESSARY	280.00	-
1	SET FRONT BONNET INSULATOR MAT CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
2	SET FRONT FENDER INNER SHIELD CLIPS L/R (SN)	NOT NECESSARY	100.00	-
2	SET FRONT FENDER QUARTER GARNISH CLIPS L/R	NECESSARY	60.00	50.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT NUMBER PLATE (SN)	NECESSARY	25.00	25.00
1	FRONT NUMBER PLATE HOLDER (SN)	NECESSARY	50.00	50.00
1	SET REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	NOT NECESSARY	40.00	-
1	REAR BOOTLID REVERSE CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
2	REAR BUMPER LOWER SEAL COVER CLIPS L/R (SN)	NECESSARY	60.00	60.00
1	REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
2	SET REAR FENDER INNER SHIELD CLIPS L/R (SN)	NOT NECESSARY	60.00	-
2	SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R (SN)	NOT NECESSARY	60.00	-
2	REAR FENDER QUARTER GARNISH CLIPS L/R (SN)	REUSE	60.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR SPARE TYRE PANEL INSULATOR MAT (SN)	NOT NECESSARY	250.00	-
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY	60.00	60.00
			2,230.00	465.00
LABOUR				
TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS.			180.00	120.00
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.			200.00	50.00
TO REMOVE AND REFIT REAR WINDSCREEN. (TO FR)		NOT NECESSARY	150.00	-
TO REMOVE, REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART. (TO FR)		NOT NECESSARY	600.00	-

Report Ref No. CS1/CTI18018264/Brd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM.	NOT NECESSARY	180.00	-
	TO REMOVE, REINSTALL PETROL TANK. (TO FR)	NOT NECESSARY	80.00	-
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	NOT NECESSARY	150.00	-
	TO SEND VEHICLE FOR CLEANING, SHAMPOO, UPHOLSTERY AND CUSHION SEAT.	NOT NECESSARY	200.00	-
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R) AND REAR BUMPER.		2,000.00	1,000.00
	TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER (L/R) AND FRONT DOOR (L/R).		2,300.00	1,100.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		180.00	50.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF BATTERY UPPER BRACKET, RADIATOR UPPER BRACKET L/R AND REAR TAILLAMP INNER PANEL L/R.		4,500.00	1,600.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	NOT NECESSARY	400.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		150.00	60.00
			11,270.00	3,980.00
GRAND TOTAL			24,956.40	10,827.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,600.00

Report Ref No. CS1/CT18018264/Brd3e2

LIM TEOW GUAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.