

Surveyor:

REF: CS3 / MSCH701177 / Bdp-1

Special Instruction:

45: \$ 10100.00

From (Person): Chua Li Suan of ComLaw Date/Time: 06-10-2018
 Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: CL AppraiserWorkshop: Gforce Autotech

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SLF 536Y Insured: FT 9096m

at Workshop m/s Gforce Autotech Tel: _____
 of 10 Kaki Bukit Rd 2 #01-34

Policy No: CLS.2018.717574 Claim No: MSC/V/17-000923

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 08062017

(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: 10/10/18 Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 11 days)Date/Time: _____ Submit Final Fig 3950, 8 days (Red \$ 6150.61 %; Original 11 days)

Date/Time	Action/Instruction
	<u>SLF 536Y - CS3 / MSCH701177 / J602</u>
	<u>FT 9096m - NA / MSCH7012306 / h4</u>
	<u>QA: 08062017</u>
	<u>QA: 08062017</u>
	<u>* type report in VIEWS, send hard copy to ComLaw. - checked with [Signature]</u>
	<u>Repair days 8</u>
	<u>TCRM [Signature]</u>
	<u>10/10/18</u>

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 11 OCT 2018

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add
Transport
Photos
Others
Total

200-120801) Date/Time 11/10/18 File Pass to thrust

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time _____

4) Date/Time _____

6) Date/Time _____

File Return to _____

File Return to _____

File Return to _____

ASS/REC BY:

REF:

CS5/ms617011477/J b2

Special Instructions

Large

Surveyor:

Murad

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MS16

Date/Time:

13/06/2017 3:20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 536Y

Insured:

FT 9096M

at Workshop m/s

Gforce Autotechnik

Tel:

8 284 6115

of

10 Kaki Bukit Rd 3 # 01-24

Policy No:

ME0/VMT/16-976912

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

08062017

CA / REV / REP. / REV 24 HRS WPI

14.06.2017 @ 9am

H.O.D. Information

Date/Time: 13/06/2017 5:07pm

Person Contacted:

Mr. Lim

Vehicle ENL 0137

Date/Time

Action/Instruction (X) Estimate

SLF 536Y - x

Estimate Repair Range \$4K - \$5K

FT 9096M - x

Final 24/5

13/06/17 4:30pm

Email to Catherine Thia thru Marmen

Dismantle Part : 14/06/2017

After repair : 19/06/2017

PRS
SIRHAN RICHARD
mehman

REF: m3th

ASSIGNMENT

From: Date: 14062017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

SLF 5367

at Workshop m/s

Gforce Autotech

of

10 Kaki Bukit Rd 2 # 01-34

Insured:

Policy No.

Claims No.

Sum Insured

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

99m

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No:

SLF 5367

Regn: 2016

22/02

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA ALTIS

cc 1598

Colour:

WHITE

Insured / Std / NI / NA

Sp. Reading:

74201

T. Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRUS? REH? S982

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 R16

MIC

R:

205/55 R16

YOKOHAMA

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

5

mm

L/Bal:

6

mm

L/Bal:

5

mm

D.O.A.

DO:

14/6

9:00 am

Survey held at

Gforce Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time: File Pass to?

1) 26/07/2017

Date/Time: File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Taxation:

1) 1st - RS \$

2) 2nd - RS \$

3) 3rd - RS \$

4) 4th - RS \$

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

PRS

Lump Sum / I.B.I: (\$

180

Catherine Chong (LKK Auto)

From: Chua Li Suan <cls@comlaw.com.sg>
Sent: Saturday, 6 October, 2018 12:15 PM
To: assignments@lkkauto.com
Subject: (yr ref : CS3/MSG17011477/JBE2) ACC ON 8.6.2017 INV FT 9096M AND SLF 536Y
ALONG TECK WHYE AVENUE MC 10310/2018 (OUR REF: CLS.2018.217574)
Attachments: SLF536Y - estimate from LKK.PDF; Survey Report.pdf; survey photos.pdf; FT9096M
e-file report.pdf; SLF536Y E-FILE REPORT.PDF

Dear Sirs

1. We act for MSIG Insurance (S) Pte Ltd and note that your surveyor did pre-repair, dismantled parts, and post-repair surveys. Attached is your report dated 31 July 2017.
2. MSIG are now requesting that you put up your paper adjustments in the light of the survey report and photos of the Plaintiff's surveyors CL Appraiser Pte Ltd. Attached are the said report and photos.
3. We also attach herewith both parties' accident reports.
4. Kindly acknowledge receipt of this email, and let us have your paper re-survey report as soon as possible. Thank you.

Warm regards
Chua Li Suan
DID: 6506 9132

ComLaw LLC
64 Cecil St #06-01
IOB Building
Singapore 049711

C L APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Vermax Car Leasing And Marketing Pte Ltd
C/o: GFORCE AutoTech Private Limited
10 Kaki Bukit Road 2
#01-34 Singapore 417868


Invoice No: CL/17427
Ref No: GFA/06/1701/TP
Date: 24 June 2017

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>SLF 536 Y</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)TRANSPORTATION	
GRAND TOTAL	S\$ 752.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

LCL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Hp: 90688689 Email: clappraiser@yahoo.com
Reg No: 20100228E

VEHICLE INSPECTION REPORT

To: Vermax Car Leasing And Marketing Pte Ltd
C/o: GFORCE AutoTech Private Limited
10 Kaki Bukit Road 2
#01-34 Singapore 417868

Date : 24 June 2017
Our ref : GFA/06/1701/TP

Accident Date : 08 June 2017
Inspection Date : 14 June 2017
Repairer Name : GFORCE AutoTech Private Limited
10 Kaki Bukit Road 2
#01-34 Singapore 417868

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SLF 536 Y
Make / Model : Toyota Corolla Altis
Chassis No : MR053REH104545982
Engine No : 1ZR554205

Year / Capacity : 2016 / 1598 cc
Colour : White
Mileage : 74701

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Michelin	205/55 R16	5 mm	Sport
Front Offside	: Michelin	205/55 R16	5 mm	Sport
Rear Nearside	: Michelin	205/55 R16	5 mm	Sport
Rear Offside	: Michelin	205/55 R16	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 82 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 10,100.00** on a contractual basis.

Under normal circumstances, the repair period would be about 11 (Eleven) working days.

ECL APPRAISER PTE LTD

Vehicle Registration No: SLF 536 Y

Our Ref No: GFA/06/1701/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear windscreen moulding	Necessary	\$ 156.80	\$ 156.80 x NNx
1	Rear bumper	Damage	\$ 488.70	\$ 488.70 x DD ✓
1	Rear bumper n/s side retainer	Necessary	\$ 47.00	\$ 47.00 x NEC ✓
1	Rear n/s fender	Damage	\$ 1,120.70	\$ 1,120.70 x DDTF
1	Rear n/s wheel hub with bearing	Damage	\$ 444.90	\$ 444.90 x NNx
1	Rear n/s shock absorber	Damage	\$ 264.50	\$ 264.50 x NNx
1	Rear n/s axle beam	Intact	\$ 1,844.30	
1	Rear n/s door	Damage	\$ 1,270.80	\$ 1,270.80 x DD ✓
2	Rear n/s door hinges	Damage	\$ 157.80	\$ 157.80 x NNx
1	Rear n/s door inner board	Damage	\$ 632.10	\$ 632.10 x NNx
1	Rear n/s door inner lock	Damage	\$ 548.30	\$ 548.30 x NNx
1	Rear n/s door regulator	Damage	\$ 344.50	\$ 344.50 x NNx
1	Rear n/s door regulator motor	Damage	\$ 529.60	\$ 529.60 x NNx
1	Rear n/s door rubber opening	Necessary	\$ 267.50	\$ 267.50 x NNx
1	N/s rocker panel	Damage	\$ 558.00	\$ 558.00 x DD ✓
1	Front n/s door	Damage	\$ 1,345.60	\$ 1,345.60 x DD ✓
1	Front n/s door inner board	Damage	\$ 632.10	\$ 632.10 x NNx
1	Front n/s door lock	Damage	\$ 642.80	\$ 642.80 x NNx
1	Front n/s door regulator	Intact	\$ 281.50	
1	Front n/s door regulator motor	Intact	\$ 299.20	
1	Front n/s door rubber opening	Necessary	\$ 248.70	\$ 248.70 x NNx
1	Front n/s door rubber	Necessary	\$ 121.60	\$ 121.60 x NNx
			\$ 12,247.00	\$ 9,822.00
			Less 25%	\$ 3,061.75
Total Cost - List Items			\$ 9,185.25	\$ 7,366.50

SPECIAL NETT ITEMS

1	Rear windscreen sealant	Necessary	\$ 80.00	\$ 50.00 40
1	Rear bumper clip (1 set)	Necessary	\$ 45.00	\$ 45.00 30
1	Rear n/s wheel rim	Damage	\$ 800.00	\$ 800.00 250
1	Rear n/s tyre (Depreciation)	Damage	\$ 350.00	\$ 175.00 x NNx
Total Cost - Special Nett items			\$ 1,275.00	\$ 1,070.00

Total cost of parts

\$ 10,460.25 \$ 8,436.50

Total: 64647.
Lis: 5100

LCL APPRAISER PTE LTD

Vehicle Registration No: SLF 536 Y

Our Ref No: GFA/06/1701/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 10,460.25	\$ 8,436.50

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 20.00
2	To remove and refit roof top linning, cushion seat, carpets and interior upholstery to assist repair.	\$ 180.00	\$ 120.00 60.00
3	To remove and refit fuel tank assembly with all attachments, pipe and hoses.	\$ 150.00	\$ 120.00 *NNX
4	To remove and refit rear undercarriage.	\$ 350.00	\$ 200.00 60.00
5	To conduct wheel alignment.	\$ 150.00	\$ 120.00 80.00
6	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 80.00
7	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 300.00	\$ 240.00 120.00
8	To apply undercoating on repaired and replaced panel.	\$ 200.00	\$ 150.00 60.00
9	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 2,000.00	\$ 1,750.00 800.00
10	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,800.00	\$ 1,320.00 800.00

GRAND TOTAL

\$ 15,850.25 \$ 12,626.50

Repair days 8

Trim lin

10/10/18

C L APPRAISER PTE LTD

Vehicle Registration No: SLF 536 Y

Our Ref No: GFA/06/1701/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 10,100.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17011477/JBE2
Date: 31/07/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/16-976912
Claimant Vehicle No :	SLF536Y	Insured Vehicle No :	FT9096M
Date of Loss:	08/06/2017	Nature of Claim:	TP
			Claim No: MSC/V/17-000923

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF536Y	Engine No:	1ZR554205
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104545982
Reg. Date:	22/02/2016 (Man. Year: 2015)	Odometer:	74701 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55/16	Rear Tyre Size:	205/55/16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/06/2017		
Date Inspected:	14/06/2017	Inspected At:	Gforce Autotech (HQ) BLK 10 KAKI BUKIT ROAD 2, #01-34 Singapore 417868
Estimated Period of Repair:	6.0 days		

Adjuster: Richard Harjanto

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4000.00 - \$5000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jul 2017)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: LKK Auto Consultants Pte Ltd/SLF536Y/31/07/2017 09:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/SLF536Y/31/07/2017 09:40. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SLF536Y/31/07/2017 09:40. Not valid without Reference section.

< END OF ESTIMATES >

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17011477/Bqbe2-1

C/O: COMLAW LLC

64 CECIL ST

#06-01 IOB BLDGSINGAPORE 049711

Date : 11-10-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FT 9096M	Veh. Inspected	SLF 536Y
Policy No.	CLS.2018.217574	Coverage (\$)	0.00
Claim No.	MSC/V/17-000923	Excess (\$)	0.00
Assign From	CHUA LI SUAN	Assign Date	06/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104545982	Colour	WHITE
Odometer	74701	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/06/2017	Inspection Date	14/06/2017
Survey held at	GFORCE AUTOTECH PRIVATE LIMITED 10 KAKI BUKIT ROAD 2 #01-34 FIRST EAST CENTRE SINGAPORE 417868		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 536Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	156.80	-
1	REAR BUMPER	DENTED	488.70	488.70
1	REAR BUMPER N/S SIDE RETAINER	NECESSARY	47.00	47.00
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	1,120.70	-
1	REAR N/S WHEEL HUB WITH BEARING	NOT NECESSARY	444.90	-
1	REAR N/S SHOCK ABSORBER	NOT NECESSARY	264.50	-
1	REAR N/S AXLE BEAM	INTACT	1,844.30	-
1	REAR N/S DOOR	DENTED	1,270.80	1,270.80
2	REAR N/S DOOR HINGES	NOT NECESSARY	157.80	-
1	REAR N/S DOOR INNER BOARD	NOT NECESSARY	632.10	-
1	REAR N/S DOOR INNER LOCK	NOT NECESSARY	548.30	-
1	REAR N/S DOOR REGULATOR	NOT NECESSARY	344.50	-
1	REAR N/S DOOR REGULATOR MOTOR	NOT NECESSARY	529.60	-
1	REAR N/S DOOR RUBBER OPENING	NOT NECESSARY	267.50	-
1	N/S ROCKER PANEL	DENTED	558.00	558.00
1	FRONT N/S DOOR	DENTED	1,345.60	1,345.60
1	FRONT N/S DOOR INNER BOARD	NOT NECESSARY	632.10	-
1	FRONT N/S DOOR LOCK	NOT NECESSARY	642.80	-
1	FRONT N/S DOOR REGULATOR	INTACT	281.50	-
1	FRONT N/S DOOR REGULATOR MOTOR	INTACT	299.20	-
1	FRONT N/S DOOR RUBBER OPENING	NOT NECESSARY	248.70	-
1	FRONT N/S DOOR RUBBER	NOT NECESSARY	121.60	-
	LESS 25% DISCOUNT		-3,061.75	-927.53
			9,185.25	2,782.57
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	REAR N/S WHEEL RIM (SN)	DAMAGED	800.00	250.00
1	REAR N/S TYRE (SN)	NOT NECESSARY	350.00	-
			1,275.00	320.00
LABOUR				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING,		80.00	20.00

Report Ref No. CS3/MSG17011477/Bqbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT ROOF TOP LINING, CUSHION SEAT, CARPETS AND INTERIOR UPHOLSTERY TO ASSIST REPAIR.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS, PIPE AND HOSES.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.		300.00	120.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		200.00	60.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR N/S FENDER.		2,000.00	800.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,800.00	800.00
			5,390.00	1,860.00
GRAND TOTAL			15,850.25	4,962.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,950.00

Report Ref No. CS3/MSG17011477/Bqbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.