

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18018346/AEA3Q2

Date: 16/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994788

Claimant
Vehicle No : SLV4752D **Insured Vehicle No :** SLL3606C

Date of Loss: 09/08/2018 Nature of Claim: TP Claim No: 8911531383SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV4752D		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR8255844
Reg. Date:	29/12/2017 (Man. Year: 2017)	Chassis No:	ZVW506100879
Colour:	Silver	Odometer:	90833 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,896.72	2,823.09	5,073.63	64.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	910.00	990.00	52.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,796.72	3,733.09	6,063.63	61.89
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	9,796.72	2,900.00	6,896.72	70.40
+ GST 7.00/7.00% (S\$)	685.77	203.00	482.77	70.40
Nett Amount (S\$)	10,482.49	3,103.00	7,379.49	70.40
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,710.45		

INSPECTION

Date of Assignment: 09/10/2018

Date Inspected: 09/10/2018 Inspected At:

Green Forest Automobile Pte Ltd (Kaki Bukit)
8 Kaki Bukit Avenue 4, #05-25,,
Premier@Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEAD LAMP -LH	Cracked	1,885.00 F	*1,080.00 FL
2	1		*FRONT BUMPER	Deformed	1,050.00 F	*972.00 FL
3	1		*FRONT BUMPER SIDE BRACKET	N/S Damaged	242.00 F	*121.00 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	1		*FRONT BUMPER FOG LAMP -LH	Cracked	385.00 F	*385.00 FL
6	1		*FRONT BUMPER FOG LAMP COVER-LH	Not Necessary	155.00 F	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	635.00 F	*- FL
8	1		*FRONT FENDER -LH	Dented	752.25 F	*752.25 FL
9	1		*FRONT FENDER INNER GARNISH -LH	Deformed	127.20 F	*127.20 FL
10	4		*FRONT FENDER INNER GARNISH CLIPS	Necessary	51.60 F	*30.00 FL
11	1		*FRONT L/H LOWER ARM	Not Necessary	287.72 F	*- FL
12	1		*FRONT L/H KNUCKLE ARM	Not Necessary	281.85 F	*- FL
13	1		*FRONT L/H KNUCKLE ARM BEARING	Not Necessary	161.40 F	*- FL
14	1		*FRONT L/H SHOCK ABSORBER	Not Necessary	381.20 F	*- FL
15	1		*FRONT L/H DOOR SIDE MIRROR	Repair	421.50 F	*- FL
16	1		*FRONT SPORT RIM -LH	Cut	600.00 FS	*200.00 FS
17	1		*FRONT TYRE -LH	Not Necessary	450.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,896.72	3,697.45
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	874.36
Total Parts (\$\$)	7,896.72	2,823.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL CUSHION	New	120.00	0.00
2	TUFF KOTE	New	120.00	0.00
3	TO WHEEL ALIGNMENT COMPUTER	New	120.00	80.00
4	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	280.00	0.00
5	TO CHECK WIRING SYSTEM	New	60.00	30.00
6	PANEL BEATING	New	600.00	400.00
7	SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (\$\$)			1,900.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >