Munico Ohisting word MSIG 10/10/2018 OD (T)/WS/TP RESTOR RESTEVA/INVIMVICS To the part Vehicle No. SUR 6367P Insured 845 3547P at Westerland H.S. Automotive Tel: 6538 1368 To be and Velocia No. BIK 2 Kaki BK+ No 2 # 01-15 10 y 28719908AVW Claus No. 566721 Sun besst Excess: DOA 06 08 2018 CA FREV / REP. / REV 24 HRS (W) H.O.D. Endomencol. De The 9 1800 1418 Form Consisted Mr. Ale Vehicle DOUT Dustries Assontinguages (+) Estimate 81863671 - NATECT 18014309/K1 DOA - 618/15 3KS 35 171 - NA FC18014369/K4 120A 6/8/18 Dismantle 15/8/2018 Wher repair sofe DOIS Submit Lls \$ 2550.00, 5 days (Red: \$ 3450.00, 58%) Repair days 5

RECEIVED 8 5 NOV 2018

TOUM

30/10/18

Tanples GE 219 74 Type M Cycle / Bus / Van / Lony / Tax / Frime Mover / Truck / Trailer or ODE TO WESTERS FOR RESTEVATING IN Colon Store Senz 17170 - 1699

Colon Store Store Store No. 10 Store No. NA

So Faradino 133466 +48 Tilladio Insured I Store NU. NA WDP 1690322J740020 Gen Gond (out / Fair / Poor / Burnt Steering Inorder Jammed / Leaked / Burnt or ---Brake Ino de Lammed Leaked / Burnt or Mod Nil / SiRtm / STD A/Rim 195/ SJR/1 Fig. The veh han commenced its BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM/ / repair at the time of inspection TOYO! YORO O The West Value R/Ball Containing Yes of No. GUL Sann Consumer? Yes o No. HIS Automotive Desigt Damages | Ent. | Rear | O/S | N/S | U/C | Roottop or CA REV / REF / 24 HRS 0/5 Rear Vehicle IN/OUT The U/C / Chassis frame / Body Structure affected doe to college Etmakdrepair range \$2500 - \$8,300 Range and No. of days has a dumit Phr Report Preti Report Days Of Repair Resurvey No. of Trip. 3 Talles Irrage (\$ Add Fee: FRS

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	06/08/2018 17:43
Date Of Accident	06/08/2018 16:00
Exact Location Of Accident	WOODLANDS CHECKPOINT /QUENE FOR IMMGRATION COUNTER
Country/State of Loss	SINGAPORE
C	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJR6367P
Insured/Policyholder	
Name Of Registered Owner	ROBINSON CAR RENTAL PTE LTD
Co Reg No	
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96168801
Alternative Phone No	OFFICE-96168801
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D-18090229MFZH/2
Cover Note Number	
Driver	
Name of Driver	FONG YVONNE (FANG YVONNE)
NRIC No	S7823523C
Date Of Birth	20/08/1978
Occupation	OUTDOOR
Date Of Driving Pass	02/04/1997
Driving Experience	21 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96168801
Fax Number	

OTHERS-96168801

NOEMAIL

Address

BLK 206 TOA PAYOH NORTH

#06-1203

Postcode

310206

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKS3547P

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

CHAN BAK THIAM

NRIC/Passport Number

S1746259H

Contact Number

97348259

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the data is of the arcident to speed up the claims process.
- The Policyholder and/or the Authorised Driver
- If a making provided must be as truthful and accurate as possible. Any wife increases at one is with each of national factor may show insurance companies to repudiate policy liability.
- 4. The issue and executance of this Form by insurance companies is not an admission of policy liability on the participle, insurance companies.
- Any false reporting may be referred to the Police for investigation
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee by made available soon application by territorial parties.
- he the polyment of this report to the insurers, you hereby consent to the archising of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)
 - processed in a makingly agree and convent that
 - If you was an expension of the General Insurance Association of Singapore (GIA) invariance personal information and discose and for process my personal data/personal information set out in this (form) and any other personal information involved by me or possessed by my insurer (collectively the "Personal Information") and discose and transfer with Personal Information to all insurers; who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers". The insurers (awverta/law form) the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposers!
 - 11 processing handling and/or dealing with my elaims including the settlement of the claims and any necessary mentigations relating to the claims.
 - in investigating the accident and/or my claims
 - and carrying out and/or dealing with my instructions or responding to any enguines by me
 - instantiating my claims including the making of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of énvelopes/mail packages), and/or
 - (v) comprising with applicable law in administering, processing, handling and/or dealing with my claims surfactively the Purposes.
 - (b) of insurers (who have insured vehicles) involved in this accident and the insurers. Savyershaw from, may me periodical to soften, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 - my Personal information may/can be disclosed by any of the insurers and/or GrA to their third party service providence agents) including their lewyers/law firms), which may be sited outside of Singapore, for one or more of the above Hurpows
 - (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
 - c. The information so collected under (d) above may be shared / disclosed
 - To all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fixed regulators. Taw enforcement and government agencies as reasonably required for the purposes stated, or
 - (i) for complying with requirements under any regulations, laws or sourt orders

Driver shighature | Of driver is not the policytosider Date & Time MEDITATION CONTRA METITION OF STREET

NRICH NAME

Sketch Plan #2

SKETCHPIAN

LIGODLAND: 1 A

CHECKFOINT

GWINTER

COUNTER

A-SJR6367 P B-SKS3547 P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

VEHICLE I	A 1	UNS	SATI	30 10 100	4 AT	hoo	GUAND	S CHECK	POINT
COUNTER									
VERTICLE	B	11/17	VECV	11CLE	A	FROM	BEHIN	0	
DAMAGE	70	V E	HICLE	A	NAS	AT	PEAR	FIGHT	BUMPER
MACKED									

DECLARATION

We declare the sower ne particulars are true in every respect

Town Names

Onder's fignature/ Int growth is not the policyholders

Date & Time

Reporting Centre Paramer à Senatore Name NAICE de Sai


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	4041W	
Vehicle No.:	SJR6367P	
Vehicle to be Exported:	No	
Intended Deregistration Date:	05 Nov 2018	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	A170	
Primary Colour:	Silver	
Manufacturing Year:	2009	
Engine No.:	26694030650962	
Chassis No.:	WDD1690322J740020	
Maximum Power Output:	85.0 kW (113 bhp)	
Open Market Value:	\$25,115.00	
Original Registration Date:	02 Jul 2009	
First Registration Date:	02 Jul 2009	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$25,115.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	01 Jul 2019	
PARF Rebate Amount: Intended COE Rebate Details	\$12,557.00	
COE Expiry Date:	01 Jul 2019	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$14,840.00	
COE Rebate Amount:	\$972.00	
Total Rebate Amount:	\$13,529.00	

The information contained herein is correct as at 05 Nov 2018







Accident Photo



Accident Photo









Accident Photo

























Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0597-18-HSA

11 September 2018

Robinson Car Rental Pte Ltd 21 Jalan Masjid Singapore 417921

INVOICE No.

0597-18-HSA

Vehicle No.

SJR6367P

- 1	С.	n	VΤ	•	٦	
3	31	1	Y	Ĺ	J	

SERVICES RENDERED

Amount due

1

Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).

Total amount payable

\$746.00 \$746.00

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0597-18-HSA

11 September 2018

ACCIDENT VEHICLE SURVEY REPORT

Robinson Car Rental Pte Ltd 21 Jalan Masjid Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No .:

SJR6367P

Odometer:

66447km

Regn. No: 52986974L

Make & Model:

Mercedes Benz A170

Colour:

Silver

Chassis number:

WDD16903225740020

Date of accident:

06/08/2018

Year of Regn .:

02/07/2009

Date inspected:

08/08/2018

Repairer at:

H S Automotive Services

Date inspected (After Repair):

20/08/2018

Blk 2 Kaki Bukit Ave 2 #02-25

Kaki Bukit Auto Hub

Singapore 417921

STATIC CHECKS, where applicable:

Steering:

serviceable

Footbrake:

serviceable

Handbrake:

serviceable

Paintwork:

Good

General condition:

Good

TIRE CONDITION:

LH / Make

RH / Make

Size

Front:

6mm/Yokohama

6mm/Yokohama

195/55R16

Rear:

6mm/Yokohama

6mm/Yokohama

195/55R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear RH portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0597-18-HSA

Vehicle No: SJR6367P

Rear air ventilator RH 1 warped 110.00 110.00 110.00	Descr	iption of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear fender inner shield clip RH - set 1 necessary 65.00 65:00 NN Rear tail lamp RH 1 fractured 370.00 370.00 CR Rear bumper 1 squashed 880.00 880.00 CUT Rear bumper clip RH - set 1 necessary 60.00 60.00 NEC Rear bumper side retainer RH/LH 2 necessary 50.00 50.00 NEC Rear bumper chrome moulding RH/EH	Rear fender RH		1	repair	2,500.00	0.00
Rear tail lamp RH 1 fractured 370.00 370.00 CRV Rear bumper 1 squashed 880.00 880.00 CUT√ Rear bumper clip RH - set 1 necessary 60.00 60.00 NEC√ Rear bumper side retainer RH/LH 2 necessary 50.00 50.00 NEC√ Rear bumper chrome moulding RH/LH 1 fractured 180.00 36.00 CUT√ Rear bumper reflector lamp RH 1 fractured 45.00 45.00 CR√ Rear bumper row cover RH 1 fractured 190.00 0.00 Rear bumper lower skirt RH 1 fractured 190.00 190.00 CuT√ Rear bumper reinforcement 1 repair 470.00 0.00 Rear shock absober RH 1 bent 55.00 55.00 Rear s	Rear fender inner shield	RH	1	fractured	125.00	125,00-NNX
Rear bumper 1 squashed 880.00 \$80.00 CUT/ Rear bumper clip RH - set 1 necessary 60.00 60.00 NEC/ Rear bumper side retainer RH/LH 2 necessary 50.00 50.00 NEC/ Rear bumper chrome moulding RH/LH /-2- deformed 180.00 \$0.00 NEC/ Rear bumper reflector lamp RH 1 fractured 45.00 45.00 CK/ Rear bumper row cover RH 1 reuse 40.00 0.00 Rear bumper lower skirt RH 1 fractured 190.00 190.00 C/√/ Rear bumper reinforcement 1 repair 470.00 0.00 Rear shock absober coil spring RH 1 bent 270.00 270.00 NNX Rear stabiliser link RH 1 bent 155.00 55.00 NNX Rear ABS sensor RH 1 shorted 270.00 270.00 NNX Rear wheel hub RH 1 dislorted 1,600.00 NNX Rear axle 1 distorted 1,600.00 NNX Rear axle lower cover 1<	Rear fender inner shield	clip RH - set	1	necessary	65.00	65.00 NNX
Rear bumper clip RH - set 1 necessary 50.00 60.00 NEC	Rear tail lamp RH		1	fractured	370.00	370.00 CRV
Rear bumper side retainer RH/LH 2 necessary 50.00 50.00 № € € € € € € € € € € € € € € € € € €	Rear bumper		1	squashed	880.00	880.00 CUTI
Rear bumper chrome moulding RH/LH RH 1/2 deformed 180.00 % 6 H80.00 CUT √ Rear bumper reflector lamp RH 1 fractured 45.00	Rear bumper clip RH - s	set	1	necessary	60.00	60.00 NECV
Rear bumper reflector lamp RH 1 fractured 45.00 ★ 5.00 ★ 7 Rear bumper tow cover RH 1 reuse 40.00 0.00 0.00 Rear bumper lower skirt RH 1 fractured 190.00 190.00 0.00 Rear bumper reinforcement 1 repair 470.00 0.00 276.00 NNX Rear shock absober RH 1 bent 270.00 276.00 NNX Rear shock absober coil spring RH 1 reuse 340.00 0.00 Rear shock absober coil spring RH 1 bent 270.00 276.00 NNX Rear shock absober coil spring RH 1 bent 55.00 0.00 0.00 Rear shock absober coil spring RH 1 bent 120.00 120.00 0.00 0.00 0.00 1.00 1.00 1.00 NNX 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	Rear bumper side retaine	er RH/LH	2	necessary	50.00	50.00 NECV
Rear bumper tow cover RH 1 reuse 40.00 0.00 Rear bumper lower skirt RH 1 fractured 190.00 <td>Rear bumper chrome mo</td> <td>oulding RH/LH RH</td> <td>1-2</td> <td>deformed</td> <td>180.00</td> <td>90.00 180.00 CUT√</td>	Rear bumper chrome mo	oulding RH/LH RH	1-2	deformed	180.00	90.00 180.00 CUT√
Rear bumper lower skirt RH	Rear bumper reflector la	mp RH	1	fractured	45.00	45.00 CR √
Rear bumper reinforcement 1 repair 470,00 0.00	Rear bumper tow cover	RH	1	reuse	40.00	0.00
Rear shock absober RH 1 bent 270.00 270.00 NNX Rear shock absober coil spring RH 1 reuse 340.00 0.00 Rear stabiliser link RH 1 bent 55.00 55.00 NNX Rear torsion arm RH 1 bent 120.00 120.00 NNX Rear ABS sensor RH 1 shorted 270.00 270.00 NNX Rear wheel hub RH 1 dislodged 330.00 330.00 DL√ Rear axle 1 distorted 1,600.00 1,600.00 NNX Rear axle lower cover 1 fractured 140.00 140.00 NNX Rear air ventilator RH 1 warped 110.00 110.00 NNX Rear air ventilator cover RH 1 warped 185.00 85.00 NNX Subtotal before discount 8,395.00 4,945.00 Rear wheel RH 1 abraded 380.00 380.00 NNX Rear wheel rim RH 1 abraded 850.00 850.00 NNX Subtotal before discount 1,230.00 1,230.00 Percentage discount 0% and 0% 0% 0.00 0.00 0.00 0.00 0.00 0.00 <td>Rear bumper lower skirt</td> <td>RH</td> <td>1</td> <td>fractured</td> <td>190.00</td> <td>190.00 CUTV</td>	Rear bumper lower skirt	RH	1	fractured	190.00	190.00 CUTV
Rear shock absober coil spring RH 1 reuse 340.00 0.00 Rear stabiliser link RH 1 bent 55.00 55.00 NNX Rear torsion arm RH 1 bent 120.00 ±20.00 NNX Rear ABS sensor RH 1 shorted 270.00 270.00 NNX Rear wheel hub RH 1 dislodged 330.00 330.00 DL√ Rear axle 1 distorted 1,600.00 1,600.00 NNX Rear axle lower cover 1 fractured 140.00 140.00 NNX Rear air ventilator RH 1 warped 110.00 110.00 NNX Rear air ventilator cover RH 1 warped 185.00 85.00 NNX Subtotal before discount 8,395.00 4,945.00 Percentage discount 0% and 10% 0.00 494.50 Sub-total 1 8,395.00 4,450.50 850.00 850.00 R × Subtotal before discount 1,230.00 1,230.00 Percentage discount 0% and 0% 0.00 0.00 0.00 Sub-total 2 1,230.00 1,230.00	Rear bumper reinforcem	ent	1	repair	470.00	0.00
Rear stabiliser link RH	Rear shock absober RH		1	bent	270.00	270.00 NNX
Rear torsion arm RH	Rear shock absober coil	spring RH	1	reuse	340.00	0.00
Rear ABS sensor RH 1 shorted 270.00 270.00 NNX Rear wheel hub RH 1 dislodged 330.00 330.00 DL√ Rear axle 1 distorted 1,600.00 1,600.00 NNX Rear axle lower cover 1 fractured 140.00 140.00 NNX Rear air ventilator RH 1 warped 110.00 HNX Rear air ventilator cover RH 1 warped 185.00 85.00 NNX Subtotal before discount 8,395.00 4,945.00 Percentage discount 0% and 10% 0.00 494.50 Sub-total 1 8,395.00 4,450.50 Rear wheel RH 1 abraded 380.00 380.00 NNX Rear wheel rim RH 1 abraded 850.00 850.00 R × Subtotal before discount 1,230.00 1,230.00 1,230.00 Percentage discount 0% and 0% 0.00 0.00 0.00 0.00 0.00 Sub-total 2 1,230.00 1,230.00 1,230.00	Rear stabiliser link RH		1	bent	55.00	55.00 NNX
Rear wheel hub RH	Rear torsion arm RH		1	bent	120.00	120.00 NNX
Rear axle 1 distorted 1,600.00 1,600.00 N N Rear axle lower cover 1 fractured 140.00 140.00 140.00 N Rear air ventilator RH 1 warped 110.00 110.00 110.00 N Rear air ventilator cover RH 1 warped 185.00 85.00 N Subtotal before discount 8,395.00 4,945.00 Percentage discount 0% and 10% 0.00 494.50 Sub-total 1 8,395.00 380.00 380.00 N Rear wheel RH 1 abraded 380.00 380.00 N Rear wheel rim RH 1 abraded 850.00 850.00 Rear wheel rim RH 1 abraded 850.00 850.00 Rear wheel rim RH 1 230.00 1,230.00 Percentage discount 0% and 0% 0.00 0.00 Sub-total 2 1,230.00 1,230.00	Rear ABS sensor RH		1	shorted	270.00	270.00 NNX
Rear axle lower cover 1 fractured 140.00 <td< td=""><td>Rear wheel hub RH</td><td></td><td>1</td><td>dislodged</td><td>330.00</td><td>330.00 DLV</td></td<>	Rear wheel hub RH		1	dislodged	330.00	330.00 DLV
Rear air ventilator RH 1 warped 110.00 110.00 HAX Rear air ventilator cover RH 1 warped 185.00 85.00 NAX Subtotal before discount 8,395.00 4,945.00 Percentage discount 0% and 10% 0.00 494.50 Sub-total 1 8,395.00 4,450.50 Rear wheel RH 1 abraded 380.00 380.00 NN X Rear wheel rim RH 1 abraded 850.00 850.00 R X Subtotal before discount 1,230.00 1,230.00 Percentage discount 0% and 0% 0.00 0.00 Sub-total 2 1,230.00 1,230.00	Rear axle		1	distorted	1,600.00	1,600.00 NNX
Rear air ventilator cover RH	Rear axle lower cover		1	fractured	140.00	140.00 AXN
Percentage discount O% and 10% 0.00 494.50	Rear air ventilator RH		1	warped	110.00	110.00 HAX?
Percentage discount O% and 10% 0.00 494.50	Rear air ventilator cover	RH	1	warped	185.00	85.00 NNXT
Sub-total 1 8,395.00 4,450.50			S	ubtotal before discount	8,395.00	
Rear wheel RH 1 abraded 380.00 380.00 NN X Rear wheel rim RH 1 abraded 850.00 850.00 R X Subtotal before discount 1,230.00 1,230.00 Percentage discount 0% and 0% 0.00 0.00 Sub-total 2 1,230.00 1,230.00		Percentage discount	0% and	10%	0.00	494.50
Rear wheel rim RH 1 abraded 850.00 850.00 € ★ Subtotal before discount 1,230.00 1,230.00 Percentage discount 0% and 0% 0.00 0.00 Sub-total 2 1,230.00 1,230.00				Sub-total 1	8,395.00	4,450.50
Subtotal before discount 1,230.00 1,230.00 Percentage discount 0% and 0% 0.00 0.00 Sub-total 2 1,230.00 1,230.00	Rear wheel RH		1	abraded	380.00	380.00 N N X
Percentage discount 0% and 0% 0.00 0.00 Sub-total 2 1,230.00 1,230.00	Rear wheel rim RH		1	abraded	850.00	850.00 R ×
Sub-total 2 1,230.00 1,230.00			S	ubtotal before discount	1,230.00	1,230.00
9000 TO 1917 CTC 1 12		Percentage discount	0% and	0%	0.00	0.00
Parts-total 9,625.00 5,680.50				Sub-total 2	1,230.00	1,230.00
				Parts-total	9,625.00	5,680.50

LABOUR

	Parts & Labour total	12,855.00	7,510.50	
	Labour total	3,230.00	1,830.00	
4. To remove and refit undercarriage.	_	380.00	300.00- [50.00
3. To conduct wheel alignment.		150.00	120.00 4	ANX60
2. To putty, re-spray painting and polish affected areas.		1,200.00	660.00-A	
frame members. To remove and refit above parts.		7,873,019,757,773	3956577338	00 01
1. To straighten and panel beating rear fender RH and rear RH	I	1,500.00	750.00 6	00.00

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : and the recommended number of working days for the repairs is :

\$6,000.00

5

B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser

Repair days 5

TGUM

30/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Su	bmitted	Ins Auth'ed	Status		
Main	07 Aug 2018 13 Aug 2018 16:07 S\$2,550.00 S\$2,550.00 View Rpt			Pending for Survey Report Cancel Case		vey				
	Main	Re	ference	CI	aim Details		Docume	nts] [Show All
CLAIM SU	BFOLDER DE	TAILS	A THE PARTY OF THE PARTY OF	THE REAL PROPERTY.	Salar Salar	[Creat	ed by insurer]	NO PERSONAL PROPERTY.	ACCIONAL SUPPLE	
Insured:	CHAN BAI	K THIAM, ID: S	746259H			30A.W22	W			
Main Claimant:	ROBINSO	N CAR RENTAL F	TE LTD, Co. F	Reg. No.: -						
Vehicle Reg	SJR636	7P			Date of Loss		2018 16:00 - :59 lonths and 4 Days	From LTA R	Reg Date (Man Yr)]
Claim Type	: TP / 566	721			Policy/Cover Note No.:		08AVW (Compreh ge: 09/04/2018 -)	
Vehicle Reg No. (Insured):	SKS3547	Р			Policy No. (Claimant):		22 - NO. V.			
<u> </u>					Excess:	S\$1,50	A STATE OF THE PARTY OF THE PAR			
Repairer:	H S Autor 67472755		(Kaki Bukit) BL	K 2 KAKI BUKI	T, AVENUE 2	, # 01-15,	KAKI BUKIT AUTO	OHUB, 4179	21 Kaki B	ukit - Tel:
Handling Insurer:							d by Christina W			
Adjuster:	12/10/20	Consultants Pte 018]	Ltd (HQ) - Tel:	6256-3561	. [Handled by	MOHD T	AUFIKH BIN HAN	4ID] [Fi	inal Rpt	due
Adj Asg. Remarks:	Liability 10	00%. TP disagree	with our SJE. Pro	ceed to appoir	nt LKK Auto (Consultant	s. Contact Person:	Mr Alex / 6	5538 1368	
ASSOCIA	TED MAIL RE	CEIVED						View All	Compose	Case Ma
MSIG_S	G (10/10/2018	3): Report Send I	Back Alerts - SI	IR6367P (TP))					
ALL ASS	OCIATED TAS	sks⊟				View	All Search Tasks	Create f	New Task	Complet
Due Dat	te Priority	Type Task	Group Sub	ject Handl	ler Assi	ned By	Completed C	On Cre	eated On	Done

Claim Documents

*SJR6367P (566721)

[SKS3547P]

TP

ROBINSON CAR RENTAL PTE LTD

Aug 6 2018 4:00PM

[CHAN BAK THIAM]

H S Automotive Services

Upl	oad Documents Uplo	ad Photos Compose New Letter	View	View in Brow	1
Ass	essment Reports		1 per	page 🔻	•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/08/18 14:24	Accident Statement From:OD - Reg. No: SKS3547P, Claimant: CHAN BAK THIAM	0	Load HTM	
Pho	Photos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	16/08/18 16:13	General View	0	Load JPG	•
2	16/08/18 16:13	General View	0	Load JPG	•
3	16/08/18 16:13	General View	0	Load JPG	•
4	16/08/18 16:13	General View	0	Load JPG	•
5	16/08/18 16:13	General View	0	Load JPG	•
6	16/08/18 16:13	General View	0	Load JPG	€
7	16/08/18 16:13	General View	0	Load JPG	•
8	16/08/18 16:13	General View	0	Load JPG	•
9	16/08/18 16:13	General View	0	Load JPG	•
10	16/08/18 16:13	General View	0	Load JPG	•
11	16/08/18 16:13	General View	0	Load JPG	•
12	16/08/18 16:13	General View	0	Load JPG	•
13	16/08/18 16:13	General View	0	Load JPG	•
14	16/08/18 16:13	General View	0	Load JPG	•
15	16/08/18 16:13	General View	0	Load JPG	•
16	16/08/18 16:13	General View	0	Load JPG	€
17	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	€
18	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	2
19	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
20	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
21	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
22	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
23	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
24	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
25	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
26	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
27	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
28	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
29	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
30	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
31	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•

Assessment Reports		ent Reports			•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
32	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
33	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
34	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
35	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
36	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	
37	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
38	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
39	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
40	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
41	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
42	21/08/18 12:02	Photographs of Damaged Parts	0	Load JPG	•
43	21/08/18 12:03	Photo After Spray	0	Load JPG	•
44	21/08/18 12:03	Photo After Spray	0	Load JPG	•
45	21/08/18 12:03	Photo After Spray	0	Load JPG	•
46	21/08/18 12:03	Photo After Spray	0	Load JPG	8
47	21/08/18 12:03	Photo After Spray	0	Load JPG	•
48	21/08/18 12:03	Photo After Spray	0	Load JPG	•
49	21/08/18 12:03	Photo After Spray	0	Load JPG	•
50	21/08/18 12:03	Photo After Spray	0	Load JPG	•
51	21/08/18 12:03	Photo After Spray	0	Load JPG	•
52	21/08/18 12:03	Photo After Spray	0	Load JPG	•
53	21/08/18 12:03	Photo After Spray	0	Load JPG	•
54	21/08/18 12:03	Photo After Spray	0	Load JPG	2
Do	cumentation		1 per	page ▼	•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	
1	08/08/18 11:22	PRI	0	Load PDF	-
2	08/08/18 14:24	TP GIA REPORT	0	Load PDF	
3	08/10/18 09:16	From: OD - Reg. No: SKS3547P, Claimant: CHAN BAK THIAM TP Survey Rpt	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	09/11/18 08:43	PRS INVOICE	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18014702/T1RD3S2-1

Date:

09/11/2018

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28719908AVW

Claimant Vehicle No:

SJR6367P

Insured Vehicle No:

SKS3547P

Date of Loss:

06/08/2018

Nature of Claim:

TP

Claim No: 566721

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJR6367P

Make & Model:

MERCEDES-BENZ A170, 1.7 (A) 02/07/2009 (Man. Year: 2009)

Engine No:

26694030650962

66448 km

Reg. Date: Colour:

Silver

Chassis No: Odometer:

WDD1690322J740020

Engine Capacity:

1699 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/55R16

Rear Tyre Size:

195/55R16

Front Left Side:

Yokohama 6 mm

Rear Left Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

Front Right Side: Yokohama 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,625.00	1,989.00	7,636.00	79.34
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,230.00	1,210.00	2,020.00	62.54
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,855.00	3,199.00	9,656.00	75.11
	Approved Total (Overridden) (S\$)		2,550.00		
	Nett Amount (S\$)	12,855.00	2,550.00	10,305.00	80.16

INSPECTION

Date of Assignment:

13/08/2018

H S Automotive Services (Kaki Bukit)

Date Inspected:

14/08/2018 Inspected At:

BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI BUKIT

AUTOHUB

Singapore 417921

Estimated Period of Repair:

5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager:

Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 09 Nov 2018) Part Source: MRM-SG

MERCEDES-BENZ A170 1.7 (A) (Catalogue:Merimen Singapore 1.0) 144 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SJR6367P)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommend	led	Parts
-----------	-----	-------

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR FENDER RH	Repair	2,500.00 F	*-FL
2	1	*REAR FENDER INNER SHIELD RH	Not Necessary	125.00 F	*-FL
3	1	*SET REAR FENDER INNER SHIELD CLIP RH	Not Necessary	65.00 F	*-FL
4	1	*REAR TAIL LAMP RH	Cracked	370.00 F	*370.00 FL
5	1	*REAR BUMPER	Cut	880.00 F	*880.00 FL
6	1	*SET REAR BUMPER CLIP RH	Necessary	60.00 F	*60.00 FL
7	2	*REAR BUMPER SIDE RETAINER RH/LH	Necessary	50.00 F	*50.00 FL
8	1	*REAR BUMPER CHROME MOULDING RH/LH	O/s Cut	180.00 F	*90.00 FL
9	1	*REAR BUMPER REFLECTOR LAMP RH	Cracked	45.00 F	*45.00 FL
10	1	*REAR BUMPER TOW COVER RH	Reuse	40.00 F	*-FL
11	1	*REAR BUMPER LOWER SKIRT RH	Cut	190.00 F	*190.00 FL
12	1	*REAR BUMPER REINFORCEMENT	Repair	470.00 F	*-FL
13	1	*REAR SHOCK ABSORBER RH	Not Necessary	270.00 F	*-FL
14	1	*REAR SHOCK ABSORBER COIL SPRING RH	Reuse	340.00 F	*-FL
15	1	*REAR STABILIZER LINK RH	Not Necessary	55.00 F	*-FL
16	1	*REAR TORSION ARM RH	Not Necessary	120.00 F	*-FL
17	1	*REAR ABS SENSOR RH	Not Necessary	270.00 F	*- FL
18	1	*REAR WHEEL HUB RH	Dislodged	330.00 F	*330.00 FL
19	1	*REAR AXLE	Not Necessary	1,600.00 F	*-FL
20	1	*REAR AXLE LOWER COVER	Not Necessary	140.00 F	*-FL
21	1	*REAR AIR VENTILATOR RH	Cracked	110.00 F	*110.00 FL
22	1	*REAR AIR VENTILATOR COVER RH	Torn	185.00 F	*85.00 FL
23	1	*REAR WHEEL RH	Not Necessary	380.00 FS	*- FS
24	1	*REAR WHEEL RIM RH	Repair	850.00 FS	*- FS
F=Fr	anchise part, S=Spc	Nett, L=ListItemDisc.	-		
	and a superior of the control of the		Sub Total (S\$)	9,625.00	2,210.00
	- List Item Discount on L Items 0.00/10.00% (S\$)				221.00
			Total Parts (S\$)	9,625.00	1,989.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recom	men	hah	laho	nir
RECUIII		ucu		Jul

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO STRAIGHTEN AND PANEL BEATING REAR FENDER RH AND REAR RH FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS.	New	1,500.00	600.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.	New	1,200.00	400.00
3	TO CONDUCT WHEEL ALIGNMENT.	New	150.00	60.00
4	TO REMOVE AND REFIT UNDERCARRIAGE.	New	380.00	150.00
	Gross Labour Cost (S\$		3,230.00	1,210.00
		35		
	Report was unsubmitted during this p	print-out.		

< END OF ESTIMATES >