

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP18050040

Date: 15 AUG 2018

Koh Wei Hao
c/o D's Graffiti Concepts Pte Ltd
Synergy @ KB 25
Kaki Bukit Road 4
06 - 26
Singapore 417800
THIRD PARTY SURVEY
ACCIDENT OCCURED ON 17 May 2018

Workshop Name and Address

D's Graffiti Concepts Pte Ltd
Synergy @ KB 25
Kaki Bukit Road 4
06 - 26
Singapore 417800

As per your instruction dated 19 May 2018
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SLQ 8391 L

1. VEHICLE PARTICULARS

Registration No : SLQ 8391 L
Model : HYUNDAI ELANTRA AD 1.6
Year / Capacity : 2017 / 1598cc
Chassis No : KMHD841CMJU508467

Engine No : G4FGHU673271
Mileage : 021 455 km
Colour : Metallic WHITE

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **front side** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 14 working days to complete
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SLQ 8391 L

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

<u>List Items</u>				
1 pc	Front bumper	bent	\$ 555.05	\$ 555.05
1 pc	Front bumper side retainer	bent	\$ 44.00	\$ 44.00
1 pc	Front bumper side bracket	bent	\$ 25.00	\$ 25.00
1 pc	Front bumper lower lid	bent	\$ 35.40	\$ 35.40
1 pc	Head lamp assy	grazed/distorted	\$ 1,417.80	\$ 1,417.80
1 pc	Front fender	bent/distorted	\$ 1,131.45	\$ 1,131.45
1 pc	Front fender splash shield	deformed	\$ 325.00	\$ 325.00
8 pcs	Front fender splash shield clips	necessary	\$ 30.40	\$ 30.40
1 pc	Front fender inner bracket	distorted	\$ 28.00	\$ 28.00
1 pc	Front kunckle arm	bent/distorted	\$ 350.00	\$ 350.00
1 pc	Front lower arm	bent/distorted	\$ 347.25	\$ 347.25
1 pc	Front absorber	bent/distorted	\$ 436.20	\$ 436.20
1 pc	Front absorber mounting	deformed	\$ 87.00	\$ 87.00
1 pc	Front wheel bearing	necessary	\$ 529.80	\$ 529.80
1 pc	Front kunckle arm	dent/distorted	\$ 425.40	\$ 425.40
Parts Sub-Total			\$ 5,767.75	\$ 5,767.75
Discount 20.00%			\$ 1,153.55	\$ 1,153.55
			\$ 4,614.20	\$ 4,614.20

Vehicle Number : SLQ 8391 L

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

<u>Special Nett Items</u>				
1 pc	Front wheel rim	distorted/deformed	\$ 500.00	\$ 500.00
1 pc	Front tyre	grazed/deformed	\$ 350.00	\$ 300.00
Special Nett Sub-Total			\$ 850.00	\$ 800.00
Spare Parts Total			\$ 5,464.20	\$ 5,414.20

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
	Spare PartsTotal c/f	\$ 5,464.20	\$ 5,414.20
1	Towing	\$ 120.00	\$ 120.00
2	To remove & replace front under carriage components.	\$ 250.00	\$ 220.00
3	To respray affected areas	\$ 1,600.00	\$ 1,400.00
4	To check & adjust computer wheel alignment (before & after)	\$ 150.00	\$ 120.00
5	To check & reconnect snap wiring system	\$ 120.00	\$ 100.00
6	To renew damaged parts, straighener and repair front fender inner panel & Aligned all parts.	\$ 1,800.00	\$ 1,600.00
7	To apply paint protection wax after painting	\$ 1,500.00	\$ 1,400.00
8	To apply rust-proofing on repaired/replaced panels.	\$ 180.00	\$ 150.00
	Total	\$ 11,184.20	\$ 10,524.20

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 9,500.00


Fong Kok Heng
Qualified Appraiser

















