

ASS. REC. BY:

REF:

CS/MSG18018447/Ggd3

n2

Special Instruction:

Surveyor:
Mennen

Guo Qiong

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time:

11/10/18 @ 10:43am

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 7036X

Insured:

FT 782A

at Workshop m/s

Serve You Motor

Tel:

9289 3188

of

BLK 5033 AMK Ind. park 2 #01-265

Policy No:

MSD/VMT/17-375950-CA

Claim No:

MSC/V/18-001356

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/10/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

10:49am @ 11/10/18

Person Contacted:

Elaine

Vehicle

☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	PC 7036 X-X
	FT 782A - NA/INC 12006869/w/
12/10/18 @	12:01 pm revised to Irene Tan via Mennen.

DOA: 3/4/2012

Signature

XRL.

REF:

MS6

C 69176 /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Serve You Motor

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC7036X

Yr Regn:

21 Dec 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yutong ZK6107HE 6690

Colour

white & Blue

A/C:

Insured / Std / NI / NA

Sp Reading

44127

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LZYTB TD 68H 1045155

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

22.5 -16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle.

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

11-10-18

Survey held at

w/s

2:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

11/10

Finalized \$2100 with Elaine.

(Red \$4732, 73%)

RECEIVED 12 OCT 2018

12/10/2018

Date/Time, File Pass to?



: Preli. Report

1) 17/10 17:55



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos:

) Others:

)

TOTAL

150
10

160

Report Format :

Lump Sum / I.B.I. (\$

MER-TP

2100

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 12 Oct 2018

Preliminary Advice

Insured Vehicle No	: FT782A	Accident Date	: 08/10/2018
TP Vehicle No	: PC7036X	Assignment Date	: 11/10/2018
Make	: YUTONG ZK6107H	Est. Duration of Repair	: 3
Date of Inspection	: SERVE YOU MOTOR SERVICE		
Inspection At	: 11/10/2018		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,837.00
Revised Amount	:S\$	2,645.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,645.00

Lump Sum Repair	:S\$	2,100.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2018		11 Oct 2018 10:43 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YONG JIA QUAN, ID: S9670290F, Tel: +6598788493		
Main Claimant:	A&S TRANSIT PTE. LTD, Co. Reg. No.: 201216917G		
Vehicle Reg. No.:	PC7036X	Date of Loss:	08/10/2018 14:00 - :59 [9 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001356	Policy/Cover Note No.:	MSD/VMT/17-375950-CA (Third Party Only) Coverage: 14/12/2017 - 13/12/2018
Vehicle Reg. No. (Insured):	FT782A	Policy No. (Claimant):	
		Excess:	
Repairer:	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265, 569536 Ang Mo Kio - Tel: 64815652		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/10/2018]		
Driver/Custodian (Insured):	YONG JIA QUAN (22 / Male), NRIC: S9670290F, Tel: +6598788493		
Adj Asg. Remarks:	on WP. Survey appt on 11/10/2018 2.30PM owner waiting. LIABILITY NOT CLEAR (NON-REPORTING) - Urgent Request Please survey today : 11.10.2018 (Thursday) ,Time: 1400 -1430 Note: Driver waiting. Kindly contact Elaine Chia @ 6481 0555 / 6481 5652 or 9239 3188		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6917G
Vehicle Details	
Vehicle No.:	PC7036X
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Oct 2018
Vehicle Make:	YUTONG
Vehicle Model:	ZK6107HE MANUAL
Primary Colour:	Multi-Colour
Manufacturing Year:	2017
Engine No.:	ISB67E525022275473
Chassis No.:	LZYTBT68H1045155
Maximum Power Output:	-
Open Market Value:	\$92,529.00
Original Registration Date:	21 Dec 2017
First Registration Date:	21 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$4,627.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,902.00
COE Rebate Amount:	\$44,931.00
Total Rebate Amount:	\$44,931.00

The information contained herein is correct as at 12 Oct 2018

OK

SERVE YOU MOTOR SERVICE

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-265, SINGAPORE 569536

TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: elainesyms@gmail.com

INS: MSIG INSURANCE SINGAPORE PTE LTD

COMPANY: A&S TRANSIT PTE LTD

Registration no. : PC 7036 X / YUTONG ZK6107HE MANUAL

Date : 10-Oct-18

Quotation No. : CM181002-1

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear bumper RH side corner panel / DD DD	\$1,850.00 X
2	1	Rear bumper DD repair X	\$2,280.00
			\$4,130.00
			Less 10%
			\$413.00
			1665 \$3,717.00

SPECIAL NETT ITEMS

1	1 set	Rear reverse sensor (4 point) \$150 each X NN	\$600.00
			\$600.00

LABOUR & MISC CHARGES

1	To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	400	\$1,500.00
2	To disconnect and refix wiring, remove and refit rear RH fog light, rear RH lamp and reverse sensor to facilitate repair.	80 40	\$120.00
3	To apply undercoating on the accident damage portion and to spray insulation foam.	NN X	\$400.00
4	Supply spray paint material and necessary items to respray on accident damage area.	2645 2.5%: 2400	\$1,500.00

TOTAL

\$3,520.00

Total Parts and Labour Cost of Repair

\$7,837.00

3 Days.
Unpainted repair
After repair photos.
Gino Qip.
11/10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18018447/GQD3N2

Date: 16/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-375950-CA
Claimant Vehicle No :	PC7036X	Insured Vehicle No :	FT782A
Date of Loss:	08/10/2018	Nature of Claim:	TP
		Claim No:	MSCV/18-001356

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC7036X	Engine No:	ISB67E525022275473
Make & Model:	YUTONG ZK6107H, 6.7 D (M)	Chassis No:	LZYTBD68H1045155
Reg. Date:	21/12/2017 (Man. Year: 2017)	Odometer:	44127 km
Colour:	White/Blue		
Engine Capacity:	6690 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	22.5-16	Rear Tyre Size:	22.5-16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,317.00	1,665.00	2,652.00	61.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	980.00	2,540.00	72.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,837.00	2,645.00	5,192.00	66.25
Approved Total (Overridden) (\$\$)		2,100.00		
Nett Amount (\$\$)	7,837.00	2,100.00	5,737.00	73.20

INSPECTION

Date of Assignment:	11/10/2018	
Date Inspected:	11/10/2018 Inspected At:	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265 Singapore 569536

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Oct 2018)		
Parts:	N/A	YUTONG ZK6107H 6.7 D (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for PC7036X)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER RH SIDE CORNER PANEL	Dented	1,850.00 FL	*1,850.00 FL
2	1		*REAR BUMPER	Repair	2,280.00 FL	*- FL
3	1		*SET REAR REVERSE SENSOR (4 POINT)	Not Necessary	600.00 FS	*- FS
				F=Franchise part. S=SpcNett. L=ListItemDisc.		
				Sub Total (\$\$)	4,730.00	1,850.00
				- List Item Discount on L Items 10.00/10.00% (\$\$)	413.00	185.00
				Total Parts (\$\$)	4,317.00	1,665.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,500.00	400.00
2	TO DISCONNECT AND REFIX WIRING,REMOVE AND REFIT REAR RH FOG LIGHT,REAR RH LAMP AND REVERSES ENSOR TO FACILITATE REPAIR	New	120.00	80.00
3	TO APPLY UNDERCOATING ON THE ACCIDENT DAMAGED PORTION AND TO SPRAY INSULATION FOAM	New	400.00	-
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON ACCIDENT DAMAGE AREA	New	1,500.00	500.00
Gross Labour Cost (\$\$)			3,520.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >