

IN THE STATE COURTS OF THE REPUBLIC OF SINGAPORE

MC/MC 8664/2018

Between

JH TOWING SERVICE (SUING AS A FIRM)
(Singapore UEN No. 53246936D)

...Plaintiff(s)

And

1. **LIBRA ENGINEERING PTE. LTD.**
(Singapore UEN No. 200514501D)
2. **TING FOO MING**
(NRIC No. S7661969G)

...Defendant(s)

AFFIDAVIT OF EVIDENCE-IN-CHIEF
OF XING GUO QIANG

I, XING GUO QIANG (NRIC NO. S7977793/E), care of 51 Ubi Ave 1 #01-25
Singapore 408933, do affirm and say as follows:-

1. I am a Licensed Appraiser Surveyor of LKK Auto Consultants Pte Ltd appointed by China Taiping Insurance (S) Pte Ltd. ("CHINA"), the insurers of motor vehicle no. GBA6573U, to conduct a re-survey of the Plaintiff's motor vehicle no. GU5738D (hereinafter referred to as "the Plaintiff's car") for the damage allegedly sustained from a road traffic accident on 4 February 2016.
2. I did a paper inspection based on LKK Auto Consultants Pte Ltd's Vehicle Damage Inspection Report dated 31st October 2017 on motor vehicle no. GU5738D. I recommended the costs of the repairs at \$2,100.00 (estimated at time of survey) and

This is the Exhibit marked “**XGO-1**” referred to in the
Affidavit of **XING GUO QIANG** affirmed/ sworn
before me on this day of April 2019

Before me

COMMISSIONER FOR OATHS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg No: 199507198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CT117006565/Gvbn2-1	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 12-10-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBA 6573U	Veh. Inspected	GU 5738D
Policy No.	DMCVSN3084761600	Coverage (\$)	0.00
Claim No.	SNM17D01843C02	Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	11/10/2018
2. Vehicle Particulars & Condition			
Make & Model	ISUZU NHR69E	c.c	3059
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	JAANHR69EY7100926	Colour	BLUE
Odometer	999999	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	6 mm
L/H Front Tyre	195 R15C	MICHELIN	6 mm
R/H Rear Tyre	165 R13C	YOKOHAMA	6 mm
L/H Rear Tyre	165 R13C	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/03/2017	Inspection Date	15/05/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 409933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GU 5738D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HYDRAULIC FLUID (1 DRUM)	NECESSARY	150.00	100.00
2	HYDRAULIC JACK HOSE	CUT	800.00	400.00
1	LIFT FORK "T" MEMBER	TO REPAIR SEE LABOUR	3,000.00	-
1	LIFT FORK "T" MEMBER HYDRAULIC CYLINDER JACK	TO REPAIR SEE LABOUR	1,800.00	-
1	LIFT FORK MAIN HYDRAULIC CYLINDER JACK	TO REPAIR SEE LABOUR	1,800.00	-
1	LIFT FORK OUTER MAIN MEMBER	TO REPAIR SEE LABOUR	4,500.00	-
1	LIFT FORK OUTER MAIN MEMBER PIVOT PIN	NECESSARY	380.00	200.00
1	LIFT FORK OUTER MAIN MEMBER SLIDING BRACKET	NOT NECESSARY	1,900.00	-
1	LIFT FORK OUTER MAIN MEMBER SLIDING BRACKET HYDRAULIC CYLINDER JACK	TO REPAIR SEE LABOUR	1,500.00	-
1	MAIN TOWING LIFTING CRANE HYDRAULIC CYLINDER JACK	TO REPAIR SEE LABOUR	1,800.00	-
2	REAR END HANG PANEL	TO REPAIR SEE LABOUR	1,400.00	-
1	REAR NUMBER PLATE	SERVICEABLE	35.00	-
2	TAILLAMP	TO REPAIR SEE LABOUR	460.00	-
			19,525.00	700.00
LABOUR				
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.			1,800.00	800.00
LABOUR TO DISMANTLE, REPLACED TOWING FORKS, JACKS, PIN ETC AND TO CHECK AND ALIGN SYSTEM FOR PROPER OPERATION. INCLUSIVE OF THE REPAIR OF LIFT FORK "T" MEMBER, LIFT FORK "T" MEMBER HYDRAULIC CYLINDER JACK, LIFT FORK MAIN HYDRAULIC CYLINDER JACK, LIFT FORK OUTER MAIN MEMBER, LIFT FORK OUTER MAIN MEMBER SLIDING BRACKET HYDRAULIC CYLINDER JACK, MAIN TOWING LIFTING CRANE HYDRAULIC CYLINDER JACK, REAR END HANG PANEL AND TAILLAMP.			3,000.00	1,000.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		200.00	60.00
	TO CHECK WIRING AND LIGHT SYSTEM.		200.00	60.00
			5,200.00	1,920.00
	GRAND TOTAL		24,725.00	2,620.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS3/CTI17006565/Gvbn2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.