



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 758E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE (CONSISTENT)	BADLY DENTED	1,320.70	953.00
1	TAILGATE "VEZEL" EMBLEM (CONSISTENT)	NECESSARY	58.20	58.20
1	TAILGATE LOGO (CONSISTENT)	NOT NECESSARY	58.70	-
1	REAR BUMPER (CONSISTENT)	DENTED / DEFORMED	985.50	762.00
10	REAR BUMPER CLIPS @\$3.50 (CONSISTENT)	NECESSARY	35.00	35.00
2	REAR BUMPER RETAINER @\$58.20 (CONSISTENT)	NOT NECESSARY	116.40	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	680.20	-
1	REAR END PANEL SEALANT (CONSISTENT)	NOT NECESSARY	25.00	-
4	REAR WINDSCREEN MOULDING @\$42.10 (CONSISTENT)	NOT NECESSARY	168.40	-
1	REAR WINDSCREEN INNER SEAL (CONSISTENT)	NECESSARY	60.00	60.00
2	REAR WINDSCREEN SEALANT @\$25.00 (CONSISTENT)	NECESSARY	50.00	50.00
	LESS 20% DISCOUNT		-711.62	-383.64
			2,846.48	1,534.56
1	REAR BUMPER CHROME PLATE (CONSISTENT)(SN)	DENTED	280.50	200.00
1	REAR PARKING SENSOR (CONSISTENT)(SN)	SHORTED	280.00	200.00
	LESS 20% DISCOUNT		-112.10	-
			448.40	400.00
<b><u>LABOUR</u></b>				
	TO KNOCK AND STRAIGHTEN THE NECESSARY PORTION.CUT AND WELD DAMAGED PANEL.ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,000.00	400.00
	TO PUTTY AND SPRAY TAILGATE COMPLETE,END PANEL AND REAR BUMPER.		800.00	400.00
	TO TRANSFER TAILGATE FITTING,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		180.00	60.00
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS.		120.00	120.00
	TO RUST PROOF THE AFFECTED AREAS.		80.00	30.00
	TO CHECK ALL WIRING AND ALL LIGHTING.		60.00	20.00

Report Ref No. CC4/ASM18018479/Upa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO INSTALL REAR PARKING SENSOR AND REAR CAMERA.		120.00	50.00
			2,360.00	1,080.00
GRAND TOTAL			5,654.88	3,014.56
RECOMMENDED COST OF REPAIRS				3,014.56

Report Ref No. CC4/ASM18018479/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.