

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1585Y

DATE 10/10/2018 14:46

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Outer Moulding (LH) <i>X see</i>			\$ 47.10
	Front Door Mirror Assy (LH) <i>Broken</i>			\$ 670.00
	Front Wheel Hub Cap (LH) <i>cracked</i>			\$ 107.10
	<i>Front Bumper X repair</i>			
	SUB TOTAL			\$ 824.20
	LESS 20%			\$ 164.84
	DISCOUNTED TOTAL			\$ 659.36
	Front Fender Advertisement Logo (LH) <i>new</i>			\$ 100.00
	Labour Charge			
	Panel Beating			\$ 220.00
	Spray Painting Charge-Bumper/Mirror			\$ 370.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	FRT Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 1,509.36

Nett

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.