

ASS. REC. BY:

REF: CS/FCI18018498/ Dtd3/n2

Special Instruction:

Surveyor: Bryan
CWS

ASSIGNMENT (Office)

From (Person): Lurene jaw

of FCI

Date/Time: 11/10/18 @ 3:23pm

Estimated Cost:

Bill to:

OD/TP/AWS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 2100B

Insured: SHB 4848P

at Workshop m/s Chunni Motor

Tel: 6542 5119

of AMK Autopoint - soon hock motor # 01-05/06

Policy No:

Claim No: D1800-7361MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

'DS'

D.O.A. 09/10/2018

CA / REV / REP. / REV 24 HRS ^{lup}

12/10/2018

H.O.D. Endorsement:

Date/Time: 3:49pm @ 11/10/18

Person Contacted:

Lynn

Vehicle IN OUT


Date/Time	Action/Instruction (✓) Estimate
	SHB 2100B - CS/FCI14018725/Rgbk3-1 DOA: 29/9/14
	SHB 4848P - CC3/AIG10010846/Dn/f2g2 DOA: 31/05/2010
19/10 @ 4:19pm	Rev Revised preli advice via email.

ASSIGNMENT

03 Aug 2022
2014 August

From: _____ Date: _____
 Estimated Cost: _____
 ODI / TP / WS / TP / RES / TO / BE / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Escorted: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SHB 21003** To Repair: **2014 August**
 Type: **Car / M.Cycle / Bus / Van / Lorry** Prime Mover /
 Truck / Trailer or _____
 Make: **Hyundai I40** CC: **1685**
 Color: **Blue Yarn** ABS: Insured / Std / H/B / HA
 Sp. Drivling: **N.A.** 18/260, Insured / Std / H/B / HA
 Engine: **D4FDEU494965**
 Chassis: **KMHLB41UMEU058018**
 Gen. Cond: Fair / Poor / Burnt
 Steering: Jammed / Leaked / Burnt or
 Brakes: Jammed / Leaked / Burnt or
 Mod: STD A/Rim / STD A/Rim or
 Tyre Size: F: **205/60R16**
 R: **11**
 BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PH / SUMI /
 TOYO / YOKO or **Hankook**
 Front: _____ Rear: _____
 R/Rat: **5** mm L/Rat: **5** mm
 L/Rat: **5** mm L/Rat: **5** mm
 D.O.A: **09/10/2018** D.O.I: **12/10/2018**
 Survey held at **Chunni AMK**
 Don. of Damages: **Front y Rear**
 The O/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or ~~12~~ Net Value: _____
 ADAC Accident Report: _____ Conclusion? : Yes or No
 CIA / PH / Seen: _____ Conclusion? : Yes or No
 Est. Repairs: **108** days Res: Yes or No
 Turn Cost: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time: _____ Action / Instruction: **First Capital SHB 4848P**

27/11/18 **Insured 2/5 17000/- - its 10 days of rep**
(Red: 11332.66 : 39%)

RECEIVED 28 NOV 2018

Date/Time, File No: _____
 : Prelim. Report
 : Final Report
 Date/Time, File No: _____

Days Of Repair: **10**
 Recovery No. of Trip: **2**

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Insp (\$)
 Weekend (\$)

Survey Fee: **170 + 270**
 Transportation: **50**
 3 + 100, 50
 Phone: **580**
 Other: **039**
766

Report Format: _____
 Lump Sum / L.B.C: (\$) **17000/-**

29/11/18



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007441MFSH

Date: 19/10/2018

Our Ref: CS/FCI18018498/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 2100B

Please be informed that we had conducted the inspection of the abovementioned vehicle 12/10/2018 at the premises of M/s Chunni Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>28,332.66</u>
Revised Estimate Amount	: S\$ <u>21,446.10</u>
"Check" Items Amount	: S\$ <u> -</u>
Market Value	: S\$ <u> -</u>
LTA Reimbursement Value	: S\$ <u> -</u>
Nett Value	: S\$ <u> -</u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	09-10-2018	Our Ref No. D18007361MFSH
Accident Date	09-10-2018	Claim Type. Third Party
Insured Vehicle	SHB4848P	Third Party Vehicle. SHB2100B
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR,#01-05/06.	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65425119/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 19 October 2018 4:19 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007361MFSH/1
Attachments: PRELI ADVISED SHB 2100B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHB 2100B**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 11 October 2018 3:51 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007361MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 12/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 11 October 2018 3:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007361MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

CHUNNI MOTOR WORKS PTE LTD

To Survey by LKK

REPAIR ESTIMATE*

VEHICLE NO : SHB 2100B

DATE : 9.10.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>2 work</i>			\$ 251.00	<i>✓</i>
	Radiator Grille H Emblem <i>2 N/C</i>			\$ 27.50	<i>✓</i>
	Front Bumper Cover <i>distorted</i>			\$ 544.50	<i>✓</i>
	Front Bumper Sponge <i>2 torn</i>			\$ 99.20	<i>✓</i>
	Front Bumper Reinforcement <i>2 Dent</i>			\$ 402.10	<i>✓</i>
	Front Bumper Bracket Top (LH/RH) <i>N/A</i>	S	22.40	\$ 44.80	<i>X</i>
	Front Bumper Bracket (LH/RH) <i>N/A</i>	S	24.60	\$ 49.20	<i>X</i>
	Headlamp Support Top Cover <i>N/A</i>			\$ 222.60	<i>X</i>
	Headlamp Support Panel Assy <i>2 work</i>			\$ 907.40	<i>✓</i>
	Headlamp (LH/RH) <i>broken mounting</i>	S	1,388.00	\$ 2,776.00	<i>✓</i>
	Radiator <i>2 1/2</i>			\$ 698.30	<i>✓</i>
	Radiator Fan Blade, Cowling, Motor Assy <i>N/A</i>			\$ 792.95	<i>X</i>
	Radiator Bracket (RH/LH) <i>N/A</i>	S	6.50	\$ 13.00	<i>X</i>
	Radiator Guard <i>2 S/C</i>	S	20.00	\$ 40.00	<i>2 mm X</i>
	Horn Unit (LH/RH) <i>N/A</i>	S	73.80	\$ 147.60	<i>X</i>
	Front Fender (LH) <i>Dented</i>			\$ 566.30	<i>✓</i>
	Aircon Condenser <i>2 1/2</i>			\$ 927.50	<i>✓</i>
	Frt Safety Belt (Assy) (LH/RH) <i>activated</i>	S	475.40	\$ 950.80	<i>✓</i>
	Inter Cooler <i>2 1/2</i>			\$ 1,032.50	<i>✓</i>
	Inter Cooler Mounting (2 PCS) <i>N/A</i>			\$ 25.90	<i>X</i>
	Airbag Complete <i>activated</i>			\$ 2,948.50	<i>✓</i>
	Airbag Control Module <i>activated</i>			\$ 1,140.40	<i>✓</i>
	Steering Angle Assy <i>N/A</i>			\$ 1,150.60	<i>X</i>
	Sensor Assy Impact -Frt Impact <i>2 Dent</i>			\$ 198.30	<i>✓</i>
	Airbag Sensor <i>N/A</i>	S	580.00	\$ 1,160.00	<i>X</i>
			<i>13470.30</i>	\$ 17,116.95	
				\$ 3,423.39	
			<i>10776.24</i>	\$ 13,693.56	
				\$ 25.00	<i>Nett X</i>
				\$ 30.00	<i>Nett X</i>
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	<i>700/-</i>
	Spray Painting Charge			\$ 500.00	<i>400/-</i>
	Wiring Charge			\$ 50.00	<i>30/-</i>
	Towing Charge		<i>1390.00</i>	\$ 50.00	<i>N/A</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00	<i>280/-</i>
	Re-programme Air Bag & Safety Belt System			\$ 550.00	<i>180/-</i>
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	<i>N/A</i>
	TOTAL LABOUR			\$ 2,780.00	

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>Bt</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>deformed</i>			\$ 96.50	✓
	Boot Lid Lock Upper <i>Bt</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>can</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>Hec</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>Hec</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>crack</i>		\$ 565.60	\$ 1,131.20	✓
	Boot Lid Trimboard <i>SLC</i>			\$ 116.40	X
	Boot Lid Trimboard Clips (10pcs) <i>H</i>			\$ 11.00	X
	Bootlid Moulding <i>SLC</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>HH</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>HH</i>			\$ 227.90	X
	Bootlid CR <i>HH</i>			\$ 56.30	X
	Rear Bumper <i>distorted</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>crack</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>crack</i>	\$	80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>Hec</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>HH</i>	\$	35.60	\$ 71.20	X
	Rear Bumper Sponge <i>crack</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>distorted</i>			\$ 228.00	✓
	Tail Lamp (LH/RH) <i>crack</i>	\$	697.80	\$ 1,395.60	✓
	Rear Panel <i>Distorted</i>			\$ 526.70	✓
	Rear Panel Garnish <i>deformed</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>Distorted</i>			\$ 495.50	✓
	Spare Tyre Holder <i>HH</i>			\$ 223.10	X
	Spare Tyre Panel <i>Distorted</i>			\$ 852.80	✓
	Rear Towing Hook <i>HH</i>			\$ 94.60	X
	Exhaust Pipe Insulator, RH <i>HH</i>			\$ 58.55	X
	Exhaust Silencer, RH <i>Distorted</i>			\$ 967.70	✓
	Exhaust Pipe Hanger, RH <i>HH</i>			\$ 58.55	X
	Exhaust Pipe Centre <i>HH</i>			\$ 730.10	X
			9368.20		
			7494.56		
				\$ 11,160.50	
				\$ 2,232.10	
				\$ 8,928.40	
				\$ 30.00	Nett ✓
				\$ 135.70	Nett ✓
				\$ 50.00	Nett ✓
				\$ 215.70	
				\$ 1,200.00	800/-
				\$ 4,000.00	600/-
				\$ 50.00	30/-
				\$ 50.00	40/-
				\$ 120.00	40/-
				\$ 240.00	60/-
				\$ 2,660.00	
				\$ 28,332.66	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SUB TOTAL
LESS 20%
DISCOUNTED TOTAL

9368.20
7494.56

215.70

12/10/2018 @ 1030m
Not done
2/sum 10
2 KKK Auto
1570.00

21446.50

2157000/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18018498/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4848P	Veh. Inspected	SHB 2100B
Policy No.		Coverage (\$)	0.00
Claim No.	D18007361MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	11/10/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHLB41UMEU058018	Colour	YELLOW
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	5 mm
L/H Front Tyre	205/60 R16	HANKOOK	5 mm
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/10/2018	Inspection Date	12/10/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2100B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RADIATOR GRILLE	CRACKED	251.00	251.00
1	RADIATOR GRILLE H EMBLEM	NECESSARY	27.50	27.50
1	FRONT BUMPER COVER	DISTORTED	544.50	544.50
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	DENTED	402.10	402.10
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	NOT NECESSARY	49.20	-
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	MOUNTING BROKEN	2,776.00	2,776.00
1	RADIATOR	BENT	698.30	698.30
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	NOT NECESSARY	792.95	-
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
2	RADIATOR GUARD @\$20.00	SERVICEABLE	40.00	-
2	HORN UNIT (LH/RH) @\$73.80	NOT NECESSARY	147.60	-
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	AIRCON CONDENSER	BENT	927.50	927.50
2	FRT SAFETY BELT (ASSY)(LH/RH) @\$475.40	ACTIVATED	950.80	950.80
1	INTER COOLER	BENT	1,032.50	1,032.50
1	INTER COOLER MOUNTING (2 PCS)	NOT NECESSARY	25.90	-
1	AIRBAG COMPLETE	ACTIVATED	2,948.50	2,948.50
1	AIRBAG CONTROL MODULE	ACTIVATED	1,140.40	1,140.40
1	STEERING ANGLE ASSY	NOT NECESSARY	1,150.60	-
1	SENSOR ASSY IMPACT-FRT IMPACT	DAMAGED	198.30	198.30
2	AIRBAG SENSOR @\$580.00	NOT NECESSARY	1,160.00	-
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID RUBBER	DEFORMED	96.50	96.50
1	BOOT LID LOCK UPPER	BENT	102.60	102.60
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-

Report Ref No. CS/FCI18018498/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID "H" EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
2	BOOT LID LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
1	BOOT LID TRIMBOARD	SERVICEABLE	116.40	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOTLID MOULDING	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM	NOT NECESSARY	27.90	-
1	BOOTLID LOWER GARNISH	NOT NECESSARY	227.90	-
1	BOOTLID CR	NOT NECESSARY	56.30	-
1	REAR BUMPER	DISTORTED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	BENT	160.60	160.60
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	NOT NECESSARY	71.20	-
1	REAR BUMPER SPONGE	TORN	118.40	118.40
1	REAR BUMPER UNDER COVER	DISTORTED	228.00	228.00
2	TAIL LAMP (LH/RH) @\$697.80	CRACKED	1,395.60	1,395.60
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL GARNISH	DEFORMED	57.70	57.70
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
1	SPARE TYRE HOLDER	NOT NECESSARY	223.10	-
1	SPARE TYRE PANEL	DENTED	852.80	852.80
1	REAR TOWING HOOK	NOT NECESSARY	94.60	-
1	EXHAUST PIPE INSULATOR,RH	NOT NECESSARY	58.55	-
1	EXHAUST SILENCER,RH	DENTED	967.70	967.70
1	EXHAUST PIPE HANGER,RH	NOT NECESSARY	58.55	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	730.10	-
	LESS 20% DISCOUNT		-5,655.49	-4,567.70
			22,621.96	18,270.80
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	FRONT NO PLATE TRIM COVER (SN)	SERVICEABLE	30.00	-

Report Ref No. CS/FCI18018498/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			270.70	215.70
	LABOUR			
	PANEL BEATING INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER.		2,200.00	1,500.00
	SPRAY PAINTING CHARGE.		1,500.00	1,000.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	RE-PROGRAMME AIR BAG & SAFETY BELT SYSTEM.		550.00	180.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE.		240.00	60.00
			5,440.00	2,960.00
	GRAND TOTAL		28,332.66	21,446.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,000.00

Report Ref No. CS/FC118018498/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.