

2-19-1992

ASS. REC. BY:

REF:

CS/CTI18018510/ Aq d3

Special Instruction:

Surveyor:  
Munnen

Adrian

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

11/10/18 4:41pm

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 3582J

Insured:

SJP 8356T

at Workshop m/s

1st Autoworks

Tel:

6 844 1985

of

23 Kaki Blk Ave 4 # 04-01

Policy No:

DMPCSN 3061571700

Claim No:

3NM18D04788C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/10/2018

12/10/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

5:22pm @ 11/10/18

Person Contacted:

Subuimi

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLC 3582J-X
	SJP 8356T-X
	us \$4950, 6 days (Red to \$500.80, 66%)

REF: CTE

PREFORM

## ASSIGNMENT

Mufmun

From

Date: 12/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLC 3582J

at Workshop m/s

First Autoworks

of

23 Kaki Bukit Ave 4 #04-01

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SLC 3582J. Yr Regn: 2016 May.

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish.

CC 1738

Colour:

White.

A/C. Insured / Std / NI / NA

Sp. Reading

178155

T/Radio: Insured / Std / NI / NA

Eng/No:

JTDG920WXX0J003914

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ R / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

195/55R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

12/10/18.

Survey held at

1st Autowork.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP China.

RECEIVED 12 NOV 2018

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) \$ + PG \$

) Photos

) Others

TOTAL

220

Report Format :

MER-TP

Lump Sum / I.B.I. (\$) :

4950

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2018		11 Oct 2018 16:41 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GOH YONG CHEE, ID: S1174007C		
Main Claimant:	ISKANDAR BIN SUPARJO, ID: S7322426H		
Vehicle Reg. No.:	SLC3582J	Date of Loss:	05/10/2018 18:00 - :59
Claim Type:	TP / SNM18D04788C02	Policy/Cover Note No.:	DMPCSN3061571700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJP8356T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number:** 5093613878-01

**Cover :** drive PREMIUM

1. Index mark and Registration Number of Vehicle : **SLC3582J**  
Chassis Number : JTDGG20WX0J003914
2. Name of Policyholder : ALPINE CAR RENTAL PTE LTD
3. Effective Date of Insurance : 01 Sep 2018
4. Expiry Date of Insurance : 31 Aug 2019
5. Persons or Classes of Persons entitled to drive#  
(a) The Policyholder.  
(b) Any other person who is driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#  
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

**This Policy does not cover**

- (a) Use for racing, pace-making, reliability trial or speed-testing.
  - (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
  - (c) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$1,400
EXCESS (SECTION 2)	: S\$1,400
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ALPINE CREDIT PTE LTD (00000615424)  
Date of Issue : 28 Aug 2018 08:52 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

1st Autoworks Pte Ltd  
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 12/10/2018

Reference: SLC3582J  
TOYOTA WISH  
Make: 1.8 CVT

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLC3582J  
CHASSIS NO.: JTDGG20WX0J003914  
ENGINE NO.: 2ZR1747510

Name of insured : Alpine Car Rental Pte Ltd  
Date of accident.: 05/10/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Rear Tailgate <i>Distorted</i>	\$ 980.70 ✓
2	1	Rear Tailgate Chrome Handle <i>Not in</i>	\$ 245.30 ✗
3	1	LHR Tailgate Lamp <i>Not in</i>	\$ 268.50 ✗
4	1	RHR Tailgate Lamp <i>Not in</i>	\$ 268.50 ✗
5	1	Valve Matic Logo <i>New</i>	\$ 78.00 ✓
6	1	Toyota Logo <i>New</i>	\$ 73.00 ✓
7	1	Tailgate Windscreen with Moulding <i>Not New</i>	\$ 1,238.00 ✗
8	1	LHR Tailgate Hinge <i>2 New</i>	\$ 102.30 ✗
9	1	RHR Tailgate Hinge <i>1 New</i>	\$ 102.30 ✗
10	1	Tailgate Latch <i>Repl</i>	\$ 348.10 ✓
11	1	Tailgate Striker <i>Not in</i>	\$ 65.70 ✗
12	1	Rear Tailgate Inner Trim <i>Out</i>	\$ 381.60 ✓
13	1	LHR Fender Inner Trim <i>2 New</i>	\$ 598.30 ✓
14	1	RHR Fender Inner Trim <i>1 New</i>	\$ 598.30 ✓
15	1	LHR Taillamp <i>New</i>	\$ 395.50 ✗
16	1	RHR Taillamp <i>Out</i>	\$ 395.50 ✓
17	1	Rear Bumper <i>Distorted</i>	\$ 784.50 ✓
18	1	LHR Bumper Reflector <i>New</i>	\$ 68.00 ✗
19	1	RHR Bumper Reflector <i>Not in</i>	\$ 68.00 ✗
20	1	LHR Fender Liner <i>2 New</i>	\$ 785.10 ✗
21	1	RHR Fender Liner <i>1 New</i>	\$ 785.10 ✗
22	1	Rear End Panel <i>Distorted</i>	\$ 395.30 ✓
23	1	Rear End Panel Trim <i>Repl</i>	\$ 298.70 ✓
24	1	Spare Tyre Panel <i>2 New</i>	\$ 1,240.70 ✗
25	1	LHR Bumper Bracket <i>Not in</i>	\$ 98.70 ✗

26	1	RHR Bumper Bracket	<i>Perk</i>	\$ 98.70	✓
----	---	--------------------	-------------	----------	---

503040  
3773.03

Parts Total: \$ 10,762.40  
Less 25%: \$ 2,690.60  
Total: \$ 8,071.80

## Labour

No.	Labour Description	Price (SGD)	
<u>Rear portion</u>			
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ <del>2,000.00</del>	<i>80</i>
2	Carry out spray painting on accident affected area	\$ <del>1,600.00</del>	<i>80</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
4	To remove and refix reverse sensor and conduct test	\$ <del>80.00</del>	<i>50</i>
5	To remove and refix reverse camera and conduct test	\$ <del>80.00</del>	<i>50</i>
6	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00	✓
7	To conduct water leakage test after repairs of vehicle	\$ 80.00	<i>x.</i>
8	To conduct realigning of exhaust pipe	\$ 80.00	<i>x.</i>
9	To remove and refix rear tail gate windscreen	\$ 120.00	✓
10	To remove and refit rear spoiler	\$ 180.00	<i>x.</i>

1930

Labour Total: \$ 4,330.00

## Others

### Other Description

No.	Qty		Price (SGD)	
<u>Rear portion</u>				
1	1	Rear number plate <i>Bert</i>	\$ 45.00	✓
2	10	Rear bumper clip <i>ra</i>	\$ <del>65.00</del>	<i>30</i>
3	6	Rear fender liner clips <i>new</i>	\$ 39.00	<i>x</i>
4	6	Rear end panel trim clip <i>new</i>	\$ <del>39.00</del>	<i>10</i>
5	1	Reverse sensor (4pcs) <i>Damaged</i>	\$ <del>440.00</del>	<i>200</i>
6	1	Rear reverse camera <i>new</i>	\$ 280.00	<i>x</i>
7	1	Rear end panel insulation seal <i>new</i>	\$ <del>120.00</del>	<i>60</i>
8	1	Rear floor panel insulation seal <i>new</i>	\$ 200.00	<i>x.</i>
9	24	Rear fender inner trim clip <i>new</i>	\$ 156.00	<i>60</i>
10	10	Tail gate inner trim board clip <i>new</i>	\$ 65.00	<i>30</i>
11	2	Rear exhaust mounting <i>not new</i>	\$ 180.00	<i>x</i>
12	1	Rear spoiler <i>not new</i>	\$ 200.00	<i>x.</i>
13	1	Tailgate windscreen sealant <i>new</i>	\$ <del>120.00</del>	<i>60</i>
14	1	Rear Spoiler Sealant <i>not new</i>	\$ 120.00	<i>x.</i>


495

Other Total: \$ 2,069.00

GRAND TOTAL: \$ 14,470.80

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Suhaimi Ong

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax:6844 5185

Adrian Lj  
w/s 06 hrs

total: 6198.03

H/s 4950

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is "On a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Atm. Adnan

**1st Autoworks Pte Ltd**

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

**TAX INVOICE**

CHINA TAIPING INSURANCE(SINGAPORE)PTE LTD

3 Anson Road, #16-00

Springleaf Tower

SINGAPORE 079909

GST Ref. No: 20-0000274-Z

Vehicle No: SLC3582J

Invoice No:

Chasis No: JTDGG20WX0J003914

Engine No: 2ZR1747510

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

**Parts**

No.	Qty.	Description	Price (SGD)
1	1	Rear Tailgate	\$ 980.70
2	1	Valve Matic Logo	\$ 78.00
3	1	Toyota Logo	\$ 73.00
4	1	Tailgate Latch	\$ 348.10
5	1	Rear Tailgate Inner Trim	\$ 381.60
6	1	LHR Fender Inner Trim	\$ 598.30
7	1	RHR Fender Inner Trim	\$ 598.30
8	1	RHR Taillamp	\$ 395.50
9	1	Rear Bumper	\$ 784.50
10	1	Rear End Panel	\$ 395.30
11	1	Rear End Panel Trim	\$ 298.70
12	1	RHR Bumper Bracket	\$ 98.70

Total: \$ 5,030.70

Less 25%: \$ 1,257.68

Parts Total : \$ 3,773.03

**Labour**

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 800.00
2	Carry out spray painting on accident affected area	\$ 800.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
4	To remove and refix reverse sensor and conduct test	\$ 50.00



<u>5</u>	To remove and refix reverse camera and conduct test	\$ 50.00
<u>6</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00
<u>7</u>	To remove and refix rear tail gate windscreen	\$ 120.00

Labour Total : \$ 1,930.00

**Other**

No.	Other Description	Price (SGD)
1	1 Rear number plate	\$ 45.00
2	10 Rear bumper clip	\$ 30.00
3	6 Rear end panel trim clip	\$ 10.00
4	1 Reverse sensor (4pcs)	\$ 200.00
5	1 Rear end panel insulation seal	\$ 60.00
6	24 Rear fender inner trim clip	\$ 60.00
7	10 Tail gate inner trim board clip	\$ 30.00
8	1 Tailgate windscreen sealant	\$ 60.00

Other Total : \$ 495.00

Total : \$ 6,198.03

Less 20% Lump Sum : \$ 1,239.61

After Lump Sum 20% : \$ 4,950.00

GST (7%) \$ 346.50

**Grand Total: \$ 5,296.50**

Yours Faithfully,



Suhaimi Ong

Service Advisor

Tel: 68441985 Fax:68445185

**E & O E**

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "IST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

**Please check and finalize with me this invoice**

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18018510/AQD3N2

Date: 13/11/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3061571700
Claimant Vehicle No :	SLC3582J	Insured Vehicle No :	SJP8356T
Date of Loss:	05/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04788C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLC3582J	Engine No:	2ZR1747510
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20WX0J003914
Reg. Date:	11/05/2016 (Man. Year: 2016)	Odometer:	178155 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,140.80	4,268.02	5,872.78	57.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	1,930.00	2,400.00	55.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>14,470.80</b>	<b>6,198.02</b>	<b>8,272.78</b>	<b>57.17</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,950.00</b>		
<b>(\$\$)</b>	<b>14,470.80</b>	<b>4,950.00</b>	<b>9,520.80</b>	<b>65.79</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,012.96</b>	<b>346.50</b>	<b>666.46</b>	<b>65.79</b>
<b>Nett Amount (\$\$)</b>	<b>15,483.76</b>	<b>5,296.50</b>	<b>10,187.26</b>	<b>65.79</b>

## INSPECTION

Date of Assignment:	11/10/2018	Inspected At:	1st Autoworks Pte Ltd (HQ)
Date Inspected:	12/10/2018		23 Kaki Bukit Ave 4, #04-01
			Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC3582J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	980.70 FL	*980.70 FL
2	1		*REAR TAILGATE CHROME HANDLE	Not Necessary	245.30 FL	*- FL
3	1		*LHR TAILGATE LAMP	Not Necessary	268.50 FL	*- FL
4	1		*RHR TAILGATE LAMP	Not Necessary	268.50 FL	*- FL
5	1		*VALVE MATIC LOGO	Necessary	78.00 FL	*78.00 FL
6	1		*TOYOTA LOGO	Necessary	73.00 FL	*73.00 FL
7	1		*TAILGATE WINDSCREEN WITH MOULDING	Not Necessary	1,238.00 FL	*- FL
8	1		*LHR TAILGATE HINGE	Not Necessary	102.30 FL	*- FL
9	1		*RHR TAILGATE HINGE	Not Necessary	102.30 FL	*- FL
10	1		*TAILGATE LATCH	Damaged	348.10 FL	*348.10 FL
11	1		*TAILGATE STRIKER	Not Necessary	65.70 FL	*- FL
12	1		*REAR TAILGATE INNER TRIM	Cracked	381.60 FL	*381.60 FL
13	1		*LHR FENDER INNER TRIM	Cracked	598.30 FL	*598.30 FL
14	1		*RHR FENDER INNER TRIM	Cracked	598.30 FL	*598.30 FL
15	1		*LHR TAILLAMP	Not Necessary	395.50 FL	*- FL
16	1		*RHR TAILLAMP	Cracked	395.50 FL	*395.50 FL
17	1		*REAR BUMPER	Distorted	784.50 FL	*784.50 FL
18	1		*LHR BUMPER REFLECTOR	Not Necessary	68.00 FL	*- FL
19	1		*RHR BUMPER REFLECTOR	Not Necessary	68.00 FL	*- FL
20	1		*LHR FENDER LINER	Not Necessary	785.10 FL	*- FL
21	1		*RHR FENDER LINER	Not Necessary	785.10 FL	*- FL
22	1		*REAR END PANEL	Dented	395.30 FL	*395.30 FL
23	1		*REAR END PANEL TRIM	Deformed	298.70 FL	*298.70 FL
24	1		*SPARE TYRE PANEL	Repair	1,240.70 FL	*- FL
25	1		*LHR BUMPER BRACKET	Not Necessary	98.70 FL	*- FL
26	1		*RHR BUMPER BRACKET	Dented	98.70 FL	*98.70 FL
27	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
28	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
29	6		*REAR FENDER LINER CLIPS	Not Necessary	39.00 FS	*- FS
30	1		*REAR END PANEL TRIM CLIP	Necessary	39.00 FS	*10.00 FS
			(6 Pcs)			
31	1		*REVERSE SENSOR (4 PCS)	Damaged	440.00 FS	*200.00 FS
32	1		*REAR REVERSE CAMERA	Not Necessary	280.00 FS	*- FS
33	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
34	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	200.00 FS	*- FS
35	1		*REAR FENDER INNER TRIM CLIP	Necessary	156.00 FS	*60.00 FS
			(24 Pcs)			
36	10		*TAIL GATE INNER TRIM BOARD CLIP	Necessary	65.00 FS	*30.00 FS
37	2		*REAR EXHAUST MOUNTING	Not Necessary	180.00 FS	*- FS
38	1		*REAR SPOILER	Not Necessary	200.00 FS	*- FS
39	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
40	1		*REAR SPOILER SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,831.40 5,525.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					2,690.60	1,257.68
Total Parts (S\$)					10,140.80	4,268.02

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	2,000.00	800.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,600.00	800.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	30.00	30.00
4	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	80.00	50.00
5	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	80.00	50.00
6	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGTAE TO NEW TAILGATE	New	80.00	80.00
7	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	-
8	TO CONDUCT REALIGNING OF EXHAUST PIPE	New	80.00	-
9	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	120.00	120.00
10	TO REMOVE AND REFIT REAR SPOILER	New	180.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>4,330.00</b>	<b>1,930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >