



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 5148D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP) (CONSISTENT)	BUCKLED /MTG CRACKED	220.00	220.00
1	R/F BUMPER BRACKET (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	30.00	-
1	FRONT BUMPER SUPPORT (WCP) (CONSISTENT)	* CHECK	95.00	-
1	FRT BUMPER ABSORBER (WCP) (CONSISTENT)	SERVICEABLE	68.00	-
1	FRT BUMPER CLAMP KIT (WCP) (CONSISTENT)	NECESSARY	30.00	30.00
1	R/F HEADLAMP (WCP) (CONSISTENT)	CUT	325.00	325.00
	COST PLUS 15%		115.20	86.25
			883.20	661.25
	<u>LABOUR</u>			
	PANEL /MECHANICAL.INCLUSIVE OF THE REPAIR OF R/F BUMPER BRACKET.		130.50	85.50
	PAINTWORK.		297.00	297.00
	PAINT/MATERIAL COSTS.		109.73	109.73
			537.23	492.23
GRAND TOTAL			1,420.43	1,153.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$109.25 NETT)				900.00

Report Ref No. CC4/ASM18018522/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.