

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18018559/T1GA3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	FBC4370R	Insured Vehicle No :	SHC5451M
Date of Loss:	08/08/2018	Nature of Claim:	TP
		Claim No:	C0474229

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC4370R	Engine No:	M445M4611
Make & Model:	PIAGGIO VESPA LX 150, 151cc	Chassis No:	ZAPM4440000010230
Reg. Date:	11/03/2008 (Man. Year: 2007)	Odometer:	0 km
Colour:	Maroon		
Engine Capacity:	151 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R11	Rear Tyre Size:	120/70 R10
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,596.39	2,429.89	166.50	6.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	1,380.00	390.00	22.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,366.39	3,809.89	556.50	12.75
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	4,366.39	3,050.00	1,316.39	30.15
+ GST 7.00/7.00% (S\$)	305.65	213.50	92.15	30.15
Nett Amount (S\$)	4,672.04	3,263.50	1,408.54	30.15
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	12/11/2018	
Date Inspected:	12/10/2018	Inspected At: Pan Euro Bikes Pte Ltd (HQ) 21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Mar 2021)	
Parts:	N/A	PIAGGIO VESPA LX 150 151cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBC4370R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH MIRROR (CONSISTENT)	Cut	45.00 FL	*45.00 FL
2	1		*LH MIRROR (CONSISTENT)	Missing	45.00 FL	*45.00 FL
3	1		*LH HANDLE GRIP (CONSISTENT)	Cut	15.00 FL	*15.00 FL
4	1		*HANDLEBAR (CONSISTENT)	Serviceable	185.00 FL	*- FL
5	1		*METER (CONSISTENT)	Cracked	225.00 FL	*225.00 FL
6	1		*HEADLAMP COVER ,RED (CONSISTENT)	Cracked	185.00 FL	*185.00 FL
7	1		*HANDLE COVER ,RED (CONSISTENT)	Cracked	165.00 FL	*165.00 FL
8	1		*STARTER BUTTON (CONSISTENT)	Cracked	18.00 FL	*18.00 FL
9	1		*HEADLAMP ASSY (CONSISTENT)	Cracked	180.00 FL	*180.00 FL
10	1		*HEADLAMP BULB (CONSISTENT)	Necessary	18.00 FL	*18.00 FL
11	1		*LH BEADING ,BLACK (CONSISTENT)	Cut	48.00 FL	*48.00 FL
12	1		*CLIP ,LH BEADING ,BLACK (CONSISTENT)	Necessary	8.00 FL	*8.00 FL
13	1		*FRONT MUDGUARD ,RED (CONSISTENT)	Cut	246.00 FL	*246.00 FL
14	1		*FRONT FORK LINK COVER ,CHROME (CONSISTENT)	Cut	45.00 FL	*45.00 FL
15	1		*LH PILLAR FOOTREST PAD (CONSISTENT)	Cut	37.00 FL	*37.00 FL
16	1		*RH PILLAR FOOTREST PAD (CONSISTENT)	Missing	37.00 FL	*37.00 FL
17	1		*FLOORBOARD (CONSISTENT)	Cracked	268.00 FL	*268.00 FL
18	1		*RH SMALL COVER ,PILLION STEP LOWER ,RED (CONSISTENT)	Cracked	42.00 FL	*42.00 FL
19	1		*RH REAR SKIRT ,RED (CONSISTENT)	Distorted	120.00 FL	*120.00 FL
20	1		*EXHAUST PLATE ,CHROME (CONSISTENT)	Cut	55.00 FL	*55.00 FL
21	1		*TAILLAMP (CONSISTENT)	Cracked	185.00 FL	*185.00 FL
22	1		*KICKSTARTER LEVER (CONSISTENT)	Cut	66.00 FL	*66.00 FL
23	1		*BELT COVER (CONSISTENT)	Dented	280.00 FL	*280.00 FL
24	1		*MAINSTAND (CONSISTENT)	Damaged	120.00 FL	*120.00 FL
25	1		*LH REAR SIGNAL ASSY (CONSISTENT)	Cracked	46.00 FL	*46.00 FL
26	1		*SET ERP UNIT (CONSISTENT)	Cracked	145.79 FS	*145.79 FS
27	1		*ERP BRACKET (CONSISTENT)	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,864.79	2,679.79
- List Item Discount on L Items 10.00/10.00% (\$\$)	268.40	249.90
Total Parts (\$\$)	2,596.39	2,429.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SEND FRONT FORK/STEM ASSY FOR RE-ALIGNMENT	New	160.00	120.00
2	SEND BODY FRAME FOR HEAT-WELD KNOCKING & RE-ALIGNMENT REPAIR	New	550.00	400.00
3	SEND BIKE FOR PAINTING	New	750.00	600.00
4	TOWING	New	60.00	60.00
5	LABOUR CHARGE	New	250.00	200.00
Gross Labour Cost (\$\$)			1,770.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >