

WSS, REC. BY:

REF: CS3/SPF18003751/11vd3⁰²

Surveyor: Tauhikh ASSIGNMENT (Office)

From (Person): Frankie Hoy of SPF Date/Time: 30/08/2018

Estimated Cost: _____ Bill to: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SIF 27984 Insured: Qx61x

at Workshop in/s: Hain Car Repairs Tel: 62710275

of B/k 1001, Bkt Merah Lane 3 # 01-49

Policy No: _____ Claim No: AEMD/105/1009/2018/017

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.G.A. 31/01/2018

(Client's Record) CA / REV / REP. / REV 24 HRS ^{1wp?} H.O.D. Endorsement: _____

Date/Time: 11:01am 27/2/18 Person Contacted: lina Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SIF 27984 - X</u>
	<u>Qx61x - X</u>
<u>14/6/18</u>	<u>Submit LS \$ 3300, 4 days</u>
<u>12/10/18</u>	<u>- pending photographs from Frankie.</u>

15/10/18 Submit LS \$ 4200 (Red 2900, 410), 4 days

5/3/19 To re-open indicate upper range \$5K - \$6K (EST)

Pass to typist. Celine 6/3/2019.

WA close date 18/11/18, re-open ref only ↓ 6/3/19

RECEIVED 15 OCT 2018

Repair days \$4

Terim lina

12/10/18

Veron Chen (LKKAuto)

From: Olivia Lau (LKKAuto)
Sent: Tuesday, 5 March 2019 3:18 PM
To: SUR; assignments
Subject: FW: URGENT - pse reply by tomorrow latestff-SLF 2798U
Attachments: 2018-017 LKK (Re-evaluation report).pdf

From: Frankie THAY (SPF)
Sent: Tuesday, 5 March 2019 3:17:32 PM (UTC+08:00) Kuala Lumpur, Singapore
To: Veron Chen (LKKAuto)
Cc: Hafizul Farhan RAHMAT (SPF); Olivia Lau (LKKAuto)
Subject: RE: URGENT - pse reply by tomorrow latestff-SLF 2798U

Veron,
Can please include the upper range repair cost (According to surveyor upper range estimated \$5K-\$6K) in the report and forward to us.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, 19 February 2019 3:29 PM
To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; SUR <sur@lkkauto.com>; Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>
Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Subject: RE: URGENT - pse reply by tomorrow latestff-SLF 2798U

Dear Rosalyn,

According to surveyor upper range estimated \$5K-\$6K

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAuto)

Sent: Monday, 18 February 2019 2:13 PM

To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: FW: URGENT - pse reply by tomorrow latestff

From: Rosalyn TAN (SPF)

Sent: Monday, 18 February 2019 2:12:25 PM (UTC+08:00) Kuala Lumpur, Singapore

To: Olivia Lau (LKKAuto)

Cc: Frankie THAY (SPF); Hafizul Farhan RAHMAT (SPF)

Subject: URGENT - pse reply by tomorrow latestff

Hi Olivia,

We have agreed that with effect Oct 2018, Survey report is to include Upper range of repair cost.

Appreciate if you can revert on the upper range of repair cost for this case.

Also, usually LKK would recommend on the duration of repair needed. Please ensure that you include the weekends if the vehicle has already been booked into the workshop on Friday or Sat so that we can allow for weekend claims too.

Cc: Frankie & Farhan, please note the above and ensure that you check through the survey reports.

Rosalyn Tan Sock Buay

Head Corporate Services & Safe Driving

Police Logistics Department/ AEMD

Singapore Police Force

DID: (65) 6478 4832 | FAX: (65) 6478 4838



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 2798U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NECESSARY	140.00	140.00
1	REAR TAILGATE	DENTED	1,583.50	953.30
2	REAR TAILGATE DAMPERS	NOT NECESSARY	420.00	-
2	REAR TAILGATE HINGES	NOT NECESSARY	110.00	-
1	REAR TAILGATE INNER BOARD	NOT NECESSARY	638.00	-
2	REAR TAILGATE LAMPS	CUT	560.00	560.00
1	REAR TAILGATE LOCK	BENT	210.00	210.00
1	REAR TAILGATE LOGO	NECESSARY	32.00	32.00
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	187.00	-
1	REAR TAILGATE RUBBER	NOT NECESSARY	195.00	-
1	REAR TAILGATE "VEZEL" EMBLEM }	NECESSARY	75.00	56.20
1	REAR TAILGATE "HYBRID" EMBLEM }	NECESSARY	76.00	76.00
2	REAR TAILLAMPS	CRACKED	1,500.00	913.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	675.90	-
1	REAR END PANEL INNER GARNISH	CUT	128.90	128.90
2	REAR SIDE BUMPERS	TO REPAIR SEE LABOUR	518.00	-
1	REAR BUMPER	DENTED	936.10	810.00
2	REAR BUMPER REFLECTORS	CRACKED	362.00	362.00
2	REAR BUMPER SIDE RETAINERS	NECESSARY	88.00	72.00
	LESS 20% DISCOUNT		-1,687.08	-862.80
			6,748.32	3,451.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR QUARTER GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	SET REAR REVERSE SENSOR (2 PCS)(SN)	SHORTED	480.00	200.00
			540.00	260.00
<u>LABOUR</u>				
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING,HARNESS WIRES,SOCKETS,REPLACE DAMAGED PARTS.		50.00	40.00

Report Ref No. CS3/SPF18003751/T1vd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.		200.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		200.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	80.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR SIDE BUMPERS.		1,050.00	600.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,050.00	600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		100.00	60.00
			2,830.00	1,520.00
	GRAND TOTAL		10,118.32	5,231.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CS3/SPF18003751/T1vd3e2-1

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.