

22/03/2012

ASS. REC. BY:

REF: CS/FCU1801-8565/UTB52

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

aws

From (Person):

Majchua

of

FCF

Date/Time: 16/10/2018 9:12am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

AV 5860C

Insured:

SHC 1580A

at Workshop m/s

Kin's Brother

Tel:

6741 7730

of

Bk 1 Kaki Bukit Ave 6 #01-01

Policy No:

Claim No:

D1800744 MFSH

Sum Insured:

Excess:

D.O.A.

10-10-2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 9:42am @ 16/10/18 Person Contacted:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	AV 5860C - X
	SHC 1580A - CS/FCU14023907 / kjjsw2
19/10@3:05	revised preli advise via email

DA: 251214

Survey no/cus

REF:

FCI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

DAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

15

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

31/5/2022

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GV5860C

Yr Regn:

802

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

Colour:

white

Sp. Reading

327123

Eng/No:

C/No:

LH162100.6870

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

radial

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/10/18

D.O.I.

12/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/6/11/18

LH16146 3yrs. 7mths. net 8354
confirmed L/S & 8300 with Susan. (Red: 17893.10 !68%)

RECEIVED 05 NOV 2018

Date/Time: File Pass to?

Bill Typist

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

TP
8300

Days Of Repair: 15

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + P + SI

Photo

Others

16 x 15 = 240.

240 + 170 = 410

410
30
50 + 50
118
678

MOTOR SURVEY ASSIGNMENT

Date	12-10-2018	Our Ref No. D18007441MFSH
Accident Date	10-10-2018	Claim Type. Third Party
Insured Vehicle	SHC1580A	Third Party Vehicle. GV5860C
Survey Location	1 KAKI BUKIT AVENUE 6 #01-01AUTOBAY @ KAKI BUKIT	
Contact Person.	SUSAN LOW	
Contact No.	67411730/ 0	Fax No. 67445746
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIU'S BROTHER AUTO ENGINEERING WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 19 October 2018 3:05 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007441MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GV 5860C on 12/10/2018
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 16 October 2018 9:44 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007441MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 16 October 2018 9:12 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007441MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2018 23:56
Date Of Accident	10/10/2018 20:15
Exact Location Of Accident	SLIP ROAD OF TANAH MERAH COAST ROAD FROM ECP(CHANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GV5860C
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	ISAACNGCL@GOLDBELLCORP.COM
Mobile Phone No	
Alternative Phone No	OFFICE-64942897

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE DIESEL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090757MFCV
Cover Note Number	N.A

Driver

Name of Driver	QUSYAIRI BIN JEFFRY
NRIC No	S9503523Z
Date Of Birth	07/02/1995
Occupation	OUTDOOR
Date Of Driving Pass	01/12/2017
Driving Experience	0 YEAR AND 10 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97523845
Fax Number	
Contact Number	
Email Address	QUSYIQA.H.20@GMAIL.COM

Passenger 1

NAME: : P1

GENDER: : MALE

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC1580A
Vehicle Make/Model/Colour	HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO / BLUE
Details Of Properties	N.A
Vehicle Category	TAXI
Name of Driver	PEK KIAN HUAT
NRIC/Passport Number	
Contact Number	92734353
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan #2 Pg. 1

ACCIDENT STATEMENT (2000 characters)

I was coming from ECP(City) on the slip road of Tanah Merah Coast Road. A vehicle YP7491P in front of me had braked. I managed to brake but before i came to a stop, a taxi SHC1580A from my rear collided onto the rear of my vehicle. The impact caused my vehicle to surge forward and collided onto the rear of vehicle YP7491P.

As told by driver of YP7491P, a road sweeper had cut across from the left lane into the right lane.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect.

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

10 October 2018 at 10:24 PM

Date/Time:

10 October 2018 at 10:24 PM

[> Back to OneMotoring](#)

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 12 Oct 2018 / 11:19:45

Receipt Date/Time : 12 Oct 2018 / 11:19:45

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181012-000860

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHC1580A				
As at 10 Oct 2018/20:15:00				
Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED				
1	Insurance Enquiry - SHC1580A Enquiry Fee 20181012111835130687	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	1196N

Vehicle Details

Vehicle No.:	GV5860C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DIESEL
Primary Colour:	White
Manufacturing Year:	2002
Engine No.:	5L5237170
Chassis No.:	LH1621006870
Maximum Power Output:	-
Open Market Value:	\$21,936.00
Original Registration Date:	08 Aug 2002
First Registration Date:	08 Aug 2002
Transfer Count:	3
Actual ARF Paid:	\$1,097.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 May 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,263.00
COE Rebate Amount:	\$16,146.00
Total Rebate Amount:	\$16,146.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 12 Oct 2018


OK

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR



Toyota Hiace

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Net Link Partners Pte Ltd » Toyota Hiace (COE till 03/2022)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Hiace (COE till 03/2022)

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

NETLINK *Your Commercial Specialist*

Specialized in New & Used Commercial Vehicles. Insurance. Hire Purchase. Scrap/Export

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$26,800
Depreciation	\$7,730 /yr
Reg Date	10-Apr-2007 (3yrs 5mths 19days COE left)
Lifespan	09-Apr-2027
Manufactured	2007
Mileage	-
Transmission	Manual
Engine Cap	2,982 cc
Curb Weight	1,820 kg
Fuel type	Diesel
Features	Powerful And Fuel Efficient Turbo Engine! 1 Owner! Flexible Loan Package! Competitive Insurance Quotations! High Trade-in Value! Call Now!
Accessories	Radio MP3 Player, Tools Kit, Reverse Sensors Plus Buzzer, Front Camera.
Description	1 Owner Agent Unit From Borneo Motors! Cheapest In Market! Powerful And Reliable Van, Excellent Condition. Call Fast Before It Gone!
COE	\$24,394
OMV	\$24,590
Dereg Value	\$16,922 as of today (change)
No. of Owners	1
Type of Veh	Van
Category	COE Car, Premium Ad Car
Availability	Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 10-Oct-2018 | Last Updated on: 12-Oct-2018

Tags: Toyota Hiace, toyota hiace, 2007 Toyota Hiace, 2007 toyota hiace, Toyota, Hiace, hiace, Used Toyota

Upfront Payment

» more Financial info



Seller Information

Company	Net Link Partners Pte Ltd	
	» dealer's pricelist	
	» 112 vehs sold 161 vehs available	
Address	71 Woodlands Industrial Park E9 #07-01, #08-08 Search cars nearby this location	
Location	Wave9	
Office No	67531661	
Contact Person(s)	Ivan Huang Pearlyn	91870392 87002017

Car Tyres



And relaxing
comes with
the draw
of a curtain.



Compare



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Toyota Hiace

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Direct Owners » Toyota Hiace (COE till 02/2022)

Resources

[Car Buying](#)[Car Selling](#)[Car Ownership](#)[Car Aftermarket](#)[On The Move](#)[Lifestyle](#)

Car Leasing

CL LEASING
YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

scoot

BRIGHTON BEACH,
MELBOURNE

Compare

Toyota Hiace (COE till 02/2022)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$25,000**

Depreciation \$7,390 /yr

Reg Date 14-Oct-2004
(3yrs 4mths 16days COE left)

Lifespan 13-Oct-2024

Manufactured 2004

Mileage -

Transmission Manual

Engine Cap 2,986 cc

Curb Weight 1,500 kg

Fuel type Diesel

Features -

Accessories -

Description COE. Left 4 Years.

COE \$24,252

OMV \$21,926

ARF \$1,097

Dereg Value \$16,412 as of today (change)

No. of Owners 2

Type of Veh Van

Category COE Car, Direct Owner Sale

Availability Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 20-Aug-2018 | Last Updated on: 10-Oct-2018

Tags: Toyota Hiace, toyota hiace, 2004 Toyota Hiace, 2004 toyota hiace, Toyota, Hiace, hiace, Used Toyota

Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$2,500 (change) Maximum 90% Loan

1st Instalment \$647

Total Upfront Payment \$3,172 (excluding insurance)

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.

Items for Toyota Hiace

» View All

100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Preferred Viewing Area

Seller Information

Contact Person(s) Francis Teo

Contact No. 98222931

Enquiry [Contact Seller](#)

USEFUL FORMS

» Indemnity form » Sales agreement

» Receipt » Hand-over form

» M01

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GV5860C181010

Estimate

Customer

Page 01 - 02

Name: MS First Capital Insurance Limited

Date: 12-10-18

Address: Motor Claims Department

Vehicle No: GV5860C

36 Robinson Road #16-01

Model/Make: Toyota Hiace

City House

Singapore 068877

Diesel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>body 100 1219.10</i>	\$ 1,472.50	
2	Tailgate "Toyota Logo" Motif <i>rec</i>	\$ 49.10	
3	Tailgate Inner Lock <i>rec/shell</i>	\$ 272.40	
4	Tailgate Weatherstrip <i>11</i>	\$ 295.10	X
5	Tailgate Outer Handle <i>rec 288.50</i>	\$ 316.50	
6	Tailgate Windscreen Rubber <i>rec</i>	\$ 285.90	<i>5075.50</i>
7	Tailgate "70 KM/H" Sticker <i>rec</i>	\$ 15.00	<i>SN 105.50</i>
8	Tailgate "8 PAX" Sticker <i>rec</i>	\$ 15.00	<i>SN 105.50</i>
9	Bumper <i>11</i>	\$ 431.00	
10	Bumper Side Retainer <i>rec</i>	\$ 65.10	
11	Bumper Clips 1 set <i>rec</i>	\$ 50.00	<i>SN</i>
12	Bumper Beam <i>11</i>	\$ 198.00	
13	End Panel Outer <i>body 500</i>	\$ 566.10	
14	Fender <i>rec</i>	\$ 1,308.30	X
15	Taillamp <i>rec</i>	\$ 354.00	
16	Tail Lamp Housing Panel <i>rec</i>	\$ 258.00	X
17	Exhaust Pipe <i>rec</i>	\$ 976.00	<i>SN</i>
18	Exhaust Pipe Mounting 02 pcs (@ \$42.50) <i>11</i>	\$ 85.00	X
19	Front Windscreen Glass <i>body 1100</i>	\$ 1,508.10	
20	Windscreen Glass Weatherstrip <i>rec</i>	\$ 303.60	<i>5075.50</i>
21	Windscreen Glass ERP Bracket <i>rec</i>	\$ 20.00	<i>SN</i>
22	Panel <i>body 1206.10</i>	\$ 1,466.30	
23	Grille <i>body</i>	\$ 482.30	
24	Grille Emblem <i>rec</i>	\$ 71.60	
25	Bumper <i>11</i>	\$ 796.80	
26	Bumper Moulding <i>11</i>	\$ 86.90	
27	Bumper Clips 1 set <i>rec</i>	\$ 48.00	<i>SN</i>
28	Head Lamp 02 pcs (@ \$725.70) <i>0/1 set 330.10</i>	\$ 1,451.40	<i>11</i>
29	Head Lamp Clip 1 set <i>11</i>	\$ 65.00	<i>SN</i>
30	Head Lamp Garnish 02 pcs (@ \$146.00) <i>rec</i>	\$ 292.00	
31	Signal Lamp 02 pcs (@ \$151.20) <i>rec</i>	\$ 302.40	
C/F Balance --> <i>25%</i>		\$ 13,907.40	



M/s Liu's Brother Auto Engrg Wks

Not Attached
12/10/18
2/5 48300/-
15 day
Zuhairi. Atkinson

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GV5860C181010

Estimate

Customer	Page 01 - 02
Name: MS First Capital Insurance Limited	Date: 12-10-18
Address: Motor Claims Department	Vehicle No: GV5860C
36 Robinson Road #16-01	Model/Make: Toyota Hiace
City House Singapore 068877	Diesel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 13,907.40	
32	Front Door m/suc 1266.10	\$ 1,568.80	
33	Door Pillar n	\$ 757.50	X
34	Wiper Arm o/sent	\$ 178.90	
35	Wiper Arm Cover o/sent 25.	\$ 136.00	
36	Wiper Arm Linkage 11	\$ 324.00	X
37	Dashboard de/cu	\$ 986.00	
38	Aircon Blower Assy cu	\$ 826.20	
39	Aircon Cooling Coil 11	\$ 2,478.30	X
	To check all wiring & electrical component for proper function	\$ 80.00	30
	Remove & reinstall 2 (Fr & Rr) Windscreen Glass to facilitate repairs	\$ 240.00	120
	Remove & reinstall Switch Box, meter instruments, disconnect wiring &	\$ 200.00	160
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 80.00	50
	To remove, replace and transfer Aircon Blower	\$ 100.00	
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 100.00	100
	Remove and replace rear exhaust pipe system to facilitate repairs 11	\$ 80.00	X
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 150.00	120
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 2,000.00	1500
	To putty & spray painting & including touch up paint on accident	\$ 2,000.00	1600

Total Parts & Labour of estimate for damaged vehicle**\$ 26,193.10**

3680

Total amount in Lump Sum Basis for repaired vehicle**SDLS:****M/s Liu's Brother Auto Engrg Wks**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18018565/Utbs2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 1580A	Veh. Inspected	GV 5860C
Policy No.		Coverage (\$)	0.00
Claim No.	D18007441MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	16/10/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (M)	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2002
Chassis No.	LH1621006870	Colour	WHITE
Odometer	327123	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185 R14	RADIAL	6 mm
L/H Front Tyre	185 R14	RADIAL	6 mm
R/H Rear Tyre	185 R14	RADIAL	6 mm
L/H Rear Tyre	185 R14	RADIAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/10/2018	Inspection Date	12/10/2018
Survey held at	LIU'S BROTHER AUTO WORK SHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 5860C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR	DENTED / BUCKLED	1,568.80	1,266.10
1	FRONT DOOR PILLAR	TO REPAIR SEE LABOUR	757.50	-
1	FRONT WIPER ARM O/S	BENT	178.90	178.90
1	FRONT WIPER ARM COVER O/S	TWISTED	136.00	35.00
1	FRONT WIPER ARM LINKAGE	NOT NECESSARY	324.00	-
1	FRONT DASHBOARD	DEFORMED / CRACKED	986.00	986.00
1	FRONT AIRCON BLOWER ASSY	CRACKED	826.20	826.20
1	FRONT AIRCON COOLING COIL	NOT NECESSARY	2,478.30	-
1	REAR TAILGATE	BADLY DENTED	1,472.50	1,219.10
1	REAR TAILGATE "TOYOTA LOGO" MOTIF	NECESSARY	49.10	49.10
1	REAR TAILGATE INNER LOCK	JAMMED / SHORTED	272.40	272.40
1	REAR TAILGATE WEATHERSTRIP	NOT NECESSARY	295.10	-
1	REAR TAILGATE OUTER HANDLE	CRACKED	316.50	288.50
1	REAR BUMPER	DISTORTED	431.00	431.00
1	REAR BUMPER SIDE RETAINER	CRACKED	65.10	65.10
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER BEAM	DISTORTED	198.00	198.00
1	REAR END PANEL OUTER	BADLY DENTED	566.10	566.10
1	REAR FENDER	TO REPAIR SEE LABOUR	1,308.30	-
1	REAR TAILLAMP	CRACKED	354.00	354.00
1	REAR TAIL LAMP HOUSING PANEL	TO REPAIR SEE LABOUR	258.00	-
2	REAR EXHAUST PIPE MOUNTING @ \$42.50	NOT NECESSARY	85.00	-
1	FRONT WINDSCREEN GLASS	BROKEN	1,508.10	1,100.00
1	FRONT PANEL	BADLY DENTED	1,466.30	1,206.10
1	FRONT GRILLE	BROKEN	482.30	482.30
1	FRONT GRILLE EMBLEM	NECESSARY	71.60	48.50
1	FRONT BUMPER	DISTORTED	796.80	455.10

Report Ref No. CS/FCI18018565/Utbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER MOULDING	TWISTED	86.90	86.90
1	SET FRONT BUMPER CLIPS	NECESSARY	48.00	48.00
2	FRONT HEAD LAMP @ \$725.70	O/S CRACKED	1,451.40	330.10
2	FRONT HEAD LAMP GARNISH @ \$146.00	CRACKED	292.00	292.00
2	FRONT SIGNAL LAMP @\$151.20	N/S BROKEN	302.40	151.20
	LESS 25% DISCOUNT		-	-2,746.43
			19,482.60	8,239.27
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TAILGATE WINDSCREEN RUBBER (50%) (SN)	NECESSARY	285.90	142.95
1	REAR TAILGATE "70KM/H" STICKER (SN)	NECESSARY	15.00	10.00
1	REAR TAILGATE "8 PAX" STICKER (SN)	NECESSARY	15.00	10.00
1	REAR EXHAUST PIPE (SN)	TO REPAIR SEE LABOUR	976.00	-
1	FRONT WINDSCREEN GLASS WEATHERSTRIP (50%) (SN)	NECESSARY	303.60	151.80
1	FRONT WINDSCREEN GLASS ERP BRACKET (SN)	NECESSARY	20.00	20.00
1	SET FRONT HEAD LAMP CLIP (SN)	NOT NECESSARY	65.00	-
			1,680.50	334.75
	<u>LABOUR</u>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		80.00	30.00
	REMOVE & REINSTALL 2 (FR & RR) WINDSCREEN GLASS TO FACILITATE REPAIRS.		240.00	120.00
	REMOVE & REINSTALL SWITCH BOX, METER INSTRUMENTS, DISCONNECT WIRING.		200.00	160.00
	TO REMOVE, REPLACE AND TRANSFER DOOR PANEL, FITTING AND MECHANISMS.		80.00	50.00
	TO REMOVE, REPLACE AND TRANSFER AIRCON BLOWER. }		100.00	100.00
	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES. }		100.00	-
	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS.	NOT NECESSARY	80.00	-
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		150.00	120.00

Report Ref No. CS/FCI18018565/Utbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC. INCLUSIVE OF THE REPAIR OF FRONT DOOR PILLAR, REAR FENDER, REAR TAIL LAMP HOUSING PANEL AND REAR EXHAUST PIPE.		2,000.00	1,500.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT TO ACCIDENT.		2,000.00	1,600.00
			5,030.00	3,680.00
GRAND TOTAL			26,193.10	12,254.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,300.00

Report Ref No. CS/FCI18018565/Utbs2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.