Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18018721/UPA3Q2

Date: 06/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100359739

Claimant
Vehicle No: Insured Vehicle No: SKK3543S

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBA5090C

Make & Model: TOYOTA HIACE, 3.0 D (M) Engine No: 1KD1674469

Reg. Date: 14/08/2007 (Man. Year: 2007) Chassis No: JTFHT02P000005050

Colour: White Odometer: 551971 km

Engine Capacity: 2982 cc
Market Value/New Car
N/A

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: CST TIRE 6 mm Rear Left Side: CST TIRE 6 mm Front Right Side: CST TIRE 6 mm Rear Right Side: CST TIRE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,031.70	3,069.03	2,962.67	49.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	740.00	840.00	53.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,611.70	3,809.03	3,802.67	49.96
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	7,611.70	3,000.00	4,611.70	60.59
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 16/10/2018

Date Inspected: 16/10/2018 Inspected At: Liu's Brother Auto Engineering

Workshop (HQ)

BLK 1 KAKI BUKIT AVE 6, #01-01

AUTO BAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

Qty	Part No	. Particulars	Condition	Repairer's	Amount
1		*FRONT BUMPER	Deformed	796.80 F	*696.40 FL
1		*FRONT BUMPER BRACKET N/S	Cracked	137.20 F	*137.20 FL
1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
1		*FRONT BUMPER GRILLE	Not Necessary	155.80 F	*- FL
1		*FRONT BUMPER WIRE BRACKET	Not Necessary	104.50 F	*- FL
1		*FRONT GRILLE	Cracked	688.20 F	*545.10 FL
1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
1		*FRONT HEADLAMP	Cracked	930.70 F	*766.01 FL
1		*SET FRONT HEADLAMP CLIP	Not Necessary	65.00 FS	*- FS
1		*FRONT STEP GARNISH	Deformed	225.70 F	*225.70 FL
1		*SET FRONT STEP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
1		*FRONT RADIATOR	Bent / Punctured	2,372.30 F	*1,618.30 FL
1		*FRONT RADIATOR TANK COWLING	Not Necessary	352.50 F	*- FL
1		*FRONT RADIATOR COOLANT	Not Necessary	45.00 FS	*- FS
1		*FRONT DOOR LTA CORPORATE DETAIL STICKER	Necessary	48.00 FS	*40.00 FS
anchise	part. S=Sp	cNett. L=ListItemDisc.			
			Sub Total (S\$)	6,031.70	4,078.71
		- List Item Discount on L Items	0.00/25.00% (S\$)	0.00	1,009.68
			Total Parts (S\$)	6,031.70	3,069.03
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*FRONT BUMPER BRACKET N/S *SET FRONT BUMPER CLIPS *FRONT BUMPER GRILLE *FRONT BUMPER WIRE BRACKET *FRONT GRILLE *SET FRONT GRILLE CLIPS *FRONT HEADLAMP *SET FRONT HEADLAMP CLIP *FRONT STEP GARNISH *SET FRONT STEP GARNISH CLIPS *FRONT RADIATOR *FRONT RADIATOR *FRONT RADIATOR TANK COWLING *FRONT RADIATOR COOLANT *FRONT DOOR LTA CORPORATE DETAIL STICKER nchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT BUMPER BRACKET N/S Cracked 1 *SET FRONT BUMPER CLIPS Necessary 1 *FRONT BUMPER GRILLE Not Necessary 1 *FRONT BUMPER WIRE BRACKET Not Necessary 1 *FRONT GRILLE CLIPS Cracked 1 *SET FRONT GRILLE CLIPS Not Necessary 1 *FRONT HEADLAMP Cracked 1 *SET FRONT HEADLAMP CLIP Not Necessary 1 *FRONT STEP GARNISH Deformed 1 *SET FRONT STEP GARNISH CLIPS Not Necessary 1 *FRONT RADIATOR Bent / Punctured 1 *FRONT RADIATOR TANK COWLING Not Necessary 1 *FRONT RADIATOR COOLANT Not Necessary 1 *FRONT RADIATOR COOLANT Not Necessary 1 *FRONT DOOR LTA CORPORATE DETAIL STICKER Necessary	1 *FRONT BUMPER Deformed 796.80 F 1 *FRONT BUMPER BRACKET N/S Cracked 137.20 F 1 *SET FRONT BUMPER CLIPS Necessary 50.00 F 1 *FRONT BUMPER GRILLE Not Necessary 155.80 F 1 *FRONT BUMPER WIRE BRACKET Not Necessary 104.50 F 1 *FRONT GRILLE Cracked 688.20 F 1 *SET FRONT GRILLE CLIPS Not Necessary 30.00 FS 1 *FRONT HEADLAMP Cracked 930.70 F 1 *SET FRONT HEADLAMP CLIP Not Necessary 65.00 FS 1 *FRONT STEP GARNISH Deformed 225.70 F 1 *SET FRONT STEP GARNISH CLIPS Not Necessary 30.00 FS 1 *FRONT RADIATOR Bent / Punctured 2,372.30 F 1 *FRONT RADIATOR TANK COWLING Not Necessary 45.00 FS 1 *FRONT DOOR LTA CORPORATE DETAIL STICKER Necessary 48.00 FS *Chist Item Discount on L Items 0.00/25.00% (\$\$) 0.00

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	300.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	600.00	380.00
4	TO REMOVE & REPLACE RADIATOR & CONDUCT PRESSURE TEST AND BLEED SYSTEM	New	100.00	40.00
	Gross Labour Cost (S\$)		1,580.00	740.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.