

ASS. REC. BY:

REF:

CS/FCI18018730/Ktrd3ⁿ²

Special Instruction:

Surveyor:

Kalin

ASSIGNMENT (Office)

From (Person):

CWS

Siffert

of

FCI

Date/Time:

15/10/2018 @ 6:41pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 1854E

Insured:

SHC 0322K

at Workshop m/s

Premier Automotive

Tel:

GS44 6689

of

23 Chungi South Ave 2 # 03-02

Policy No:

Claim No:

D18007466 MFS#

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/10/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:11am @ 16/10/18

Person Contacted:

Vincent

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 1854E - CC3 / AIG 14002677 / H1ha 3q2 - 1 JUA: 10/2/15

SHC 0322K - CC3 / TMI 17015372 / K1qbn2 JUA: 8/5/2017

Revnt 1A thru email.

Surrender

Kahin

REF: FCI

ASSIGNMENT

From:

Date:

16/10/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHD 1854E

at Workshop n/s

Premier Automotive

of

23 changi south Ave 2 #03-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD 1854E

Yr Regn:

22 Oct, 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA optima

c.c.

1685

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

543393

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNA 6M414ME5 447671

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxx

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

14/10/18

D.O.I.

16/10/18

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/11/18

Checked 458450 / 2.671.
Red: 83112.90, 871.

RECEIVED 05 NOV 2018

Date/Time, File Pass to?



: Preli. Report

1) typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.T. (\$ 450)

130

50

50

22

252



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007466MFSH

Date: 22 October 2018

Our Ref: CS/FCI18018730/K1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1854E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16.10.2018 at the premises of M/s PREMIUM AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,562.90</u> .
Revised Estimate Amount	: S\$ <u>615.40</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KALVIN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	15-10-2018	Our Ref No. D18007466MFSH
Accident Date	14-10-2018	Claim Type. Third Party
Insured Vehicle	SHC0322K	Third Party Vehicle. SHD1854E
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/245050)



PRI Documents



Close



PRI Header Details

Claim No	D18007466MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PREMIER LTD..
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : VINCENT CHUA)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446689 , Phone: 62148880 , Fax: 62141511 EmailId: VINCENT.CHUA@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0322K	TP Vehicle No	SHD1854E
PRI Recieved Date	15-10-2018 07:30:40 PM	Surveyor Appointed Date	15-10-2018 06:40:55 PM	Surveyor Accept Date	16-10-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	16-10-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Enquire Transaction History

Transaction History Details

Log Date/Time:	22 Oct 2013 / 09:19:43	Receipt No.:	AACCK001-AX239-131022-000004
Asset Type:	Vehicle	Transaction Amount:	\$73,800.00
Asset ID:	SHD1854E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131022091943239191		
Vehicle No.:	SHD1854E		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	22 Oct 2013		
Original Registration Date:	22 Oct 2013		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5447671		
Engine No.:	D4FDDH308018		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,836.00		
Minimum PARF Benefit:	\$7,401.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	22 Oct 2013 09:19:43		
COE No.:	2013102201000927K		
COE Expiry Date:	21 Oct 2021		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$61,324.00		
Lifespan Expiry Date:	21 Oct 2021		
Owner ID Type:	Company		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

15-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1854 E

1 pc	Rear bumper <i>X/4.5</i>	\$	696.00
1 pc	Rear bumper lower cover <i>6-7</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X 5.5</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X 3.5</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X 5.5</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X 5.5</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X 3.5</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X 5.5</i>	\$	36.00
		\$	1,861.00
		Less 10%	\$ 186.10
		\$	1,674.90

S/NETT

1 set	Rear bumper clips <i>X 2.5</i>	\$	48.00
1 set	Reverse sensor <i>X 5.5</i>	\$	280.00
1 pc	Rear bumper top protector <i>4.5</i>	\$	80.00 <i>50</i>
Sundry		\$	50.00 <i>X 2.5</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 <i>X 2.5</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>X 2.5</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc		\$	650.00 <i>200</i>
To putty and spray painting on rear bumper, end panel <i>X</i>		\$	400.00 <i>180</i>
To apply rustproofing on the repaired and replaced panels.		\$	80.00 <i>X 2.5</i>
		\$	3,562.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kalin (Kaly)
16/10/18 10.00 Ls
2 07.1
Ls
Alvin Pong Ue



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18018730/K1rd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 322K	Veh. Inspected	SHD 1854E	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18007466MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	15/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5447671	Colour	SILVER	
Odometer	543393	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/10/2018	Inspection Date	16/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1854E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-186.10	-20.60
			1,674.90	185.40
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			458.00	50.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		650.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, END PANEL.		400.00	180.00

Report Ref No. CS/FCI18018730/K1rd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
			1,430.00	380.00
GRAND TOTAL			3,562.90	615.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				450.00

Report Ref No. CS/FCI18018730/K1rd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.