

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18018734/R1GA3Q2

Date: 08/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : GBG7750L	Insured Vehicle No :	SHA7685C
Date of Loss: 31/08/2018	Nature of Claim: TP	Claim No: MCT18080918

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG7750L		
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Engine No:	1KD2683103
Reg. Date:	31/10/2017 (Man. Year: 2017)	Chassis No:	KDH2010215598
Colour:	Grey	Odometer:	46332 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	640.00	880.00	57.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,520.00	640.00	880.00	57.89
+ GST 7.00/7.00% (S\$)	106.40	44.80	61.60	57.89
Nett Amount (S\$)	1,626.40	684.80	941.60	57.89
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	15/10/2018	
Date Inspected:	17/10/2018 Inspected At:	AAK Logistics Services Pte Ltd (Penjuru) 4 Penjuru Close Singapore 608574
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Apr 2020)
Parts:	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG7750L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PABEL BEATING	New	800.00	300.00
2	SPRAY PAINTING	New	600.00	300.00
3	RUST PROOF	New	120.00	40.00
Gross Labour Cost (S\$)			1,520.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >