



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
MR KWEK JU YANG MARK (GUO ZUYANG MARK)		Cust No/Name	/MR KWEK JU YANG MARK (GUO ZUYAN)
87 LORONG K TELOK KURAU		Reg No/Reg Date	SKZ4869S / 26/01/2016
SINGAPORE 425779		Date In/Mileage	/ 0
Contact No Mobile: 92210281		Chassis No	VF73ABHZTFJ811999
		Engine No	10JBHD3020538
		Make/Model	CIT/6C4P 1.6 BLUEHDI EAT6 CONFORT
		Colour/Trim	1SM / 8MF

Account No	Terms	Date/Time Printed	GSE	Operator	WIP No
CSM00073	Cash	15/10/2018/ 12:03	TLC	442 / CocoLu	13832

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR DOOR LH, SIDE SILL LH, REPAIR REAR FENDER LH, REAR BUMPER				4200.00
E PNT88000 REMOVE & INSTALL DOOR TRIMS & GLASS				240.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY TRANSFER RIM TO TYRE				30.00
E PNT98000 SPRAY PAINT FOR SIDE SILL LH, REAR DOOR LH, REAR FENDER LH, REAR BUMPER				2100.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				80.00
M SUNDRY Sundry				20.00
M REAR DOOR LH ASS	1.00	1361.00	0.00	1361.00
M REAR DOOR SEAL LH	1.00	193.00	0.00	193.00
M SEALING PANEL LH	1.00	106.00	0.00	106.00
M DECOR STRIP LH	1.00	146.00	0.00	146.00
M DOOR FIXINGS	1.00	219.00	0.00	219.00
M SIDE WINDOW LH	1.00	251.00	0.00	251.00
M WINDOW LIFTER LH	1.00	550.00	0.00	550.00
M UNDER-BODY LH	1.00	847.00	0.00	847.00
M ALLOY WHEEL 6.5 J16 CH5-47	1.00	571.00	0.00	571.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Parts	4,244.00
Labour	6,660.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	130.00
Total (w/o GST)	11,034.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.