

TPALG Vivian

SJU333PC

Toyota Vios

MRO53HY9305126393

	Rear Bumper Fascia Deland	381.10 ✓
	↳ Side Retainer LH New	132.25 ✓
	↳ Clips New	12.90x8 = 103.20 30
	↳ Lower Spoiler (Acc) Deland	550.54 ✓
	↳ Dust cover LH	132.25 X
3pus	↳ Dust cover clips } New	12.90x3 = 38.70 X
	↳ Side attachment	141.40 X
	Tail Lamp Assy LH cracked	374.45 325
	↳ Sealant New	50.00 20(SN)
	↳ Clips New	12.90 ✓
	↳ Base panel Repairs	191.60 X
	Rear Fender LH Distorted	974.45 ✓
	↳ Fender Air Vane Deland	174.20 ✓
	↳ Inner Trim Board 3MP	374.45 X
6pus	↳ Inner Trim Board Clips } New	12.90x6 X
	Rear wheel Housing panel (Outer) Repairs	972.25 X
	Fuel Lip cover Dented	78.00 ✓
	Fuel Lip Lock Dented	35.00 ✓
2pus	Fuel Lip Rivets New	12.90x2 = 25.80 ✓
	Fuel Lip Spring New	10.20 X
	Rear Door Assy LH Dented	937.70 ✓
	↳ Door protector Deland	121.10 ✓
	↳ Door Lock Dented	361.75 ✓
	↳ Door Frame Black Sticker New	43.10 ✓
	↳ Door weatherstripe Not New	182.35 X
	Rear Windscreen Glass moulding New	171.20 ✓
	↳ Glass sealant New	60.54 ✓
	↳ Inner seal New	50. ✓
	↳ Clips New	12.90x14
		= 51.60

30 A'ZONE

Labour charge

towing	80 X.
To check wiring system	50 30
To full coat affected areas	180 50
To remove & refit interior upholstery	180 60
To remove & refit rear window screen glass	180 120
To respray affected areas	1250 900
To check & adjust computer wheel alignment	120 X.
To renew damaged parts, straighten & repair and align all parts.	1200 900
To remove & refit reverse sensor	120 50

List 3883 SS
 Len 25%: 2912.66.
 S.N: 630

Labour: 2110
 Total: ~~5652.66~~
 L/S: 4.5K.
 08 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: