

ASS. REG. NO.

REP.

CS/ASM18018770/ Ksd302

Smart Claim

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person)

Kitty Teo

ASM(AxA)

Date/Time 16/10/2018

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

8KN 5353U

Insured

at Workshop on/s

K. Kim Hin Auto

Tel.

6452 7018

of

160 Sin Ming Drive #02-20

Policy No.

Claim No.

88M00Z7R

Sum Insured

Excess

NIL

Make of Veh.

(Client's Record)

D.O.A. 12/10/2018

CA / REV / REP. / REV 24 HRS

17/10/2018

H.O.D. Endorsement

Date/Time

4:30pm @ 16/10/18

Person Contacted

Shumein

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

8KN 5353U - X

17/10/18

@ 18:28 p.m. revised IA to Kitty Teo via smart claim.

18/10/18

@ 09:44 a.m. revised IA emailed to Kitty Teo via smart claim.

18/10/18

@ 10:03 a.m. consent authorised repair to Shumein (repairer)

via email.

REF: ASM (AXA)

ASSIGNMENT

From

Date

17/10/2018

Estimated Cost

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No.

SKN 53534

at Workshop no.

K. Kim Hin

of

160 Sin Ming Drive # 02-20

Insured

Policy No.

Claims No.

Sum Insured.

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value.

\$ 83k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

1.8.1

%

3 Val.

Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacted:

Vehicle IN / OUT

Veh No

SKN 53534 Regr 10 13

Type M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make.

Volkswagen GTi cc - 1998 84

Colour

M. Red A/C Insured / Std / NI / NA

Sp. Reading

64312

T. Radon Insured / Std / NI / NA

Eng. No.

C. No.

WVW ZZZ AUZDW 154966

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40R18

BS / DUN / EXNOVA GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

12/10/18

D.O.A.

17/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

18/10/18 Mr Ng to Carhouse

13/03/19 Confirmed P/P \$ 7,391.91 @ 6 days with Kenneth.
(83,543.74 Red - 32%)

RECEIVED 17 MAR 2019

Date/Time File Pass to?

13/02/19

1)

Type

Date/Time File Return to?

2.



Preli. Report



Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) S + R \$

) Photos

) Other

) TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$




Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$ 7,391.91 p/p)

250
250



Service Request Details

Claim

S8M00Z7R

Reference

None

Loss Date

October 12, 2018

Request Date

October 16, 2018

Due Date

October 23, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Print	Close
-------	-------

Vehicle Information

Incident Vehicle Registration #

SKN5353U

Make

VOLKSWAGEN

Model

GOLF 2.0 GTI

Service Address

160 Sin Ming Drive, #... 575722

Primary Contact/Insured

NG GUAT HOON SAMANTHA (HUANG YUEFEN)

53 HAZEL PARK TERRACE, 678886, Singapore

samanthang00@gmail.com

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

EXCESS NIL

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

View Message

TYPE



SENT

10/16/18 3:31 PM

FROM

TEO Kitty

SUBJECT

WP SURVEY

BODY

Hi Please get estimate.



10/15/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	9471D

Vehicle Details

Vehicle No.:	SKN5353U
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF GTI 2.0 TSI 5G19TY
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	CHH003356
Chassis No.:	WVWZZZAUZDW154966
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$33,661.00
Original Registration Date:	29 Oct 2013
First Registration Date:	29 Oct 2013
Transfer Count:	1
Actual ARF Paid:	\$34,126.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Oct 2023
PARF Rebate Amount:	\$25,594.00

Intended COE Rebate Details

COE Expiry Date:	28 Oct 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$87,910.00
COE Rebate Amount:	\$44,262.00
Total Rebate Amount:	\$69,856.00

The information contained herein is correct as at 15 Oct 2018

OK

Shirley Hiew (LKK Auto)

From: survey@kkimhin.com.sg
Sent: Wednesday, 13 March 2019 3:27 PM
To: 'Shirley Hiew (LKK Auto)'; admin1@kkimhin.com.sg; simon@kkimhin.com.sg
Cc: service@kkimhin.com.sg; 'Sandra Khong'; 'SUR'
Subject: RE: SKN 5353U OD (AXA)

Hi Shirley,

Confirm you figure P/P=\$7,391.91
Thank you.

Regard
Meng Huat
K. Kim Hin Auto

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 13 March 2019 11:22 AM
To: admin1@kkimhin.com.sg; simon@kkimhin.com.sg; survey@kkimhin.com.sg
Cc: service@kkimhin.com.sg; 'Sandra Khong' <sandrakhong@gmail.com>; SUR <sur@lkkauto.com>
Subject: RE: SKN 5353U OD (AXA)

Dear Shuman,

Please confirmed final fig \$7,391.91 @ 6 days of repairs before excess \$0/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: admin1@kkimhin.com.sg [<mailto:admin1@kkimhin.com.sg>]
Sent: Thursday, 18 October 2018 10:21 AM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>; simon@kkimhin.com.sg; survey@kkimhin.com.sg
Cc: service@kkimhin.com.sg; 'Sandra Khong' <sandrakhong@gmail.com>
Subject: RE: SKN 5353U OD (AXA)
Importance: High

Dear Shirley,

Noted with thanks.

Dear Simon and Meng Huat,

Kindly note.

Thank you.

Best Regards,

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 18 October 2018 10:03 AM
To: admin1@kkimhin.com.sg
Cc: SUR; service@kkimhin.com.sg; simon@kkimhin.com.sg; survey@kkimhin.com.sg
Subject: SKN 5353U OD (AXA)

Dear Shuman,

As instructed by our client, please proceed to repair the insured vehicle **SKN 5353U** (Excess \$ NIL/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

« Re:WP SURVEY

Type

🗉 Question

Message

Hi Received audatex, please authorise if damages consistent and within ERV. Thanks.

Reply

« IA - SKN 5353U

Type

🔍 Question

Message

Hi Kitty, IA uploaded. We are pending repair cost from repairer. Nett value - \$ 3,144.00. Thanks. From :
Shirley Hiew

[Reply](#)

« IA AMENDED - SKN 5353U

Type


🔗 Question

Message

Hi Kitty, IA amended & Uploaded. Damages consistent, repair cost economical. We have authorised repair.

Thanks. From : Shirley Hiew

0 / 12



Auto
Consultants
Pte Ltd

Company Registration No: 198601100R

SUITE 02-01, #02-25 PAVAN INDUSTRIAL PARK, SINGAPORE 409031 TEL : (665) 62562561 FAX : (665) 62564514

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/10/2018

Survey Details:

Date of loss	12-Oct-18
Date of appointment	16-Oct-18
Date of survey	17-Oct-18
Location of survey	160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKN 5353U
Make and Model	VOLKSWAGEN GOLF GTI 2.0 TSI 5G19TY
Date of registration	29/10/2013
Excess	NIL
Market Value	\$83,000
Part Rebate	\$69,856
Nett Loss	\$13,144

Repair details:

Initial Estimate	10,867.17
------------------	-----------

Proposed/Revised repair cost:

Parts	\$4,141.50
Check items (estimate)	\$3,504.18
Labour	\$1,565.93
Total	\$9,211.61
Lump Sum(if applicable)	\$

Number of days for repair	6 DAYS
---------------------------	--------



LKK
Auto
Consultants
Pte Ltd

Company Registration No: 198807188R

51, BURLAND ROAD, #02-25 PAVILLION INDUSTRIAL PARK, SINGAPORE 409923 TEL : (65) 62563561 FAX : (65) 62564313

Remarks:

IA AMENDED. DAMAGES CONSISTENT, REPAIR COST
ECONOMICAL. WE HAVE AUTHORISED REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

Company Registration No: 199607188R

SUITE 501, #02-25 PAVANUR INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62563553

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/10/2018

Survey Details:

Date of loss	12-Oct-18
Date of appointment	16-Oct-18
Date of survey	17-Oct-18
Location of survey	160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKN 5353U
Make and Model	VOLKSWAGEN GOLF GTI 2.0 TSI 5G19TY
Date of registration	29/10/2013
Excess	NIL
Market Value	\$73,000
Part Rebate	\$69,856
Nett Loss	\$3,144

Repair details:

Initial Estimate	10,867.17
------------------	-----------

Proposed/Revised repair cost:

Parts	\$4,141.50
Check items (estimate)	\$3,504.18
Labour	\$1,565.93
Total	\$9,211.61
Lump Sum(if applicable)	\$

Number of days for repair	6 DAYS
---------------------------	--------



Auto
Compliance
Pte. Ltd.

Company Registration No. 198607100R

STURDYVILLE #02-25 PAVILION INDUSTRIAL PARK, SINGAPORE 408933 TEL : (65) 62563563 FAX : (65) 62563315

Remarks:

WE ARE PENDING REPAIR COST FROM REPAIRER. NETT
VALUE \$ 3,144.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

MPKI:8113914 / K Kim Hin Auto Pte Ltd - HQ
 CTRY DATE & TIME 15/10/2018 16:33
 SUBMITTED BY: Wong Shi Man

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 16:33
Date Of Accident	12/10/2018 15:05
Exact Location Of Accident	HILLVIEW AVE TWDS HILLVIEW RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN5353U
Insured/Policyholder	
Name Of Registered Owner	NG GUAT HOON SAMANTHA
NRIC No	S8019471D
Email Address	SAMANTHANG00@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81180688
Alternative Phone No	OFFICE-81180688

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	GOLF-2.0 GTI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1512397
Cover Note Number	

Driver

Name of Driver	NG GUAT HOON SAMANTHA
NRIC No	S8019471D
Date Of Birth	02/07/1980
Occupation	INDOOR
Date Of Driving Pass	25/05/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81180688
Fax Number	
Contact Number	OFFICE-81180688
Email Address	SAMANTHANG00@GMAIL.COM

Address 53 HAZEL PARK TERRACE
 Postcode 678886
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT PANJANG NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 42 FAJAR ROAD , POSTCODE: 679005 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8929999 - FAX NO: 67673650
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKS8534T
 Vehicle Make/Model/Colour BMW 523i
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SYED SEGAFI BIN SYED KHAIED ALSREE
 NRIC/Passport Number S8904707B
 Contact Number 82981254
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/con be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan Pg. 2

SKETCH PLAN



A: SKN 5353U

B: SKS 8534T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

⊗ There is road works on the right. A SKS 8534T suddenly stop and
 my car hit on the rear portion

DECLARATION

-We declare the foregoing particulars are true in every respect.


 Police Officer's Signature


Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:


 Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

15/10/18 @ 2:30pm


Police Report Pg. 1




CONFIDENTIAL

NOTICE OF COMPLIANCE

This is to inform that Mr / Ms Ng Guat Hoon Samantha
 NRIC/FIN S8019471D, residing at 53 Hazel Park Terrace has reported to police a non-
 injury traffic accident which occurred at along Hillview Ave towards Hillview Road
 on 12/10/2018 at 1505 hrs am/pm involving the following vehicles:

- I SKN5353U 
- II SKS8534T (S8904707B)
- III -
- IV -

2. If the accident was reported to Police within 24 hours of its accident occurrence,
 he/she therefore has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer	: <u>Sgt Austin Tan Ri Quan</u> 
Date	: <u>12/10/2018</u>
Time	: <u>1505</u> hrs
S/D Ref	: <u>132</u>
Police Post/Unit	: <u>Bukit Panjang NPC</u> <u>Bukit Panjang NPC</u> <u>1 Segar Road #01-05</u> <u>Singapore 677738</u> <u>Tel : 6892 9999</u>

Original - To be issued to informant
 Duplicate - To be retained at NPC or Police Post

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: KKHA0043
Version: LKKAUTOC/4
Date Calculated: 17/10/2018 09:29

Full Report - V1
Registration: SKN5353U
Printed: 17/10/2018 17:37

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	12/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	VOLKSWAGEN	FROM 01/2013	SPEAK CONTROL
Model:	Golf	OCCUPANT PROTECT SYS	WHEELS 7.5J X 18 ALU
Sub Model:	GTI	TYRES 225/40 YR 18	BLUE MOTION TECHNO
Model Sheet Number:	6B1 04	CHROME PACKAGE	CLIMATRONIC
Registration:	SKN5353U	D/MIRROR W/AMBIENT	XENON HEADLAMP/LED
Registration Month:	October	LIGHT-/RAIN SENSOR	FRT/RR ELECT WINDOWS
Registration Year:	2013	KEYLESS ENTRY	AUTO DIPPING MIRROR
VIN Number:	WVWZZZAUZDW154966	8 SPEAKER	MULTIMEDIA SYSTEM
Manufacture Year:	2013	NAVI "DISCOVER PRO"	FOG LAMPS
Odometer:	Not Known	LIGHT SWITCHING AUTO	HEADLAMP WASHERS
Colour:		PARK ASSISTENT	LEATHER TRIM
Engine Number:	CHH003356	HEATED FRONT SEATS	STRG WHEEL LEATHER
Fuel Level:	%	DOOR TRIM IMIT LEATH	ANTI-THEFT ALARM
		STOP-START SYSTEM	MULTI FUNC INDICATOR
		R/F ELECTRIC SEAT	INTER LIGHT AMBIENCE
		FRONT CENTRE ARMREST	REAR CENTRE ARMREST
		SMOKER EQUIPMENT	ALTERNATOR 140A
		HD COOLING	2.0 LTR 162 KW
		6 SPEED DSG	DYNAMIC STEERING
		SELECT DRIVE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status		
Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	16/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:		

Claim Reference:


Assessment Number: KKHA0043

Version: LKKAUTOC/4

Date Calculated: 17/10/2018 09:29

Registration: SKN5353U

Printed: 17/10/2018 17:37

Tread Depth LHR:
Damage Areas:Tread Depth RHR:
Direction of Impact:**Addresses****Cost Summary**

Total Labour	\$1,462.50
Total Paint/Material	\$238.43
Total Parts	\$7,321.75
Total of Additional Costs	\$188.00
Excess:	TBA
Grand Total Exc GST:	\$9,210.68
7 % GST:	\$644.75
Grand Total Inc GST:	\$9,855.43

Repair Information**LABOUR**Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
87 03 17 00	DRAIN + REFILL REFRIGERANT	6.0	27.00
66 05 19 00	R + R RADIATOR GRILLE	2.0	9.00
63 29 19 50	R + R FRONT BUMPER COVER (RADIATOR GRILLE REMOVED)	4.0	18.00
63 29 55 68	RENEW FRONT BUMPER COVER (REMOVED)	16.0	72.00
63 29 41 53	INCLUDES: CONVERT ATTACHED PARTS REPAIR FRONT BUMPER COVER (COMPOSITE WORK)	1.0	4.50
94 15 56 50	(1 BRACKET FITTED) RENEW HEADLAMPS (REMOVED)	9.0	40.50
50 55 19 50	INCLUDES: CONVERT ATTACHED PARTS R + R LEFT FRONT WING (BUMPER COVER REMOVED)	7.0	31.50
50 55 51 50	INCLUDES: R + R WHEEL AND WHEELHOUSE SHELL	3.0	13.50
NO NUMBER	L/F WING SEAL (COMPOSITE WORK)	3.0	13.50
NO NUMBER	RENEW L/WING BADGE	3.0	13.50
55 22 19 00	RENEW R/WING BADGE	6.0	27.00
55 22 55 50	REMOVE/REFIT BONNET PANEL INCLUDES: ADJUST BONNET CLEARANCES	4.0	18.00
55 25 56 50	RENEW BONNET (BONNET REMOVED)	2.0	9.00
	INCLUDES: R + R ALL PARTS RENEW BOTH FRONT BONNET HINGES		

Claim Reference:

Assessment Number: KKHA0043

Version: LKKAUTOC/4

Date Calculated: 17/10/2018 09:29

Registration: SKN5353U

Printed: 17/10/2018 17:37

55 25 15 50	(BONNET REMOVED)	1.0	4.50
55 25 15 50	ADJUST L/F BONNET HINGE	1.0	4.50
50 38 09 50	ADJUST R/F BONNET HINGE	9.0	40.50
	DETACH + REFIT FRONT LOCK CARRIER (BUMPER COVER REMOVED) (SERVICE POSITION)		
50 38 19 50	DOES NOT INCLUDE: ADJUST HEADLAMPS R + R FRONT LOCK CARRIER (LOCK CARRIER PANEL DETACHED)	8.0	36.00
50 38 55 50	INCLUDES: CROSSMEMBER R + R RENEW FRONT LOCK CARRIER (REMOVED)	9.0	40.50
50 34 55 50	INCLUDES: CONVERT ATTACHED PARTS RENEW FRONT CROSSMEMBER	1.0	4.50
66 61 20 00	R + R L/- AND R/WINDSCREEN MOULDING	2.0	9.00
24 25 19 20	R + R AIR CLEANER	4.0	18.00
21 43 19 70	R + R CHARGE AIR COOLER (RADIATOR REMOVED)	3.0	13.50
19 08 19 50	R + R ELECTRIC FAN	1.0	4.50
19 70 55 50	RENEW RADIATOR (REMOVED)	1.0	4.50
51 01 75 00)	INCLUDES: CONVERT ATTACHED PARTS RUST PROOFING BODY SHELL PART	2.0	9.00
51 01 75 50	APPLY CAVITY SEALING ON LEFT FRONT WING (COMPOSITE WORK)	1.0	4.50
51 01 75 50	APPLY RUST PROOFING AT BONNET (COMPOSITE WORK)	1.0	4.50
94 15 06 10	ADJUST HEADLAMPS INCLUDES: ADJUST FRONT FOG LAMPS	3.0	13.50
94 64 16 00	ALIGN FRONT FOG LAMPS	3.0	13.50
0245	PANEL WORK FRONT	15.0*	67.50
9852	READ OUT FAULT MEM AFTER REP	30.0*	135.00
1000	R/F WING SEAL (COMPOSITE WORK)	3.0*	13.50
1000	RENEW FRT GAS PRESS. SPRING (REMOV)	1.0*	4.50
1000	R + R BONNET LOCK CABLE	1.0*	4.50
1000	APPLY CAVITY SEALING ON R/F WING	1.0*	4.50
1000	R+R RIGHT FRT WING (BUMPER C RMV)	7.0*	31.50
1481	REPAIR LEFT FRONT DOOR	8.0*	36.00
LABOUR COST		182.0	
Total Work Units			
Corrosion Protection			
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.4HRS	18.00
Sub Total		18.2HRS	\$819.00
Paint Labour		14.3HRS	\$643.50
Total Labour		32.5HRS	\$1,462.50

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	22.0	
741	L/F WING NEW PART PAINTING	9.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	11.0	

Claim Reference:

Full Report - V1

Assessment Number: KKHA0043

Registration: SKN5353U

Version: LKKAUTOC/4

Printed: 17/10/2018 17:37

Date Calculated: 17/10/2018 09:29

410	GRILLE NEW PART PAINT K1R	4.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	24.0	
303	L/F CENTRE SENSOR SURFACE PAINT	4.0	
304	R/F CENTRE SENSOR SURFACE PAINT	4.0	
305	L/F OUTER SENSOR SURFACE PAINT	4.0	
306	R/F OUTER SENSOR SURFACE PAINT	4.0	
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0	
301	NEW PART PAINTING LF INNER SENSOR	5.0*	
302	NEW PART PAINTING RF INNER SENSOR	5.0*	
742	PART PAINTING RF WING NEW	9.0*	
LABOUR COST - PAINT			
	TIME(PAINT)	113.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	143.0	
	Total Paintwork Labour	14.3HRS	\$643.50
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$86.69
	New Part Painting - Plastic K1R		\$59.04
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$21.92
	Repair Painting		\$33.18
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$238.43
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$238.43

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
399	1	2-COMP ADHESIVE SENS	D 180 KU2 A1		0%	0.00F
398	1	APPLICATOR	D 009 500 25		0%	0.00G
471	1	BONNET	5G0 823 031 J		0%	490.00*
523	1	BONNET SEAL	5G0 823 707		0%	50.00*
4465	1	CONDENSER	5Q0 816 411BH		0%	290.00*
283	1	FRONT BUMPER COVER	5G0 807 217 AD		0%	460.00*
			GRU			
340	1	FRT BUMPER SUPPORT	5G0 807 109 AK		0%	270.00*
299	1	FRT CTR COWL GRILLE	5G0 853 677 C 9B9		0%	90.00*
930	1	FRT LOCK CARRIER	5G0 805 588 R		0%	490.00*
260	1	FRT NO PLATE BRKT	5G0 807 287 C 9B9		0%	60.00*
410	1	GRILLE	5G0 853 651 AJ		0%	280.00*
			BTU			
8745	1	INTERCOOLER	5Q0 145 803 R		0%	290.00*
7790	1	L/ELECTRIC FAN	5Q0 959 455 BJ		0%	360.00*
329	1	L/F BUMPER GUIDE	5G0 807 049 A		0%	30.00*
525	1	L/F COVER SEAL	5G0 823 709 A		0%	65.00*
307	1	L/F CTR SENSOR BRKT	5G0 919 493 B		0%	5.15U
321	1	L/F INN SENSOR BRKT	5G0 919 493 C		0%	25.00*
791	2	L/F NUT	N 908 173 02		0%	0.84F
311	1	L/F OUT SENSOR BRKT	5G0 998 399 A		0%	25.00*
			GRU			

Claim Reference:

Full Report - V1

Assessment Number: KKHA0043

Registration: SKN5353U

Version: LKKAUTOC/4

Printed: 17/10/2018 17:37

Date Calculated: 17/10/2018 09:29

1415	1	L/F WATER DEFLECTOR	5G0 854 327 B 5AP	0%	50.00*
741	1	L/F WING	5G0 821 105 A	0%	335.00*
811	1	L/F WING BADGE	5G0 853 688 L JZQ	0%	65.00*
939	1	L/HEADLAMP MOUNTING	5G0 805 269	0%	35.00*
989	1	L/LOCK CARRIER STRUT	5G0 805 931	0%	60.00*
475	1	LEFT BONNET HINGE	5G0 823 301 B	0%	65.00*
561	1	LEFT HEADLAMP ASSY	5G2 941 753 A	0%	890.00*
995	1	LOCK CARRIER SUPPORT	5G0 805 567	0%	60.00*
493	1	LOWER LOCK	5G1 823 509 C	0%	160.00*
1000	1	PARKING SENSOR SEAL	\$15 @ 4PCS	0%	60.00*
397	1	PLASTIC PRIMER	D 822 150 A1	0%	0.00F
330	1	R/F BUMPER GUIDE	5G0 807 050 A	0%	30.00*
526	1	R/F COVER SEAL	5G0 823 709 A	0%	65.00*
308	1	R/F CTR SENSOR BRKT	5G0 919 494 B	0%	5.15U
322	1	R/F INN SENSOR BRKT	5G0 919 493 C	0%	25.00*
312	1	R/F OUT SENSOR BRKT	5G0 998 399 A	0%	25.00*
			GRU		
1416	1	R/F WATER DEFLECTOR	5G0 854 328 B 5AP	0%	50.00*
812	1	R/F WING BADGE	5G0 853 688 M	0%	65.00*
			JZQ		
940	1	R/HEADLAMP MOUNTING	5G0 805 270	0%	35.00*
990	1	R/LOCK CARRIER STRUT	5G0 805 932	0%	60.00*
7761	1	RADIATOR	5Q0 121 251 GN	0%	280.00*
476	1	RIGHT BONNET HINGE	5G0 823 302 B	0%	65.00*
562	1	RIGHT HEADLAMP ASSY	5G2 941 754 A	0%	890.00*
f: OEM Parts			Saving		\$33.67
g: Original			Sub Total		\$6,656.14
h: Secondhand			Mark Up From Cost (10 %)		\$665.61
p: Parallel			Sundry Parts (Fixed)		\$0.00
x: Exchange			Total Parts		\$7,321.75

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$40.00
RAD. COOLANT SPECIALIST		\$48.00
AIRCON GAS SPECIALIST	0%	\$100.00
Total Extras		\$188.00

Final Calculation

Total Parts	\$7,321.75
Labour	
Total Panel/Mechanical	\$801.00
Total Paintwork	\$643.50
Corr Prot Internal 4 WU	\$18.00
Total Labour	\$1,462.50
Additional Costs	
Corr Prot Materials External	\$0.00
Cost of Specialist	\$188.00
Total of Additional Costs	\$188.00
Total Paint/Material Costs	\$238.43
Grand Total Excludes GST	\$9,210.68

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: KKHA0043

Registration: SKN5353U

Version: LKKAUTOC/4

Printed: 17/10/2018 17:37

Date Calculated: 17/10/2018 09:29

GST @ 7 %

\$644.75

Grand Total Includes GST

\$9,855.43

Assessment Notes

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHA0043
Version: K.KIMHIN/1
Date Calculated: 16/10/2018 08:50

Full Report - V1
Registration: SKN5353U
Printed: 16/10/2018 15:50

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	12/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer: VOLKSWAGEN
Model: Golf
Sub Model: GTI
Model Sheet Number: 6B1 04
Registration: SKN5353U
Registration Month: October
Registration Year: 2013
VIN Number: WVVZZZAUZDW154966
Manufacture Year: 2013
Odometer: Not Known
Colour:
Engine Number: CHH003356
Fuel Level: %

Model Specs

FROM 01/2013
OCCUPANT PROTECT SYS
TYRES 225/40 YR 18
CHROME PACKAGE
D/MIRROR W/AMBIENT
LIGHT-/RAIN SENSOR
KEYLESS ENTRY
8 SPEAKER
NAVI "DISCOVER PRO"
LIGHT SWITCHING AUTO
PARK ASSISTENT
HEATED FRONT SEATS
DOOR TRIM IMIT LEATH
STOP-START SYSTEM
R/E ELECTRIC SEAT
FRONT CENTRE ARMREST
SMOKER EQUIPMENT
HD COOLING
6 SPEED DSG
SELECT DRIVE
SPEAK CONTROL
WHEELS 7.5J X 18 ALU
BLUE MOTION TECHNO
CLIMATRONIC
XENON HEADLAMP/LED
FRT/RR ELECT WINDOWS
AUTO DIPPING MIRROR
MULTIMEDIA SYSTEM
FOG LAMPS
HEADLAMP WASHERS
LEATHER TRIM
STRG WHEEL LEATHER
ANTI-THEFT ALARM
MULTI FUNC INDICATOR
INTER LIGHT AMBIENCE
REAR CENTRE ARMREST
ALTERNATOR 140A
2.0 LTR 162 KW
DYNAMIC STEERING
TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel:

Place of Inspection:

Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Severity of Impact:

Vehicle Status on

Inspection:

Date of Inspection:

16/10/2018

Tread Depth RHF:

K.KIM HIN AUTO PTE LTD

Claim Reference:

Full Report - V1

Assessment Number: KKHA0043

Registration: SKN5353U

Version: K.KIMHIN/1

Printed: 16/10/2018 15:50

Date Calculated: 16/10/2018 08:50

55 22 55 50	INCLUDES: ADJUST BONNET CLEARANCES RENEW BONNET (BONNET REMOVED)	4.0	18.00
55 31 19 ZAX	INCLUDES: R + R ALL PARTS RENEW FRT GAS PRESSURE SPRING (REMOVED)	1.0	4.50
55 25 56 50	RENEW BOTH FRONT BONNET HINGES (BONNET REMOVED)	2.0	9.00
55 25 15 50	ADJUST L/F BONNET HINGE	1.0	4.50
55 25 15 50	ADJUST R/F BONNET HINGE	1.0	4.50
55 14 19 50)	R + R BONNET LOCK CABLE	1.0	4.50
50 38 09 50	DETACH + REFIT FRONT LOCK CARRIER (BUMPER COVER REMOVED) (SERVICE POSITION)	9.0	40.50
50 38 19 50	DOES NOT INCLUDE: ADJUST HEADLAMPS R + R FRONT LOCK CARRIER (LOCK CARRIER PANEL DETACHED)	8.0	36.00
50 38 55 50	INCLUDES: CROSSMEMBER R + R RENEW FRONT LOCK CARRIER (REMOVED)	9.0	40.50
50 34 55 50	INCLUDES: CONVERT ATTACHED PARTS RENEW FRONT CROSSMEMBER	1.0	4.50
66 61 20 00	R + R L/- AND R/WINDSCREEN MOULDING	2.0	9.00
24 25 19 20	R + R AIR CLEANER	4.0	18.00
21 43 19 70	R + R CHARGE AIR COOLER (RADIATOR REMOVED)	3.0	13.50
19 20 55 50	RENEW COOLING BLOWER HOUSING	1.0	4.50
19 70 55 50	INCLUDES: R + R ELECTRIC FAN RENEW RADIATOR (REMOVED)	1.0	4.50
51 01 75 00)	INCLUDES: CONVERT ATTACHED PARTS RUST PROOFING BODY SHELL PART	2.0	9.00
51 01 75 50	APPLY CAVITY SEALING ON LEFT FRONT WING (COMPOSITE WORK)	1.0	4.50
51 01 75 50	APPLY CAVITY SEALING ON RIGHT FRONT WING (COMPOSITE WORK)	1.0	4.50
51 01 75 50	APPLY RUST PROOFING AT BONNET (COMPOSITE WORK)	1.0	4.50
94 15 06 10	ADJUST HEADLAMPS	3.0	13.50
94 64 16 00	INCLUDES: ADJUST FRONT FOG LAMPS ALIGN FRONT FOG LAMPS	3.0	13.50
0245	PANEL WORK FRONT	13 30.0*	135.00
9852	READ OUT FAULT MEM AFTER REP	8 30.0* 7	135.00
1481	REPAIR LEFT FRONT DOOR	8 30.0*	135.00

LABOUR COST

Total Work Units	219.0	
Corrosion Protection		
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.5HRS	22.50
Sub Total	21.9HRS	\$985.50
Paint Labour	14.3HRS	\$643.50
Total Labour	36.2HRS	\$1,629.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0043

Version: K.KIMHIN/1

Date Calculated: 16/10/2018 08:50

Full Report - V1

Registration: SKN5353U

Printed: 16/10/2018 15:50

330	1	R/F BUMPER GUIDE	5G0 807 050 A	0%	0.1	30.00*	✓
339	1	FRT BUMPER C-MEMBER	5G0 807 651 A	0%	R	130.00*	X
340	1	FRT BUMPER SUPPORT	5G0 807 109 AK	0%		270.00*	?
397	1	PLASTIC PRIMER	D 822 150 A1	0%	Sm	6.22U	X
398	1	APPLICATOR	D 009 500 25	0%	Sm	2.70U	X
399	1	2-COMP ADHESIVE SENS	D 180 KU2 A1	0%	Sm	24.75U	X
410	1	GRILLE	5G0 853 651 AJ	0%	CM	280.00*	✓
			BTU				
471	1	BONNET	5G0 823 031 J	0%	Bu	490.00*	✓
475	1	LEFT BONNET HINGE	5G0 823 301 B	0%		65.00*	?
476	1	RIGHT BONNET HINGE	5G0 823 302 B	0%		65.00*	?
481	1	BONNET INSULATION	5G0 863 831	0%	R	150.00*	X
493	1	LOWER LOCK	5G1 823 509 C	0%		160.00*	?
494	1	SAFETY LATCH	5G0 823 186 B	0%	R	60.00*	X
497	1	BONNET GAS STRUT	5G0 823 359 A	0%	Sm	70.00*	X
500	1	BONNET REL CABLE	5G2 823 531 D	0%	Sm	65.00*	X
523	1	BONNET SEAL	5G0 823 707	0%		50.00*	?
525	1	L/F COVER SEAL	5G0 823 709 A	0%	Re	65.00*	✓
526	1	R/F COVER SEAL	5G0 823 709 A	0%		65.00*	?
561	1	LEFT HEADLAMP ASSY	5G2 941 753 A	0%	mg, as	890.00*	✓
562	1	RIGHT HEADLAMP ASSY	5G2 941 754 A	0%	mg, as	890.00*	✓
741	1	L/F WING	5G0 821 105 A	0%	A	335.00*	✓
742	1	R/F WING	5G0 821 106 A	0%	R	335.00*	X
791	2	L/F NUT	N 908 173 02	0%		0.84U	?
792	2	R/F NUT	N 908 173 02	0%		0.84U	?
811	1	L/F WING BADGE	5G0 853 688 L JZQ	0%	Re	65.00*	✓
812	1	R/F WING BADGE	5G0 853 688 M	0%	Re	65.00*	✓
			JZQ				
930	1	FRT LOCK CARRIER	5G0 805 588 R	0%		490.00*	?
939	1	L/HEADLAMP MOUNTING	5G0 805 269	0%		35.00*	?
940	1	R/HEADLAMP MOUNTING	5G0 805 270	0%		35.00*	?
941	1	L/CTR INN H-LAMP BRK	5G0 804 593 A	0%	R	40.00*	X
942	1	R/CTR INN H-LAMP BRK	5G0 804 594	0%	R	40.00*	X
989	1	L/LOCK CARRIER STRUT	5G0 805 931	0%	Bu	60.00*	✓
990	1	R/LOCK CARRIER STRUT	5G0 805 932	0%	Bu	60.00*	✓
995	1	LOCK CARRIER SUPPORT	5G0 805 567	0%		60.00*	?
1415	1	L/F WATER DEFLECTOR	5G0 854 327 B 5AP	0%		50.00*	?
1416	1	R/F WATER DEFLECTOR	5G0 854 328 B 5AP	0%	0.1	50.00*	✓
4465	1	CONDENSER	5Q0 816 411BH	0%		290.00*	?
7761	1	RADIATOR	5Q0 121 251 GN	0%		280.00*	?
7767	1	FAN SHROUD	3Q0 121 205	0%	R	160.00*	X
7790	1	L/ELECTRIC FAN	5Q0 959 455 BJ	0%		360.00*	?
8745	1	INTERCOOLER	5Q0 145 803 R	0%		290.00*	?
1000	1	TOWING CVR	Renew	0%	R	35.00*	X
1000	1	PARKING SENSOR SEAL	\$15 @ 4PCS	0%		60.00*	?

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

(10 %)

Sundry Parts

(Fixed)

Total Parts

\$7,995.65

\$799.57

\$0.00

\$8,795.22

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHA0043
Version: K.KIMHIN/1
Date Calculated: 16/10/2018 08:50

Full Report - V1
Registration: SKN5353U
Printed: 16/10/2018 15:50

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	12/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	Estimated Repair Time:
Policy Number:	Quote Due Date:
Other Reference:	Actual Repair Days:
Third Party:	Parts Ordered Date:
Insured Amount:	Hire Car Start:
Under Warranty:	Hire Car End:
Warranty Expired:	Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer:	VOLKSWAGEN
Model:	Golf
Sub Model:	GTI
Model Sheet Number:	6B1 04
Registration:	SKN5353U
Registration Month:	October
Registration Year:	2013
VIN Number:	WVWZZZAUZDW154966
Manufacture Year:	2013
Odometer:	Not Known
Colour:	
Engine Number:	CHH003356
Fuel Level:	%

Model Specs

FROM 01/2013	SPEAK CONTROL
OCCUPANT PROTECT SYS	WHEELS 7.5J X 18 ALU
TYRES 225/40 YR 18	BLUE MOTION TECHNO
CHROME PACKAGE	CLIMATRONIC
D/MIRROR W/AMBIENT	XENON HEADLAMP/LED
LIGHT-/RAIN SENSOR	FRT/RR ELECT WINDOWS
KEYLESS ENTRY	AUTO DIPPING MIRROR
8 SPEAKER	MULTIMEDIA SYSTEM
NAVI "DISCOVER PRO"	FOG LAMPS
LIGHT SWITCHING AUTO	HEADLAMP WASHERS
PARK ASSISTANT	LEATHER TRIM
HEATED FRONT SEATS	STRG WHEEL LEATHER
DOOR TRIM IMIT LEATH	ANTI-THEFT ALARM
STOP-START SYSTEM	MULTI FUNC INDICATOR
R/F ELECTRIC SEAT	INTER LIGHT AMBIENCE
FRONT CENTRE ARMREST	REAR CENTRE ARMREST
SMOKER EQUIPMENT	ALTERNATOR 140A
HD COOLING	2.0 LTR 162 KW
6 SPEED DSG	DYNAMIC STEERING
SELECT DRIVE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Tyres Condition:
Tread Depth LHF:

LKK Auto Consult - Vehicle not to be repaired by the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from insurance company

Acknowledged by Repairer
Signature: 
Date: 

Severity of Impact:
Vehicle Status on
Inspection:
Date of Inspection:

16/10/2018

Not Authorized
L.B.I
Recovery Repairing
6 days


Tread Depth RHF:

K.KIM HIN AUTO PTE LTD

Claim Reference:
Assessment Number: KKHA0043
Version: K.KIMHIN/1
Date Calculated: 16/10/2018 08:50

Full Report - V1
Registration: SKN5353U
Printed: 16/10/2018 15:50

Tread Depth LHR:
 Damage Areas:



Tread Depth RHR:
 Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,629.00
Total Paint/Material	\$254.95
Total Parts	\$8,795.22
Total of Additional Costs	\$188.00
Excess:	TBA
Grand Total Exc GST:	\$10,867.17
7 % GST:	\$760.70
Grand Total Inc GST:	\$11,627.87

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$0.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
87 03 17 00	DRAIN + REFILL REFRIGERANT	6.0	27.00
66 05 19 00	R + R RADIATOR GRILLE	2.0	9.00
63 29 19 50	R + R FRONT BUMPER COVER (RADIATOR GRILLE REMOVED)	4.0	18.00
63 29 55 68	RENEW FRONT BUMPER COVER (REMOVED)	16.0	72.00
63 29 41 53	INCLUDES: CONVERT ATTACHED PARTS REPAIR FRONT BUMPER COVER (COMPOSITE WORK) (1 BRACKET FITTED)	1.0	4.50
94 15 56 50	RENEW HEADLAMPS (REMOVED)	9.0	40.50
50 55 19 50	INCLUDES: CONVERT ATTACHED PARTS R + R LEFT FRONT WING (BUMPER COVER REMOVED)	7.0	31.50
50 55 51 50	INCLUDES: R + R WHEEL AND WHEELHOUSE SHELL		
NO NUMBER	L/F WING SEAL (COMPOSITE WORK)	3.0	13.50
50 55 19 50	RENEW L/WING BADGE	3.0	13.50 X
50 55 19 50	R + R RIGHT FRONT WING (BUMPER COVER REMOVED)	7.0	31.50
50 55 51 50	INCLUDES: R + R WHEEL AND WHEELHOUSE SHELL		
NO NUMBER	R/F WING SEAL (COMPOSITE WORK)	3.0	13.50
55 22 19 00	RENEW R/WING BADGE	3.0	13.50 X
	REMOVE/REFIT BONNET PANEL	6.0	27.00

K.KIM HIN AUTO PTE LTD**Claim Reference:****Assessment Number: KKHA0043****Version: K.KIMHIN/1****Date Calculated: 16/10/2018 08:50****Full Report - V1****Registration: SKN5353U****Printed: 16/10/2018 15:50**

5042 19 50	Renew Centre Radiation Mounting Support	1.0	4.50
01 50 0034x	Self Diagnosis - Read Error Memory	2.0	9.00
55 22 55 50	INCLUDES: ADJUST BONNET CLEARANCES RENEW BONNET (BONNET REMOVED) INCLUDES: R + R ALL PARTS	4.0	18.00
55 31 19 ZAX	RENEW FRT GAS PRESSURE SPRING (REMOVED)	1.0	4.50
55 25 56 50	RENEW BOTH FRONT BONNET HINGES (BONNET REMOVED)	2.0	9.00
55 25 15 50	ADJUST L/F BONNET HINGE	1.0	4.50
55 25 15 50	ADJUST R/F BONNET HINGE	1.0	4.50
55 14 19 50)	R + R BONNET LOCK CABLE	1.0	4.50
50 38 09 50	DETACH + REFIT FRONT LOCK CARRIER (BUMPER COVER REMOVED) (SERVICE POSITION)	9.0	40.50
50 38 19 50	DOES NOT INCLUDE: ADJUST HEADLAMPS R + R FRONT LOCK CARRIER (LOCK CARRIER PANEL DETACHED) INCLUDES: CROSSMEMBER R + R	8.0	36.00
50 38 55 50	RENEW FRONT LOCK CARRIER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	9.0	40.50
50 34 55 50	RENEW FRONT CROSSMEMBER	1.0	4.50
66 61 20 00	R + R L/- AND R/WINDSCREEN MOULDING	2.0	9.00
24 25 19 20	R + R AIR CLEANER	4.0	18.00
21 43 19 70	R + R CHARGE AIR COOLER (RADIATOR REMOVED)	3.0	13.50
19 20 55 50	RENEW COOLING BLOWER HOUSING INCLUDES: R + R ELECTRIC FAN	1.0	4.50
19 70 55 50	RENEW RADIATOR (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	1.0	4.50
51 01 75 00)	RUST PROOFING BODY SHELL PART	2.0	9.00
51 01 75 50	APPLY CAVITY SEALING ON LEFT FRONT WING (COMPOSITE WORK)	1.0	4.50
51 01 75 50	APPLY CAVITY SEALING ON RIGHT FRONT WING (COMPOSITE WORK)	1.0	4.50
51 01 75 50	APPLY RUST PROOFING AT BONNET (COMPOSITE WORK)	1.0	4.50
94 15 06 10	ADJUST HEADLAMPS INCLUDES: ADJUST FRONT FOG LAMPS	3.0	13.50
94 64 16 00	ALIGN FRONT FOG LAMPS	3.0	13.50
0245	PANEL WORK FRONT	15 30.0*	135.00
9852	READ OUT FAULT MEM AFTER REP	5 20.0*	135.00
1481	REPAIR LEFT FRONT DOOR	5 30.0*	135.00

LABOUR COST**Total Work Units****219.0****Corrosion Protection****Corrosion Protection External Labour****0.0HRS****0.00****Corrosion Protection Internal Labour****0.5HRS****22.50****Sub Total****21.5HRS****\$988.50****Paint Labour****14.3HRS****\$643.50****Total Labour****35.8HRS****\$1,629.00****PAINT WORK****Time Basis 10 WU = 1 HR. Price = \$45.00/HR**

K.KIM HIN AUTO PTE LTD**Claim Reference:****Assessment Number: KKHA0043****Version: K.KIMHIN/1****Date Calculated: 16/10/2018 08:50****Full Report - V1****Registration: SKN5353U****Printed: 16/10/2018 15:50**

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT PEARL/MICA		
301	L/F INNER SENSOR NEW PART PAINTING	5.0	
302	R/F INNER SENSOR NEW PART PAINTING	5.0	
471	BONNET NEW PART PAINTING	22.0	
741	L/F WING NEW PART PAINTING	9.0	
742	R/F WING NEW PART PAINTING	9.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	11.0	
410	GRILLE NEW PART PAINT K1R	4.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	24.0	
303	L/F CENTRE SENSOR SURFACE PAINT	4.0	
304	R/F CENTRE SENSOR SURFACE PAINT	4.0	
305	L/F OUTER SENSOR SURFACE PAINT	4.0	
306	R/F OUTER SENSOR SURFACE PAINT	4.0	
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0	
LABOUR COST - PAINT			
TIME(PAINT)		113.0	
Preparation Main Work Plastic		5.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		143.0	
Total Paintwork Labour		14.3HRS	
MATERIAL COST - PAINT			
New Part Painting			
New Part Painting - Plastic K1R			
Material-Constant Main Work Metal			
Surface-/Blend Paint			
Repair Painting			
Material-Const Main Work Plastic			
Total Excluding Pearlescent Uplift			
Pearlescent Uplift @ 0.0%			
Total Paint Material Cost			

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
260	1	FRT NO PLATE BRKT	5G0 807 287 C 9B9		0%	60.00
283	1	FRONT BUMPER COVER	5G0 807 217 AD		0%	460.00
			GRU			
299	1	FRT CTR COWL GRILLE	5G0 853 677 C 9B9		0%	90.00
301	1	L/F INNER SENSOR	5Q0 919 275 B		0%	110.00
			GRU			
302	1	R/F INNER SENSOR	5Q0 919 275 B		0%	110.00
			GRU			
307	1	L/F CTR SENSOR BRKT	5G0 919 493 B		0%	5.15U
308	1	R/F CTR SENSOR BRKT	5G0 919 494 B		0%	5.15U
311	1	L/F OUT SENSOR BRKT	5G0 998 399 A		0%	25.00
			GRU			
312	1	R/F OUT SENSOR BRKT	5G0 998 399 A		0%	25.00
			GRU			
321	1	L/F INN SENSOR BRKT	5G0 919 493 C		0%	25.00
322	1	R/F INN SENSOR BRKT	5G0 919 493 C		0%	25.00
329	1	L/F BUMPER GUIDE	5G0 807 049 A		0%	30.00
945	1	Front B. d.c	5G0 807 049 A		0%	30.00

Full Report - V1

Registration: SKN5353U

Printed: 16/10/2018 15:50

Date Calculated: 16/10/2018 08:50

QTY	UNIT	DESCRIPTION	ITEM NO	UNIT PRICE	TOTAL PRICE	REMARKS
330	1	R/F BUMPER GUIDE	5G0 807 050 A	0%	30.00*	
339	1	FRT BUMPER C-MEMBER	5G0 807 651 A	0%	130.00*	
340	1	FRT BUMPER SUPPORT	5G0 807 109 AK	0%	270.00*	
397	1	PLASTIC PRIMER	D 822 150 A1	0%	6.22U	
398	1	APPLICATOR	D 009 500 25	0%	2.70U	
399	1	2-COMP ADHESIVE SENS	D 180 KU2 A1	0%	24.75U	
410	1	GRILLE	5G0 853 651 A1	0%	280.00*	
			BTU			
471	1	BONNET	5G0 823 031 J	0%	490.00*	
475	1	LEFT BONNET HINGE	5G0 823 301 B	0%	65.00*	
476	1	RIGHT BONNET HINGE	5G0 823 302 B	0%	65.00*	
481	1	BONNET INSULATION	5G0 863 831	0%	150.00*	
493	1	LOWER LOCK	5G1 823 509 C	0%	160.00*	
494	1	SAFETY LATCH	5G0 823 186 B	0%	60.00*	
497	1	BONNET GAS STRUT	5G0 823 359 A	0%	70.00*	
500	1	BONNET REL CABLE	5G2 823 531 D	0%	65.00*	
523	1	BONNET SEAL	5G0 823 707	0%	50.00*	
525	1	L/F COVER SEAL	5G0 823 709 A	0%	65.00*	
526	1	R/F COVER SEAL	5G0 823 709 A	0%	65.00*	
561	1	LEFT HEADLAMP ASSY	5G2 941 753 A	0%	890.00*	
562	1	RIGHT HEADLAMP ASSY	5G2 941 754 A	0%	890.00*	
741	1	L/F WING	5G0 821 105 A	0%	335.00*	
742	1	R/F WING	5G0 821 106 A	0%	335.00*	
791	2	L/F NUT	N 908 173 02	0%	0.84U	
792	2	R/F NUT	N 908 173 02	0%	0.84U	
811	1	L/F WING BADGE	5G0 853 688 L JZQ	0%	65.00*	
812	1	R/F WING BADGE	5G0 853 688 M JZQ	0%	65.00*	
930	1	FRT LOCK CARRIER	5G0 805 588 R	0%	490.00*	
939	1	L/HEADLAMP MOUNTING	5G0 805 269	0%	35.00*	
940	1	R/HEADLAMP MOUNTING	5G0 805 270	0%	35.00*	
941	1	L/CTR INN H-LAMP BRK	5G0 804 593 A	0%	40.00*	
942	1	R/CTR INN H-LAMP BRK	5G0 804 594	0%	40.00*	
989	1	L/LOCK CARRIER STRUT	5G0 805 931	0%	60.00*	
990	1	R/LOCK CARRIER STRUT	5G0 805 932	0%	60.00*	
995	1	LOCK CARRIER SUPPORT	5G0 805 567	0%	60.00*	
1415	1	L/F WATER DEFLECTOR	5G0 854 327 B 5AP	0%	50.00*	
1416	1	R/F WATER DEFLECTOR	5G0 854 328 B 5AP	0%	50.00*	
4465	1	CONDENSER	5Q0 816 411BH	0%	290.00*	
7761	1	RADIATOR	5Q0 121 251 GN	0%	280.00*	
7767	1	FAN SHROUD	3Q0 121 205	0%	160.00*	
7790	1	L/ELECTRIC FAN	5Q0 959 455 B1	0%	360.00*	
8745	1	INTERCOOLER	5Q0 145 803 R	0%	290.00*	
1000	1	TOWING CVR	Renew	0%	35.00*	
1000	1	PARKING SENSOR SEAL	\$15 @ 4PCS	0%	60.00*	
f: OEM Parts		Sub Total			\$7,995.65	
g: Original		Mark Up From Cost	(10 %)		\$799.57	
h: Secondhand		Sundry Parts	(Fixed)		\$0.00	
n: Parallel		Total Parts			\$8,795.22	

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

K.KIM HIN AUTO PTE LTD**Claim Reference:****Full Report - V1****Assessment Number: KKHA0043****Registration: SKN5353U****Version: K.KIMHIN/1****Printed: 16/10/2018 15:50****Date Calculated: 16/10/2018 08:50**

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	not \$40.00 75m
RAD. COOLANT SPECIALIST		not \$48.00 20m
AIRCON GAS SPECIALIST	0%	not \$100.00 50m
Total Extras		\$188.00

Final Calculation**Total Parts \$8,795.22****Labour**

Total Panel/Mechanical	\$963.00 619
Total Paintwork	\$643.50 630.50
Corr Prot Internal S WU	\$22.50

Total Labour \$1,629.00**Additional Costs**

Corr Prot Materials External	\$0.00
Cost of Specialist	\$188.00

Total of Additional Costs \$188.00**Total Paint/Material Costs \$254.95****Grand Total Excludes GST \$10,867.17**GST @ 7 % **\$760.70****Grand Total Includes GST \$11,627.87****Assessment Notes**

10935.67

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: KKHA0043
Version: LKKAUTOC/7
Date Calculated: 13/03/2019 02:15

Full Report - V1
Registration: SKN5353U
Printed: 13/03/2019 10:17

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	12/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	Estimated Repair Time:
Policy Number:	Quote Due Date:
Other Reference:	Actual Repair Days:
Third Party:	Parts Ordered Date:
Insured Amount:	Hire Car Start:
Under Warranty:	Hire Car End:
Warranty Expired:	Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer:	VOLKSWAGEN
Model:	Golf
Sub Model:	GTI
Model Sheet Number:	6B1 04
Registration:	SKN5353U
Registration Month:	October
Registration Year:	2013
VIN Number:	WVWZZZAUZDW154966
Manufacture Year:	2013
Odometer:	Not Known
Colour:	
Engine Number:	CHH003356
Fuel Level:	%

Model Specs

FROM 01/2013	SPEAK CONTROL
OCCUPANT PROTECT SYS	WHEELS 7.5J X 18 ALU
TYRES 225/40 YR 18	BLUE MOTION TECHNO
CHROME PACKAGE	CLIMATRONIC
D/MIRROR W/AMBIENT	XENON HEADLAMP/LED
LIGHT-/RAIN SENSOR	FRT/RR ELECT WINDOWS
KEYLESS ENTRY	AUTO DIPPING MIRROR
8 SPEAKER	MULTIMEDIA SYSTEM
NAVI "DISCOVER PRO"	FOG LAMPS
LIGHT SWITCHING AUTO	HEADLAMP WASHERS
PARK ASSISTENT	LEATHER TRIM
HEATED FRONT SEATS	STRG WHEEL LEATHER
DOOR TRIM IMIT LEATH	ANTI-THEFT ALARM
STOP-START SYSTEM	MULTI FUNC INDICATOR
R/F ELECTRIC SEAT	INTER LIGHT AMBIENCE
FRONT CENTRE ARMREST	REAR CENTRE ARMREST
SMOKER EQUIPMENT	ALTERNATOR 140A
HD COOLING	2.0 LTR 162 KW
6 SPEED DSG	DYNAMIC STEERING
SELECT DRIVE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	16/10/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:

Claim Reference:

Full Report - V1

Assessment Number: KKHA0043

Registration: SKN5353U

Version: LKKAUTOC/7

Printed: 13/03/2019 10:17


Date Calculated: 13/03/2019 02:15

Tread Depth LHR:

Tread Depth RHR:

Damage Areas:

Direction of Impact:



Addresses

Cost Summary

Total Labour	\$1,296.00
Total Paint/Material	\$254.41
Total Parts	\$5,736.50
Total of Additional Costs	\$105.00
Excess:	TBA
Grand Total Exc GST:	\$7,391.91
7 % GST:	\$517.43
Grand Total Inc GST:	\$7,909.34

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
87 03 17 00	DRAIN + REFILL REFRIGERANT	6.0	27.00
66 05 19 00	R + R RADIATOR GRILLE	2.0	9.00
63 29 19 50	R + R FRONT BUMPER COVER (RADIATOR GRILLE REMOVED)	4.0	18.00
63 29 55 68	RENEW FRONT BUMPER COVER (REMOVED)	16.0	72.00
63 29 41 53	INCLUDES: CONVERT ATTACHED PARTS REPAIR FRONT BUMPER COVER (COMPOSITE WORK) (1 BRACKET FITTED)	1.0	4.50
94 15 56 50	RENEW HEADLAMPS (REMOVED)	9.0	40.50
50 55 19 50	INCLUDES: CONVERT ATTACHED PARTS R + R LEFT FRONT WING (BUMPER COVER REMOVED)	7.0	31.50
50 55 51 50	INCLUDES: R + R WHEEL AND WHEELHOUSE SHELL L/F WING SEAL (COMPOSITE WORK)	3.0	13.50
50 55 19 50	R + R RIGHT FRONT WING (BUMPER COVER REMOVED)	7.0	31.50
50 55 51 50	INCLUDES: R + R WHEEL AND WHEELHOUSE SHELL R/F WING SEAL (COMPOSITE WORK)	3.0	13.50
55 22 19 00	REMOVE/REFIT BONNET PANEL	6.0	27.00
55 22 55 50	INCLUDES: ADJUST BONNET CLEARANCES RENEW BONNET	4.0	18.00

Claim Reference:

Full Report - V1

Assessment Number: KKHA0043

Registration: SKN5353U

Version: LKKAUTOC/7

Printed: 13/03/2019 10:17

Date Calculated: 13/03/2019 02:15

	(BONNET REMOVED)		
	INCLUDES: R + R ALL PARTS		
55 25 56 50	RENEW BOTH FRONT BONNET HINGES	2.0	9.00
	(BONNET REMOVED)		
55 25 15 50	ADJUST L/F BONNET HINGE	1.0	4.50
55 25 15 50	ADJUST R/F BONNET HINGE	1.0	4.50
55 14 19 50)	R + R BONNET LOCK CABLE	1.0	4.50
50 38 09 50	DETACH + REFIT FRONT LOCK CARRIER	9.0	40.50
	(BUMPER COVER REMOVED)		
	(SERVICE POSITION)		
	DOES NOT INCLUDE: ADJUST HEADLAMPS		
50 38 19 50	R + R FRONT LOCK CARRIER	8.0	36.00
	(LOCK CARRIER PANEL DETACHED)		
	INCLUDES: CROSSMEMBER R + R		
50 38 55 50	RENEW FRONT LOCK CARRIER (REMOVED)	9.0	40.50
	INCLUDES: CONVERT ATTACHED PARTS		
50 42 19 50	RENEW CENTRE RADIATOR MOUNTING SUPPORT	1.0	4.50 A
50 34 55 50	RENEW FRONT CROSSMEMBER	1.0	4.50
66 61 20 00	R + R L/- AND R/WINDSCREEN MOULDING	2.0	9.00
21 43 19 70	R + R CHARGE AIR COOLER	3.0	13.50
	(RADIATOR REMOVED)		
51 01 75 00)	RUST PROOFING BODY SHELL PART	2.0	9.00
51 01 75 50	APPLY CAVITY SEALING ON LEFT FRONT WING	1.0	4.50
	(COMPOSITE WORK)		
51 01 75 50	APPLY CAVITY SEALING ON RIGHT FRONT WING	1.0	4.50
	(COMPOSITE WORK)		
51 01 75 50	APPLY RUST PROOFING AT BONNET	1.0	4.50
	(COMPOSITE WORK)		
01 50 00 ZAX	SELF DIAGNOSIS: READ ERROR MEMORY	2.0	9.00 A
	(V.A.S. 6160 / V.A.S. 6150)		
94 15 06 10	ADJUST HEADLAMPS	3.0	13.50
	INCLUDES: ADJUST FRONT FOG LAMPS		
94 64 16 00	ALIGN FRONT FOG LAMPS	3.0	13.50
0245	PANEL WORK FRONT	15.0*	67.50
0339	REPAIR FRT BUMPER C-MEMBER	5.0*	22.50
1481	REPAIR LEFT FRONT DOOR	8.0*	36.00

LABOUR COST

Total Work Units	147.0	
Corrosion Protection		
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.5HRS	22.50
Sub Total	14.7HRS	\$661.50
Paint Labour	14.1HRS	\$634.50
Total Labour	28.8HRS	\$1,296.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	22.0	
741	L/F WING NEW PART PAINTING	9.0	
742	R/F WING NEW PART PAINTING	9.0	

283	FRONT BUMPER COVER NEW PART PAINT K1R	11.0	
410	GRILLE NEW PART PAINT K1R	4.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	24.0	
301	L/F INNER SENSOR SURFACE PAINT	4.0	
302	R/F INNER SENSOR SURFACE PAINT	4.0	
303	L/F CENTRE SENSOR SURFACE PAINT	4.0	
304	R/F CENTRE SENSOR SURFACE PAINT	4.0	
305	L/F OUTER SENSOR SURFACE PAINT	4.0	
306	R/F OUTER SENSOR SURFACE PAINT	4.0	
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0	
LABOUR COST - PAINT			
	TIME(PAINT)	111.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	141.0	
	Total Paintwork Labour	14.1HRS	\$634.50
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$102.17
	New Part Painting - Plastic K1R		\$59.04
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$22.42
	Repair Painting		\$33.18
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$254.41
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$254.41

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
399	1	2-COMP ADHESIVE SENS	D 180 KU2 A1		0%	0.00F
398	1	APPLICATOR	D 009 500 25		0%	0.00F
471	1	BONNET	5G0 823 031 J		0%	490.00*
500	1	BONNET REL CABLE	5G2 823 531 D		0%	65.00*
283	1	FRONT BUMPER COVER	5G0 807 217 AD		0%	460.00*
			GRU			
945	1	FRONT GUIDE	5G0 805 705 G		0%	55.00* A
340	1	FRT BUMPER SUPPORT	5G0 807 109 AK		0%	270.00*
930	1	FRT LOCK CARRIER	5G0 805 588 R		0%	490.00*
260	1	FRT NO PLATE BRKT	5G0 807 287 C 9B9		0%	60.00*
410	1	GRILLE	5G0 853 651 AJ		0%	280.00*
			BTU			
329	1	L/F BUMPER GUIDE	5G0 807 049 A		0%	30.00*
307	1	L/F CTR SENSOR BRKT	5G0 919 493 B		0%	0.00F
321	1	L/F INN SENSOR BRKT	5G0 919 493 C		0%	25.00*
791	2	L/F NUT	N 908 173 02		0%	0.00F
311	1	L/F OUT SENSOR BRKT	5G0 998 399 A		0%	25.00*
			GRU			
741	1	L/F WING	5G0 821 105 A		0%	335.00*
989	1	L/LOCK CARRIER STRUT	5G0 805 931		0%	60.00*
297	1	L/LWR AIR VENT GRILL	5G0 853 665 E 989		0%	75.00*
475	1	LEFT BONNET HINGE	5G0 823 301 B		0%	65.00*

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: KKHA0043

Registration: SKN5353U

Version: LKKAUTOC/7

Printed: 13/03/2019 10:17

Date Calculated: 13/03/2019 02:15

561	1	LEFT HEADLAMP ASSY	5G2 941 753 A	0%	890.00*
397	1	PLASTIC PRIMER	D 822 150 A1	0%	0.00F
330	1	R/F BUMPER GUIDE	5G0 807 050 A	0%	30.00*
308	1	R/F CTR SENSOR BRKT	5G0 919 494 B	0%	0.00F
322	1	R/F INN SENSOR BRKT	5G0 919 493 C	0%	25.00*
792	2	R/F NUT	N 908 173 02	0%	0.00F
312	1	R/F OUT SENSOR BRKT	5G0 998 399 A	0%	25.00*
			GRU		
1416	1	R/F WATER DEFLECTOR	5G0 854 328 B 5AP	0%	50.00*
742	1	R/F WING	5G0 821 106 A	0%	335.00*
990	1	R/LOCK CARRIER STRUT	5G0 805 932	0%	60.00*
476	1	RIGHT BONNET HINGE	5G0 823 302 B	0%	65.00*
562	1	RIGHT HEADLAMP ASSY	5G2 941 754 A	0%	890.00*
494	1	SAFETY LATCH	5G0 823 186 B	0%	60.00*
f: OEM Parts			Saving		\$45.65
g: Original			Sub Total		\$5,215.00
h: Secondhand			Mark Up From Cost (10 %)		\$521.50
p: Parallel			Sundry Parts (Fixed)		\$0.00
x: Exchange			Total Parts		\$5,736.50

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$35.00
RAD.COOLANT SPECIALIST		\$20.00
AIRCON GAS SPECIALIST	0%	\$50.00
Total Extras		\$105.00

Final Calculation

Total Parts	\$5,736.50
Labour	
Total Panel/Mechanical	\$639.00
Total Paintwork	\$634.50
Corr Prot Internal 5 WU	\$22.50
Total Labour	\$1,296.00
Additional Costs	
Corr Prot Materials External	\$0.00
Cost of Specialist	\$105.00
Total of Additional Costs	\$105.00
Total Paint/Material Costs	\$254.41
Grand Total Excludes GST	\$7,391.91
GST @ 7 %	\$517.43
Grand Total Includes GST	\$7,909.34

Assessment Notes



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1888 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

V/S: K.KIM HUN AUTO PTE LTD

160 SIN MING DRIVE

#02-18/19/20/21 SIN MING AUTOCITY

SINGAPORE 575722

SKN5353L

MENG HUAT

NO: DL9209325

PAGE: 1

DATE: 18/10/2018

A/C CODE: LDKK241

TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 VSG0 807 287 C 9B9 ✓	LIC PLATE HOLDER	VA-2	1 ✓	60.00	60.00
2 VSG0 807 217 ED GRU ✓	FR BUMPER (W PARK ASSIST AND HEADLIGHT WASHER)	VA-24	1 ✓	460.00	460.00
3 VSG0 807 049 A ✓	GUIDE PROFILE LH	VB2-10	1 ✓	30.00	30.00
4 VSG0 807 050 A ✓	GUIDE PROFILE RH	VB2-10	1 ✓	30.00	30.00
5 VSG0 919 493 C ✓	FRONT PARKING SENSOR BRACKET	DDS	2	25.00	50.00
6 VSG0 919 493 B ✓	FRONT PARKING SENSOR BRACKET	DDS	2	25.00	50.00
7 VSG0 807 109 H ✓	FR REINF	VA-24	1 ✓	270.00	270.00
8 VSG2 941 753 A ✓	HEADLAMP LID LH	VA-12	1 ✓	890.00	890.00
9 VSG2 941 754 A ✓	HEADLIGHT RH DRL	VA-10	1 ✓	890.00	890.00
10 VSG0 805 931 ✓	HEADLAMP BRACE LH	VB6-15	1 ✓	60.00	60.00
11 VSG0 805 932 ✓	HEADLAMP BRACE RH	VB6-15	1 ✓	60.00	60.00
12 VSG0 805 588 L ✓	SUPPORT PANEL	MHD	1	490.00	490.00
13 VSG0 805 705 H ✓	GUIDE SECTION	VB14-2	1 ✓	55.00	55.00
14 VSG0 853 665 E 9B9	FR FOG LAMP COVER LH	DDS	1	75.00	75.00
15 VSG0 823 031 J	BONNET	DDS	1	490.00	490.00

TOTAL QUANTITY: 17

TOTAL SIN 3,960.00

ADD GST @ 7% 277.20

GRAND TOTAL SIN 4,237.20

#02-21

Print: MT/18/10/2018 4:44:08 PM

SALESMAN: MT

This document is computer generated. No signature required

GOODS SOLD ARE NOT RETURNABLE

R & C E

GOODS RECEIVED BY





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE

#02-18/19/20/21 SIN MING AUTO CITY

SINGAPORE 575722

~~SKW3333U~~

MENG HUAT

NO: DLI9209377

PAGE: 1

DATE: 20/10/2018

A/C CODE: LDKK241

TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 VSG0 853 651 AJ BTU	FRT GRILLE	VBA-31	1	280.00	280.00
TOTAL QUANTITY:			1	TOTAL	SIN 280.00
				ADD GST @ 7%	19.60
				GRAND TOTAL	<u>SIN 299.60</u>

#02-21

CM
Q

18/10/2018

64001

10-10-18

AKP

Print / MT / 20/10/2018 9:54:08 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729872

TEL: 6385 1255 FAX: 6385 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0118201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988



Dept Direct: 6417 8988





日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

K KIM HIN AUTO PTE LTD

160 SIN MING DRIVE #02-18/19/20/21

SIN MING AUTO CITY

SINGAPORE 575722

TEL: 64527018 MENG FAX: 64583895

ATTN: MENG HUAT

Dept. Direct: 6417 8791 / 8713 9999



Dept. Direct: 6303 9810

Dept. Direct: 6305 9611

Dept. Direct: 6417 9792



Dept. Direct: 6417 8791

Dept. Direct: 6417 9795

Dept. Direct: 6417 9796

Dept. Direct: 6417 9797

Wiper blade:

NWFI (Nippon Wiper blade), Saker (Made in Korea),

Ford (Made in Germany)

Spark plug:

Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201810-13124

DATE : 24/10/2018

CUSTOMER ID : KKI001

VEH REG. NO. : SKN5353U

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	UPRICE	AMOUNT
5G0823186A/L	BONNET TOP CATCH	U1	1	60.00	60.00
		SUPPLIER			

CR
4

Car 18/10/2018
64527018
575722

SUB-TOTAL : 60.00

ADD GST 7.00 % : 4.20

TOTAL AMOUNT SGD : 64.20

[P] 24/10/2018 2:24:34PM

[E] 24/10/2018 2:24:12PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd

Sales Executive ANN



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature

Signature / Co Stamp / Date