



Case Details

Case Reference Number : TAX/10/18/2058

Type of Repair : Accident Repair

Vehicle Registration Number : SHB991J

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-4108-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd

Accident Date and Time : 13/10/2018 12:55 AM

Vehicle Age(In Months) : 10

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval		
					List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair
One Time Key In			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Given
One Time Key In			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Given
One Time Key In			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Given
One Time Key In			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Given
One Time Key In			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Given
One Time Key In			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Given
One Time Key In			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Check
One Time Key In			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Given
One Time Key In			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Given
One Time Key In			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Given
One Time Key In			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Given
One Time Key In			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace
Total Spare Part Cost								1,429.36	Surveyor Total			
Lump Sum Discount (%)								0.00	Lump Sum Dis (%)			
Final Spare Part Cost								1,429.36	Final Sur Total			

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		676.00	200.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	676.00	200	
Total:		676.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
Total:		378.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	TO WASH AND VACUUM	60.00	0	NN
5	TO REPLACE SUNDRY PARTS	100.00	0	NN
Total:		460.00	60.00	

LKF Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,429.36	120.00
Total Labour Cost	676.00	200.00
Total Spray Painting	378.00	200.00
Other	460.00	60.00
Overall Total	2,943.36	580.00
Lump Sum Repair Option		
Lump Sum Total	0.00	580.00
Surveyor Approved Amount		580.00
No of Repair Days*	4	2
Remarks	-	PART BY PART REPAIR. 2 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature	NAZ LKK 15/10/18 1615 PIP 2 DAYS CHECK ITEMS PHOTOS	NM
Survey Date	15/10/2018	AFTER REPAIR PHOTOS

Save

Clear