



Case Details

Case Reference Number : TAX/10/18/2033

Type of Repair : Accident Repair

Vehicle Registration Number : SHB1802R

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-4038-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 08/10/2018 01:25 AM

Vehicle Age(In Months) : 45

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
			Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace ✓ CCA
One Time Key In			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ✓ NPL
One Time Key In			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check ?
One Time Key In			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check ?
One Time Key In			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check ?
One Time Key In			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check ?
One Time Key In			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Given XSVL
One Time Key In			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Given XSVL
One Time Key In			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Given XSVL
One Time Key In			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace ✓ CCA
Total Spare Part Cost								1,783.33		Surveyor Total	834.20	
Lump Sum Discount (%)								20.00		Lump Sum Dis (%)	0	
Final Spare Part Cost								1,426.66		Final Sur Total	834.20	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT RH PORTION	845.00	200	
Total:		845.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	NN
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		260.00	20.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1		80.00	20	
	TO CHECK WIRING AND SYSTEM FUNCTION			
2	TO WASH AND VACUUM	60.00	0	NN
3	TO REMOVE AND REFIT WIRE HARDESS	120.00	0	NN
Total:		260.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,426.66	834.20
Total Labour Cost	845.00	200.00
Total Spray Painting	558.00	200.00
Other	260.00	20.00
Overall Total	3,089.66	1,254.20
Lump Sum Repair Option	☒	☒
Lump Sum Total	3,100.00	1,250.00
Surveyor Approved Amount		1,250.00
No of Repair Days*	4	2
Remarks	-	LUMP SUM REPAIR. 2 DAYS. CHECKED ITEMS PHOTOS. AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature		
		Save Clear
Survey Date	11/10/2018	

NAZ LKK
9/10/18 1115
L/S
2 DAYS

CHECK ITEMS PHOTOS
AFTER REPAIR PHOTOS.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: