



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2008150
INV Date 07/12/2020
Reference CC3/CTI18018867/Kka3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 636A
Insured Veh. GBD 4768Y
Claim No. SNM18D04995/C02
Policy No. DMCVSN3107471600
Accident Date 11/10/2018
Inspection Date 15/10/2018

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18018867/Kka3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-12-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|------------------|-----------------------|------------|
| Insured Veh. | GBD 4768Y | Veh. Inspected | SHD 636A |
| Policy No. | DMCVSN3107471600 | Coverage (\$) | 0.00 |
| Claim No. | SNM18D04995/C02 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 15/10/2018 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|----------------------|---------------------|----------------------|
| Make & Model | RENAULT LATITUDE (A) | c.c | 1995 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | VF1ABL15AUC283390 | Colour | METALLIC WHITE / RED |
| Odometer | 128477 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 215/60 R16 | GITI | 9 mm |
| L/H Front Tyre | 215/60 R16 | GITI | 9 mm |
| R/H Rear Tyre | 215/60 R16 | GITI | 9 mm |
| L/H Rear Tyre | 215/60 R16 | GITI | 9 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 11/10/2018 | Inspection Date | 15/10/2018 |
| Survey held at | TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 2 Working Days |
|-------------------------------------|-----------------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 636A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|----------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | BUMPER COVER REAR | BUCKLED / DENTED | 1,108.46 | 1,108.46 |
| 1 | BUMPER LOWER REAR | DENTED / CRACKED | 768.84 | 768.84 |
| 1 | BUMPER BRACKET CTR REAR | SERVICEABLE | 113.47 | - |
| 1 | BUMPER BRACKET SIDE RH REAR | SERVICEABLE | 135.97 | - |
| 1 | BUMPER RETAINER RH REAR | SERVICEABLE | 44.99 | - |
| 1 | BUMPER REFLECTOR RH | SERVICEABLE | 43.61 | - |
| 1 | BUMPER BRACKET SIDE LH REAR | SERVICEABLE | 135.97 | - |
| 1 | BUMPER RETAINER LH REAR | SERVICEABLE | 44.99 | - |
| 1 | BUMPER REFLECTOR LH | SERVICEABLE | 43.61 | - |
| 1 | BUMPER BEAM REAR | NOT NECESSARY | 777.52 | - |
| 1 | BUMPER BEAM BRACKET LH REAR | TO REPAIR SEE LABOUR | 225.95 | - |
| 1 | BUMPER BEAM BRACKET RH REAR | TO REPAIR SEE LABOUR | 225.95 | - |
| 1 | OUTER PANEL REAR (END PANEL) | TO REPAIR SEE LABOUR | 1,471.77 | - |
| 1 | OUTER PANEL REAR (END PANEL) TRIM | SERVICEABLE | 404.56 | - |
| 1 | TAILLAMP RH | SERVICEABLE | 552.55 | - |
| 1 | TAILLAMP PANEL RH | TO REPAIR SEE LABOUR | 986.70 | - |
| 1 | TAILLAMP LH | SERVICEABLE | 552.55 | - |
| 1 | TAILLAMP PANEL LH | TO REPAIR SEE LABOUR | 986.70 | - |
| 1 | BOOT REAR | TO REPAIR SEE LABOUR | 2,872.68 | - |
| 1 | BOOT FINISHER | SERVICEABLE | 470.06 | - |
| 1 | BOOT WEATHERSTRIP | SERVICEABLE | 323.05 | - |
| 1 | BOOT REFLECTOR LAMP LH | SERVICEABLE | 493.35 | - |
| 1 | BOOT REFLECTOR LAMP RH | SERVICEABLE | 493.35 | - |
| 1 | BOOT BADGE "RENAULT" | NOT NECESSARY | 225.36 | - |
| 1 | BOOT BADGE | NOT NECESSARY | 225.36 | - |

Report Ref No. CC3/CTI18018867/Kka3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| 1 | BOOT STRUT LH | SERVICEABLE | 276.08 | - |
| 1 | BOOT STRUT RH | SERVICEABLE | 276.08 | - |
| 1 | BOOT HINGE LH | TO REPAIR SEE LABOUR | 367.84 | - |
| 1 | BOOT HINGE RH | TO REPAIR SEE LABOUR | 367.84 | - |
| 1 | BOOT INNER TRIM | SERVICEABLE | 586.45 | - |
| 1 | BOOT SWITCH | SERVICEABLE | 168.13 | - |
| 1 | BOOT LOCK | TO REPAIR SEE LABOUR | 202.67 | - |
| 1 | BOOT LOCK CATCH | TO REPAIR SEE LABOUR | 74.40 | - |
| | LESS 10% DISCOUNT | | -1,604.69 | -187.73 |
| | | | 14,442.17 | 1,689.57 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET PARKING AID (SN) | SERVICEABLE | 700.00 | - |
| 1 | SET REAR BUMPER CLIP (SN) | NECESSARY | 66.00 | 66.00 |
| 1 | SET BUMPER BRACKET CTR CLIP (SN) | NECESSARY | 33.00 | 33.00 |
| 1 | SET BUMPER BRACKET SIDE CLIP RH RR (SN) | NOT NECESSARY | 10.00 | - |
| 1 | SET BUMPER RETAINER RH CLIP RR (SN) | NOT NECESSARY | 20.00 | - |
| 1 | SET BUMPER BRACKET SIDE CLIP LH RR (SN) | NOT NECESSARY | 10.00 | - |
| 1 | SET BUMPER RETAINER CLIP LH RR (SN) | NOT NECESSARY | 20.00 | - |
| 1 | SET BUMPER LOWER REAR RIVET (SN) | NOT NECESSARY | 22.00 | - |
| 1 | SET BUMPER LOWER REAR CLIP (SN) | NECESSARY | 66.00 | 66.00 |
| 1 | EXHAUST MOUNTING REAR (SN) | SERVICEABLE | 17.82 | - |
| 2 | REAR WINDSCREEN SEALANT (SN) | NOT NECESSARY | 80.00 | - |
| 1 | WINDSCREEN MOULDING (SN) | NOT NECESSARY | 100.00 | - |
| 1 | REAR WINDSCREEN INNER SPONGE SEAL (SN) | NOT NECESSARY | 100.00 | - |
| | | | 1,244.82 | 165.00 |
| | <u>LABOUR</u> | | | |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 3,000.00 | 220.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL),TAILLAMP PANEL RH,TAILLAMP PANEL LH,BOOT REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK AND BOOT LOCK CATCH. | | 2,200.00 | 200.00 |
| | TO RUST-PROOFING OF THE AFFECTED AREAS. | NOT NECESSARY | 170.00 | - |
| | TO REINSTALL REAR BUMPER PARKING SENSOR. | | 170.00 | 60.00 |
| | TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO REPAIR AND REALIGN REAR EXHAUST PIPE. | NOT NECESSARY | 170.00 | - |
| | TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. | NOT NECESSARY | 170.00 | - |
| | TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. | NOT NECESSARY | 220.00 | - |
| | | | 6,610.00 | 480.00 |
| GRAND TOTAL | | | 22,296.99 | 2,334.57 |
| RECOMMENDED COST OF REPAIRS | | | | 2,334.57 |

Report Ref No. CC3/CTI18018867/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 636A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

