

ASS. REC. BY:

REF:

CS/GA118018875/UH6<sup>72</sup>

Special Instruction:

Surveyor

## ASSIGNMENT (Office)

From (Person):

Sharon Ng

of

GAL

Date/Time:

17/10/2018 558pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 5581D

Insured:

YP 4451Z

at Workshop m/s

Fastech Auto

Tel:

6746 5405.

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

CLMDMVC000003510

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS' WPI

H.O.D. Endorsement:

Date/Time:

17/10/2018

Person Contacted:

Nancy

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLB 5581D - 006 / 07117020620 / Uka3n2

DUA 2610 2017

Signature *no/cus*

REF:

*CAA/*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

*6*

days

Res.: Yes or No

Lum Sum:

*20*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

*LIA 6W72*

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

*SLB5581D*

Yr Regn:

*4 16*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

*Horde vezel*

C.C.

*1496*

Colour

*Black*

A/C:

Insured / Std / NI / NA

Sp. Reading

*36176*

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

*RU11113860*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

*215/60R18*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*have C14*

*30/10/18 1/5 \$7200 confirmed with Acc. (Red: 12/11/18, 62%)*

RECEIVED 31 OCT 2018

Date/Time. File Pass to?

1) *31/10 Typist*

Date/Time. File Return to?

2)

Report Format:

*TP*

Lump Sum / I.B.I. (\$

*7200*

Days Of Repair:

*6*

Resurvey No. of Trip:

*2*

Survey Fee:

Transportation:

) \$ + P5. \$

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

TOTAL

*1450*

## Catherine Chong (LKK Auto)

---

**From:** Ng, Sharon <Sharon.Ng@sg.gaig.com> on behalf of Motor Claims <MotorClaims@sg.gaig.com>  
**Sent:** Wednesday, 17 October, 2018 5:58 PM  
**To:** 'assignments@lkkauto.com'; SUR  
**Subject:** FW: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SLB5581D || GAIC ref: CLMOMVC000003510  
**Attachments:** SLB5581D (MSIG).PDF; YP4951Z (OI).pdf

Dear LKK

Please conduct without prejudice survey to TP vehicle no. SLB5581D at Fastech Auto.

Attached are both accident reports to check on damages consistency.

Regards  
Sharon  
Great American

---

**From:** Nancy Lam <nancy.lam@fastechauto.com.sg>  
**Sent:** Wednesday, October 17, 2018 5:20 PM  
**To:** Motor Claims <MotorClaims@sg.gaig.com>  
**Subject:** [External] RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SLB5581D || GAIC ref: CLMOMVC000003510

WITHOUT PREJUDICE

Dear Sharon

Please arrange LKK Auto Consultants to survey the car.

Regards,  
Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

---

**From:** Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com] On Behalf Of Motor Claims  
**Sent:** Wednesday, October 17, 2018 5:16 PM  
**To:** Nancy Lam <nancy.lam@fastechauto.com.sg>  
**Subject:** RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SLB5581D || GAIC ref: CLMOMVC000003510

WITHOUT PREJUDICE

Dear Nancy

Please forward your client's accident report and furnish the repair estimates.

We may conduct PRI on without prejudice basis, append below is our list of surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Investigation Solutions Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP Knights Pte Ltd

Kindly let us know which SJE is selected.

Regards  
Sharon  
Great American

---

**From:** Nancy Lam <[nancy.lam@fastechauto.com.sg](mailto:nancy.lam@fastechauto.com.sg)>  
**Sent:** Wednesday, October 17, 2018 2:34 PM  
**To:** Motor Claims <[MotorClaims@sg.gaig.com](mailto:MotorClaims@sg.gaig.com)>  
**Subject:** [External] REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SLB5581D

*Hi Sir*

*My client claiming your insured YP 4951Z..*

*Please kindly arrange PRS for SLB 5811L .*

*Date of accident 15.10.2018*

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,  
Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0399N
<b>Vehicle Details</b>	
Vehicle No.:	SLB5581D
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B4033865
Chassis No.:	RU11113860
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,129.00
Original Registration Date:	13 Apr 2016
First Registration Date:	13 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$10,181.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2026
PARF Rebate Amount:	\$7,635.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$34,437.00
<b>Total Rebate Amount:</b>	<b>\$42,072.00</b>

The information contained herein is correct as at 18 Oct 2018

OK

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D SLB5581D

not authorized  
H/W  
H/S \$7200/2  
17/10/18  
6 dy.

## List Item:

1 PCS	REAR WINDSCREEN MOULDING
1 PCS	TAILGATE 953
1 PCS	TAILGATE OUTER HANDLE GARNISH
1 PCS	TAILGATE 'H' LOGO
2 PCS	TAILGATE REFLECTORS @\$280
1 PCS	TAILGATE 'VEZEL' EMBLEM
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE LOCK STRIKER
1 PCS	TAILGATE INNER TRIM BOARD
1 SET	TAILGATE INNER TRIM BOARD CLIPS
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE KEYLESS SENSOR
1 PCS	REAR BUMPER CENTRE
2 PCS	REAR BUMPER SIDES @\$235.10
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.20
2 PCS	REAR BUMPER SCREW SPACERS @\$12
2 PCS	REAR BUMPER REFLECTORS @\$151.20
2 PCS	TAILLAMPS @\$460.60
2 PCS	TAILLAMP HOUSING PANELS @\$195
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR BUMPER LOWER DIFFUSER
1 SET	REAR BUMPER LOWER DIFFUSER CLIPS
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$45
1 PCS	REAR EXHAUST HEAT SHIELD
2 PCS	REAR FENDER INNER TRIMS @\$295.30
1 SET	REAR FENDER INNER TRIM CLIPS
2 PCS	REAR FENDER OUTER GARNISH @\$195.80
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOOLS SPONGE
2 PCS	REAR FENDERS @\$1100

List Item Total:

## Special Nett Item:

1 SET	REAR BUMPER REVERSER SENSOR
1 PCS	REAR REVERSE CAMERA
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR FLOOR PANEL INSULATOPR

Special Nett Total:

## Labour Charge:

TO CHECK WIRING

neu	\$	121.30	/
3edg	\$	1,100.90	/
cna	\$	285.30	/
neu	\$	35.80	/
cne	\$	560.00	/
neu	\$	56.20	/
3ed/shoth	\$	198.50	/
11	\$	25.50	X
de/cne	\$	321.70	/
neu	\$	50.00	/
4w1	\$	135.70	/
cne	\$	180.00	/
m/pe	\$	762.70	/
m/ston	\$	470.20	pc
11	\$	70.40	X
11	\$	24.00	X
m/ston	\$	302.40	lpc
cne	\$	921.20	/
n	\$	390.00	X
3edg	\$	514.00	/
4w1	\$	125.00	/
de/4w1	\$	348.20	/
neu	\$	50.00	/
11	\$	899.20	X
11	\$	90.00	X
11	\$	98.30	X
de/cne	\$	590.60	/
11	\$	50.00	X
m/ston	\$	391.60	lpc
n	\$	912.30	X
m/pe	\$	685.00	/
n	\$	2,200.00	X
	\$	12,966.00	

(20%)

7476.3  
8981.04

short	\$	280.00	200
short	\$	500.00	350
neu	\$	50.00	40
neu	\$	50.00	/
11	\$	180.00	X
	\$	1,060.00	

\$ 80.00 30

TO DISMANTLE & REPLACE REVERSE SENSOR	\$ 80.00	50
TO TRANSFER TAILGATE MECHANISM	\$ 100.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN	\$ 150.00	120
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$ 150.00	80
TO DISMANTLE & REPLACE REAR EXHAUST	11 \$ 100.00	X
TO SPRAY RUST PROOFING	\$ 150.00	80
TO MOUNT VEHICLE ON CAR O-LINER	11 \$ 380.00	X
TO DISMANTLE & REFIX PETROL TANK	11 \$ 100.00	X
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	\$ 2,000.00	1000
TO PUTTY & SPRAY PAINTING	\$ 2,000.00	1000
Labour Charge Total:	\$ 5,290.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 19,316.00

9046.04  
723~

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18018875/Utbn2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 05-11-2018		
		Code : GAI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YP 4951Z	Veh. Inspected	SLB 5581D	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003510	Excess (\$)	0.00	
Assign From	SHARON NG	Assign Date	17/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11113860	Colour	BLACK	
Odometer	36176	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	7 mm	
L/H Front Tyre	215/60 R16	DUNLOP	7 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/10/2018	Inspection Date	17/10/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 5581D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR WINDSCREEN MOULDING	NECESSARY	121.30	121.30
1	TAILGATE	BADLY DENTED	1,100.90	953.00
1	TAILGATE OUTER HANDLE GARNISH	CRACKED	285.30	285.30
1	TAILGATE "H" LOGO	NECESSARY	35.80	35.80
2	TAILGATE REFLECTORS @\$280.00	CRACKED	560.00	560.00
1	TAILGATE "VEZEL" EMBLEM	NECESSARY	56.20	56.20
1	TAILGATE INNER LOCK	BENT / SHORTED	198.50	198.50
1	TAILGATE LOCK STRIKER	NOT NECESSARY	25.50	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	321.70	321.70
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE WEATHERSTRIP	TWISTED	135.70	135.70
1	TAILGATE KEYLESS SENSOR	CRACKED	180.00	180.00
1	REAR BUMPER CENTRE	DENTED / DEFORMED	762.70	762.70
2	REAR BUMPER SIDES @\$235.10	N/S DENTED	470.20	235.10
2	REAR BUMPER SIDE RETAINERS @\$35.20	NOT NECESSARY	70.40	-
2	REAR BUMPER SCREW SPACERS @\$12.00	NOT NECESSARY	24.00	-
2	REAR BUMPER REFLECTORS @\$151.20	N/S CRACKED	302.40	151.20
2	TAILLAMPS @\$460.60	CRACKED	921.20	921.20
2	TAILLAMP HOUSING PANELS @\$195.00	TO REPAIR SEE LABOUR	390.00	-
1	REAR END PANEL	BADLY DENTED	514.00	514.00
1	REAR END PANEL TOP GARNISH	TWISTED	125.00	125.00
1	REAR BUMPER LOWER DIFFUSER	DEFORMED / TWISTED	348.20	348.20
1	SET REAR BUMPER LOWER DIFFUSER CLIPS	NECESSARY	50.00	50.00
1	REAR EXHAUST	NOT NECESSARY	899.20	-
2	REAR EXHAUST MOUNTINGS @\$45.00	NOT NECESSARY	90.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	98.30	-
2	REAR FENDER INNER TRIMS @\$295.30	DEFORMED / CRACKED	590.60	590.60

Report Ref No. CS/GAI18018875/Utn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER INNER TRIM CLIPS	NOT NECESSARY	50.00	-
2	REAR FENDER OUTER GARNISH @\$195.80	N/S TORN	391.60	195.80
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	912.30	-
1	REAR FLOOR PANEL TOOLS SPONGE	DENTED / DEFORMED	685.00	685.00
2	REAR FENDERS @\$1100.00	TO REPAIR SEE LABOUR	2,200.00	-
	LESS 20% DISCOUNT		-	-1,495.26
			12,966.00	5,981.04
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR REVERSE CAMERA (SN)	SHORTED	500.00	350.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	180.00	-
			1,060.00	640.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACE REVERSE SENSOR.		80.00	50.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REPLACE REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		150.00	80.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS,REAR FLOOR PANEL AND REAR FENDERS.		2,000.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		2,000.00	1,000.00
			5,290.00	2,420.00
	<b>GRAND TOTAL</b>		<b>19,316.00</b>	<b>9,041.04</b>

Report Ref No. CS/GAI18018875/Utn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,200.00
---	--	--	----------

Report Ref No. CS/GAI18018875/Utbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.