

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18018884/KRS3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800056711

Claimant
Vehicle No : SJL5567S **Insured Vehicle No :** SMA1225C

Date of Loss: 13/10/2018 Nature of Claim: TP Claim No: 0392438680SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL5567S	Engine No:	3ZZ4811291
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106123458
Reg. Date:	02/12/2008 (Man. Year: 2008)	Odometer:	219799 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Presa 9 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Presa 9 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,840.87	3,771.97	2,068.90	35.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	2,220.00	1,090.00	32.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,150.87	5,991.97	3,158.90	34.52
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	9,150.87	1,500.00	7,650.87	83.61
+ GST 7.00/7.00% (S\$)	640.56	105.00	535.56	83.61
Nett Amount (S\$)	9,791.43	1,605.00	8,186.43	83.61
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		2,534.80		

INSPECTION

Date of Assignment: 16/10/2018

Date Inspected: 17/10/2018 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,
#01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Bent	792.00 FL	*792.00 FL
2	2		*BOOT HINGES	Repair	143.60 FL	*- FL
3	1		*BOOT CENTER EMBLEM	Necessary	57.40 FL	*57.40 FL
4	1		*BOOT BADGE 1.6	Necessary	42.20 FL	*42.20 FL
5	1		*BOOT BADGE COROLLA	Necessary	46.50 FL	*46.50 FL
6	1		*BOOT BADGE ALTIS	Necessary	48.20 FL	*48.20 FL
7	1		*BOOT OUTER MOULDING	Serviceable	239.00 FL	*- FL
8	1		*BOOT LAMP LH	Cut	185.00 FL	*185.00 FL
9	1		*BOOT LOCK	Dented	106.00 FL	*106.00 FL
10	1		*BOOT LOCK CATCH	Distorted	32.00 FL	*32.00 FL
11	2		*BOOT STOPPERS	Serviceable	20.60 FL	*- FL
12	1		*BOOT TRIM BOARD	Cracked	282.00 FL	*282.00 FL
13	10		*BOOT TRIM BOARD CLIPS	Necessary	38.00 FL	*38.00 FL
14	1		*BOOT WEATHERSTRIP (50%)	Cut	143.25 FS	*95.50 FS
15	1		*REAR BUMPER	Bent	495.00 FL	*495.00 FL
16	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
17	1		*REAR BUMPER BRACKETS	N/S Bent	175.00 FL	*87.50 FL
18	1		*REAR BUMPER SPONGE	Cracked	129.00 FL	*129.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Repair	315.00 FL	*- FL
20	1		*REAR BUMPER TOP RETAINERS	N/S Distorted	158.00 FL	*79.00 FL
21	1		*REAR BUMPER REFLECTOR LH	Serviceable	37.00 FL	*- FL
22	1		*REAR BUMPER CORNER HOLDERS	N/S Distorted	147.00 FL	*73.50 FL
23	2		*TAILLAMPS ASSY	Cracked	772.00 FL	*772.00 FL
24	1		*END PANEL	Bent	607.00 FL	*607.00 FL
25	1		*END PANEL GARNISH	Mtg Distorted	203.00 FL	*203.00 FL
26	1		*SPARE TYRE PANEL	Repair	763.00 FL	*- FL
27	1		*SPARE TYRE TOP BOARD	Dented	362.00 FL	*362.00 FL
28	2		*REAR FENDER TRIM BOARDS	Serviceable	690.00 FL	*- FL
29	1		*REAR BUMPER REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
30	1		*REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS
31	1		*ROADSIDE TRIANGLE	Cracked	75.00 FS	*75.00 FS
32	1		*PORTABLE VACCUM CLEANER	Not Necessary	105.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,571.75	4,890.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,730.88	1,118.83
Total Parts (S\$)	5,840.87	3,771.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /REFIT BOOT FITTINGS /ANCILLARY ACCESSORIES	New	80.00	50.00
2	TO CONDUCT ELECTRICAL CHECK ,REPLACE ,REVERSE SENSORS ,MODULE REWIRING ETC	New	120.00	70.00
3	TO SUPPLY END PANEL JOINT SEALANT	New	60.00	30.00
4	TO DISMANTLE /TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS /GARNISH AND REAR FENDERS INNER TRIMS BOARD /GARNISH TO FACILITATE REPAIR	New	80.00	60.00
5	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED /REPAIR PANEL	New	100.00	60.00
6	TO PROVIDE TRANSPORATION (TOWING)	New	70.00	50.00
7	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF REAR CHASSIS MEMBER ,INNER PANEL,SPARE TYRE PANEL,REAR LH FENDER ,FLOOR PANEL,CNT,WELD END PANEL AND PARTS REPLACEMENT	New	1,400.00	900.00
8	TO RESPRAY AFFECTED AREAS BOOT ,BUMPER ,END PANE,SPARE TYRE PANEL ,TAILLAMP PANEL *2 ,FENDERS	New	1,400.00	1,000.00
Gross Labour Cost (\$\$)			3,310.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >