



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 4299A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	SERVICEABLE	497.50	-
10	REAR BUMPER CLIP (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	112.70	-
1	REAR BUMPER LOWER GARNISH CENTRE (CONSISTENT)	TO REPAIR SEE LABOUR	582.60	-
1	REAR BUMPER LOWER GARNISH RH (CONSISTENT)	TO REPAIR SEE LABOUR	149.70	-
	LESS 25% DISCOUNT		-345.63	-
			1,036.87	-
	<b><u>LABOUR</u></b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,RHR FENDER).INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER GARNISH CENTRE AND REAR BUMPER LOWER GARNISH RH.		600.00	300.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,RHR FENDER)		600.00	400.00
	TO CHECK WIRING.		50.00	15.00
	TO TUFF COAT.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT REVERSE SENSOR.	NOT NECESSARY	120.00	-
			1,420.00	715.00
<b>GRAND TOTAL</b>			<b>2,456.87</b>	<b>715.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>715.00</b>

Report Ref No. CC4/ASM18018910/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.