



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates		S	LV 5069 L
Parts	(a) Cost / List Price Items	\$	11,306.33
	Plus/Less25%	\$	2,826.58
	Total of Cost / List	\$	8,479.75
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	804.20
Total I	Parts Cost	\$	9,283.95
Labou	r	\$	3,950.00
Total		\$	13,233.95

Not lochante Rehmy Bapaing

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: Date:

Name of Surveyor	:	Kennerh
Company		6 K/c
Survey conducted on	:	16710/18at
Remarks By Surveyor		
(a) The repair of this vehicle is auth	orized	/ is not authorized until further notice.
(b) Recommended Days of Repair	:	day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:\$_	
(e) Signature of surveyor	:	



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

#### **Spare Parts**

Vehicle No. Make & Model: Chassis No

**SLV 5069 L** 

TOYOTA CHR ZYX102085469

Submit By

Year Manufacture

Carmen Lim

2017

Engine No. Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	Ry	1	\$45.00	S.N	
2	Front number plate garnish	nel	1	\$89.70		-
3	Front grille		1	\$422.92		7
4	Front grille emblem		1	\$1,641.20		7
5	Front bumper		1	\$441.90		1
6	Front bumper clip		10	\$40.00		7
7	Front bumper reinforcement		1	\$487.30		7
8	Front bumper side retainer LH		1	\$123.90		X
9	Front bumper side retainer RH		1	\$123.90		X
10	Front bumper bracket LH	7	1	\$201.50		×
11	Front bumper bracket RH	n	1	\$201.50		X
12	Front bumper sponge		1	\$89.50		7
13	Front bumper sensor	Ph	2	\$379.60	S.N	X
14	Front bumper lower grille		1	\$494.20		7
15	Reverse sensor		2	\$379.60	S.N	7
16	Rear bumper	Bu	1	\$398.30		
17	Rear bumper clip	h	10	\$40.00		
18	Rear bumper side retainer LH	2	1	\$97.80		X
19	Rear bumper side retainer RH	Ju	1	\$97.80		X
20	Rear bumper bracket LH		1	\$122.67		7
21	Rear bumper bracket RH		1	\$122.67		7
22	Rear bumper reinforcement		1	\$398.90		7
23	Rear bumper reflector LH	Su	1	\$62.30		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

#### **Spare Parts**

Vehicle No. : Make & Model :

Chassis No :

SLV 5069 L

TOYOTA CHR ZYX102085469 Submit By : Year Manufacture :

Carmen Lim 2017

Engine No.

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
24	Rear bumper reflector RH	Sn	1	\$62.30		X
25	Rear bumper reflector garnish LH	Sh	1	\$108.70		×
26	Rear bumper reflector garnish RH	2	1	\$108.70		X
27	Rear bumper lower garnish Centre	cni	1	\$397.60		
28	Rear bumper tow cover	ne	1 1	\$21.69		
29	Tail door	R	1	\$1,022.50		
30	Tail door lock	1	7 1	\$478.40		X
31	Tail door emblem	Na	1	\$61.70		
32	Wording "CH-R"	Na	1	\$51.36		_
33	Wording "HYBRID"	Na	1	\$49.87		
34	Tail door garnish		1	\$882.70		?
35	Taildoor reflector LH	32	1	\$486.70		×
36	Taildoor reflector RH	Su	1	\$489.70		×
37	Tail end panel		1	\$701.25		7
38	Tail end panel garnish		1	\$295.50		7
39	Tail end panel garnish clip		8	\$28.00		7
40	Boot weatherstrip	Su	1	\$361.70		X
41						
42						
43						
44						
45						
46						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## **ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

#### Labour

Vehicle No.	:	SLV 5069 L	Submit By :	Carmen Lim	
Make & Model	: -	TOYOTA CHR	Year of Manufacture:	2017	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL,		
	SPARE TYRE WELL PANEL) (600) (800)	\$1,600.00	?
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL,		0
-	SPARE TYRE WELL PANEL)	\$1,400.00	9001
3	To check wiring	\$50.00	201
4	To remove & refit front bumper sensor	\$120.00	501
5	To remove & refit rear bumper sensor	\$120.00	501
6	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	?
7	To remove & refit rear windscreen.	\$120.00	
8	To tuff coat.	\$150.00	?
9	To transfer boot mechanism to new boot	\$120.00	601
10	To conduct water leakage tests to ensure proper air and		
	sealing	\$120.00	201

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.