

22/03/2002

ASS. REC. BY:

REF: CS/SMO18018940/K+d3n2 Special Instruction:

Survivor:
menmen

Kenneth

ASSIGNMENT (Office)

From (Person): Chan Shu Hui Agnes of SMO Date/Time: 18/10/18 @ 11-08am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8LJ 871H Insured: SGH 1578T

at Workshop m/s Complete VMS Tel: 6455 0012

of 176 Sin Ming Drive # 03-14

Policy No: D18MTPV0100 9173 Claim No: CMTP1804543

Sum Insured: Excess:

Make of Veh: D.O.A. 17/10/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 1 WP

H.O.D. Endorsement:

Date/Time: 11:11am @ 17/10/18 Person Contacted: Li Hui Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	8LJ 871H-X
	SGH 1578T-NA-INC16014932/Cr3 DoA: 10/08/16
27/10	Perfected preli advise via menmen
31/12	11Lm 836001 Cabins (Red: 255684:46%)

REF: SMO

ASSIGNMENT

From:

Date:

18/10/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLJ 871 H

at Workshop m/s

Complete VMS

of

176 Sin Ming Drive # 03-14

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLJ 871 H

Yr Regn:

11 / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV

c.c.

1496

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

22417

T/Radio:

Insured / Std / NI / NA

Eng/No:

17

C/No:

JMRU1830GX200974

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

4

mm

L/Bal.

6

mm

L/Bal.

4

mm

D.O.A.

17/10/18

D.O.I.

18/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/10 File pass to Catherine

RECEIVED 31 DEC 2018

Date/Time, File Pass to?



Preli. Report

1) 31/12 Typist



Final Report

Date/Time, File Return to?

2)

Tp

Report Format:

Lump Sum / I.B.I: (\$ 3600)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

10

260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 22 Oct 2018

Preliminary Advice

Insured Vehicle No	: SGH1578T	Accident Date	: 17/10/2018
TP Vehicle No	: SLJ871H	Assignment Date	: 18/10/2018
Make	:	Est. Duration of Repair	: 5.00
Date of Inspection	: 18/10/2018		
Inspection At	: COMPLETE VMS PTE LTD (HQ) 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,492.04
Revised Amount	:S\$	2,639.28
Check Items (Estimated)	:S\$	690.96
Total	:S\$	3,330.24
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	17 Oct 2018		18 Oct 2018 11:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	IN THE ESTATE OF MELIANA KOHAR WIJAYA, ID: S2195828Z		
Main Claimant:	CHAN WAI LEONG		
Vehicle Reg. No.:	SLJ871H	Date of Loss:	17/10/2018 09:00 - :59
Claim Type:	TP / CMTD1804543	Policy/Cover Note No.:	D18MTPV01009173 (Comprehensive)
Vehicle Reg. No. (Insured):	SGH1578T	Policy No. (Claimant):	
		Excess:	
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/10/2018]		
Adj. Asg. Remarks:	Please assign case to Mr Kenneth Kong		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHAN WAI LEONG
BLK 33 CHAI CHEE AVE #03-244
SINGAPORE 461033

Attention : THE OWNER

Contact : 97739196

Estimate : ES006479

Date : 17/10/2018

Vehicle Num. : SLJ871H

Make/Model : HONDA HRV 1.5-2016

Chassis/Eng# : JHMRU1830GX200974/L15B4530974

Accident Date : 17/10/2018

Claim No. :

Reference :

Policy No. :

Not Notified

Recovery B4 pain

4-5 days

83600

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | |
|-----|---|-----------------------------|
| 1. | 1 | LIST ITEMS : |
| 2. | 1 | TAIL GATE |
| 3. | 1 | TAIL GATE LOCK |
| 4. | 1 | HRV EMBLEM |
| 5. | 1 | IVTEC EMBLEM |
| 6. | 1 | H LOGO |
| 7. | 2 | REAR W/SCREEN MOULDING SIDE |
| 8. | 1 | REAR W/SCREEN MOULDING TOP |
| 9. | 1 | REAR END PANEL |
| 10. | 1 | REAR END PANEL TOP GARNISH |
| 11. | 1 | BOOT WEATHERSTRIP |
| 12. | 6 | REAR BUMPER |
| 13. | 2 | REAR BUMPER CLIP |
| | | REAR BUMPER BRACKET |

List TotalS\$:

20.00% Discount S\$:

- | | | |
|----|---|-----------------------|
| 1. | 1 | SPECIAL NETT ITEMS : |
| 2. | 1 | REAR W/SCREEN SEALANT |
| | | REVERSE SENSOR |

Special Nett Total S\$:

LABOUR :

REMOVE & REINSTALL REAR W/SCREEN GLASS
TRANSFER TAILGATE COMPONENT TO NEW GATE
RUST PROOFING TREATMENT

Bt	1,160.90	✓
✓	189.50	x
✓	37.00	✓
✓	45.10	✓
✓	34.70	x
✓	51.80	✓
✓	103.60	✓
✓	71.90	✓
✓	395.70	✓
✓	118.00	✓
✓	96.80	x
✓	782.70	✓
✓	5.90	✓
✓	37.50	✓
✓	75.00	✓

3,146.30

629.26

2,517.04

✓	65.00	✓
✓	280.00	✓
✓	345.00	✓

345.00

1201	180.00	✓
601	150.00	✓
301	100.00	✓

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHAN WAI LEONG
BLK 33 CHAI CHEE AVE #03-244
SINGAPORE 461033

Attention : THE OWNER
Contact : 97739196

Estimate : ES006479

Date : 17/10/2018
Vehicle Num. : SLJ871H
Make/Model : HONDA HRV 1.5-2016
Chassis/Eng# : JHMRU1830GX200974/L15B4530974
Accident Date : 17/10/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPRAY PAINT DAMAGED AREA AFFECTED		1,100.00 <i>tool</i>
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR		
		CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		1,100.00 <i>tool</i>
		Labour Total S\$:		2,630.00

SingDollars : Five Thousand Four Hundred Ninety-Two & Cents Four Only

Total S\$: 5,492.04
=====

6156.04

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHAN WAI LEONG
BLK 33 CHAI CHEE AVE #03-244
SINGAPORE 461033

Attention : THE OWNER
Contact : 97739196

Supplementary Estimate : ES006482

Date : 19/10/2018
Vehicle Num. : SLJ871H
Make/Model : HONDA HRV 1.5-2016
Chassis/Eng# : JHMRU1830GX200974/L15B4530974
Accident Date : 19/10/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|-----------------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | SPARE TIRE COMPARTMENT SPONGE | | |
| 3. | 1 | SPARE TIRE OUTER COVER | | |
| 4. | 1 | REAR END PANEL ANTENNA KEY SENSOR | | |
| | | REAR END PANEL BUZZER | | |

List TotalS\$:
20.00% Discount S\$:

CM	275.00	—
CM	205.00	—
CM	182.00	—
CM	169.00	—
	831.00	
	166.20	
	664.80	

part. # 2200-24
SN # 240-00
Supply # 664.80
Labour # 1510-00
4615-00
48 # 3700-00
=

SingDollars : Six Hundred Sixty-Four & Cents Eighty Only

Total S\$: 664.80
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18018940/KTD3N2

Date: 02/01/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01009173
Claimant Vehicle No :	SLJ871H	Insured Vehicle No :	SGH1578T
Date of Loss:	17/10/2018	Nature of Claim:	TP
		Claim No:	CMTD1804543

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ871H	Engine No:	L15B4530974
Make & Model:	HONDA HR-V, 1.5 LX CVT (A)	Chassis No:	JHMRU1830GX200974
Reg. Date:	28/11/2016 (Man. Year: 2016)	Odometer:	22417 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,526.84	3,105.04	421.80	11.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,410.00	1,220.00	46.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,156.84	4,515.04	1,641.80	26.67
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	6,156.84	3,600.00	2,556.84	41.53
+ GST 7.00/7.00% (S\$)	430.98	252.00	178.98	41.53
Nett Amount (S\$)	6,587.82	3,852.00	2,735.82	41.53

INSPECTION

Date of Assignment: 18/10/2018

Date Inspected: 18/10/2018 Inspected At:

COMPLETE VMS PTE LTD (HQ)
176 Sin Ming Drive #03-14 Sin Ming
Autocare Complex
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jan 2019)	
Parts:	N/A	HONDA HR-V 1.5 LX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ871H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,160.90 FL	*1,160.90 FL
2	1		*TAIL GATE LOCK	Repair	189.50 FL	*- FL
3	1		*HRV EMBLEM	Necessary	37.00 FL	*37.00 FL
4	1		*IVTEC EMBLEM	Necessary	45.10 FL	*45.10 FL
5	1		*H LOGO	Not Necessary	34.70 FL	*- FL
6	2		*REAR W/SCREEN MOULDING SIDE	Necessary	103.60 FL	*103.60 FL
7	1		*REAR W/SCREEN MOULDING TOP	Necessary	71.90 FL	*71.90 FL
8	1		*REAR END PANEL	Bent	395.70 FL	*395.70 FL
9	1		*REAR END PANEL TOP GARNISH	Mtg Distorted	118.00 FL	*118.00 FL
10	1		*BOOT WEATHERSTRIP	Serviceable	96.80 FL	*- FL
11	1		*REAR BUMPER	Buckled	782.70 FL	*782.70 FL
12	6		*REAR BUMPER CLIP	Necessary	35.40 FL	*35.40 FL
13	2		*REAR BUMPER BRACKET	Repair	75.00 FL	*- FL
14	1		*SPARE TIRE COMPARTMENT SPONGE	Cracked	275.00 FL	*275.00 FL
15	1		*SPARE TIRE OUTER COVER	Cracked	205.00 FL	*205.00 FL
16	1		*REAR END PANEL ANTENNA KEY SENSOR	Cracked	182.00 FL	*182.00 FL
17	1		*REAR END PANEL BUZZER	Cracked	169.00 FL	*169.00 FL
18	1		*REAR W/SCREEN SEALANT	Necessary	65.00 FS	*40.00 FS
19	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,322.30	3,821.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	795.46	716.26
Total Parts (\$\$)	3,526.84	3,105.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL REAR W/SCREEN GLASS	New	180.00	120.00
2	RUST PROOFING TREATMENT	New	100.00	30.00
3	TRANSFER TAILGATE COMPONENT TO NEW GATE	New	150.00	60.00
4	SPRAY PAINT DAMAGED AREA AFFECTED	New	1,100.00	600.00
5	TO CUT OFF REAR END PANEL,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	New	1,100.00	600.00
Gross Labour Cost (S\$)			2,630.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >