



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 1915Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BUMPER (LOWER) (CONSISTENT)	CUT	395.00	395.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	691.00	-
1	REAR BUMPER REVERSE LAMP (CONSISTENT)	NOT NECESSARY	166.00	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	621.00	-
1	REVERSE SENSOR (CONSISTENT)	DAMAGED	172.00	172.00
	LESS 10% DISCOUNT		-204.50	-56.70
			1,840.50	510.30
	<b>LABOUR</b>			
	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		550.00	200.00
	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION .		450.00	200.00
			1,000.00	400.00
	<b>GRAND TOTAL</b>		<b>2,840.50</b>	<b>910.30</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>700.00</b>

Report Ref No. CC4/ASM18018972/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.