
































2










GBA5383H [SLJ2282U] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



1/32: Chassis Number



2/32: Odometer Reading



3/32: Inspection Photo



4/32: Inspection Photo

GBA5383H [SLJ2282U] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



5/32: Inspection Photo



6/32: Inspection Photo



7/32: Inspection Photo



8/32: Inspection Photo

GBA5383H [SLJ2282U] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



9/32: Inspection Photo



10/32: Inspection Photo



11/32: Inspection Photo




12/32: Inspection Photo

GBA5383H (SLJ2282UI - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/32: Inspection Photo



14/32: Inspection Photo



15/32: Inspection Photo




16/32: Inspection Photo

GBA5383H [SLJ2282U] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



17/32: Inspection Photo



18/32: Inspection Photo



19/32: Inspection Photo



20/32: Inspection Photo

GBA5383H [SLJ2282U] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



21/32: Inspection Photo



22/32: Inspection Photo



23/32: Inspection Photo




24/32: Inspection Photo


GBA5383H [SLJ2282U] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



25/32: Inspection Photo



26/32: Inspection Photo




27/32: Inspection Photo



28/32: Inspection Photo

GBA5383H [SLJ2282U] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)




29/32: Inspection Photo



30/32: Inspection Photo



31/32: Inspection Photo



32/32: Inspection Photo