

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 26 Oct 2018

Preliminary Advice

Vehicle No	: SLF8488A	Accident Date	: 08/10/2018
Make	: TOYOTA SIENTA	Policy No.	: PNPV2018-00011312
Assignment Date	: 19/10/2018	Excess	: S\$500.00
Date of Inspection	: 25/10/2018	Est. Duration of Repair	: 5.00
Inspection At	: DYNAMIC AUTOWORK PTE. LTD (HQ) 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,779.00
Revised Amount	:S\$	3,712.15
Check Items (Estimated)	:S\$	7,611.04
Total	:S\$	11,323.19
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	48,600.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,400.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair using list price on Lump Sum basis.