	REF: Independent	CS/TP1801	9087/Rlvbn2	62532.	• •
Birrent Loque		ASSIGNMENT			ма
	_		SHO 23085	Yr Regn. 2016 / M	14
2 - 110	Date: 19-10-2018	Veh No.	M,Cycle / Bus / Van / Lorry	/ Laxi / Prime Mover /	
From:		Type w.our r	Trailer of		
Estimated Cost:	n RESTEVATINVIMV	1 ruck /	Toyoth venerale 2	5× 00 2453	
	SHD 2308J	Make:	Oyour occurred	OF Marie Control of the Control of t	NA
To Inspect Vehicle No:	Prime Auto	Colour	274980	T/Radio: Insured / Std / NI	NA NA
at Workshop m/s	6 Benvi Place	Sp.Reading	714100		
of	P Dales	Eng/No:		48	
Insured		G/No:	A44300020	()	
Policy No.		Gen. Gond:	Good Poor / Burnt		
Claims No.	Constitution of the Consti	Steering: M	order / Jammed / Leaked /	Burnt or	
Sum Insured:	Excess:	Brake: M	forder / Jammed / Leaked	Burnt or	
(Client's Record)		Modi Ni	ILL SEIN / STD A/Rim O	r _	
Make of Veh:		Tyre Size:	F: 215	breit .	
	3pm		D.	۸٠.	
(Policy Condition)		1	LEVNOVA LGY LEST LIZA	A / MIC / OHTSU / PIR / SUM	VI
Remark: The veh had	commenced its N/S			SOME	
repair at the	time of inspection.	TOYOT	YOKO or Q	Rear	
	18	Front	_	R/Bal. 6	mm
Bal. or Market Value:	Consistent? : Yes or No	R/Bal.	6 mm	L/Bal. 6	mm
IDAC Accident Rport:	Consistent? : Yes or No	L/Bal.	6 mm	D.O.I. 19/10/1	8
GIA / PR Seen:	Dec. Ves or No		17/18/18		
Est. Repairs:	aud Ves or No	* Property Company	held at PR	IME AUTO	or
Lum Sum:	% 3 Val., Tes of III	Des. of	Damages B Lear / O	DIS NIS UIC Rooftop	301
CA / REV / RE	P. / 24 HRS				
	Person Contacted:	The	U/C / Chassis frame / E	Body Structure affected due	
Date:	C - (Instruction			DOG: 18-10-2007	
Date / Time A	HD 2308J - CS/INCOGUTE	old /Gprl		The state of the s	
			las vaosis		
3/11/15	1123am Alice said x	ehicle Still U	moka jetem		
11,118	LS \$18,700 CONTIN	1 6	(Red 17.654	4.48, 4819	
1 8/11/21	LS \$18,700 CONTIN	red by enem	0. 1		
istuite	CEIVE	D 1 3 NOV 201	8		
	RECEIVE	D 1 3 HOLES	2018		
	RECE	IVED 1 9 HOL	7010		26×15=3
Park Park	: Preli. Report		Of Repair: 17	Survey Fee:	170+39
Date/Time, File Pass	Final Report	Resu	rvey No. of Trip:	Transportation:	50
1)			7)S+R5SI	50
Date/Time, File Retu		Add Fee:	Site Insp (\$) Photos (S)	72
2) 13/11 - 3	typist		Interview (\$		80
			Tech Invs (\$) Others (1/1/8	
Report Form		Γ	: Weekend (\$	1 11	812
Lump Sum /	11.B.1; (\$ 18, 700)	, limited		TOTAL	1012

Veron Chen (LKKAuto)

From:

Alice Leong <aliceleong@primeautoclaims.com>

Sent:

Monday, 12 November 2018 12:49 PM Veron Chen (LKKAuto); Rasul (LKKAuto)

To: Cc:

Subject:

RE: FINALISE TO SHD2308J

Importance:

High

Hi Veron,

We confirm your below amount.

Thank you

Alice Leong

Manager, Motor Claims

Prime Auto Claims Service Pte Ltd 6 Benoi Place Singapore 629927 T (65): 6861 0908 1 F (65) 6515 2948 HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: 12 November, 2018 12:25 PM

To: Alice Leong <aliceleong@primeautoclaims.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: FINALISE TO SHD2308J

Dear Alice,

WITHOUT PREJUDICE

Base on our calulation

List \$24,135.68 (less 25%)= \$18,101.76

Special Nett

\$235

Labour

\$ 5160

Offer Lump Sum \$ 18,700 @ 17 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong <a include a liceleong@primeautoclaims.com>

Sent: Friday, 9 November 2018 12:23 PM To: Rasul (LKKAuto) < Rasul@lkkauto.com>

Cc: SUR <sur@lkkauto.com> Subject: FINALISE TO SHD2308J

Importance: High

Hi Rasul,

We enclosed our before & after repair photos & our calculation sheet for your retention. Shall we finalize at LS \$19,050/- and 17 days

Please let us have your confirmation within three days from our e-mail. (Independent survey Malaysia case)

Thank you

Alice Leong

Manager, Motor Claims

Prime Auto Claims Service Pte Ltd 6 Benoi Place Singapore 629927 T (65): 6861 0908 1 F (65) 6515 2948 HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

> Back to OneMotoring

ehicle Owner Particulars	A 10000000
wner ID Type:	Company
wner ID: ehicle Details	6293Z
ehicle No.:	SHD2308J
ehicle to be Exported:	No
ntended Deregistration Date:	22 Oct 2018
ehicle Make:	TOYOTA
ehicle Model:	VELLFIRE HYBRID 2.5X CVT
rimary Colour:	White
fanufacturing Year:	2015
ngine No.:	2ARH659700
hassis No.:	AYH300022045
Maximum Power Output:	145.0 kW (194 bhp)
)pen Market Value:	\$40,822.00
Original Registration Date:	23 May 2016
First Registration Date:	23 May 2016
ransfer Count:	0
Actual ARF Paid: ntended PARF Rebate Details	\$41,651.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2024
PARF Rebate Amount: Intended COE Rebate Details	\$31,238.00
COE Expiry Date:	22 May 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,463.00
COE Rebate Amount:	\$25,448.00
Total Rebate Amount:	\$56,686.00
Message Please note that the 8-year COE for this vehicle cannot the vehicle reaches its statutory lifespan (if applicable)	ot be further renewed. The vehicle must be de-registered upon COE expiry or when a), whichever is earlier.

The information contained herein is correct as at 22 Oct 2018

OK

> Back to OneMotoring

quire Transfer Fee /ehicle Details			
/ehicle No.:	SHD2308J		
Vehicle Type:	H11 - Public Transport Taxi (Station Wagon)		
Vehicle Attachment 1 :	Air-Con (Taxi)		
Vehicle Scheme :	Taxi (Company)		
Vehicle Make :	TOYOTA		
Vehicle Model:	VELLFIRE HYBRID 2.5X CVT		
Chassis No.:	AYH300022045		
Propellant:	Petrol-Electric		
Engine No. :	2ARH659700		
Motor No.:	2JM2FM659700		
Engine Capacity:	2493 cc		
Power Rating:	155.0 kW		
Maximum Power Output:	145.0 kW (194 bhp)		
Maximum Laden Weight:	2495 kg		
Unladen Weight :	2110 kg	0.00	
Year Of Manufacture:	2015		
Original Registration Date :	23 May 2016		
Lifespan Expiry Date :	22 May 2024		
COE Category:	A - Car up to 1600cc & 97kW (130bhp)		
PQP Paid:	\$36,463.00		
COE Expiry Date :	22 May 2024		
Road Tax Expiry Date :	22 Nov 2018		
PARF Eligibility Expiry Date:	22 May 2024		
Inspection Due Date :	22 Nov 2018		
Intended Transfer Date:	18 Oct 2018		
CO2 Emission :	129.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$7,500.00		
CO Emission :			
HC Emission:			
NOx Emission :			
	•	u	If the road tax is renewed
The current road tax expiry is 2 after 22 Nov 2018, late renewa	2 Nov 2018. You may renew the road tax from 23 Aug I fee(s) will be imposed. Please use Enquire Road Tax F ent (if any), of a vehicle will follow the vehicle to the ne	Payable to check on the late fee(s) pay w registered owner when its ownersh	rable. hip is being transferred.
Amount Payable (From 23)	Nov 2018 to 22 May 2017		Amount After GST
Amount Payable (From 20	Amount Before Con	GST Amount (S\$)	(5\$
	(S\$)	(22)	25.00
Transfer Fee:	25.00		25.0
Sub Total:		7	510.0
Nett Road Tax Amount (After Offsetting Over Payment):	510.00	(535.0
Total Amount Payable:	DE for this vehicle cannot be further renewed. The veh	nicle must be de-registered upon COE	expiry or when the vehicle
Please note that the 8-year CO reaches its statutory lifespan You may print this page	of applicable), whichever is earlier.		

Print

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

aforesaid.	ou hereby consent to the archiving of this report at the centre and to copies of the report being made availabl
	ACCIDENT STATEMENT
Date Of Report	18/10/2018 11:28
Date Of Accident	17/10/2018 19:30
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHD2308J
Insured/Policyholder	
Name Of Registered Owner	PRIME CAR RENTAL & TAXI SERVICES PTE LTD
Co Reg No	199606293Z
Email Address	NOEMAIL
Mobile Phone No	

Alternative Phone No Vehicle Particulars

Manufacturer TOYOTA

Model VELLFIRE HYBRID 2.5X CVT

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

OFFICE-68982000

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

5068045737-04

Cover Note Number

Driver

Name of Driver KAMARUDDIN BIN MATSOM

NRIC No S0035192Z Date Of Birth 15/01/1954 Occupation OUTDOOR Date Of Driving Pass 14/02/1984

Driving Experience 34 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97991644

Fax Number

Contact Number

EMail Address NOEMAIL Address

BLK. 17 DOVER CRESCENT #14-54 SINGAPORE

Postcode

130017

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JQR8661 (PRIVATE CAR)

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

4

Passenger 1

NAME:

: PASSENGER A

GENDER:

: MALE

Passenger 2

NAME:

: PASSENGER B

GENDER:

: FEMALE

Passenger 3

NAME:

: PASSENGER C

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes.Please state which Police Station

10 UBI AVENUE 3

Police Station Name Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20181017/2009D

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

JQR8661

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SMA9226Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

KAMARUDDIN BIN MATSOM

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHD2308J

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

BLK. 17 DOVER CRESCENT #14-54 SINGAPORE

Postcode

130017

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

TANING OUT

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

Individual Statement Pg. 1

		경우하기 열차 없다. 그리고 있는데 사고를 하는데 없다고 있다.	
	CITY)		C SMA9226 Y. A SHO23083
	PIE (PIETE EUNOS TO	J B B	B Jar8661
	STANCES OF THE A	T/2018 1017/2009D.	
		INVESTMENT OF THE STATE OF THE	
ECLARATION		Jan. 011.	olan.
ECLARATION We declare the fore	going particulars are	true in every respect.	olan.
ECLARATION We declare the fore	going particulars are	true in every respect. $7an$; 010 .	Peporting Centre Personnel's Signature

GIARMC SketchPlankorm_v3

POLICE REPORT Pg. 1





T/20181017/2009D

Report No. T/20181017/2009D

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT Date/Time Report Made: Vide Report No.: Station Diary No.: 17/10/2018 21:35 Informant's Particulars Name of Informant: Address: KAMARUDDIN BIN MATOM APT BLK 17 DOVER CRESCENT #14-54 DOVER VILLE SINGAPORE 130017 ID Type / ID No .: Contact No.: NRIC NO / S0035192Z Home/Office: Mobile: 97991644 Nationality: Email: SINGAPORE CITIZEN Sex: Age: Date of Birth: Type of Informant: Male 64 15/01/1954 Driver Race: Language: Institution / School Name: Chinese Occupation: Driving Licence Information: Taxi driver Class: 2,3 Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/10/2018 19:30	Type of Location Straight Road
PIE TUAS TO	EXPRESSWAY WARDS PAYA LEBAR	EXIT		
Weather: Clear	The second was a s	Road Surface: Dry		Road Speed Limit:
Tantin Class		Traffic Control:		Traffic Volume:
Traffic Flow: One Way Type of Collisi		Not Controlled		Heavy

Details of V	ehicle Invo	Ived	9-00-7-5007E	- WHEAT		
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
JOR8661	Car	TOYOTA		43,01	Condition	0
SHD2308J	Car	TOYOTA	VELLFIRE HYBRID 2.5X CVT	White		0
SMA9226Y	Car	TOYOTA	PRIUS ALPHA HYBRID 1.8S CVT	Silver		0

POLICE REPORT Pg. 1



Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



T/20181017/2009D

2 of 3

Report No. T/20181017/2009D

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION I WAS TRAVELLING ALONG THE SAID LOCATION. I NOTICE THE VEHICLE INFRONT OF ME STOP THEIR VEHICLE, THUS I FOLLOW SUIT. I MANAGE TO BRAKE ON TIME BUT SADLY, THE VEHICLE FROM MY REAR COLLIDED ONTO MY REAR AND THE IMPACT CAUSED MY VEHICLE TO COME INTO CONTACT WITH THE ONE INFRONT, WE THEN EXCHANGE PARTICULARS AND WAITED FOR TRAFFIC POLICE TO ARRIVE AT THE SCENE. THOUGH NOT VERY SERIOUS, I STILL SUFFERED MINOR INJURY.

POLICE REPORT Pg. 1



Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



T/20181017/2009D

3 of 3

Report No. T/20181017/2009D

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: TP / NG JIN SHENG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/10/2018 21:35
Officer In Charge Of Case: TP / GIT / Insp MOHAMMED FADZLY BIN ABDUL AZIZ Contact No.: 65476355	Classification Of Case:
Authentication Stamp	



Prime Auto Claims Service Pte Ltd GST Reg. No : 201606560M

GST Reg. No : 201606560M 6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948

Date: 18.10.2018

Prime Car Rental & Taxi Services Pte. Ltd. 5 Benoi Place Singapore 629926

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2308J TOYOTA VELLFIRE HYBRID 2.5 (2015)

To Supply

1)	1pc	Front bumper De	\$	1,785.00
2)	1set	Front bumper clip /w /		60.00
3)	1pc	Front bumper reinforcemnet 7. X Soc	Š	447.10
4)	1pc	Front bumper sponge? × 800	Š	631.00
5)	1pc	Front bumper left side retainer	\$ \$ \$	120.35
6)	1pc	Front bumper right side retainer × 500	\$	120.35
7)	1pc	Front bumper lower absorber 52618-58020 XSCC	Ś	135.49
8)	1pc	Radiator lower no. 1 grille CRA /	Š	320.00
9)	1pc	Right radiator grille finish plate 7 × 811	Š	23.72
10)		Front bonnet 800/	\$	563.50
11)	1pc	Front bonnet seal Ne	Š	60.00
12)	1pc	Front bonnet insulator 53341-58070 X 11	Š	251.66
13)	1pc	Front bonnet right hinge 34 -	Ś	56.40
14)	1pc	Front bonnet left hinge 3 4	\$	56.40
15)	1pc	Front bonnet lock 114	Ś	126.72
16)	1pc	Front bonnet cable X X 1	Ś	80.31
17)	1pc	Front bonnet front chrome CRA	Š	531.20
18)	1pc	Front chrome grille CPA/	\$ \$	1,335.80
19)	1pc	Front grille top cover CRA	Š	238.50
20)	1pc	Brace panel & H/ 2 x sn	\$	47.91
21)	1pc	Fan shroud 16711-36220 - 7 x suc	\$	281.12
22)	1pc	Fan shroud No. 2 16712-36070 •	\$	116.63
23)	1pc	Fan motor 16363-36090 ? X 811	\$	410.70
24)	1pc	Fan motor 16363-36090 . Fan motor No. 2 16363-31460 ? . X	\$	415.14
25)	1pc	Front radiator upper support sub assy R\$	\$	1,430.70
26)	1pc	Radiator 9 / sm	\$	1,901.40

120			
Jon Kara			
27.1	Radiator seal ? X11 Radiator cover sub-assy ? X11	ے	12.20
27) 1pc	Radiator seal 7 XM	\$	13.39
28) 1pc	Radiator cover sub-assy	\$	228.84
29) 1pc	Radiator reserve tank assy 16740-28152	\$	370.52
30) 1pc	Radiator reserve tank assy 16740-28152	\$	78.44
31) 1pc	Radiator fan blade (9 blades)	\$	223.70
32) 1pc	A/con fan blade (7 blades)	\$	163.87
33) 1pc	A/COII COIIGEIISEI 80400-30030	\$	1,479.80
34) 1pc	Inverter cooler assy G9010-58040	\$	774.90
35) 1pc	Inverter cooler hose No.5 G9225-58030 7 X	\$	107.10
36) 1pc	High pitched horn assy 86510-48190 ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓	\$ \$ \$	100.04
37) 1pc	Low pitched horn assy 86520-30670 X	\$	118.54
38) 1pc	Right head lamp (RA /	\$	3,525.00
39) 1pc	Right head lamp center garnish 📈 🗥 🤊	\$	100.00
40) 1pc	Left head lamp CM /	\$	3,525.00
41) 1pc	Tail gate 34	\$	2,200.00
42) 1pc	Tail gate "Vellfire" emblem 🖊	\$	80.00
43) 1pc	Tail gate "Toyota" logo 🖊 /	\$ \$ \$ \$	90.00
44) 1pc	Tail gate " E-Four" emblem **-/	\$	70.00
45) 1pc	Tail gate "Hybrid Synergy Drive" emblem	\$	60.00
46) 1pc	Tail gate weatherstrip		400.00
47) 1pc	Tail gate lock &	\$ \$	420.00
48) 1pc	Tail gate lock stricker 2 × 1 ~	\$	180.00
49) 1pc	Rear glass moulding ~~	\$ \$	160.00
50) 1pc	Rear bumper 176		1,050.00
51) 1set	Rear bumper clip 🛰 🖊	\$	50.00
52) 1pc	Rear bumper left retainer Ne	\$	130.00
53) 1pc	Rear bumper right retainer	\$	130.00
54) 1pc	Rear bumper left bracket	\$	145.00
55) 1pc	Rear bumper right bracket	\$	145.00
56) 2pcs	Rear bumper left & right tow hook cover 6 @ \$35.00	\$	70.00
57) 4pcs	Rear bumper center parking sensor (@ \$381.60	\$	1,526.40
58) 4pcs	Rear bumper center parking sensor cover @ \$31.70	\$	126.80
59) 1pc	Rear bumper left reflector	\$	90.00
60) 1pc	Rear right lower corner panel OE	\$	200.00
61) 1pc	Rear right lower corner panel clip /	\$	40.00
62) 1pc	Rear left lower corner panel 46/	\$	200.00
63) 1pc	Rear left lower corner panel clip Ne	\$	40.00
64) 1pc	Rear end panel inner & outer 74 /	\$	840.00
65) 1pc	Rear end panel top garnish 🌃	\$	400.00
66) 1pc	Rear floor panel & rear floor member 58311-58160 14	\$	1,690.00
67) 1pc	Rear floor heat insulator 58321-58010 ? X AA	\$	280.00
68) 1pc	Rear floor left side member sub 57603-58110	\$	1,027.40
69) 1pc	Rear floor cross member sub assy 57608-58130 reg	\$	922.10
70) 1pc	Rear floor side left panel 58314-58020	\$	324.10
71) 1pc	Rear floor deck box 7. × 2 NN	\$	684.00
72) 1pc	Carrier spare wheel 7, × 5	\$	46.40

\$ \$ \$	498.50 430.00
ş	430.00
	326.70
7	320.70
s \$	37,428.64
	(9,357.16)
\$	28,071.48
Ś	38:00 35°
Š	65-00 50
ς.	45.00
4	50.00
¢	
\$	55.00
s \$	253.00
\$	80.00
\$	150.00 (00 300.00 (50
\$	300.00150
\$	120.00 📉 🤊 🤈
\$	120.00
\$	120.00 80
\$	60:00 30
\$	180:00 /00
\$	200:00 (00
\$	1,500.00 800
\$	1,200.00/000
	\$ \$ \$ \$ \$ \$ \$ \$ \$

- 12) To cut/welding rear end panel, floor member & floor panel. Straighten rear left chasis end panel. Remove rear bumper, tail gate last row of seat to facilitate the repair. Replace the above parts.
- 2,000.00 / 200
- 13) To putty, respray painting tail gate inlet & outer, rear floor panel, end panel, rear bumper, right & left corner panels & left chasis frame. To polish.

Sub total L/charges	\$ 8,030.00
Estimated Grand total	\$ 36,354.48

LKK Auto Consultants hence notify the Repairer of the following:
To resurvey before a spray painting
To display damaged part(s) during resurvey

- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be reserveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Regation sport



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M 6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948

Date: 18.10.2018

Prime Car Rental & Taxi Services Pte. Ltd. 5 Benoi Place Singapore 629926

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2308J TOYOTA VELLFIRE HYBRID 2.5 (2015)

To Supply

)	1pc	Front bumper De	\$	1,785.00	
2)	1set	Front bumper clip / /	Ś	60.00	
3)	1pc	Front bumper reinforcemnet 7.	\$ \$ \$	447.10 X	
4)	1pc	Front bumper sponge ?	s	631.00	
5)	1pc	Front bumper left side retainer	\$	120.35	
6)	1pc	Front bumper right side retainer 🗡	\$	120.35X	
7)	1pc	Front bumper lower absorber 52618-58020	\$	135.49×	
8)	1pc	Radiator lower no. 1 grille	\$	320.00 🗸	
9)	1pc	Right radiator grille finish plate ?	\$	23.72×	
10)	1pc	Front bonnet ***	\$	- 563.50	
11)	1pc	Front bonnet seal ML	\$	60.00	
12)	1pc	Front bonnet insulator 53341-58070		251.66 X	
13)	1pc	Front bonnet right hinge %	\$	56.40	
14)	1pc	Front bonnet left hinge 74 -	\$	56.40	
15)	1pc	Front bonnet lock T# /	\$	126.72	
16	1	1pc	Front bonnet cable X	\$	80.31×	
17)	1pc	Front bonnet front chrome CRA	\$ \$	531.20	
18)	1pc	Front chrome grille CPA/	\$	1,335.80	
19)	1pc	Front grille top cover CRA	\$	238.50	
20)	1pc	Brace panel & H/	\$	47.91	
21)	1pc	Fan shroud 16711-36220 - 0	\$	281.12X	
22)	1pc	Fan shroud No. 2 16712-36070 -	\$ \$	116.63×	
23)	1pc	Fan motor 16363-36090 ?		410.70X	
24)	1pc	Fan motor No. 2 16363-31460 ?	\$	415.14	
25)	1pc	Front radiator upper support sub assy R	\$	1,430.70	
26)	1pc	Radiator 9	\$	1 001 10	20
					6732.5	18

7		0		
27)	1pc	Radiator seal '	\$	13.39×
28)	1pc	Radiator cover sub-assy \$\frac{9}{2}\$	\$	228.84×
29)	1pc	Radiator reserve tank assy 16740-28152	\$	370.52×
30)	1pc	Radiator reserve tank bracket 16611-36020 X		78.44×
31)	1pc	Radiator fan blade (9 blades) 7	\$	223.70×
32)	1pc	A/con fan blade (7 blades)	\$	163.87X
33)		A/con condenser 88460-58030 ?	\$	1,479.80
34)	10.00	Inverter cooler assy G9010-58040		774.90 X
35)		Inverter cooler hose No.5 G9225-58030 ?	\$	107.10×
36)	200000000000000000000000000000000000000	High pitched horn assy 86510-48190 ✓	Ś	100.04×
37)	1pc	Low pitched horn assy 86520-30670 X	\$ \$ \$	118.54×
38)	1pc	Right head lamp (RA /	Ś	3,525.00
39)	1pc	Right head lamp center garnish 🖌	Ś	100.00×
40)	1pc	Left head lamp CPA /	Š	3,525.00
41)		Tail gate 84	\$ \$ \$	2,200.00
42)	X-000000	Tail gate "Vellfire" emblem 🚧	Ś	80.00
43)	200	Tail gate "Toyota" logo W		90.00
44)		Tail gate " E-Four" emblem	\$	70.00
45-)	1pc	Tail gate "Hybrid Synergy Drive" emblem	s	60.00
46)	1pc	Tail gate weatherstrip	\$	400.00
47)	1pc	Tail gate lock Eut	\$	420.00
48)	1pc	Tail gate lock stricker *X	\$	180.00×
49)	1pc	Rear glass moulding ***	\$	160.00
50)	1pc	Rear bumper 74	\$ \$ \$ \$ \$ \$ \$	1,050.00
51)	1set	Rear bumper clip /	s	50.00
52)	1pc	Rear bumper left retainer N	\$	130.00
53)	1pc	Rear bumper right retainer ***	\$	130.00
54)	1pc	Rear bumper left bracket W/	\$	145.00
55)	1pc	Rear bumper right bracket	\$	145.00
56)	2pcs	Rear bumper left & right tow hook cover 6 @ \$35.00	\$	70.00
57)	4pcs	Rear bumper center parking sensor ~ / @ \$381.60	\$	1,526.40
58)	4pcs	Rear bumper center parking sensor cover @ \$31.70	\$	126.80
59)	1pc	Rear bumper left reflector CRA	\$	90.00
60)	1pc	Rear right lower corner panel 06	\$	200.00
61)	1pc	Rear right lower corner panel clip **	\$	40.00
62)	1pc	Rear left lower corner panel 46/	\$	200.00
63)	1pc	Rear left lower corner panel clip New/	\$	40.00
64)	1pc	Rear end panel inner & outer 74 /	\$	840.00
65)	1pc	Rear end panel top garnish 🌃 🖊	\$	400.00
66)	1pc	Rear floor panel & rear floor member 58311-58160 M	\$	1,690.00
67)	1pc	Rear floor heat insulator 58321-58010 .	\$	280.00≺
68)	1pc	Rear floor left side member sub 57603-58110 report	\$	1,027.40
69)	1pc	Rear floor cross member sub assy 57608-58130 regard	\$	922.10×
70)	1pc	Rear floor side left panel 58314-58020	\$	324.10×
71)	1pc	Rear floor deck box .	\$	684.00×
72)	1pc	Carrier spare wheel 7.	\$	46.40×
				/

17403,20

0			
73) 1pc Spare tyre carrier .	\$	498.50 X	
74) 1pc Exhaust tail pipe 🗶	\$ \$	430.00	1
75) 1pc Sensor wire ?	\$	326.70	430/
	Sub total parts \$	37,428.64)4	86.282
	s: 25% discount \$	(9,357.16) - 6	141.42
	\$	28,071.48 (8	
To Supply S.Nett Parts			
	e	38.00 35	-
1) 1pc Front license no. plate CM	3	65.00 50	
2) 1set Rear glass inner seal	\$	45.00	
3) 1tube Rear glass sealant	à	50.00	5
4) 1pc Anti slip mat 44 -	\$ \$ \$ \$	55.00	-
5) 1pc "Prime taxi" sticker	,	35.00	
Sub to	otal S.Nett Parts \$	253.00	35,00
L/charges			
1) Towing charges (use King Dolley)	\$	80.00	
2) To tuff kote.	\$	150.00 (c	v
 To remove & replace reverse sensors & sensor wires. To reset n sensor light. 	neter \$	300.0015	ש
4) To remove & replace exhaust tail pipe.	\$	120.00	?
5) To remove & refit rear glass.	\$	120.00	
6) To transfer tail gate trim board, handle & mechanism parts.	\$	120.00 8	U
7) To focus right & left head lamp.	\$	120.00 8 69.00 3	ن
	Check \$	180:00 (0	n o
8) To remove radiator fan & fan cowling. Replace radiator & etc. (cooling system.	Circon	7	
9) To remove & fit a/con condenser & inverter cooler. Replace co inverter cooler. Refill a/con gas & inverter cooler oil.	ondensor & \$	200:00 (C	N
10) To remove front bumper, front grille, right & left head lamp. R support top panel, front bumper, left & right head lamps, fron front grille & etc.	eplace front \$ t bonnet,	1,500.00 8	ಶು
 To putty, respray painting front bonnet, front bumper, suppor in pearl white. To polish. 	t panel \$	1,200.00/0	טענ

- 12) To cut/welding rear end panel, floor member & floor panel. Straighten rear left chasis end panel. Remove rear bumper, tail gate last row of seat to facilitate the repair. Replace the above parts.
- \$ 2,000.00 1200
- 13) To putty, respray painting tail gate inlet & outer, rear floor panel, end panel, rear bumper, right & left corner panels & left chasis frame. To polish. -

Sub total L/charges	\$	8,030.00 5(60.00
Estimated Grand total	\$	36,354.48 33,819,86
lar h	:	- 4,76386
V	(•	19051,40
		V

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/pile spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rey atto want



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Interna	tionale Des Experts En Autom	obile
PRIME AUTO CLAIMS	SERVICE PTE LTD	Ref : CS/TP1801908	7/R1vbn2
BENOI PLACE SING	APORE 629927	Date: 28-11-2018	
ON BEHALF OF PRIME SERVICES PTE LTD	E CAR RENTAL & TAXI	Code: TP474	
	Policy Particula	rs :- THIRD PARTY CLAI	M
Insured Veh.		Veh. Inspected	SHD 2308J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/10/2018
2.	Vehicle Pa	rticulars & Condition	
Make & Model	TOYOTA VELLFIRE 2.5X	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	AYH300022045	Colour	WHITE
Odometer	274980	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3.	Conc	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	215/65 R15	GOODRIDE	6 mm
L/H Front Tyre	215/65 R15	GOODRIDE	6 mm
R/H Rear Tyre	215/65 R15	GOODRIDE	6 mm
L/H Rear Tyre	215/65 R15	GOODRIDE	6 mm
4.	Descri	ption of Damages	
	STAINED DAMAGES AT THE	FRONT AND REAR PORTIO	ON.
DAMAGES SEE D		eral Information	
5. Accident Date	17/10/2018	Inspection Date	19/10/2018
	PRIME AUTO CLAIMS SER		70.87.0.9733300.033
Survey held at	6 BENOI PLACE SINGAPORE 629927		
5a.		Remarks	
A)THE INSPECTION B)IN ACCORDAN	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BA S, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.
5b.	Estim	ate Days of Repair	
ESTIMATED NOR	RMAL PERIOD FOR REPAIR:	17 Working D	ays



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2308J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,785.00	1,785.00
	SET FRONT BUMPER CLIP	NECESSARY	60.00	60.00
	FRONT BUMPER REINFORCEMENT	SERVICEABLE	447.10	-
	FRONT BUMPER SPONGE	SERVICEABLE	631.00	Y-
	FRONT BUMPER LEFT SIDE RETAINER	NECESSARY	120.35	120.35
	FRONT BUMPER RIGHT SIDE RETAINER	SERVICEABLE	120.35	
	FRONT BUMPER LOWER ABSORBER 52618-58020	SERVICEABLE	135.49	-
	RADIATOR LOWER NO 1 GRILLE	CRACKED	320.00	320.00
	RIGHT RADIATOR GRILLE FINISH PLATE	SERVICEABLE	23.72	
	FRONT BONNET	BUCKLED	563.50	563.50
1	FRONT BONNET SEAL	NECESSARY	60.00	60.00
	FRONT BONNET INSULATOR 53341-58070	NOT NECESSARY	251.66	
	FRONT BONNET RIGHT HINGE	BENT	56.40	56.40
1	FRONT BONNET LEFT HINGE	BENT	56.40	56.40
1	FRONT BONNET LOCK	BENT	126.72	126.7
1	FRONT BONNET CABLE	NOT NECESSARY	80.31	
1	FRONT BONNET FRONT CHROME	CRACKED	531.20	531.2
9	FRONT CHROME GRILLE	CRACKED	1,335.80	1,335.8
100	FRONT GRILLE TOP COVER	CRACKED	238.50	238.5
19	BRACE PANEL	BENT	47.91	47.9
- 19	FAN SHROUD 16711-36220	SERVICEABLE	281.12	2
	FAN SHROUD NO.2 16712-36070	SERVICEABLE	116.63	3
	FAN MOTOR 16363-36090	SERVICEABLE	410.70	o l
	FAN MOTOR NO.2 16363-31460	SERVICEABLE	415.14	4
	FRONT RADIATOR UPPER SUPPORT SUB ASSY	BENT	1,430.70	1,430.7
100	1 RADIATOR	SERVICEABLE	1,901.4	о
	RADIATOR SEAL	NOT NECESSARY	13.3	9
- 63	RADIATOR COVER SUB-ASSY	NOT NECESSARY	228.8	4
	1 RADIATOR RESERVE TANK ASSY 16740-28152	NOT NECESSARY	370.5	2
	1 RADIATOR RESERVE TANK BRACKET 16611-36020	NOT NECESSARY	78.4	4
	1 RADIATOR FAN BLADE (9 BLADES)	NOT NECESSARY	223.7	0
	1 A/CON FAN BLADE (7 BLADES)	NOT NECESSARY	163.8	7
	1 A/CON CONDENSER 88460-58030	NOT NECESSARY	1,479.8	0
	1 INVERTER COOLER ASSY G9010-58040	NOT NECESSARY	774.9	0

Report Ref No. CS/TP18019087/R1vbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	INVERTER COOLER HOSE NO.5 G9225-58030	NOT NECESSARY	107.10	7.2
311	HIGH PITCHED HORN ASSY 86510-48190	NOT NECESSARY	100.04	15-
	LOW PITCHED HORN ASSY 86520-30670	NOT NECESSARY	118.54	12
	RIGHT HEAD LAMP	CRACKED	3,525.00	3,525.00
	RIGHT HEAD LAMP CENTER GARNISH	NOT NECESSARY	100.00	
	LEFT HEAD LAMP	CRACKED	3,525.00	3,525.00
	TAIL GATE	BENT	2,200.00	2,200.00
	TAIL GATE "VELLFIRE" EMBLEM	NECESSARY	80.00	80.00
	TAIL GATE "TOYOTA" LOGO	NECESSARY	90.00	90.00
- 8	TAIL GATE "E-FOUR" EMBLEM	NECESSARY	70.00	70.00
	TAIL GATE "HYBRID SYNERGY DRIVE" EMBLEM	NECESSARY	60.00	60.00
	TAIL GATE WEATHERSTRIP	NECESSARY	400.00	400.00
	TAIL GATE LOCK	CUT	420.00	420.00
100	TAIL GATE LOCK STRICKER	NOT NECESSARY	180.00	
	REAR GLASS MOULDING	NECESSARY	160.00	160.00
	REAR BUMPER	DEFORMED	1,050.00	1,050.00
- 69	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
	REAR BUMPER LEFT RETAINER	NECESSARY	130.00	130.00
21	REAR BUMPER RIGHT RETAINER	NECESSARY	130.00	130.00
	REAR BUMPER LEFT BRACKET	NECESSARY	145.00	145.0
	REAR BUMPER RIGHT BRACKET	NECESSARY	145.00	145.0
	REAR BUMPER LEFT & RIGHT TOW HOOK COVER @\$35.00	сит	70.00	70.0
_	REAR BUMPER CENTER PARKING SENSOR @\$381.60	NECESSARY	1,526.40	1,526.4
	REAR BUMPER CENTER PARKING SENSOR COVER @\$31.70	NECESSARY	126.80	126.8
	REAR BUMPER LEFT REFLECTOR	CRACKED	90.00	90.0
-	REAR RIGHT LOWER CORNER PANEL	DEFORMED	200.0	0 200.0
	REAR RIGHT LOWER CORNER PANEL CLIP	NECESSARY	40.0	0 40.0
	REAR LEFT LOWER CORNER PANEL	DEFORMED	200.0	0 200.0
	REAR LEFT LOWER CORNER PANEL CLIP	NECESSARY	40.0	0 40.0
	1 REAR END PANEL INNER & OUTER	BENT	840.0	0 840.0
33	1 REAR END PANEL TOP GARNISH	DEFORMED	400.0	0 400.0
	1 REAR FLOOR PANEL & REAR FLOOR MEMBER 58311- 58160	BENT	1,690.0	0 1,690.0
	1 REAR FLOOR HEAT INSULATOR 58321-58010	NOT NECESSARY	280.0	0

Report Ref No. CS/TP18019087/R1vbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR LEFT SIDE MEMBER SUB 57603-58110	TO REPAIR SEE LABOUR	1,027.40	-
1	REAR FLOOR CROSS MEMBER SUB ASSY 57608-58130	TO REPAIR SEE LABOUR	922.10	1,17
1	REAR FLOOR SIDE LEFT PANEL 58314-58020	TO REPAIR SEE LABOUR	324.10	-
1	REAR FLOOR DECK BOX	NOT NECESSARY	684.00	-
	CARRIER SPARE WHEEL	NOT NECESSARY	46.40	-
	SPARE TRYE CARRIER	NOT NECESSARY	498.50	-
1	EXHAUST TAIL PIPE	NOT NECESSARY	430.00	-
	SENSOR WIRE	NOT NECESSARY	326.70	-
	LESS 25% DISCOUNT		-9,357.16	
			28,071.48	18,101.76
	SPECIAL NETT ITEMS			
1	FRONT LICENSE NO PLATE (SN)	CRACKED	38.00	
1	SET REAR GLASS INNER SEAL (SN)	NECESSARY	65.00	1
1	TUBE REAR GLASS SEALANT (SN)	NECESSARY	45.00	
1	ANTI SLIP MAT (SN)	NECESSARY	50.00	
1	"PRIME TAXI" STICKER (SN)	NECESSARY	55.00 253.00	
	LABOUR			
	TOWING CHARGES (USE KING DOLLEY).		80.00	80.00
	TO TUFF KOTE.		150.00	100.00
	TO REMOVE & REPLACE REVERSE SENSORS & SENSOR WIRES TO RESET METER SENSOR LIGHT.		300.00	150.00
	TO REMOVE & REPLACE EXHAUST TAIL PIPE.	NOT NECESSARY	120.00	
	TO REMOVE & REFIT REAR GLASS.		120.00	120.00
	TO TRANSFER TAIL GATE TRIM BOARD, HANDLE & MECHANISM PARTS.		120.00	80.00
	TO FOCUS RIGHT & LEFT HEAD LAMP.		60.00	30.00
	TO REMOVE RADIATOR FAN & FAN COWLING.REPLACE RADIATOR & ETC.CHECK COOLING SYSTEM.		180.00	100.00
	TO REMOVE & FIT A/CON CONDENSER & INVERTER COOLER.REPLACE CONDENSOR & INVERTER COOLER.REFILL A/CON GAS & INVERTER COOLER OIL.		200.00	
	TO REMOVE FRONT BUMPER, FRONT GRILLE, RIGHT & LEFT HEAD LAMP. REPLACE FRONT SUPPORT TOP PANEL, FRONT BUMPER, LEFT & RIGHT HEAD LAMPS, FRONT BONNET, FRONT GRILLE & ETC.		1,500.00	800.00

Report Ref No. CS/TP18019087/R1vbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

18,700.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, RESPRAY PAINTING FRONT BONNET, FRONT BUMPER, SUPPORT PANEL IN PEARL WHITE. TO POLISH.		1,200.00	1,000.00
	TO CUT/WELDING REAR END PANEL, FLOOR MEMBER & FLOOR PANEL. STRAIGHTEN REAR LEFT CHASIS END PANEL. REMOVE REAR BUMPER, TAIL GATE LAST ROW OF SEAT TO FACILITATE THE REPAIR. REPLACE THE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR LEFT SIDE MEMBER SUB 57603-58110, REAR FLOOR CROSS MEMBER SUB ASSY 57608-58130 AND REAR FLOOR SIDE LEFT PANEL 58314-58020.	R END PANEL,FLOOR MEMBER & 2,000.00 HTEN REAR LEFT CHASIS END BUMPER,TAIL GATE LAST ROW TE THE REPAIR.REPLACE THE IVE OF THE REPAIR OF REAR IBER SUB 57603-58110,REAR TR SUB ASSY 57608-58130 AND TT PANEL 58314-58020.	1,200.00	
	TO PUTTY,RESPRAY PAINTING TAIL GATE INLET & OUTER,REAR FLOOR PANEL,END PANEL,REAR BUMPER,RIGHT & LEFT CORNER PANELS & LEFT CHASIS FRAME.TO POLISH.		2,000.00	77-4-100-00-00-0
	PRODUCTION OF THE SERVICE OF THE PRODUCTION OF T		8,030.00	5,160.00
	GRAND TOTAL		36,354.48	23,496.76

Report Ref No. CS/TP18019087/R1vbn2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.