

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7369E

Vehicle Details

Vehicle No.: SGF4489H
Vehicle to be Exported: No
Intended Deregistration Date: 24 Oct 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA 1.6
Primary Colour: Gold
Manufacturing Year: 2006
Engine No.: 3ZZ4556710
Chassis No.: MR053ZEC107116344
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$16,950.00
Original Registration Date: 11 Apr 2006
First Registration Date: 11 Apr 2006
Transfer Count: 0
Actual ARF Paid: \$18,645.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Apr 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$23,039.00
COE Rebate Amount: \$11,350.00
Total Rebate Amount: \$11,350.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Oct 2018

OK

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 7369E

Vehicle Details

Vehicle No.: SGF4489H
Vehicle to be Exported: Yes
Intended Deregistration Date: 22 Oct 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA 1.6
Primary Colour: Gold
Manufacturing Year: 2006
Engine No.: 3ZZ4556710
Chassis No.: MR053ZEC107116344
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$16,950.00
Original Registration Date: 11 Apr 2006
First Registration Date: 11 Apr 2006
Transfer Count: 0
Actual ARF Paid: \$18,645.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Apr 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$23,039.00
COE Rebate Amount: \$11,374.00
Total Rebate Amount: \$11,374.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Oct 2018

OK



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00003401	Date of Loss:	18/10/2018
Vehicle Reg. No.:	SGF4489H	Driveable?	
Driver Age/Info:	24 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YAM BOO TECK		
Driver:	IGNATIUS YAM WEI		
Make/Model:	TOYOTA COROLLA, 1.6 (A)	Vehicle Reg. Date:	11/04/2006
Vehicle Colour:	GOLD		
Engine No:	3ZZ4556710	Chassis No:	MR053ZEC107116344
Odometer:	280480 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO POLICE REPORT		
Remarks:	VEHICLE IN WORKSHOP.		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

Not Authorized
TOTAL LOSS?
EXCESS \$5000
28/10/18

COST OF CLAIMS

Parts		
Miscellaneous Items		
Labour		
Paintwork Labour		
Towing		
	Calculated Gross Total (S\$)	11,271.00
	- Excess (S\$)	5,000.00
	(S\$)	6,271.00
	+ GST 7.00% (S\$)	438.97
	Nett Amount (S\$)	6,709.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This claim is handled by: SUHELMI BIN SUHARMAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Oct 2018)
 Parts: 143 TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SGF4489H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER DIS ✓	0.00	0.00	*140.00 F
2	1		*FRONT BUMPER SIDE RETAINER RH Bef ✓	0.00	0.00	*15.00 F
3	10		*FRONT BUMPER CLIPS rec ✓	0.00	0.00	*25.00 F
4	1		*FOG LAMP COVER RH SWC X	0.00	0.00	*25.00 F
5	1		*HEADLAMP RH 11 X	0.00	0.00	*115.00 F
6	1		*FRONT WHEEL HOUSE PANEL RH 12 X	0.00	0.00	*245.00 F
7	1		*FRONT FENDER RH DD ✓	0.00	0.00	*120.00 F
8	1		*FRONT FENDER INNER SHIELD RH To in ✓	0.00	0.00	*35.00 F
9	10		*FRONT FENDER INNER SHIELD CLIPS rec ✓	0.00	0.00	*25.00 F
10	1		*WING MIRROR ASSY RH 320 ✓	0.00	0.00	*160.00 F
11	1		*FRONT DOOR RH 3050 ✓	0.00	0.00	*480.00 F
12	1		*FRONT DOOR UPPER HINGE RH 11 X	0.00	0.00	*40.00 F
13	1		*FRONT DOOR LOWER HINGE RH Bef ✓	0.00	0.00	*40.00 F
14	1		*FRONT DOOR WEATHER STRIP RH rec ✓	0.00	0.00	*45.00 F
15	1		*FRONT DOOR INNER LOCK RH ?	0.00	0.00	*120.00 F
16	1		*FRONT DOOR OUTER PROTECTOR MOULDING RH 520 ✓	0.00	0.00	*48.00 F
17	1		*FRONT DOOR OUTER CHROME MOULDING RH 320 ✓	0.00	0.00	*25.00 F
18	1		*ROCKER PANEL RH 12 X	0.00	0.00	*250.00 F
19	1		*CENTRE DOOR PILLAR RH 12 X	0.00	0.00	-
REPAIR						
20	1		*REAR DOOR RH 10/30 ✓	0.00	0.00	*480.00 F
21	1		*REAR DOOR UPPER HINGE RH Bef ✓	0.00	0.00	*40.00 F
22	1		*REAR DOOR LOWER HINGE RH Bef ✓	0.00	0.00	*40.00 F
23	1		*REAR DOOR WEATHER STRIP RH rec ✓	0.00	0.00	*45.00 F
24	1		*REAR DOOR INNER LOCK RH ?	0.00	0.00	*120.00 F
25	1		*REAR DOOR OUTER PROTECTOR MOULDING RH 25 ✓	0.00	0.00	*48.00 F
26	1		*REAR DOOR OUTER CHROME MOULDING RH rec ✓	0.00	0.00	*25.00 F
27	1		*REAR FENDER RH 12 X	0.00	0.00	-
REPAIR						
28	1		*TAIL LAMP ASSY RH 12 ✓	0.00	0.00	*115.00 F
29	1		*REAR BUMPER 12 X	0.00	0.00	*125.00 F
30	1		*REAR BUMPER SIDE RETAINER RH 11 X	0.00	0.00	*15.00 F
31	10		*REAR BUMPER CLIPS rec ✓	0.00	0.00	*25.00 F
32	1		*FRONT SHOCK ABSORBER RH Bef ✓	0.00	0.00	*100.00 F
33	1		*FRONT ABSORBER TOP MOUNTING RH rec ✓	0.00	0.00	*70.00 F
34	1		*FRONT ABSORBER STOPPER RH rec ✓	0.00	0.00	*35.00 F
35	1		*FRONT ABSORBER DUST COVER RH 11 X	0.00	0.00	*45.00 F
36	1		*FRONT KNUCKLE ARM RH Bef ✓	0.00	0.00	*95.00 F

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
37	1		*FRONT KNUCKLE BEARING RH <i>Rec</i>	0.00	0.00	*55.00 F
38	1		*FRONT WHEEL HUB RH <i>SH</i>	0.00	0.00	*100.00 F
39	1		*FRONT LOWER ARM RH <i>Buc</i>	0.00	0.00	*105.00 F
40	1		*FRONT LOWER ARM BALL JOINT RH <i>tw</i>	0.00	0.00	*75.00 F
41	1		*FRONT STABILIZER LINK RH <i>Rec</i>	0.00	0.00	*90.00 F
42	1		*FRONT ABS SENSOR RH <i>?</i>	0.00	0.00	*185.00 F
43	1		*FRONT DRIVE SHAFT RH <i>SH</i>	0.00	0.00	*580.00 F
44	1		*FRONT TIE ROD END RH <i>SH</i>	0.00	0.00	*65.00 F
45	1		*STEERING RACK & PINION ASSY <i>SH/tw</i>	0.00	0.00	*900.00 F
46	1		*FRONT CROSS MEMBER <i>?</i>	0.00	0.00	*680.00 F
Total Parts (S\$)						6,211.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT SPORT RIM RH 14	480.00
2	1	FRONT TYRE RH (WESTLAKE) 185/70R14	200.00
Sub Total (S\$)			680.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILITATE REPAIR	New 1100	1,500.00
2	TO REMOVE & INSTALL RHF DOOR COMPONENTS	New 60	90.00
3	TO REMOVE & INSTALL RHR DOOR COMPONENTS	New 60	90.00
4	TO REMOVE & INSTALL SEATS, CARPETS & TRIMS TO FACILITATE REPAIR	New 80	180.00
5	TO REMOVE & INSTALL RHF SPORT RIM INCLUDING TYRE BALANCING	New ✓	20.00
6	TO REMOVE & INSTALL BOTH FRONT UNDERCARRIAGE PARTS	New ✓	350.00
7	TO REMOVE & INSTALL FRONT CROSS MEMBER	New	150.00
8	TO REST & RE-PROGRAM ABS WARNING LIGHT	New ?	200.00
9	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New ✓	70.00
10	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New 20	30.00
11	TO SPRAY PAINT ON AFFECTED AREAS	New 1400	1,700.00
Gross Labour Cost (S\$)			4,380.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	19 Oct 2018	19 Oct 2018 14:35 S\$11,271.00	19 Oct 2018 16:44 Edit Adj Rpt	S\$7,826.00 Edit Estimates	S\$7,826.00 View Rpt	Pending for Survey Report

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	YAM BOO TECK , ID: S1607369E		
Vehicle Reg. No.:	SGF4489H	Date of Loss:	18/10/2018 00:00 - :59 [150 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800013452	Policy/Cover Note No.:	PNPV2018-00003401 (Comprehensive)
		Excess:	S\$5,000.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/10/2018]		
Driver/Custodian:	IGNATIUS YAM WEI (24 / Male), NRIC: S9436299G, Tel: +6596319625		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (23/10/2018): **Alert - Adj Mandate Revoked - SGF4489H - Claim Handler: Josey Loh**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SGF4489H (1201800013452)

OD

Oct 18 2018 12:00AM

[YAM BOO TECK]

ETHOZ Protect Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Assessment Reports

 1 per page
 ☒

No	Finalized On		Thumbnail	Print
1	19/10/18 14:35	ETHOZ Protect Pte Ltd (Bukit Batok)		
		Repairer Estimates		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 15:01	Adjuster Immediate Advice		Load HTM

Photos/Images

 3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/18 08:29	General View		Load JPG ☒
2	24/10/18 08:29	General View		Load JPG ☒
3	24/10/18 08:29	General View		Load JPG ☒
4	24/10/18 08:29	General View		Load JPG ☒
5	24/10/18 08:29	General View		Load JPG ☒
6	24/10/18 08:29	General View		Load JPG ☒
7	24/10/18 08:29	General View		Load JPG ☒
8	24/10/18 08:29	General View		Load JPG ☒
9	24/10/18 08:29	General View		Load JPG ☒
10	24/10/18 08:29	General View		Load JPG ☒
11	24/10/18 08:29	General View		Load JPG ☒
12	24/10/18 08:29	General View		Load JPG ☒
13	24/10/18 08:29	General View		Load JPG ☒
14	24/10/18 08:29	General View		Load JPG ☒
15	24/10/18 08:29	General View		Load JPG ☒
16	24/10/18 08:29	General View		Load JPG ☒
17	24/10/18 08:29	General View		Load JPG ☒
18	24/10/18 08:29	General View		Load JPG ☒
19	24/10/18 08:29	General View		Load JPG ☒
20	24/10/18 08:29	General View		Load JPG ☒
21	24/10/18 08:29	General View		Load JPG ☒
22	24/10/18 08:29	General View		Load JPG ☒
23	24/10/18 08:29	General View		Load JPG ☒
24	24/10/18 08:29	General View		Load JPG ☒
25	24/10/18 08:29	General View		Load JPG ☒
26	24/10/18 08:29	General View		Load JPG ☒
27	24/10/18 08:29	General View		Load JPG ☒
28	24/10/18 08:29	General View		Load JPG ☒
29	24/10/18 08:29	General View		Load JPG ☒
30	24/10/18 08:29	General View		Load JPG ☒
31	24/10/18 08:29	General View		Load JPG ☒
32	24/10/18 08:29	General View		Load JPG ☒

Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)		Thumbnail Print
33	24/10/18 08:29	General View		Load JPG ☒
34	24/10/18 08:29	General View		Load JPG ☒
35	24/10/18 08:29	General View		Load JPG ☒
36	24/10/18 08:29	General View		Load JPG ☒
37	24/10/18 08:29	General View		Load JPG ☒
38	24/10/18 08:29	General View		Load JPG ☒
39	24/10/18 08:29	General View		Load JPG ☒
40	24/10/18 08:29	General View		Load JPG ☒
41	24/10/18 08:29	General View		Load JPG ☒
42	24/10/18 08:29	General View		Load JPG ☒
43	24/10/18 08:29	General View		Load JPG ☒
44	24/10/18 08:29	General View		Load JPG ☒
45	24/10/18 08:29	General View		Load JPG ☒
46	24/10/18 08:29	General View		Load JPG ☒
47	24/10/18 08:29	General View		Load JPG ☒
48	24/10/18 08:29	General View		Load JPG ☒
49	24/10/18 08:29	General View		Load JPG ☒
50	24/10/18 08:29	General View		Load JPG ☒
51	24/10/18 08:29	General View		Load JPG ☒
52	24/10/18 08:29	General View		Load JPG ☒
53	24/10/18 08:29	General View		Load JPG ☒
54	24/10/18 08:29	General View		Load JPG ☒
55	24/10/18 08:29	General View		Load JPG ☒
56	24/10/18 08:29	General View		Load JPG ☒
57	24/10/18 08:29	General View		Load JPG ☒
58	24/10/18 08:29	General View		Load JPG ☒
59	24/10/18 08:29	General View		Load JPG ☒
60	24/10/18 08:29	General View		Load JPG ☒
61	24/10/18 08:29	General View		Load JPG ☒
62	24/10/18 08:29	General View		Load JPG ☒
63	24/10/18 08:29	General View		Load JPG ☒
64	24/10/18 08:29	General View		Load JPG ☒
65	24/10/18 08:29	General View		Load JPG ☒
66	24/10/18 08:29	General View		Load JPG ☒
67	24/10/18 08:29	General View		Load JPG ☒
68	24/10/18 08:29	General View		Load JPG ☒
69	24/10/18 08:29	General View		Load JPG ☒
70	24/10/18 08:29	General View		Load JPG ☒
71	24/10/18 08:29	General View		Load JPG ☒
72	24/10/18 08:29	General View		Load JPG ☒
73	24/10/18 08:29	General View		Load JPG ☒
74	24/10/18 08:29	General View		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	23/10/18 15:05	MARK ESTIMATE		Load PDF ☐
2	25/10/18 15:42	LTA REBATE		Load PDF ☐

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	18/10/18 16:08	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	18/10/18 15:58	Accident Photo	 Load JPG	☒
2	18/10/18 15:58	Accident Photo	 Load JPG	☒
3	18/10/18 15:58	Accident Photo	 Load JPG	☒
4	18/10/18 15:58	Accident Photo	 Load JPG	☒
5	18/10/18 15:58	Accident Photo	 Load JPG	☒
6	18/10/18 15:58	Accident Photo	 Load JPG	☒
7	18/10/18 15:58	Accident Photo	 Load JPG	☒
8	18/10/18 15:58	Accident Photo	 Load JPG	☒
9	18/10/18 16:08	Accident Photo	 Load JPG	☒
10	18/10/18 16:08	Accident Photo	 Load JPG	☒
11	18/10/18 16:08	Accident Photo	 Load JPG	☒
12	18/10/18 16:08	Accident Photo	 Load JPG	☒
13	18/10/18 16:08	Accident Photo	 Load JPG	☒
14	18/10/18 16:08	Accident Photo	 Load JPG	☒
15	18/10/18 16:08	Accident Photo	 Load JPG	☒
16	18/10/18 16:08	Accident Photo	 Load JPG	☒
17	18/10/18 16:08	Accident Photo	 Load JPG	☒
18	18/10/18 16:08	Accident Photo	 Load JPG	☒
19	18/10/18 16:08	Accident Photo	 Load JPG	☒
20	18/10/18 16:08	Accident Photo	 Load JPG	☒
21	18/10/18 16:08	Accident Photo	 Load JPG	☒
22	18/10/18 16:08	Accident Photo	 Load JPG	☒
23	18/10/18 16:08	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	18/10/18 15:58	Sketch Plan	 Load TIF	
2	18/10/18 15:58	DRIVER DL	 Load JPG	☒
3	18/10/18 15:58	INSURANCE CERT	 Load JPG	☒
4	18/10/18 15:58	INSURANCE CERT	 Load JPG	☒
5	18/10/18 15:58	POLICE REPORT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18019096/UVD3S2

Date: 25/10/2018

REFERENCE

Insured/Claimant:	YAM BOO TECK	Policy No:	PNPV2018-00003401	Claim No:	1201800013452
Date of Loss:	18/10/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGF4489H	Engine No:	3ZZ4556710
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053ZEC107116344
Reg. Date:	11/04/2006 (Man. Year: 2006)	Odometer:	209480 km
Colour:	Gold		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$16,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/70R14	Rear Tyre Size:	185/70R14
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,211.00	4,246.00	1,965.00	31.64
Miscellaneous Items	680.00	420.00	260.00	38.24
Labour	4,380.00	3,160.00	1,220.00	27.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,271.00	7,826.00	3,445.00	30.57
- Excess (S\$)	5,000.00	5,000.00	0.00	0.00
(S\$)	6,271.00	2,826.00	3,445.00	54.94
+ GST 7.00/7.00% (S\$)	438.97	197.82	241.15	54.94
Nett Amount (S\$)	6,709.97	3,023.82	3,686.15	54.94

INSPECTION

Date of Assignment:	19/10/2018	Present Location:	ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected:	22/10/2018	Inspected At:	ETHOZ Protect Pte Ltd (Bukit Batok)
Estimated Period of Repair:	0.0 days		30 Bukit Batok Crescent
			Singapore 658075

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,305.00 NETT)

TOTAL LOSS ASPECT

Market Value :	\$16,000.00
OMV :	\$16,950.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$23,039.00
COE Rebate (2) :	\$11,362.00
Total Rebate (1) + (2) = :	\$11,362.00

The total amount incurred will be Market Value \$16,000.00 minus Total Rebate \$11,362.00 = \$4,638.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2018)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF4489H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	140.00 F	*140.00 F
2	1		*FRONT BUMPER SIDE RETAINER RH	Bent	15.00 F	*15.00 F
3	10		*FRONT BUMPER CLIPS	Necessary	25.00 F	*25.00 F
4	1		*FOG LAMP COVER RH	Serviceable	25.00 F	*- F
5	1		*HEADLAMP RH	Not Necessary	115.00 F	*- F
6	1		*FRONT WHEEL HOUSE PANEL RH	Repair	245.00 F	*- F
7	1		*FRONT FENDER RH	Dented	120.00 F	*120.00 F
8	1		*FRONT FENDER INNER SHIELD RH	Torn	35.00 F	*35.00 F
9	10		*FRONT FENDER INNER SHIELD CLIPS	Necessary	25.00 F	*25.00 F
10	1		*WING MIRROR ASSY RH	Broken	160.00 F	*160.00 F
11	1		*FRONT DOOR RH	Badly Dented	480.00 F	*480.00 F
12	1		*FRONT DOOR UPPER HINGE RH	Not Necessary	40.00 F	*- F
13	1		*FRONT DOOR LOWER HINGE RH	Bent	40.00 F	*40.00 F
14	1		*FRONT DOOR WEATHER STRIP RH	Necessary	45.00 F	*45.00 F
15	1		*FRONT DOOR INNER LOCK RH	*Check	120.00 F	*- F
16	1		*FRONT DOOR OUTER PROTECTOR MOULDING RH	Broken	48.00 F	*48.00 F
17	1		*FRONT DOOR OUTER CHROME MOULDING RH	Broken	25.00 F	*25.00 F
18	1		*ROCKER PANEL RH	Repair	250.00 F	*- F
19	1		*CENTRE DOOR PILLAR RH (NPA)	Repair	-	*- F
20	1		*REAR DOOR RH	Dented / Bent	480.00 F	*480.00 F
21	1		*REAR DOOR UPPER HINGE RH	Bent	40.00 F	*40.00 F
22	1		*REAR DOOR LOWER HINGE RH	Bent	40.00 F	*40.00 F
23	1		*REAR DOOR WEATHER STRIP RH	Necessary	45.00 F	*45.00 F
24	1		*REAR DOOR INNER LOCK RH	*Check	120.00 F	*- F
25	1		*REAR DOOR OUTER PROTECTOR MOULDING RH	Distorted	48.00 F	*48.00 F
26	1		*REAR DOOR OUTER CHROME MOULDING RH	Necessary	25.00 F	*25.00 F
27	1		*REAR FENDER RH (NPA)	Repair	-	*- F
28	1		*TAIL LAMP ASSY RH	Cracked	115.00 F	*115.00 F
29	1		*REAR BUMPER	Repair	125.00 F	*- F
30	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	15.00 F	*- F
31	10		*REAR BUMPER CLIPS	Necessary	25.00 F	*25.00 F
32	1		*FRONT SHOCK ABSORBER RH	Bent	100.00 F	*100.00 F
33	1		*FRONT ABSORBER TOP MOUNTING RH	Necessary	70.00 F	*70.00 F
34	1		*FRONT ABSORBER STOPPER RH	Necessary	35.00 F	*35.00 F
35	1		*FRONT ABSORBER DUST COVER RH	Not Necessary	45.00 F	*- F
36	1		*FRONT KNUCKLE ARM RH	Bent	95.00 F	*95.00 F
37	1		*FRONT KNUCKLE BEARING RH	Necessary	55.00 F	*55.00 F
38	1		*FRONT WHEEL HUB RH	Bent	100.00 F	*100.00 F
39	1		*FRONT LOWER ARM RH	Buckled	105.00 F	*105.00 F
40	1		*FRONT LOWER ARM BALL JOINT RH	Twisted	75.00 F	*75.00 F
41	1		*FRONT STABILIZER LINK RH	Bent	90.00 F	*90.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT ABS SENSOR RH	*Check	185.00 F	*- F
43	1		*FRONT DRIVE SHAFT RH	Broken	580.00 F	*580.00 F
44	1		*FRONT TIE ROD END RH	Bent	65.00 F	*65.00 F
45	1		*STEERING RACK & PINION ASSY	Bent / Twisted	900.00 F	*900.00 F
46	1		*FRONT CROSS MEMBER	*Check	680.00 F	*- F

F=Franchise part.

Total Parts (S\$)	6,211.00	4,246.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT SPORT RIM RH 14 (BENT / CRACKED)	480.00	300.00
2	1	FRONT TYRE RH (WESTLAKE) 185/70R14 (60%) (PUNCTURED)	200.00	120.00
Sub Total (\$\$)			680.00	420.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,500.00	1,100.00
2	TO REMOVE & INSTALL RHF DOOR COMPONENTS	New	90.00	60.00
3	TO REMOVE & INSTALL RHR DOOR COMPONENTS	New	90.00	60.00
4	TO REMOVE & INSTALL SEATS,CARPETS & TRIMS TO FACILITATE REPAIR	New	180.00	80.00
5	TO REMOVE & INSTALL RHF SPORT RIM INCLUDING TYRE BALANCING	New	20.00	20.00
6	TO REMOVE & INSTALL BOTH FRONT UNDERCARRIAGE PARTS {	New	350.00	350.00
7	TO REMOVE & INSTALL FRONT CROSS MEMBER }	New	150.00	0.00
8	TO REST & RE-PROGRAM ABS WARNING LIGHT (*Check)	New	200.00	0.00
9	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	70.00	70.00
10	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00	20.00
11	TO SPRAY PAINT ON AFFECTED AREAS	New	1,700.00	1,400.00
Gross Labour Cost (\$\$)			4,380.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >