

INSURER:

FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00003401	Date of Loss:	18/10/2018
Vehicle Reg. No.:	SGF4489H	Driveable?	
Driver Age/Info:	24 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YAM BOO TECK		
Driver:	IGNATIUS YAM WEI		
Make/Model:	TOYOTA COROLLA, 1.6 (A)	Vehicle Reg. Date:	11/04/2006
Vehicle Colour:	GOLD		
Engine No:	3ZZ4556710	Chassis No:	MR053ZEC107116344
Odometer:	280480 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO POLICE REPORT		
Remarks:	VEHICLE IN WORKSHOP.		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

Not Authorized
TOTAL LOSS?
Excess \$5000
27/10/18

COST OF CLAIMS**Amount**

Parts	6,211.00
Miscellaneous Items	680.00
Labour	4,380.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	11,271.00
- Excess (S\$)	5,000.00
(S\$)	6,271.00
+ GST 7.00% (S\$)	438.97
Nett Amount (S\$)	6,709.97

This claim is handled by: SUHELMI BIN SUHARMAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Parts: 143
 Labour: Repairer's
 Print Code: (Unsubmitted, no print-code for SGF4489H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>Dis ✓</i>	0.00	0.00	*140.00 F
2	1		*FRONT BUMPER SIDE RETAINER RH <i>Ref ✓</i>	0.00	0.00	*15.00 F
3	10		*FRONT BUMPER CLIPS <i>Ref ✓</i>	0.00	0.00	*25.00 F
4	1		*FOG LAMP COVER RH <i>SWC X</i>	0.00	0.00	*25.00 F
5	1		*HEADLAMP RH <i>11 X</i>	0.00	0.00	*115.00 F
6	1		*FRONT WHEEL HOUSE PANEL RH <i>2 X</i>	0.00	0.00	*245.00 F
7	1		*FRONT FENDER RH <i>DD ✓</i>	0.00	0.00	*120.00 F
8	1		*FRONT FENDER INNER SHIELD RH <i>To in ✓</i>	0.00	0.00	*35.00 F
9	10		*FRONT FENDER INNER SHIELD CLIPS <i>Ref ✓</i>	0.00	0.00	*25.00 F
10	1		*WING MIRROR ASSY RH <i>320 ✓</i>	0.00	0.00	*160.00 F
11	1		*FRONT DOOR RH <i>3050 ✓</i>	0.00	0.00	*480.00 F
12	1		*FRONT DOOR UPPER HINGE RH <i>11 X</i>	0.00	0.00	*40.00 F
13	1		*FRONT DOOR LOWER HINGE RH <i>Ref ✓</i>	0.00	0.00	*40.00 F
14	1		*FRONT DOOR WEATHER STRIP RH <i>Ref ✓</i>	0.00	0.00	*45.00 F
15	1		*FRONT DOOR INNER LOCK RH <i>?</i>	0.00	0.00	*120.00 F
16	1		*FRONT DOOR OUTER PROTECTOR MOULDING RH <i>SR0 ✓</i>	0.00	0.00	*48.00 F
17	1		*FRONT DOOR OUTER CHROME MOULDING RH <i>320 ✓</i>	0.00	0.00	*25.00 F
18	1		*ROCKER PANEL RH <i>2 X</i>	0.00	0.00	*250.00 F
19	1		*CENTRE DOOR PILLAR RH <i>2 X</i>	0.00	0.00	-
			REPAIR			
20	1		*REAR DOOR RH <i>DD/Ref ✓</i>	0.00	0.00	*480.00 F
21	1		*REAR DOOR UPPER HINGE RH <i>Ref ✓</i>	0.00	0.00	*40.00 F
22	1		*REAR DOOR LOWER HINGE RH <i>Ref ✓</i>	0.00	0.00	*40.00 F
23	1		*REAR DOOR WEATHER STRIP RH <i>Ref ✓</i>	0.00	0.00	*45.00 F
24	1		*REAR DOOR INNER LOCK RH <i>?</i>	0.00	0.00	*120.00 F
25	1		*REAR DOOR OUTER PROTECTOR MOULDING RH <i>DS ✓</i>	0.00	0.00	*48.00 F
26	1		*REAR DOOR OUTER CHROME MOULDING RH <i>Ref ✓</i>	0.00	0.00	*25.00 F
27	1		*REAR FENDER RH <i>2 X</i>	0.00	0.00	-
			REPAIR			
28	1		*TAIL LAMP ASSY RH <i>11 X ✓</i>	0.00	0.00	*115.00 F
29	1		*REAR BUMPER <i>2 X</i>	0.00	0.00	*125.00 F
30	1		*REAR BUMPER SIDE RETAINER RH <i>11 X</i>	0.00	0.00	*15.00 F
31	10		*REAR BUMPER CLIPS <i>Ref ✓</i>	0.00	0.00	*25.00 F
32	1		*FRONT SHOCK ABSORBER RH <i>Ref ✓</i>	0.00	0.00	*100.00 F
33	1		*FRONT ABSORBER TOP MOUNTING RH <i>Ref ✓</i>	0.00	0.00	*70.00 F
34	1		*FRONT ABSORBER STOPPER RH <i>Ref ✓</i>	0.00	0.00	*35.00 F
35	1		*FRONT ABSORBER DUST COVER RH <i>11 X</i>	0.00	0.00	*45.00 F
36	1		*FRONT KNUCKLE ARM RH <i>Ref ✓</i>	0.00	0.00	*95.00 F

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

No	Qty	Particulars	Amount
1	1	FRONT SPORT RIM RH 14	480.00
2	1	FRONT TYRE RH (WESTLAKE) 185/70R14	200.00
Sub Total (S\$)			680.00

*rep/one 300
pur 6th*

Estimates on Labour

No Particulars

Labour Items

No	Particulars	Lab.Type	Amount
1	LABOUR TO FACILITATE REPAIR	New	1,500.00
2	TO REMOVE & INSTALL RHF DOOR COMPONENTS	New	90.00
3	TO REMOVE & INSTALL RHR DOOR COMPONENTS	New	90.00
4	TO REMOVE & INSTALL SEATS, CARPETS & TRIMS TO FACILITATE REPAIR	New	180.00
5	TO REMOVE & INSTALL RHF SPORT RIM INCLUDING TYRE BALANCING	New	20.00
6	TO REMOVE & INSTALL BOTH FRONT UNDERCARRIAGE PARTS	New	350.00
7	TO REMOVE & INSTALL FRONT CROSS MEMBER	New	150.00
8	TO REST & RE-PROGRAM ABS WARNING LIGHT	New	200.00
9	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	70.00
10	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00
11	TO SPRAY PAINT ON AFFECTED AREAS	New	1,700.00
Gross Labour Cost (S\$)			4,380.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
37	1		*FRONT KNUCKLE BEARING RH			
38	1		*FRONT WHEEL HUB RH	0.00	0.00	*55.00 F
39	1		*FRONT LOWER ARM RH	0.00	0.00	*100.00 F
40	1		*FRONT LOWER ARM BALL JOINT RH	0.00	0.00	*105.00 F
41	1		*FRONT STABILIZER LINK RH	0.00	0.00	*75.00 F
42	1		*FRONT ABS SENSOR RH	0.00	0.00	*90.00 F
43	1		*FRONT DRIVE SHAFT RH	0.00	0.00	*185.00 F
44	1		*FRONT TIE ROD END RH	0.00	0.00	*580.00 F
45	1		*STEERING RACK & PINION ASSY	0.00	0.00	*65.00 F
46	1		*FRONT CROSS MEMBER	0.00	0.00	*900.00 F
Total Parts (\$\$)						6,211.00

F=Franchise part

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: