

ASS. REC. 16/

REL CS3/LPC18011268/T1rd3-1ⁿ²

Surveyor

Taufik

ASSIGNMENT (Office)

From Person

Gerald Poh

LPC

Date/Time

22/10/2018

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/C

To Inspect Vehicle No.

SLM 7847S

Insured

SJT 6688C

at Workshop to/

Verve Motorclinic

Tel

9159 5951

of

No. 25 Kaki Bukit Rd 4 #03-39

Policy No.

Claim No.

18/18/18/VP05/020687

Sum Insured

Excess

Make of Veh.
(Client's Record)

D.O.A.

19/06/2018

CA / REV / REP. / REV 24 HRS

lap?

H.O.D. Endorsement

Date/Time

21/6/18 @ 11:32am

Person Contacted


Mr. Jaron

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLM 7847S - X
	SJT 6688C - CC-11/18/18/00083/103
	Submit PRS report

Submit LIs \$3100 @ 4 days
Red: \$480, 15%.



15/11/2018
LIs \$3100, 4 days

RECEIVED 16 NOV 2018.

LPC


ASSIGNMENT

01/06/2018

SLM 78475

01/06/2018 July

Vehicle
Estimate No. 1234
OD (TP) WS / TP RES / OD RES / EVA / INV / MV
Insured Vehicle No. SLM 78475
at Workshop Verve Motorclinic
No. 25 kaki Bkt Rd 4 #03-49
Insured
Policy No.
Classified
Sign Insured
(Client's Record)
Make of Veh.



(Policy Condition)
Remarks: The veh had commenced its repair at the time of inspection.

Ref. to Market Value
at Acc. Accident Report Consistent? Yes or No
at Acc. Accident Report Consistent? Yes or No
Est. Repairs: days Res. Yes or No
Lump Sum: % 3 Val. Yes or No

CA / REV / REP. / 24 HRS (wps)
Date: Person Contacted
Vehicle: IN / OUT

Vehicle: SLM 78475
Type: M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mercedes Benz C200 cc 1796
Colour: Silver A/C Insured / Std / NI / NA
Sp. Features: 22053 Insurance Insured / Std / NI / NA
Engine: WDD2040412 A166 559
Gear: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / B/Rim / STD A/Rim or
Tyre Size: F. 235 / 4711- R.
BS / DUN / EXNOVA / GY / FS / LIZA / MK / DHTSU / PIR / SUMI /
TOYO / YOKO or
Front: 6 mm Rear: 6 mm
R/Bal: 6 mm L/Bal: 6 mm
D.O.A: 21/6/18 457
Survey held at: Verve Motorclinic
Dist. of Damages: Fnt / Rear / O/S / N/S / UIC / Rontop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 12/7 728 / 429

RECEIVED 1 JUL 2018

Date/Time File Pass to? : Prof. Report
by: Final Report
Date/Time File Return by?

Days Of Repair:
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp: \$5
☐ Int. Insp: \$5
☐ Equip. Insp: \$5
☐ Night Insp: \$5

Survey Fee:
Transportation:
Total:

Report Format: 925
Lump Sum / LB: \$5

450


Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 22 October 2018 12:30 PM
To: Admin-D (LKKAuto)
Attachments: 22102018122710.pdf; 22102018122741.pdf; 22102018122815.pdf;
22102018122833.pdf

Dear Catherine,

FYA

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 18/18/18/VP05/020687

Your Ref : CS3/LPC18011268/T1rd3n2

22 October 2018

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF SLM7847S

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of SLM7847S
- b) GIA report of SLM7847S
- c) GIA report & photos of SJT6688C

Kindly study the documents and let us have your report by 29 October 2018.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

Verve Motorclinic Pte Ltd

25 Kaki Bukit Road 4 #03-39 Synergy @ KB

Singapore 417800

H/P no. 9159 5951 (Jaron)

Email : mail4jaron@yahoo.com.sg

Date : 20/07/2018

Name : M/s. Kinetic Regency Pte Ltd

Date of Accident : 19/06/2018

Address : C/o. 25 Kaki Bukit Road 4
Synergy@KB #03-39
Singapore 417800

Vehicle Model : M/Benz C200 Kompressor

Final Repair Cost For SLM7847S

Lump Sum Repair Costs

\$ 3,580.00



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0400618

Date of Report : 17/07/2018

To : M/s. Kinetic Regency Pte Ltd
C/o. 25 Kaki Bukit Road 4
Synergy@KB #03-39
Singapore 417800

Date of Assignment : 20/06/2018
Report requested by : M/s. Kinetic Regency Pte Ltd
Date of Accident : 19/06/2018
Date of Inspection : 20/06/2018
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SLM7847S
Make & Model : M/Benz C200 Kompressor
Date of Registration : 29/07/2008
Colour : Met. Silver

Engine Capacity (cc) : 1796cc
Mileage (km) : 220052km
Chassis / Frame No. : WDD2040412A166559
Engine No. : 27195031077529

TYRE CONDITION

Front LH : 4 mm
Make : Bridgestone

Front RH : 4 mm
Make : Bridgestone

Rear LH : 4 mm
Make : Michelin

Rear RH : 4 mm
Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Verve Motorclinic Pte Ltd
25, Kaki Bukit Road 4, Synergy@KB, #03-39, Singapore 417800

ASSESSMENT

Repairer's Estimate : \$ 6,705.30
Revised Amount : \$ 4,478.00
Less Excess : \$ -
Recommended Reserve : \$ 3,580.00 (Lump Sum)

Estimated Normal Period of Repairs : 4 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 8722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SLM7847S

Report No. : PAS/TP/0400618

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Verve Motorclinic Pte Ltd, 25, Kaki Bukit Road 4, Synergy@KB, #03-39, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, LH taillamp, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$4,478.00.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,580.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SLM7847S

Report No. : PAS/TP/0400618

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Rr bumper	Dented	\$ 1,425.00	\$ 1,425.00 1290
2	1 pc	Rr bumper moulding	Dented/Necessary	\$ 283.00	\$ 283.00
3	4 pcs	Rr bumper sensor	Dented/Damaged	\$ 224.00 140	\$ 896.00 2pcs \$ 448.00 280
4	2 pcs	Rr bumper guide R/L	Necessary	\$ 52.00	\$ 104.00
5	1 pc	Rr bumper crossmember	Dented	\$ 652.00	\$ 652.00
6	1 pc	Rr end panel	Dented/Repair	\$ 869.00	\$ -
7	1 pc	Rr end panel garnish	Dented/Deformed	\$ 128.00	\$ 128.00
8	2 pcs	Taillamp R/L	LH Broken	\$ 680.00	\$ 680.00 426
9	1 pc	Rr end panel	Dented/Repair		(Refer labour no. 2, 4 & 5)
				\$ 5,717.00	\$ 3,720.00 3163
Less Discount : 10%				\$ 571.70	10% \$ 372.00
List Parts Sub-Total :				\$ 5,145.30	\$ 3,348.00 2846.70
Parts Total :				\$ 5,145.30	\$ 3,348.00

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check rear electrical wiring system.	\$ 30.00	\$ 20.00
2	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 100.00	\$ 80.00 40
3	To remove, replace and/or transfer rear reverse sensors & reset control unit.	\$ 180.00	\$ 160.00 130
4	To straighten, repair, realign on affected area and replace damaged parts.	\$ 600.00	\$ 440.00 400
5	To spray painting, blending on affected and adjacent area.	\$ 600.00	\$ 400.00
6	To spray anti-rust coating on new and affected panels.	\$ 50.00	\$ 30.00 1020
Labour Total :		\$ 1,560.00	\$ 1,130.00
Total (Parts & Labour) :		\$ 6,705.30	\$ 4,478.00

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 3,580.00

Under normal circumstances, the repairs should be completed within a reasonable period of 4 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

48 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Notes: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC18011268/T1rd3n2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 19-11-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJT 6688C	Veh. Inspected	SLM 7847S	
Policy No.	Z18VP05017082	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020687	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	22/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C200	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WDD2040412A166559	Colour	SILVER	
Odometer	220053	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45 R17	MICHELIN	6 mm	
L/H Front Tyre	235/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	235/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	235/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/06/2018	Inspection Date	21/06/2018	
Survey held at	VERVE AUTOCLINIC BLK 25 KAKI BUKIT ROAD 4 #03-39 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 7847S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RR BUMPER	DENTED	1,425.00	1,290.00
1	RR BUMPER MOULDING	DENTED / NECESSARY	283.00	283.00
4	RR BUMPER SENSOR @\$224.00	DENTED / DAMAGED (2 PCS ONLY)	896.00	280.00
2	RR BUMPER GUIDE R/L @\$52.00	NECESSARY	104.00	104.00
1	RR BUMPER CROSSMEMBER	DENTED	652.00	652.00
1	RR END PANEL	TO REPAIR SEE LABOUR	869.00	-
1	RR END PANEL GARNISH	DENTED / DEFORMED	128.00	128.00
2	TAILLAMP R/L @\$680.00	N/S BROKEN	1,360.00	426.00
	LESS 10% DISCOUNT		-571.70	-316.30
			5,145.30	2,846.70
LABOUR				
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		30.00	20.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC, FOR NECESSARY REPAIRS.		100.00	40.00
	TO REMOVE, REPLACE AND/OR TRANSFER REAR REVERSE SENSOR & RESET CONTROL UNIT.		180.00	130.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR END PANEL.		600.00	400.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		600.00	400.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		50.00	30.00
	-		-	-
	-		-	-
	-		-	-
			1,560.00	1,020.00
GRAND TOTAL			6,705.30	3,866.70

Report Ref No. CS3/LPC18011268/T1rd3n2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00
---	--	--	----------

Report Ref No. CS3/LPC18011268/T1rd3n2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.