

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18019113/UKA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800099952
Claimant
Vehicle No : SJS4225Z **Insured Vehicle No :** SGL3318T
 Date of Loss: 20/10/2018 Nature of Claim: TP Claim No: 3386470993SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS4225Z**
 Make & Model: HONDA STREAM, 1.8 X (A) Engine No: R18A1801398
 Reg. Date: 14/08/2009 (Man. Year: 2008) Chassis No: RN61091356
 Colour: Grey Odometer: 165312 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15
 Front Left Side: ACELERE 6 mm Rear Left Side: ACELERE 6 mm
 Front Right Side: ACELERE 6 mm Rear Right Side: ACELERE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,025.02	9,392.40	13,632.62	59.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,620.00	3,510.00	4,110.00	53.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,645.02	12,902.40	17,742.62	57.90
Approved Total (Overridden) (S\$)		9,200.00		
(S\$)	30,645.02	9,200.00	21,445.02	69.98
+ GST 7.00/7.00% (S\$)	2,145.15	644.00	1,501.15	69.98
Nett Amount (S\$)	32,790.17	9,844.00	22,946.17	69.98
+ Loss of Use (11.0 x S\$80.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,726.00		
Global Sum Settlement (S\$)		10,700.00		

INSPECTION

Date of Assignment: 22/10/2018
 Date Inspected: 22/10/2018 Inspected At: Kim Chwee Auto Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6 #01-48,
 AutoBay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,123.20 FL	*638.90 FL
2	1		*FRONT BONNET LOCK	Twisted	197.80 FL	*105.60 FL
3	2		*FRONT BONNET HINGE	Not Necessary	152.00 FL	*- FL
4	1		*FRONT BONNET INSULATOR	Deformed	199.50 FL	*199.50 FL
5	1		*FRONT BONNET SEAL	Necessary	37.20 FL	*37.20 FL
6	1		*FRONT SUPPORT PANEL	Bent / Buckled	765.20 FL	*466.20 FL
7	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed / Torn	210.30 FL	*210.30 FL
8	1		*FRONT GRILLE	Cracked	351.60 FL	*285.40 FL
9	1		*FRONT GRILLE EMBLEM	Necessary	28.40 FL	*28.40 FL
10	1		*FRONT GRILLE MOULDING	Cracked	291.30 FL	*291.30 FL
11	2		*FRONT HORN	Cracked (1 PCS ONLY)	152.60 FL	*76.30 FL
12	2		*FRONT HEAD LAMP	Cracked	1,965.80 FL	*1,530.40 FL
13	1		*FRONT HEAD LAMP LOWER BRACKET	N/S Cracked	153.60 FL	*76.80 FL
14	1		*FRONT BUMPER	Dented	1,082.70 FL	*635.60 FL
15	1		*FRONT BUMPER REINFORCEMENT	Dented	541.30 FL	*285.40 FL
16	2		*FRONT BUMPER SIDE RETAINER	Bent	65.00 FL	*65.00 FL
17	1		*FRONT BUMPER TOP BEAM	No such part	101.20 FL	*- FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	123.50 FL	*- FL
19	2		*FRONT BUMPER FOG LAMP	Not fitted	904.60 FL	*- FL
20	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	391.20 FL	*- FL
21	1		*RADIATOR	Bent / Cracked	1,284.20 FL	*1,284.20 FL
22	1		*RADIATOR FAN MOTOR	Not Necessary	656.30 FL	*- FL
23	1		*RADIATOR FAN COWLING	Not Necessary	165.20 FL	*- FL
24	1		*RADIATOR FAN BLADE	Not Necessary	99.20 FL	*- FL
25	1		*AIRCOND CONDENSER	Bent / Punctured	1,195.20 FL	*826.60 FL
26	1		*AIRCOND FAN MOTOR	Not Necessary	569.50 FL	*- FL
27	1		*AIRCOND FAN COWLING	Not Necessary	164.20 FL	*- FL
28	1		*AIRCOND FAN BLADE	Not Necessary	95.20 FL	*- FL
29	1		*FRONT FENDER	N/S Buckled	1,370.40 FL	*685.20 FL
30	2		*FRONT FENDER COWLING	Not Necessary	370.40 FL	*- FL
31	1		*REAR BOOT	Badly Dented	1,284.70 FL	*903.00 FL
32	1		*REAR BOOT LOCK	Twisted / Jammed	295.40 FL	*145.00 FL
33	1		*REAR BOOT LOCK CATCH	Not Necessary	95.20 FL	*- FL
34	1		*REAR BOOT CENTRE GARNISH	Not Necessary	235.90 FL	*- FL
35	1		*REAR BOOT RUBBER	Twisted	215.30 FL	*166.80 FL
36	2		*REAR BOOT ABSORBER	Not Necessary	336.20 FL	*- FL
37	2		*REAR BOOT HINGE	Not Necessary	184.00 FL	*- FL
38	1		*REAR BOOT EMBLEM (STREAM)	Necessary	55.60 FL	*35.00 FL
39	1		*REAR BOOT INNER TRIM BOARD	Deformed / Cracked	352.60 FL	*225.30 FL
40	1		*REAR BOOT INNER PULL CABLE GARNISH	Not Necessary	165.20 FL	*- FL
41	1		*REAR BOOT CENTRE EMBLEM	Not Necessary	65.02 FL	*- FL
42	1		*REAR BOOT WIPER MOTOR	Not Necessary	756.80 FL	*- FL
43	2		*REAR FENDER INNER GARNISH	Not Necessary	828.00 FL	*- FL
44	2		*REAR TAIL LAMP	Cracked	1,779.60 FL	*676.60 FL
45	2		*REAR TAIL LAMP PANEL	Repair	322.40 FL	*- FL
46	1		*REAR FLOOR PANEL	Repair	1,102.30 FL	*- FL
47	1		*REAR FLOOR PANEL TOP COVER BOARD	Repair	351.20 FL	*- FL
48	1		*REAR END PANEL	Badly Dented	725.30 FL	*306.40 FL
49	1		*REAR END PANEL (LOWER)	Badly Dented	365.20 FL	*184.50 FL
50	1		*REAR END PANEL TOP GARNISH	Twisted	170.30 FL	*170.30 FL
51	1		*REAR BUMPER	Dented	951.50 FL	*665.40 FL
52	1		*REAR BUMPER TOP BEAM	No such part	215.20 FL	*- FL
53	2		*REAR BUMPER SIDE RETAINER	Bent	63.40 FL	*63.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*REAR BUMPER LOWER BRACKET	Bent	130.00 FL	*130.00 FL
55	1		*REAR BUMPER TOWING COVER	Twisted	64.40 FL	*28.00 FL
56	2		*REAR NUMBER PLATE LAMP	Not Necessary	96.00 FL	*- FL
57	1		*REAR EXHAUST SILENCER	Not Necessary	984.50 FL	*- FL
58	2		*REAR EXHAUST RUBBER	Not Necessary	76.00 FL	*- FL
59	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*40.00 FS
60	3		*FRONT GRILLE CLIPS	Not Necessary	15.00 FS	*- FS
61	1		*FRONT BONNET INSULATOR CLIPS (12 PCS)	Necessary	60.00 FS	*40.00 FS
62	8		*FRONT BUMPER LOWER CLIPS	Necessary	40.00 FS	*40.00 FS
63	10		*REAR BOOT INNER BOARD CLIPS	Necessary	50.00 FS	*40.00 FS
64	1		*REAR BOOT WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
65	4		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
66	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
67	12		*REAR FENDER INNER GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
68	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
69	1		*REAR REVERSE CAMERA	Not Necessary	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,440.02	11,678.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,415.00	2,285.60
Total Parts (\$\$)	23,025.02	9,392.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	200.00	30.00
2	TUFF KOTE	New	200.00	120.00
3	TOWING	New	120.00	0.00
4	REMOVE AND REPLACE AIRCOND CONDENSER AND REFILL GAS	New	160.00	100.00
5	REMOVE AND REPLACE RADIATOR	New	100.00	0.00
6	REMOVE AND REFIX REAR BOOT WINDSCREEN	New	160.00	120.00
7	REMOVE AND REFIX BOOT GARNISH ITEM	New	200.00	60.00
8	REMOVE AND REPLACE REAR EXHAUST PIPE	New	160.00	0.00
9	REMOVE AND REFIX UPHOLSTERY AND CUSHION SEAL	New	160.00	80.00
10	REMOVE AND REPLACE REVERSE CAMERA	New	160.00	0.00
11	REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	3,000.00	1,200.00
12	TO SPRAY PAINTING AND ETC	New	3,000.00	1,800.00
Gross Labour Cost (\$\$)			7,620.00	3,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >