

ASS. REC. BY:

REF

CS/ICS18019251/Uvd3n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

murmur
Crystabelle Tan

of

ICS

Date/Time:

22/10/18 @ 6:31pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 9689J

Insured:

SLJ 3161D

at Workshop m/s

Liu's Brother

Tel:

67411730

of

No. 1 Kaki Bkt Ave 6 # 01-01

Policy No:

Claim No:

DMPC1800401H/02/CT

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/10/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

24/10/2018

Date/Time:

9:49am @ 22/10/18

Person Contacted:

Susan

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKQ 9689J - NA / AIG / 8019086 / 13

DOA: 20/10/18

SLJ 3161D - NA / AIG / 8019086 / 13

DOA: 20/10/18

Susan arrange on 24/10/18.

Signature NO/CUS

REF:

SCIC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKQ 9689J
11w's Bn

at Workshop/mis

of

insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vehl

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days
20 %

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTAF7000

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SKQ 9689J

Yr Regn:

11/15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make

Mercedes Benz 250

1991

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

53338

T. Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 21203623050251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 265/35 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

20/10/18

D.O.A.

24/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time

Action / Instruction

21/11/18 2/5 8000 confirmed with Subin. (Red 7298.20, 4810)

RECEIVED 02 NOV 2018

Date/Time File Pass to:

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Date/Time File Return to:

2 2/11 - typist

Add Fee:

☐ : Site Insp (S)
☐ : Interview (S)
☐ : Tech Insp (S)
☐ : Wheel-end (S)

Report Format:

merimen

Lump Sum / L.B.I: (S)

8000p

Phone:

Other:

TOTAL

450
10

460

Nivitha (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Monday, 22 October 2018 6:31 PM
To: assignments
Cc: ECICS Claims; Susan Low; Jasmine Low
Subject: RE: Request for 3rd party claims survey SKQ9689J Claims against SLJ3161D - (Our Ref : DMPC1800401H/02/CT)

Dear LKK

Please refer to below email and arrange PRI.

Best regards,
Crystabelle Tan
Claims Division
DID: +65 6303 0190
FAX: +65 6338 9267
Email: crystabelle_tan@ecics.com.sg

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

From: Jasmine Low [mailto:liusbrojasmine@yahoo.com]
Sent: Monday, 22 October, 2018 6:29 PM
To: Crystabelle Tan Gek Peng (ECICS, Claims)
Cc: ECICS Claims; Susan Low
Subject: Re: Request for 3rd party claims survey SKQ9689J Claims against SLJ3161D - (Our Ref : DMPC1800401H/02/CT)

Hi All,

We would like to choose No 1 (LKK)

Thank You.

Regards

Jasmine Low

M/s Liu's Brother Auto
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel : 67411730
Fax: 67445746

On Monday, 22 October 2018, 18:14, "Crystabelle Tan Gek Peng (ECICS, Claims)"
<Crystabelle_Tan@ecics.com.sg> wrote:

Dear Jasmine

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards,
Crystabelle Tan
Claims Division
DID: +65 6303 0190
FAX: +65 6338 9267
Email: crystabelle_tan@ecics.com.sg

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

From: Jasmine Low [mailto:liusbrojasmine@yahoo.com]
Sent: Monday, 22 October, 2018 5:48 PM
To: Desmond Lee Ker Wen (ECICS, Claims); ECICS Claims; Janice Goh Siew Geok (ECICS, Claims)
Subject: Request for 3rd party claims survey SKQ9689J Claims against SLJ3161D

Re: Request for 3rd party survey SKQ9689J Claims against SLJ3161D

Accident on 20/10/2018 Along Paya Lebar Rd TWDS Sims Ave next to Paya Lebar SQ

Involving SKQ9689J and SLJ3161D

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Jasmine Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit

Singapore 417883 ☎: 6741 1730 📠: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :- _____

follow us on  facebook follow us on  twitter visit our website  **ECICS**
ecics.com.sg insurance

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8045J
Vehicle Details	
Vehicle No.:	SKQ9689J
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 SEDAN (R18)
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	27492030212893
Chassis No.:	WDD2120362B050251
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$49,580.00
Original Registration Date:	09 Jan 2015
First Registration Date:	09 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$56,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2025
PARF Rebate Amount:	\$42,309.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jan 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$72,002.00
COE Rebate Amount:	\$44,691.00
Total Rebate Amount:	\$87,000.00

The information contained herein is correct as at 24 Oct 2018

OK

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liusbro@gmail.com

Invoice/Ref No: SKQ9689J181020

Estimate

Customer

Name: ECICS Limited

Address: Motor Claims Department

7 Temasek Boulevard #10-01

Suntec Tower One Singapore 038987

Date: 22-10-18

Vehicle No: SKQ9689J

Model/Make: Mercedes Benz
E250 Sedan (R18)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bootlid <i>20/3uc 2439.10</i>	\$ 2,560.00	N
2	Bootlid "Mercedes Logo" Motif <i>neu</i>	\$ 56.00	N
3	Bootlid "E250" Emblem <i>neu</i>	\$ 78.00	N
4	Bootlid "7G-Tronic" Emblem <i>neu</i>	\$ 120.00	N
5	Bootlid Outer Chrome Moulding <i>scr/neu</i>	\$ 110.00	N
6	Bootlid Reflector 02 pcs (@ 385. N) <i>scr/cro</i>	\$ 770.00	N
7	Bootlid Inner Lock <i>neu</i>	\$ 270.00	N
8	Bootlid Weather Strip <i>70.1</i>	\$ 166.00	N
9	Bumper <i>20/2</i>	\$ 1,540.00	N
10	Bumper PDC Sensor 04 pcs (@ S\$223.30) <i>shld</i>	\$ 893.20	N
11	Bumper Sponge <i>NF</i>	\$ 179.00	N
12	Bumper Chrome Moulding Sides 02 pcs (@ S\$120.00 N) <i>neu</i>	\$ 240.00	N
13	Bumper Clips 1 set <i>neu</i>	\$ 60.00	N
14	Bumper Lower Garnish <i>cu7</i>	\$ 230.00	N
15	Bumper Side Retainers 02 pcs (@ S\$30.00) <i>11</i>	\$ 60.00	N
16	Bumper Exhaust Chrome 2 pcs (@ S\$28.00 N) <i>scr</i>	\$ 56.00	N
17	Bumper Reinforcement <i>715</i>	\$ 745.00	N
18	Tail Lamp 02 pcs (@ S\$700.00 N) <i>MSB20 645</i>	\$ 1,400.00	N
19	End Panel <i>3rd 50D 1016.32</i>	\$ 1,160.00	N
20	End Panel Top Garnish <i>scr</i>	\$ 120.00	N
21	Floor Panel <i>11</i>	\$ 1,265.00	N
22	Floor Panel Top Board <i>102</i>	\$ 610.00	N
	To check all wiring & electrical component for proper function	\$ 50.00	20
	Remove and rereplace rear PDC sensor	\$ 80.00	50
	Remove and refix rear Bootlid & mechanism	\$ 100.00	80
	Remove and refix seat cushion & upholstery	\$ 100.00	80
	To remove & replace rear exhaust Pipe	\$ 100.00	X
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 900.00	600
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,200.00	800

Total Parts & Labour of estimate for damaged vehicle

\$ 15,298.20

Total amount in Lump Sum Basis for repaired vehicle



M/s Liu's Brother Auto Engrg Wks

LKX/SDLS consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
neu
24/10/18
2/5 \$8000/-
5 day

P-928872
10%
8389.84
1640
10049.84
8039.87

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18019251/UVD3N2

Date: 07/11/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SKQ9689J	Insured Vehicle No :	SLJ3161D
Date of Loss:	20/10/2018	Nature of Claim:	TP
		Claim No:	DMPC1800401H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ9689J	Engine No:	27492030212893
Make & Model:	MERCEDES-BENZ E250, 2.0 (A)	Chassis No:	WDD2120362B050251
Reg. Date:	09/01/2015 (Man. Year: 2014)	Odometer:	53338 km
Colour:	Grey		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/35R18	Rear Tyre Size:	265/35R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,688.20	8,359.85	4,328.35	34.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,690.00	920.00	35.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,298.20	10,049.85	5,248.35	34.31
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	15,298.20	8,000.00	7,298.20	47.71

INSPECTION

Date of Assignment:	22/10/2018	
Date Inspected:	24/10/2018 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2018)
Parts: 143	MERCEDES-BENZ E250 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKQ9689J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Dented/Buckled	2,560.00 F	*2,439.10 FN
2	1	*REAR BOOTLID MERCEDES LOGO MOTIF	Necessary	56.00 F	*56.00 FN
3	1	*REAR BOOTLID E250 EMBLEM	Necessary	78.00 F	*78.00 FN
4	1	*REAR BOOTLID 7G-TRONIC EMBLEM	Necessary	120.00 F	*120.00 FN
5	1	*REAR BOOTLID OUTER CHROME MOULDING	Scratched/Necessary	110.00 F	*110.00 FN
6	2	*REAR BOOTLID REFLECTOR	Scratched/Cracked	770.00 F	*770.00 FN
7	1	*REAR BOOTLID INNER LOCK	Twisted	270.00 F	*270.00 FN
8	1	*REAR BOOTLID WEATHER STRIP	Torn	166.00 F	*166.00 FN
9	1	*REAR BUMPER	Dented/Deformed	1,540.00 F	*1,540.00 FN
10	1	*REAR BUMPER PDC SENSOR (4 Pcs)	Shorted (1Pc Only)	893.20 F	*223.30 FN
11	1	*REAR BUMPER SPONGE	Not fitted	179.00 F	*- FN
12	2	*REAR BUMPER CHROME MOULDING SIDES	Necessary	240.00 F	*240.00 FN
13	1	*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FN
14	1	*REAR BUMPER LOWER GARNISH	Cut	230.00 F	*230.00 FN
15	2	*REAR BUMPER SIDE RETAINERS	Not Necessary	60.00 F	*- FN
16	2	*REAR BUMPER EXHAUST CHROME	Serviceable	56.00 F	*- FN
17	1	*REAR BUMPER REINFORCEMENT	Dented	745.00 F	*715.00 FN
18	1	*REAR TAIL LAMP	N/s Broken	1,400.00 F	*645.00 FN
19	1	*REAR END PANEL	Badly Dented	1,160.00 F	*1,016.32 FN
20	1	*REAR END PANEL TOP GARNISH	Serviceable	120.00 F	*- FN
21	1	*REAR FLOOR PANEL	Not Necessary	1,265.00 F	*- FN
22	1	*REAR FLOOR PANEL TOP BOARD	Warped	610.00 F	*610.00 FN

F=Franchise part. N=NetItemDisc.

Sub Total (\$\$)	12,688.20	9,288.72
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	928.87
Total Parts (\$\$)	12,688.20	8,359.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE AND REREPLACE REAR PDC SENSOR	New	80.00	50.00
3	REMOVE AND REFIX REAR BOOTLID & MECHANISM	New	100.00	80.00
4	REMOVE AND REFIX SEAT CUSHION & UPHOLSTERY	New	100.00	80.00
5	TO REMOVE & REPLACE REAR EXHAUST PIPE	New	100.00	-
6	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	60.00
7	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	900.00	600.00
8	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	1,200.00	800.00
Gross Labour Cost (S\$)			2,610.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >