

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2006367

INV Date 15/09/2020

Reference CC3/CTI18019267/Kes3s2

Code

PROFESSIONAL SERVICE FEE

Vehicle No. SHF 613E

Insured Veh. **GBH 5968J**

Claim No. SNM18D04952C02

Policy No. DMCVSN3047741800

Accident Date 12/10/2018

Inspection Date 22/10/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile							
CHIN	IINA TAIPING INSURANCE (S) PTE LTD Ref : CC3/CTI18019267/Kes3s2							
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 15-09-2020 Code: CTI						
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	GBH 5968J	Veh. Inspected	SHF 613E				
	Policy No.	DMCVSN3047741800	Coverage (\$)	0.00				
	Claim No.	SNM18D04952C02	Excess (\$)	0.00				
	Assign From		Assign Date	22/10/2018				
2.		Vehicle Partic	culars & Condition					
	Make & Model	RENAULT LATITUDE (A)	c.c	1995				
	Engine No.	HIDDEN	Year of Reg.	2014				
	Chassis No.	VF1ABL15AUC278452	Colour	METALLIC WHITE / RED				
	Odometer	481923	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	NIL				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	215/60 R16	GITI	9 mm				
	L/H Front Tyre	215/60 R16	GITI	9 mm				
	R/H Rear Tyre	215/60 R16	LING LONG	7 mm				
	L/H Rear Tyre	215/60 R16	LING LONG	7 mm				
4.		•	on of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	REAR PORTION.					
	DAMAGES SEE D	ETAILS.						
5.		General	Information					
	Accident Date	12/10/2018	Inspection Date	22/10/2018				
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD					
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	5b. Estimate Days of Repair							
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days							



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 613E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	DISTORTED	135.97	135.97
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
	LESS 10% DISCOUNT		-668.58	-454.36
			6,017.20	4,089.20
	SPECIAL NETT ITEMS			
1	SET WHEELARCH CLIP REAR LH (SN)	NOT NECESSARY	30.50	_
	,		30.50	-
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		3,000.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			7,870.00	1,190.00

Report Ref No. CC3/CTI18019267/Kes3s2



Page No.:2 of 2

GRAND TOTAL	13,917.70	5,279.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		4,200.00

Report Ref No. CC3/CTI18019267/Kes3s2

KONG SENG CHEONG

Licensed Appraiser