

ASS. REC. BY:

REF: CS/AIG/18019269 / Ur d3

Special Instruction: n2

Surveyor: Manan ASSIGNMENT (Office)

From (Person): Azlan Syairidina of AIG Date/Time: 23/10/18 @ 2:17pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV 1114C Insured: SDV 9595C

at Workshop m/s Mahlian Motor Tel: 6282 3336

of No. 38 Defu lane 9

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/10/18

(Client's Record) CA / REV / REP. / REV 24 HRS up 24/10/2018 @ After 11am

Date/Time: 5:03pm @ 23/10/18 Person Contacted: wan RO Vehicle IN / OUT (IN)

Date/Time	Action/Instruction (✓) Estimate
	SKV 1114C - X
	SDV 9595C - NA (AIG) 8000900/h4 Boa: 16/2/2017

REF: **ALG**

REF: **ALG**

ASSIGNMENT

From: _____ Date: **24/10/2018**

Estimated Cost: _____

ON / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKV1114C**

at Workshop m/s: **Mah Tian Motor**

of: **No-38 Defu Lane 9**

Insured: _____


Policy No.: **SDV 9595C**

Claims No.: _____

Sum Insured: _____ Excess: _____

(Client's Record) **After Lam**

Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: **7.31** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SKV1114C** Yr Regn: **8, 15**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or **CA**

Make: **BMW 318i** c.c. **1499**

Colour: **Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **57715** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **W1BA8E32070K497620**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/50R17**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front **6** mm Rear **6** mm

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **19/10/18** D.O.I. **24/10/18**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MSH.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTA 64304
	by #3068-40
11/11/18	No second hand parts confirmed fuel fig #6375.91 with Sihu.
	Red: \$ 4735.49, 43%.

RECEIVED 07 NOV 2018

Date/Time, File Pass to? : Preli. Report

1) **tpust** : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: **TP**

Lump Sum / I.B.I: (\$ **6375.91**)

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee:	250
Transportation:	20
S + RS: \$	
Photos	
Others	
TOTAL	270

- Pre repair inspection request - SKV1114C VS SDV9595C (OI) DOA 19/10/2018

From: Azlan, Syezairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit
Sent: 23/10/2018 2:17:45 PM
Attachments:  PRI - SDV9595C AND SKV1114C.pdf  4785_001.pdf

Hi,

Please refer to the enclosed request from **VISION LAW LLC**.

Claim no : 60687919655G003
Case Owner : KAI JYE WUI

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Azlan, Syezairdina
Sent: Tuesday, October 23, 2018 10:14 AM
To: jactan@visionlawllc.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDV9595C AND SKV1114C ON 19/10/2018

Without Prejudice

Your Reference : AM.jt.Ins.M46.SKV1114C.18 (sj)
Our Reference : SDV9595C

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI DIO MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
JANICE HAN JIA LIN
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#10-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ **HEAD OFFICE**
TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com
BRANCH
TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.M46.108431.18 (sj)
Your Ref: SDV 9595 C

23 October 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

BY FAX: 6415-3727
email: syazairdina.azlan@aig.com
Email: noormariesa.abukassim@aig.com

Dear Sirs,

ACCIDENT INVOLVING SKV 1114 C & SDV 9595 C ON 19 OCTOBER 2018 ALONG UPPER SERANGOON ROAD AT ABOUT 1930 HOURS

We refer to your email dated 23 October 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus Chua of LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Mah Lian Motor Vehicle Repairer
No.38 Defu Lane 9
Singapore 539278
Contact Person: Mr Goh / Ms Si Hui (6282 3336)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALI M
(HEAD OFFICE)

cc: SKV 1114 C – By Fax: 6289-3336

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0412A
Vehicle Details	
Vehicle No.:	SKV1114C
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	B.M.W.
Vehicle Model:	318I SEDAN LED NAV
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	F9951204B38B15A
Chassis No.:	WBA8E32070K497620
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,993.00
Original Registration Date:	31 Aug 2015
First Registration Date:	31 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$28,991.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2025
PARF Rebate Amount:	\$21,743.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,140.00
COE Rebate Amount:	\$42,562.00
Total Rebate Amount:	\$64,305.00

The information contained herein is correct as at 24 Oct 2018

OK

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : AXA Insurance Pte Ltd
 8 Shenton Way #24-01
 Singapore 068811

TEL: 6880 5500 FAX: 6880 5501
 ATTN: Motor Claim Department

Your Ref No: GAN KIM KEE
 Claim Type: Third Party
 Accident Date: 19/10/2018

Estimate No: ES1700344
Date: 19 Oct 2018
Policy No: VPA/1655635
Veh Reg No: SKV1114C
Make/Model: B.M.W. 318I SEDAN
 LED NAV
Chassis No: WBA8E32070K497620
Engine No: F9951204B38B15A
Reg. Date: 31/08/2015

Estimate Repair Cost to Vehicle No :SKV1114C

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
36 To spray & painting at accident dented area .	600	1 JOB	650.00	
37 To rush proofing at accident area .	30	1 JOB	200.00	
38 To move & refit headlamp , fog lamp , headlamp control unit to reset & realignment .	30	1 JOB	60.00	
			1,660.00	1,660.00
			Total	SS 11,111.40
			Add GST @ 7%	777.80
			Total Amount Payable	SS 11,889.20

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND EIGHT HUNDRED EIGHTY NINE AND CENTS TWENTY ONLY

**For MAH LIAN MOTOR VEHICLE
 REPAIRER**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-5595.70
 5%
 535.91
 14200 1060
 6375.91

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18019269/URD3N2

Date: 12/11/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100494596
Claimant Vehicle No :	SKV1114C	Insured Vehicle No :	SDV9595C
Date of Loss:	19/10/2018	Nature of Claim:	TP
		Claim No:	6068791965SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV1114C	Engine No:	F9951204B38B15A
Make & Model:	BMW 318i, 1.5 SEDAN LED NAV (A)	Chassis No:	WBA8E32070K497620
Reg. Date:	31/08/2015 (Man. Year: 2015)	Odometer:	57715 km
Colour:	Grey		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,451.40	5,315.91	4,135.49	43.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,060.00	600.00	36.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,111.40	6,375.91	4,735.49	42.62
+ GST 7.00/7.00% (S\$)	777.80	446.31	331.49	42.62
Nett Amount (S\$)	11,889.20	6,822.22	5,066.98	42.62

INSPECTION

Date of Assignment:	23/10/2018		
Date Inspected:	24/10/2018	Inspected At:	Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	982.75 F	*982.75 FL
2	1		*FRONT BUMPER MOUNTING SUPPORT	Bent	8.45 F	*8.45 FL
3	2		*FRONT BUMPER NOZZLE COVER LH	Not fitted	84.40 F	*- FL
4	1		*FRONT BUMPER RETAINER LH	Cracked	36.00 F	*36.00 FL
5	1		*FRONT BUMPER CENTER LOWER GRILLE	Not Necessary	121.95 F	*- FL
6	1		*FOG LAMP BRACKET LH	Not Necessary	41.85 F	*- FL
7	1		*FRONT BUMPER CENTER LOWER TRIM LH	Cracked	90.25 F	*90.25 FL
8	1		*FRONT GRILLE LH	Not Necessary	115.65 F	*- FL
9	1		*FOG LAMP COVER LH	Cut	90.25 F	*90.25 FL
10	1		*FOG LAMP COVER TRIM LH	Torn	51.90 F	*51.90 FL
11	1		*FOG LAMP COVER TRIM LH	Not Necessary	39.25 F	*- FL
12	1		*FOG LAMP LH	Cracked	417.15 F	*417.15 FL
13	1		*HEADLAMP ASSY LH	Broken	3,068.40 F	*3,068.40 FL
14	1		*HEADLAMP CONTROL UNIT	Not Necessary	893.90 F	*- FL
15	1		*HEADLAMP AIM LH	Not Necessary	165.40 F	*- FL
16	1		*LED MODULE LH	Not Necessary	150.55 F	*- FL
17	1		*LED FAN LH	Not Necessary	395.80 F	*- FL
18	1		*LED SIGNAL MODULE LH	Not Necessary	786.65 F	*- FL
19	1		*AIR DUST TOP	Not Necessary	56.65 F	*- FL
20	1		*AIR DUST LOWER	Not Necessary	51.50 F	*- FL
21	1		*BRAKE AIR DUST LH	Not Necessary	51.50 F	*- FL
22	1		*FRONT FENDER LH	Dented/Bemt	682.50 F	*682.50 FL
23	1		*FRONT FENDER BRACKET LH	Not Necessary	32.15 F	*- FL
24	1		*FRONT FENDER BRACKET LH	Not Necessary	32.15 F	*- FL
25	1		*FRONT FENDER BRACKET LH	Not Necessary	32.15 F	*- FL
26	1		*FRONT FENDER SHIELD LH	Torn	51.50 F	*51.50 FL
27	1		*FRONT FENDER SHIELD LH	Torn	116.55 F	*116.55 FL
28	1		*FRONT FENDER SHIELD LH	Repeated	116.55 F	*- FL
29	1		*FRONT FENDER SHIELD LH	Repeated	145.65 F	*- FL
30	1		*FRONT PANEL CROSSLINK	Not Necessary	164.95 F	*- FL
31	1		*FRONT LOCK PANEL	Not Necessary	15.50 F	*- FL
32	1		*FRONT CROSSLINK V BAR	Not Necessary	110.00 F	*- FL
33	1		*HEADLAMP LOWER BRACKET	Not Necessary	53.95 F	*- FL
34	1		*SPARE TANK	Not Necessary	197.60 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,451.40	5,595.70
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	279.79
Total Parts (\$\$)	9,451.40	5,315.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY & PAINTING AT ACCIDENT DENTED AREA	New	650.00	600.00
2	TO RUSH PROOFING AT ACCIDENT AREA	New	200.00	30.00
3	TO REMOVE & REFIT HEADLAMP, FOG LAMP, HEADLAMP CONTROL UNIT TO RESET & REALIGNMENT	New	60.00	30.00
4	LABOUR CHARGE TO CUT, WELD, DISMANTLE, REMOVE, REFIT ALL ABOVE PARTS	New	750.00	400.00
Gross Labour Cost (S\$)			1,660.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >