Surveyor Kenneth CWS From (Person): Karen Tan	ASSIGNMENT (OF FCI		offine: 23/10/180	5.21pm
Estimated Cost:	Bill to:			
OD / P WS/TP RES/OD R	SHF 637S	Insured:	SHC 8886 7	•
at Workshop m/s	trans-Cab Auto	Tel:	G287 6666	
of	No. 2 AMIC ST-63			
Policy No:	-Clair	n No: 01800	7667 MFSH	
Sum Insured:	Ех	cess:		
Make of Veh:		D.0	D.A. [9/10/201	8
(Client's Record)				
CA / REV / REP. / REV 24		e Wil Veh	H.O.D. Endorsement:	
Date/Time: 9 02em@24110	Person Contacted: Zh	e was ven	icio II vi co ci	
Date/Time Action/Instruction	on (/) Estimate			1
SHF 537	S-CC3 II 16009322/1	Jub392	DOA: 17/05	
	64- NSIINC180028581	Klabn 2	DOA: 10 00	3-018
		1		
Revert	1A through email.			
11111				

3/harmic	REF: FCI		
3114000	ASS	IGNMENT O	
From:	Date: 24/10/2018	Veh No. 5/1/ 537	S Yr Regn: 06 259
Estimated Cost:	27110 200	Type: M.Car / M.Cycle / Bus / Van / L.	orry / Prime Mover /
WS / TP RES / OD RE	S/FVA/INV/MV	Truck / Trailer or	
To Inspect Vehicle No:	SHF 5375	Make: Renault 6	orihode 00 1985
	Trans. Cab	colour White / Rea	A/C: Insured / Std / NI / NA
of No-2 At	MK 8+ 63	Sp.Reading	T/Radio: Insured / Std / NI / NA
nsured:		Eng/No:	-1 278201
Policy No.			15 Auc 278306
Claims No.		Gen. Cond: Good / Fair / Poor / Burn	
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leaked	
(Client's Record)		Brake: In order / Jammed / Leaked	
Make of Veh:		Modi: All S/Rim / STD A/Rim	_
	MEST HE REQUIRE	Tyre Size: F:	15/60K16
(Policy Condition)		R:	
Remark: The veh had commer	nced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZ/	
repair at the time of	inspection.	TOYO / YOKO or	Giti
Bal. or Market Value:	· ·	Front	Rear
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. 6 mm	R/Bal. 0 mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. 6 mm	L/Bal. mm
Est. Repairs: 1/2		D.O.A. 19/10/18	D.O.I. 24/10/18
Lum Sum: 20	% 3 Val.: Yes or No	Survey held at	
	(Nc)	Des. of Damages : Frt Rear Of	S / N/S / U/C / Rooftop or
CA / REV / REP. / 24	Vehicle: IN / OU		
Date: Person	Contacted:		ody Structure affected due to collision.
Date / Time Action / Inst			
25/10 Fle pg1	(Red & 22857.01	01 7)	
D9501	(Red . \$ 22831.01	, 167.)	
(onfirm	with the Wei		
	RECEIVED 3 0 OCT 2	018	
	KLOLIVLD 3 0 00. L		
	1	Davis Of Bonsier 14	121,000 10
Date/Time, File Pass to?	: Preli. Report	Days Of Repair: 14	13×15= 19
1) typit \	: Preli. Report : Final Report	Days Of Repair: 1% Resurvey No. of Trip: ~	Survey Fee: 170 + 19
1) typit Date/Time, File Return to?	: Final Report	Resurvey No. of Trip:	-
1) typit Z	=	Resurvey No. of Trip: ~	Survey Fee: 170 + 19. Transportation: 50
1) Typist Date/Time, File Return to?	: Final Report	Resurvey No. of Trip:	Survey Fee: 170 + 19. Transportation: 50
1) typit Date/Time, File Return to? 2) Report Format:	: Final Report Add I	Resurvey No. of Trip: ~	Survey Fee: 170 + 19. Transportation: 50 S+PS,_SI Photos 55 11



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18007667MFSH

Date: 26 October 2018

Our Ref: CS/FCI18019302/Krd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHF 537S .

Please be informed that we had conducted the inspection of the above mentioned vehicle on <u>24/10/2018</u> at the premises of M/s <u>TRANS-CAB AUTO PTE LTD</u> and have the following to report:-

Workshop Estimate Amount	: S\$	23,807.01	
Revised Estimate Amount	: S\$	1,177.96	
"Check" Items Amount	: S\$	584.284.00	
Market Value	: S\$	-	
LTA Reimbursement Value	: <u>S</u> \$	•	
Nett Value	: <u>S\$</u>		

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KENNETH Automotive Assessor



MS First Capital Insurance Limited | GaReg No. 195000108C | GST Reg No. Mg C001676-9 6 Raffles Quay #21-00 Singapore 048580 Tet (65) 6222 2311 | Fax: (65) 6222 3547

Claims & Motor Underwitting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

23-10-2018

Our Ref No. D18007667MFSH

Accident Date

19-10-2018

Claim Type. Third Party

Insured Vehicle

SHC8886Y

Third Party Vehicle. SHF537S

Survey Location

NO. 2 ANG MO KIO STREET 63

Contact Person.

KEK ZHEWEI

Contact No.

62876666/0

Fax No. 62571330

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

TRANS-CAB AUTO

SERVICES PTE LTD

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

KARENT

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Friday, October 26, 2018 2:30 PM

To:

'CWS Motor Claims'

Cc:

'Karen Tan'; SUR

Subject:

RE: SURVEY ASSESSMENT - D18007667MFSH/1

Attachments:

SHF 537S.pdf

Dear Sir/ Madam,

Enclosed preliminary revised SHF 537S.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, October 24, 2018 9:03 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18007667MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 23 October 2018 5:21 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan < karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18007667MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey. Kindly submit your report via CWS within the next 14 days. Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

This email has been checked for viruses by AVG antivirus software.
www.avg.com
37

Janice Lee (LKKAuto)

From:

Zhe Wei <zhewei.kek@transcab.com.sg>

Sent:

Tuesday, October 30, 2018 10:50 AM

To:

Janice Lee (LKKAuto)

Cc:

'Ng Wai Yin' RE: SHF 537S

Subject: Attachments:

image001.wmz

Hi Janice,

L/S repair confirmed \$950/-.

Thank you.

Kindly quote our reference in your future replies to us.

Best Regards, Kek Zhewei Claims Officer



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63. Singapore 569111 Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]

Sent: Tuesday, October 30, 2018 10:19 AM

To: zhewei.kek@transcab.com.sg

Cc: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Subject: SHF 537S

Dear Zhe Wei,

Kindly confirm L/S \$950 @ 1.5 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHF5375
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB.4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001589
Chassis No.:	VF1ABL15AUC278306
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998,00
Original Registration Date:	13 Jun 2014
First Registration Date:	13 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$26,094.00
Total Rebate Amount: Message	\$35,467.00
at the contract of the contrac	be further renewed. The vehicle must be de-registered upon COE expiry or when the

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Oct 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHF 537S

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Nor Norhankel USmy & 950L

AAD1810-232

SHF 537S

VF1ABL15AUC278306

RENAULT

LATITUDE

19.10.18

FCIL

PART

LIST

			03890
1	1 BUMPER COVER REAR	\$	1,108.46 ¥
2	1 BUMPER LOWER REAR	\$ '	768.84
3	1 BUMPER BRACKET CTR REAR	\$	JL 113.47
4	1 BUMPER BRACKET SIDE RH REAR	\$	ر 135.97
5	1 BUMPER RETAINER RH REAR	\$	اد 44.99
6	1 BUMPER REFLECTOR RH	\$	امر 43.61
7	1 BUMPER BRACKET SIDE LH REAR	\$	√ _{135.97}
8	1 BUMPER RETAINER LH REAR	\$	5∟ _{44.99}
9	1 BUMPER REFLECTOR LH	\$	√ _{43.61}
10	1 BUMPER BEAM REAR	\$	N 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	N 225.95
13	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	√S 404.56
15	1 TAILLAMP RH	\$	√s 552.55 \
16	1 TAILLAMP PANEL RH	\$	n 986.70 X
17	1 TAILLAMP LH	\$	√ 552.55
18	1 TAILLAMP PANEL LH	\$	N 986.70
19	1 BOOT REAR	\$	A 2,872.68
20	1 BOOT FINISHER	\$	مر 470.06
21	1 BOOT WHEATERSTRIP	\$	امر 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>^</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	493.35
24	1 BOOT BADGE 'RENAULT'	\$	225.36
25	1 BOOT BADGE	\$	~~ 225.36 \
26	1 BOOT STRUT LH	\$	Sh 276.08
27	1 BOOT STRUT RH	\$	رم _{276.08}
28	1 BOOT HINGE LH	\$	N 367.84
29	1 BOOT HINGE RH	\$	M 367.84

	cab Auto Services Pte Ltd			AAD1810-232
	ng Mo Kio Street 63 Singapore 569111			
Tel No.	: 6287 6666 Fax No. : 6257 1330			
CO./GS	T Reg. No. 201019626G			
SHF 53	75			
30	1 BOOT INNER TRIM		\$	Sh 586.45 X
31	1 BOOT SWITCH		\$	∫∠ 168.13 ×
32	1 BOOT LOCK		\$	A 202.67 ×
33	1 BOOT LOCK CATCH		\$	M 74.40 X
		TOTAL	\$	16,046.87
		10%	\$	1,604.69
			\$	14,442.19
		,		
	Special Nett			
1 1	SET PARKING AID		\$	Sh 700.00
(7)	SET REAR BUMPER CLIP		\$	vn 66.00
	SET BUMPER BRACKET CTR CLIP		\$	~~ 33.00
	SET BUMPER BRACKET SIDE CLIP RH RR		\$	10.00
	SET BUMPER RETAINER RH CLIP RR		\$	nn 20.00 } X
55.7	SET BUMPER BRACKET SIDE CLIP LH RR		\$	nn 10.00
	SET BUMPER RETAINER CLIP LH RR		\$	20.00
	SET BUMPER LOWER REAR RIVET		\$	nn 22.00)
	SET BUMPER LOWER REAR CLIP		\$	NG 66.00
10	1 BOOT STICKER "Trans-cab"		\$	an 80.00 X
11	1 BOOT STICKER "6555-3333"		\$	~~ 80.00 x
12	1 EXHAUST MOUNTING REAR		\$	~~ 17.82 X
13	2 REAR WINDSCREEN SEALANT		\$	ペル 80.00 X
14	1 WINDSCREEN MOULDING		\$	An 100.00 ×
15	1 REAR WINDSCREEN INNER SPONGE SEAL		\$	~~ 100.00 X
10.00		TOTAL	\$	1,404.82
	тот	TAL PARTS	\$	15,847.01
			-	
	LABOUR			2201
	Putty And Spray Painting Of The Affected Po	ortion.	\$	3,000.00
	Panel Beating, Knocking And Straightening	The		
	Necessary Portion, Remove And Renewal Of	Parts,		2001
	Adjust And Realign The Same		\$	3,000.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Adional Adjointy Repairer

SHIP

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 537S

To transfer of tire, rim and on wheel balancing.	\$ 170.00 X	
To remove and refit interior fittings, trimings, garnish,		
	\$ 12 380.00 X	
To Rust-Proofing Of The Affected Areas.	\$ 170.00 X	
To reinstall rear bumper parking sensor.	\$ ~~ 170.00 X	
To transfer of bootlid fittings, attachments and		
perform water seepage test.	\$ 170.00 X	
To repair and realign rear exhaust pipe.	\$ 170.00 X	
To drop rear exhaust box, renew the same, to repair		
and realign centre exhaust pipe.	\$ ~ 170.00 X	
To transfer of rear end panel fittings, attachment and		
perform water seepage test.	\$ ~~ 170.00 X	
To transfer of rear windscreen fittings and conduct		
water seepage test.	\$ 170.00 X	
To check steering geometry and computer wheel	200	
alignment	\$ 220.00 X	
TOTAL	\$ 7,960.00	
Over All Total	\$ 23,807.01	
LUMP SUM (REPAIR DAY)	10-DAYS	
LKK Auto C: *vitants hence notify the Repairer the following: • To resurvey a seafter spray painting • To display the page part(s) during resurvey • Page process are subject to confirmation	16 day	
Third carty servey is on a "Without Prejudice" basis No illingal more cation(s) is allowed Subtlementally item(s) must be resurveyed and is subject to final approval from Insurance Company		

AAD1810-232



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	CONTROL MATERIAL AND A STATE OF THE STATE OF	
IRS'	CAPITAL INSUR	RANCE LTD	Ref : CS/FCI1801930	UZ/Krd3NZ
86 RC #16-0	BINSON ROAD 1 CITY HOUSESI	NGAPORE 068877	Date: 01-11-2018 Code: FCI2	
		Policy Particula	rs :- THIRD PARTY CLA	IM
•	Insured Veh.	SHC 8886Y	Veh. Inspected	SHF 537S
	Policy No.		Coverage (\$)	0.00
E - E	Claim No.	D18007667MFSH	Excess (\$)	0.00
	Assign From	KARENT	Assign Date	23/10/2018
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	VF1ABL15AUC278306	Colour	WHITE / RED
	Odometer	523162	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.	TO STORE STREET	Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	GITI	6 mm
	L/H Front Tyre	215/60 R16	GITI	6 mm
	R/H Rear Tyre	215/60 R16	GITI	8 mm
	L/H Rear Tyre	215/60 R16	GITI	8 mm
4.		THE RESERVE AND PROPERTY OF THE PERSON OF TH	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	19/10/2018	Inspection Date	24/10/2018
	Survey held at	TRANS-CAB AUTO SERVICE	ES PTE LTD	
	330	NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.			Remarks	
	B)THE INSPECTI	NSISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A' ICE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA	ASIS. IISED REPAIRS.
5b.			ate Days of Repair	TO THE REAL PROPERTY.
	ESTIMATED NOR	RMAL PERIOD FOR REPAIR:	1.500 Workin	ng Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 537S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	<i>a</i>
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	
	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	1
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	2
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	8
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	8
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	10
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	8
	TAILLAMP RH	SERVICEABLE	552.55	5
1 8	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	
	TAILLAMP LH	SERVICEABLE	552.55	5
	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	
	1 BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	3
9	1 BOOT FINISHER	SERVICEABLE	470.00	3
	1 BOOT WEATHERSTRIP	SERVICEABLE	323.0	5
8	1 BOOT REFLECTOR LAMP LH	SERVICEABLE	493.3	5
	1 BOOT REFLECTOR LAMP RH	SERVICEABLE	493.3	5
	1 BOOT BADGE "RENAULT"	NOT NECESSARY	225.3	6
	1 BOOT BADGE	NOT NECESSARY	225.3	6

Report Ref No. CS/FCI18019302/Krd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	BOOT STRUT LH	SERVICEABLE	276.08	- 2
- 1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE	367.84	Ş-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	
1	BOOT SWITCH	SERVICEABLE	168.13	
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	
	LESS 10% DISCOUNT		-1,604.68	-76.88
	AND		14,442.18	691.96
	SPECIAL NETT ITEMS			
- 1	SET PARKING AID (SN)	SERVICEABLE	700.00	139
	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	
	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	
	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	
	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	
,	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	
	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	
	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	
- 7	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	
1	1 EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	2
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	
1	1 WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	
8	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	4
			1,404.82	66.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	220.00

Report Ref No. CS/FCI18019302/Krd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER COVER REAR, BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK AND BOOT LOCK CATCH.		3,000.00	
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	1
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	1 -
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	
	ACC TO DATA CHINE DE SENTE PER CONTROL DE CO		7,960.00	420.00
	GRAND TOTAL		23,807.00	1,177.96
	RECOMMENDED COST OF LUMP SUM REPAIRS	ASSESSMENT OF THE PARTY OF THE	II STATE OF STREET	950.00

Report Ref No. CS/FCI18019302/Krd3n2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.