

ASS. REC. BY:

REF:

CS/FCI/18019304/Kvd3n2

Special Instruction:

Surveyor
CWS

Kennedy

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time:

23/10/18 @ 6.15 pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 3389P

Insured:

SHC 7902R

at Workshop m/s

C.S. Ong Auto

Tel:

6484 1933

of

10 AMK Ind. Park 2A #02-16 AMK

Policy No:

Claim No:

D18007676MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

9.07am @ 24/10/18

Person Contacted:

Mrs. Ong

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SMC 3389P - NS/INC/18019255/Klgb
	SHC 7902R - NS/INC/18019255/Klgb
	DOA: 21/10/2018
	DOA: 21/10/2018
25/10/18	Email preli. revised to FCI
1/11	@ 1530L email & confirm (Red 5500.92, 789)

REF: FCI

ASSIGNMENT

From: Date: 24/10/2018

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MYTo Inspect Vehicle No: SMC 3389P
at Workshop m/s C.S. Ong Auto
of 10 AMK Ind. Park 2A # 02-16

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 2103%

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS^{up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMC 3389P Yr Regn: 06 18

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toy Priv^{CA}

Colour: M. Grey

Sp. Reading: 18370

Eng/No:

C/No: 8VW 50

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / ☐ YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 2/11/18

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 24/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/10 File pass to Corham

RECEIVED 01 NOV 2018

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

1/11 - typist

Report Format: cws

Lump Sum / I.B.I: (\$ 1550)

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

150

50

15

215



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18007676MFSH

Our ref: CS/FCI18019304/Kvd3

Date : 25/10/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMC 3389P


We thank for your instruction on 23/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/10/2018 at the premises of M/s C.S.ONG AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,050.92
Revised Estimate Amount	: S\$1,920.00
"Check" Items Amount	: S\$841.73
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	23-10-2018	Our Ref No. D18007676MFSH
Accident Date	21-10-2018	Claim Type. Third Party
Insured Vehicle	SHC7902R	Third Party Vehicle. SMC3389P
Survey Location	10 ANG MO KIO IND PARK 2A #02-16 AMK AUTO POINT	
Contact Person.	HUILING	
Contact No.	64841933/ 0	Fax No. 64841922
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	C.S. ONG AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	RIAZ LLC	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 25 October 2018 11:26 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007676MFSH/1, SMC 3389P
Attachments: SMC 3389P PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMC 3389P
Date of survey: 24/10/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 24 October 2018 9:11 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007676MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 23 October 2018 6:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007676MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

C. S. ONG AUTO PTE. LTD.

Business.Reg.No.: 201408916W

GST Reg.No.: 201408916W

10, Ang Mo Kio Ind. Park 2A, #02-16 AMK Autopoint, Singapore (568047).

Tel: 6484 1933 Fax: 6484 1922

E-Mail: csongauto@yahoo.com.sg

Not Attached
Respray B4 paint
5 days
\$1550/h

To: Motor Claims Department,
MS FIRST CAPITAL INSURANCE LIMITED

Date: 23-10-2018

Accident Involving Vehicles SMC3389P & SHC7902R [Your Insured] on 21/10/2018 @
2015Hrs BETWEEN BLK 612 & BLK 613 CLEMENTI WEST STREET 21 CARPARK

Estimated Repair Costs For SMC3389P (Toyota Prius)

ZVW506118536

1Pc	Rear Bumper	<i>1P</i>	\$	550.80	<i>X</i>
1Set	Rear Bumper Clips	<i>na</i>	\$	35.00	<i>X</i>
1Pc	Rear Bumper Side Retainer LH	<i>1P</i>	\$	102.33	<i>X</i>
1Pc	Rear LH Fender	<i>1P</i>	\$	899.80	<i>X</i>
1Pc	Rear LH Fender Shield	<i>1P</i>	\$	35.00	<i>X</i>
1Set	Rear LH Fender Shield Clips	<i>na</i>	\$	1,256.90	<i>X</i>
1Pc	Rear LH Door	<i>1P</i>	\$	452.30	<i>X</i>
1Pc	Rear LH Inner Lock	<i>1P</i>	\$	177.60	<i>X</i>
1Pc	Rear LH Door Weatherstrip Rubber	<i>1P</i>	\$	169.20	<i>X</i>
1Pc	Rear LH Absorber	<i>1P</i>	\$	488.70	<i>X</i>
1Pc	Rear LH Knuckle	<i>1P</i>	\$	633.60	<i>X</i>
<i>check with Kenneth</i>	1Set Rear LH Wheel Bearing & Hub	<i>} wheel alignment repair if damaged</i>			

Parts Sum: \$ 4,801.23

Parts Less 25%: \$ 1,200.31

Parts Total: \$ 3,600.92

Special Nett. Items

1Pc	Rear LH Tyre	<i>1P</i>	\$	350.00	<i>X</i>
1Pc	Rear LH Tyre Sport Rim <i>Cgo</i>	<i>1P</i>	\$	500.00	<i>✓</i>
Special Nett. Items Total:				\$	850.00

Labour & MISC Charges

* To remove all interior upholstery items on all rear affected areas to facilitate repair and to replace all back once repair is done. \$ 200.00 *801*

* To panel beat all affected areas, replace new parts and realign all above. \$ 1,000.00 *6001*

* To putty and re-spray new paintwork on all rear affected areas.	8601	\$ 1,000.00
* To conduct wheel alignment	601	\$ 100.00
* To check all wiring systems on all affected areas.	nn 201	\$ 150.00 X
* To apply anti-rust agent & coating on all affected areas.	nn	\$ 150.00 X
Labour & MISC Charges Total:		\$ 2,600.00
Parts Total:		\$ 3,600.92
Special Nett. Items Total:		\$ 850.00
Labour & MISC Charges Total:		\$ 2,600.00
Grand Total:		\$ 7,050.92

LKK Auto Consultants hence notify the Repaire of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaire

Signature: _____

Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18019304/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7902R	Veh. Inspected	SMC 3389P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007676MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	23/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZVW506118536	Colour	METALLIC GREY	
Odometer	18370	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TOYO	9 mm	
L/H Front Tyre	195/65 R15	TOYO	9 mm	
R/H Rear Tyre	195/65 R15	TOYO	9 mm	
L/H Rear Tyre	195/65 R15	TOYO	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/10/2018	Inspection Date	24/10/2018	
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 3389P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	550.80	-
1	SET REAR BUMPER CLIPS	NOT NECESSARY	35.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	102.33	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	899.80	-
1	REAR LH FENDER SHIELD	SERVICEABLE	35.00	-
1	SET REAR LH FENDER SHIELD CLIPS	NOT NECESSARY	1,256.90	-
1	REAR LH DOOR	TO REPAIR SEE LABOUR	452.30	-
1	REAR LH INNER LOCK	TO REPAIR SEE LABOUR	177.60	-
1	REAR LH DOOR WEATHERSTRIP RUBBER	SERVICEABLE	169.20	-
1	REAR LH ABSORBER	SERVICEABLE	488.70	-
1	REAR LH KNUCKLE	SERVICEABLE	633.60	-
	LESS 25% DISCOUNT		-1,200.31	-
			3,600.92	-
SPECIAL NETT ITEMS				
1	REAR LH TYRE (SN)	SERVICEABLE	350.00	-
1	REAR LH TYRE CAP (SN)	DENTED	500.00	150.00
			850.00	150.00
LABOUR				
	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS ON ALL REAR AFFECTED AREAS TO FACILITATE REPAIR AND TO REPLACE ALL BACK ONCE REPAIR IS DONE.		200.00	80.00
	TO PANEL BEAT ALL AFFECTED AREAS, REPLACE NEW PARTS AND REALIGN ALL ABOVE. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR LH FENDER, REAR LH DOOR AND REAR LH INNER LOCK.		1,000.00	600.00
	TO PUTTY AND RE-SPRAY NEW PAINTWORK ON ALL REAR AFFECTED AREAS.		1,000.00	660.00
	TO CONDUCT WHEEL ALIGNMENT.		100.00	60.00
	TO CHECK ALL WIRING SYSTEMS ON ALL AFFECTED AREAS.	NOT NECESSARY	150.00	-

Report Ref No. CS/FCI18019304/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST AGENT & COATING ON ALL AFFECTED AREAS.	NOT NECESSARY	150.00	-
			2,600.00	1,400.00
GRAND TOTAL			7,050.92	1,550.00
RECOMMENDED COST OF REPAIRS				1,550.00

Report Ref No. CS/FCI18019304/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.