



Your Ref: 18.25368 PD-O

Date: 18th Jan 2019

Our Ref : CS3/ASM18010174/Avbe2-1

M/s AXA Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKC 3699T

INSURED VEHICLE: SKB 6028R

ACCIDENT DATE: 26/05/2018

We thank you for your instruction on 23/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKC 3699T from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicle SKC 3699T and SKB 6028R.
- c) Final Repair Bill of SKC 3699T from N-51 Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SKC 3699T.

Pre-Repair Inspection Date : 18/06/2018 at M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKC 3699T
Make & Model	: Volvo XC60 T5 2.0 AT ABS D/AB 2WD 5DR Turbo
Year of Registration	: 2012
Chassis Number	: YV1DZ475BC2341899
Engine Capacity	: 1999 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.