

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 9693S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL-DOOR RH (SN)(CONSISTENT)	BENT	1,687.30	1,687.30
1	PANEL-DOOR RH (SN)(CONSISTENT)	BENT	1,960.90	1,960.90
1	SEAL-DOOR (SN)(CONSISTENT)	NECESSARY	230.40	230.40
1	SEAL-DOOR (SN)(CONSISTENT)	NECESSARY	188.20	188.20
2	SOUND DEADENING PAD (SN)(CONSISTENT)	NECESSARY	500.00	500.00
1	ALLOY "18" CHALICE TW (SN)(CONSISTENT)	NOT NECESSARY	1,428.60	-
			5,995.40	4,566.80
	<u>LABOUR</u>			
	TO REPLACE FRT RH DOOR,REAR RH DOOR.REPAIR REAR RH FENDER,RH ROCKER PANEL,ETC.		4,500.00	2,700.00
	TO PUTTY SPRAYPAINT ON FRT RH DOOR,REAR RH DOOR,REAR RH FENDER,RH ROCKER PANEL,ETC.		4,000.00	3,200.00
	TO TRANSFER FRT RH DOOR PART.		500.00	500.00
	TO TRANSFER REAR RH DOOR PART.		500.00	500.00
	TO REPLACE REAR RH RIM.	NOT NECESSARY	50.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	280.00	-
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		486.00	486.00
			10,316.00	7,386.00
	GRAND TOTAL		16,311.40	11,952.80

RECOMMENDED COST OF REPAIRS	11,952.80

Report Ref No. CC4/ASM18019337/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.