

簡福星嘢多工廠
KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

INVOICE NO : TEST
DATE : 07-11-2018

VEHICLE NO. : SGW166B
ACCIDENT DATE : 23-10-2018 08:05
THIRD PARTY REF. : SLF9289B

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SGW166B MERCEDES-BENZ E250A

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT BONNET	1150.00 —
1	FRONT BONNET LOCK CENTRE TOP	35.00 —
1	FRONT BONNET HOOK LH	19.00 —
1	FRONT BONNET CABLE	38.00 —
1	FRONT TOP PANEL	83.00 —
1	FRONT BRACE PANEL	18.00 —
1	FRONT HEADLAMP PANEL LH	133.00 —
1	FRONT BONNET LOWER LOCK LH	22.00 —
1	FRONT HEADLAMP LH	2420.00 —
1	FRONT GRILLE EMBLEM	70.00 —
1	FRONT GRILLE SURROUND CHROME	190.00 —
1	FRONT FENDER LH	480.00 —
1	FRONT FENDER SHIELD FRT	103.00 —
1	FRONT BUMPER	720.00 —
1	FRONT BUMPER FOAM	69.00 —
1	FRONT BUMPER REINFORCEMENT	270.00 —
1	FRONT BUMPER REINFORCEMENT BRACKET LH	147.00 —
1	FRONT BUMPER SIDE BRACKET LH / side carrier LH	34.00 —
1	FRONT BUMPER LOWER GRILLE	39.00 —
1	FRONT BUMPER FOGLAMP COVER LH	26.00 —
1	FRONT BUMPER CENTRE CARRIER	47.00 *
1	AIR CON CONDENSER	580.00 —
1	AIR CLEANER HOSE	102.00 —
1	RADIATOR ASSY	650.00 —
1	RADIATOR FAN ASSY	700.00 —

1/3

VEHICLE NO. : SGW166B
 ACCIDENT DATE : 23-10-2018 08:05
 THIRD PARTY REF. : SLF9289B

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	WASHER TANK	83.00
1	FRONT HEADLAMP HID CONTROL UNIT LH	390.00
1	A/C PRESSURE SWITCH	58.00
1	FRONT GRILLE MESH (gate)	98.00
1	INTERCOOLER	530.00
2	FRONT BONNET SPRING @\$9.00	18.00
1	RADIATOR TOP GARNISH	21.00
1	RADIATOR LOWER GARNISH	44.00
1	FRONT BUMPER REINFORCEMENT SIDE BRACKET LH	29.00
1	FRONT BUMPER TOP BEAM	133.00
1	FRONT GRILLE GARNISH	95.00
1	FRONT SUPPORT TOP COVER	73.00
2	RADIATOR TOP BRACKET ^{bush} @\$13.00	26.00
2	RADIATOR TOP BRACKET CLIP @\$7.00	14.00
1	WASHER TANK BUSH	5.50
2	FRONT GRILLE GARNISH CHROME @\$21.00 LH x2	42.00
1	FRONT BUMPER REINFORCEMENT TOP BRACKET LH	62.00
10	RIVET @\$2.00	20.00
1	WASHER TANK MOTOR	9.00
		9,895.50
ADD 15 %		1,484.33
TOTAL (A)		11,379.83

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	30.00
TOTAL (C)		30.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
---	------------------------	-------

2/3

VEHICLE NO. : SGW166B
ACCIDENT DATE : 23-10-2018 08:05
THIRD PARTY REF. : SLF9289B

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	TO REMOVE/REFIT/REFILL AIR CON GAS	80.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	850.00
1	SPRAY PAINTING CHARGES	1000.00
1	TO PERFORM SPECIALIST JOB TO CALIBRATE HEADLAMP CONTROL UNIT	500.00
TOTAL (D)		<u>2,460.00</u>
TOTAL REPAIR COST :		<u>13,869.83</u>
G S T % :		<u>970.88</u>
INVOICE AMOUNT :		<u>14,840.71</u>

REPAIR DETAILS

Reference

Part Source: MRM-SG
 Version: 1.0 (Last Synchronised: 24 Oct 2018)
 Part: 143
 MEROCEDES-BENZ E250 1.8 CGI (A) (Catalogue Merlimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SW166B/24/10/2018 10:18

Validity: These estimates are valid only if they contain the part code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/Values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	*FRONT BONNET		0.00	0.00	*1,150.00 F
2	1	*FRONT BONNET EMBLEM	<i>inc</i>	0.00	0.00	*50.00 F
3	1	*FRONT BONNET HINGE RH	<i>inc</i>	0.00	0.00	*75.00 F
4	1	*FRONT BONNET HINGE LH	<i>inc</i>	0.00	0.00	*75.00 F
5	1	*FRONT BONNET LOCK CENTRE TOP	<i>inc</i>	0.00	0.00	*35.00 F
6	1	*FRONT BONNET LOCK LOWER LH	<i>inc</i>	0.00	0.00	*36.00 F
7	1	*FRONT BONNET LOCK LOWER RH	<i>inc</i>	0.00	0.00	*36.00 F
8	1	*FRONT BONNET HOOK RH	<i>inc</i>	0.00	0.00	*17.00 F
9	1	*FRONT BONNET HOOK LH	<i>inc</i>	0.00	0.00	*17.00 F
10	1	*FRONT BONNET STOPPER RH	<i>inc</i>	0.00	0.00	*12.00 F
11	1	*FRONT BONNET STOPPER LH	<i>inc</i>	0.00	0.00	*12.00 F
12	1	*FRONT BONNET CABLE	<i>inc</i>	0.00	0.00	*34.00 F
13	1	*FRONT TOP PANEL	<i>inc</i>	0.00	0.00	*75.00 F
14	1	*FRONT BRACE PANEL	<i>inc</i>	0.00	0.00	*22.00 F
15	1	*FRONT HEADLAMP PANEL RH	<i>inc</i>	0.00	0.00	*130.00 F
16	1	*FRONT HEADLAMP PANEL LH	<i>inc</i>	0.00	0.00	*130.00 F
17	1	*FRONT HEADLAMP RH	<i>inc</i>	0.00	0.00	*3,366.00 F
18	1	*FRONT HEADLAMP LH	<i>inc</i>	0.00	0.00	*2,380.00 F
19	1	*FRONT HEADLAMP HID BULB	<i>inc</i>	0.00	0.00	*240.00 F
20	1	*FRONT HEADLAMP HID CONTROL UNIT LH	<i>inc</i>	0.00	0.00	*435.00 F
21	1	*FRONT HEADLAMP PANEL STOPPER RH	<i>inc</i>	0.00	0.00	*10.00 F
22	1	*FRONT GRILLE	<i>inc</i>	0.00	0.00	*590.00 F
23	1	*FRONT GRILLE EMBLEM	<i>inc</i>	0.00	0.00	*65.00 F
24	1	*FRONT GRILLE HANDLE	<i>inc</i>	0.00	0.00	*168.00 F
25	1	*FRONT GRILLE SURROUND CHROME	<i>inc</i>	0.00	0.00	*520.00 F
26	1	*FRONT FENDER LH	<i>inc</i>	0.00	0.00	*180.00 F
27	1	*FRONT FENDER SHIELD RH	<i>inc</i>	0.00	0.00	*13.00 F
28	1	*FRONT FENDER SHIELD RH	<i>inc</i>	0.00	0.00	*13.00 F
29	1	*FRONT FENDER SHIELD RH	<i>inc</i>	0.00	0.00	*13.00 F
30	1	*FRONT FENDER SHIELD RH	<i>inc</i>	0.00	0.00	*13.00 F
31	1	*FRONT BUMPER	<i>inc</i>	0.00	0.00	*685.00 F
32	1	*FRONT BUMPER FOAM	<i>inc</i>	0.00	0.00	*65.00 F
33	1	*FRONT BUMPER REINFORCEMENT	<i>inc</i>	0.00	0.00	*255.00 F
34	1	*FRONT BUMPER REINFORCEMENT BRACKET LH	<i>inc</i>	0.00	0.00	*136.00 F
35	1	*FRONT BUMPER SIDE CARRIER LH	<i>inc</i>	0.00	0.00	*32.00 F
36	1	*FRONT BUMPER LOWER GRILLE	<i>inc</i>	0.00	0.00	*35.00 F
37	1	*FRONT BUMPER FOG LAMP COVER LH	<i>inc</i>	0.00	0.00	*24.00 F
38	1	*FRONT BUMPER SENSOR INNER LH	<i>inc</i>	0.00	0.00	*68.00 F
39	1	*FRONT BUMPER SENSOR LH	<i>inc</i>	0.00	0.00	*193.00 F
40	1	*FRONT BUMPER SENSOR RING INNER LH	<i>inc</i>	0.00	0.00	*6.00 F
41	1	*FRONT BUMPER SENSOR RING LH	<i>inc</i>	0.00	0.00	*6.00 F
42	1	*FRONT BUMPER SIDE BRACKET LH	<i>inc</i>	0.00	0.00	*25.00 F
43	1	*FRONT BUMPER TOP RUBBER	<i>inc</i>	0.00	0.00	*12.00 F
44	1	*FRONT BUMPER TOP BRACKET	<i>inc</i>	0.00	0.00	*169.00 F

Kan Fook Sing Motor Workshop/SW166B/24/10/2018 10:18 Not valid without Reference section
 Generated using Merlimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1	*AIR CON CONDENSER	<i>inc</i>	0.00	0.00	*830.00 F
46	1	*AIR CON LIQUID PIPE	<i>inc</i>	0.00	0.00	*116.00 F
47	1	*AIR CON SUCTION HOSE	<i>inc</i>	0.00	0.00	*116.00 F
48	1	*AIR DUCT	<i>inc</i>	0.00	0.00	*60.00 F
49	1	*AIR CLEANER HOSE	<i>inc</i>	0.00	0.00	*98.00 F
50	1	*RADIATOR ASSY	<i>inc</i>	0.00	0.00	*670.00 F
51	1	*RADIATOR TOP HOSE	<i>inc</i>	0.00	0.00	*40.00 F
52	1	*RADIATOR FAN ASSY	<i>inc</i>	0.00	0.00	*720.00 F
53	1	*WASHER TANK	<i>inc</i>	0.00	0.00	*78.00 F
54	1	*WASHER PUMP ASSY	<i>inc</i>	0.00	0.00	*2,496.00 F
55	1	*THROTTLE BODY	<i>inc</i>	0.00	0.00	*2,166.00 F
56	1	*FRONT NUMBER PLATE GARNISH	<i>inc</i>	0.00	0.00	*95.00 F

Sub Total (S\$) 17,787.00
 + Margin on L/N Items (6.00% (S\$)) 2,668.05
 Total Parts (S\$) 20,455.05

Kan Fook Sing Motor Workshop/SW166B/24/10/2018 10:18 Not valid without Reference section.
 Generated using Merlimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	FRONT NUMBER PLATE	30.00
Sub Total (S\$)			30.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	PAINTWORK LABOUR	New	1,200.00
2	TO CHECK WIRING SYSTEM	New	30.00
3	TO REMOVE/RETIREFILL AIR CON GAS	New	80.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	850.00
Gross Labour Cost (S\$)			2,230.00

Kan Fook Sing Motor Workshop/SGW1669/24/10/2018 10:18. Not valid without Reference section.

Generated using Meridian e-Claims IEAS

< END OF ESTIMATES >

7 Days.
part by part.
before paint photo.
Gmo King - 888087
Gross, TGA
Not Authorised.



簡福星摩嘜工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61, D'Almeida Lane 12 Singapore 330147
Tel: (65) 6747 9550, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: yong@kfs.net, patricia@kfs.net
Branch: 1, Kaki Bukit Avenue 6 #01-108 Singapore 437883
Tel: (65) 6483 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

DATE : 01-11-2018

*

VEHICLE NO. : SGM166B

ACCIDENT DATE : 23-10-2018 08:05

THIRD PARTY REF. : SLF9289B

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SGM166B MERCEDES-BENZ E250A

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT GRILLE GARNISH	95.00
2	FRONT GRILLE GARNISH CHROME@21.00	42.00
1	FRONT BUMPER CENTRE CARRIER	47.00
1	FRONT BUMPER REINFORCEMENT TOP BRACKET LH	62.00
1	FRONT BUMPER REINFORCEMENT SIDE BRACKET LH	29.00
1	FRONT BUMPER TOP BEAM	133.00
10	RIVETS@2.00	20.00
1	WASHER TANK MOTOR	9.00
1	WASHER TANK BUSH	5.50
1	RADIATOR TOP GARNISH	21.00
1	RADIATOR LOWER GARNISH	44.00
2	RADIATOR TOP BRACKET@13.00	26.00
2	RADIATOR TOP BUSH@7.00	14.00
1	INTERCOOLER	530.00
		1,077.50
ADD 15 %		161.63
TOTAL (A)		1,239.13
SUPPLEMENTARY TOTAL		1,239.13

Switch lock LH ✓

Gmo KL

01/11/18



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
 TEL NO : 64523938 (6 LINES) FAX NO : 64527936
 A/C DEPT : 64590882
 Business Reg & GST NO : 201512120M



D199312

TAX INVOICE

REPRINT

KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

INDUSTRIAL PARK E

S (539147)

REMARK : SGW 166 B WDD 2120362A787146

DELIVER TO :

INV NO : I199312

DATE : 26/10/2018

A/C NO : 334721

TERM : 30

PAGE : 1 OF 1

ISSUE : HONG

Printed on 26/10/2018 18:18:58

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	000 817 1016MB	GRILL MERCEDES STAR	SS3B08✓	1	PCS	70.00	70.00✓
2	204 500 0200MB	INTERCOOLER	2W2B11✓	1	PCS	530.00	530.00✓
3	204 500 0393MB	RADIATOR FAN ASSY	2W1D03✓	1	PCS	700.00	700.00✓
4	204 880 0227MB	BONNET SPRING	SS2C00✓	2	PCS	9.00	18.00✓
5	204 880 0260MB	BONNET LOCK BOTTOM LH&RH	SS2C16✓	1	PC	35.00	35.00✓
S6	212 505 2930MB	RAD AIR BAFFLE <i>Top (Top)</i>	3W3J05	1	PC	21.00	21.00✓
S7	212 505 3230MB	RAD AIR BAFFLE <i>Low (Lower)</i>	3W3J05	1	PC	44.00	44.00✓
8	212 620 0185MB	HEAD LAMP LOWER STRUT LH <i>Left</i>	SS2H24✓	1	PCS	29.00	29.00✓
9	212 620 0900MB	STRUT PANEL	SS2H17✓	1	PC	18.00	18.00✓
S10	212 620 1100MB	TOP PANEL	3W3A05	1	PCS	83.00	83.00✓
S11	212 620 1500MB	FRONT BUMPER REINFORCEMENT	3W2F02	1	PCS	270.00	270.00✓
S12	212 620 4600MB	HEADLAMP PANEL LH	3W3B03	1	PCS	133.00	133.00✓
S13	212 690 5430MB	COVERING, FRT FENDER F.LH	3W3F02	1	PCS	103.00	103.00✓
14	212 880 0060MB	BONNET LOCK TOP LH&RH	SS2C16✓	1	PCS	19.00	19.00✓
S15	212 880 0135MB	IMPACT ABSORBER	3W3F03	1	PCS	69.00	69.00✓
S16	212 880 0357MB	BONNET	3W1C16	1	PCS	1,150.00	1,150.00✓
S17	212 880 0559MB	BONNET CABLE	SS2C00✓	1	PCS	38.00	38.00✓
S18	212 880 1118MB	FENDER LH	3W2J05	1	PCS	480.00	480.00✓
S19	212 880 1403MB	BEAM <i>Long beam</i> GRILLE SUPPORT	3W3E04	1	PCS	133.00	133.00✓
S20	212 880 3000 9999	FRONT BUMPER 9999	3W2D12	1	PCS	720.00	720.00✓
S21	212 885 0522MB	COVER BUMPER <i>lower grille</i>	3W3A03	1	PC	39.00	39.00✓
S22	212 885 0622MB	COVER BUMPPER AREA <i>grille chrome</i>	3W2G02	1	PCS	95.00	95.00✓
23	212 885 1922MB	COVER BUMPER AREA <i>Fog lamp L&R</i>	SS2K19✓	1	PC	26.00	26.00✓
S24	212 885 3765MB	PANELLING <i>Orkt / side carrier</i>	3W3J06	1	PCS	34.00	34.00✓
25	274 090 0400MB	AIR INTAKE HOSE	SS3H06✓	1	PCS	102.00	102.00✓

RECEIVED BY

PICKED BY: JOHNSON 88514

SUB-TOTAL : S\$ 4,959.00

ADD 7% GST : S\$ 347.13

TOTAL : S\$ 5,306.13

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D199767

REPRINT

TAX INVOICE

KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

INDUSTRIAL PARK E

S (539147)

REMARK : SGW 166 B WDD 2120362A787146

DELIVER TO :

INV NO : I199767

DATE : 30/10/2018

A/C NO : 334721

TERM : 30

PAGE : 1 OF 1

ISSUE : HONG

Printed on 30/10/2018 12:33:58

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
S1	099 500 6203MB	RADIATOR (NO WARRANTY)	3W2A20	1	PCS	650.00	650.00
2	204 500 0654MB	A/C CONDERSOR	2W1D04	1	PCS	580.00	580.00
S3	212 500 0455MB	RAD TOP COVERING	3W3D07	1	PC	73.00	73.00
4	204 869 0100MB	WIPER TANK	SS3D13	1	PCS	83.00	83.00
5	204 869 0014MB	WATER TANK BRACKET	SS2C26	1	PCS	5.50	5.50
6	169 504 0114MB	RAD BOT MOUNTING	SS2G09	2	PCS	13.00	26.00
7	000 991 2595MB	RAD CLIP	SS2A25	2	PCS	7.00	14.00

RECEIVED BY

PICKED BY: XIN 8839

SUB-TOTAL : S\$ 1,431.50

ADD 7% GST : S\$ 100.21

TOTAL : S\$ 1,531.71

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D199603

REPRINT

KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

INDUSTRIAL PARK E

S (539147)

REMARK : SGW 166 B WDD 2120362A787146

DELIVER TO :

TAX INVOICE

INV NO : I199603

DATE : 29/10/2018

A/C NO : 334721

TERM : 30

PAGE : 1 OF 1

ISSUE : HONG

Printed on 29/10/2018 15:08:56

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	212 885 2321MB	MOULDING LH <i>garden channel</i>	SS2Q08	1	PCS	21.00	21.00
2	212 885 2521MB	MOULDING LH	SS2Q08	1	PCS	21.00	21.00
3	221 869 0121CP	WIPER TANK MOTOR	SS2C27	1	PCS	9.00	9.00
4	003 990 9497MB	RIVET <i>has extra carrier</i>	SS2A30	10	PCS	2.00	20.00
5	212 885 4265MB	BASIC MOUNTING FOR B <i>carrier</i>	3W3A03	1	PCS	47.00	47.00
6	212 620 0995MB	FRT MEMBER ABSORBER LH	3W3A08	1	PCS	147.00	147.00
7	212 620 0514MB	FRT BRACKET LH <i>right side bracket</i>	SS2H21	1	PC	62.00	62.00

RECEIVED BY

PICKED BY: M

SUB-TOTAL : S\$ 327.00

ADD 7% GST : S\$ 22.89

TOTAL : S\$ 349.89

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D199783

REPRINT

TAX INVOICE

KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

INDUSTRIAL PARK E

S (539147)

REMARK : SGW 166 B WDD 2120362A787146

DELIVER TO :

INV NO : I199783

DATE : 30/10/2018

A/C NO : 334721

TERM : 30

PAGE : 1 OF 1

ISSUE : HONG

Printed on 31/10/2018 5:06:53

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	212 885 2574MB	MOULDING (single round molding)	3W	1	PCS	190.00	190.00
2	212 885 1400MB	FRT GRILL (large)	3W	1	PCS	98.00	98.00

RECEIVED BY

PICKED BY:

SUB-TOTAL : S\$ 288.00

ADD 7% GST : S\$ 20.16

TOTAL : S\$ 308.16

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D200219

REPRINT

TAX INVOICE

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
INDUSTRIAL PARK E
S (539147)
REMARK : SGW 166 B wdd2120362a787146

DELIVER TO :

INV NO : I200219
DATE : 01/11/2018
A/C NO : 334721
TERM : 30
PAGE : 1 OF 1
ISSUE : TTH

Printed on 03/11/2018 2:34:22

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	218 900 7306MB	CONTROL UNIT	SS3B09	1	PCS	390.00	390.00

RECEIVED BY

PICKED BY:

8514

SUB-TOTAL : S\$ 390.00
ADD 7% GST : S\$ 27.30
TOTAL : S\$ 417.30

Goods sold are not returnable except Repairs/Service at authorized workshop.



特立機器貿易 MEGA POWER ENGINEERING & TRADING

Automobile Air Conditioning System Is Our Business

Head Office: 39 Genting Road Singapore 349485 Tel: 6842 3389 Fax: 6042 3373
Email: mega1969@singnet.com.sg Business Reg. No. 40869100W

TAX INVOICE

GST Reg# : M8-8002998-3
Invoice No. : INV 10069567
Invoice Date : 3-Nov-2018
Terms : 60DAYS
PO No :
Vehicle No : SGW166B
Chassis No :
Staff : MS NEO

Bill To: KAN001
KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
Attn : Account Dept

Ship To: KG1
KAN FOOK SING MOTOR WORKSHOP
1 KAKI BUKIT AVE 6
#01-108 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883
Attn : XIAO LING
Tel: 67479560

Remarks:

ORDER BY DAVID=====

S/NC	DESCRIPTION	MOQ	BIN	WH	QTY	PRICE	SP	TOTAL (SGD)
PO Number :	DO Number :							
1 PS-00057				KB	1	58.00		58.00
MB211 3P PR/SWITCH								

Rate : 1 SGD : 1.000000 SGD
Note : Goods sold are not returnable.
All Brand New compressor sold are without warranty.
Late payment is subject to 2% interest per month.

SUB-TOTAL 58.00 SGD
DISC 0.00% (-) SGD
GST 7% 4.06 SGD
AMOUNT 62.06 SGD

This is a computer-generated document.
No signature is required.
Printed on: 03/11/2018 16:50:32

CUSTOMER COPY

Customer Signature & Stamp



Blk 5025, Ang Mo Kio Ind Park 2 #01-55/57 S(589528) Tel: 6482 3389 Fax: 6481 1187
No. 13 Kaki Bukit Rd 4 #01-27 Bartley Biz Centre S(417807) Tel: 6385 3389 Fax: 6385 3329

No. 5 Soon Lee St #01-26 Pioneer Point S(627607) Tel: 6252 3389 Fax: 6275 3389
No. 21 Toh Guan Rd East #01-33 Toh Guan Centre S(608609) Tel: 67663389 Fax: 6318 2454



TAX INVOICE

INVOICE NO. 8125754

DATE	31/10/2018	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	166	OUR REF.	15177

GST REG.NO.: M2-0090482-6 CO REG.NO.: 198905613E

ACCOUNT NUMBER: KANFOOK1 TIME:17:16
KAN FOOK SING MOTOR WORKSHOP
61,DEFU LANE 12,
SINGAPORE 539147

539147
Telephone No : 67479560

ROUTE
FRONT

DELIVER TO :

KAN FOOK SING MOTOR WORKSHOP
61,DEFU LANE 12,
SINGAPORE 539147



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA212 820 25 39	HEADLAMP LH	68-1B	1 PC	2,420.00	2,420.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor

HDK

Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046
Account No.: 503-309-511-3
*Please send a screen shot of your payment/
transfer confirmation to
account@minghee.com

SIGN & COMPANY'S STAMP



DATE
ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義純車私人有限公司
MIN GHEE AUTO PTE LTD

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. 8125905

DATE	01/11/2018	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.		OUR REF.	15738

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: KANFOOK1 TIME:16:39
KAN FOOK SING MOTOR WORKSHOP
61,DEFU LANE 12,
SINGAPORE 539147

539147
Telephone No : 67479560

ROUTE
UB12

DELIVER TO :

KAN FOOK SING MOTOR WORKSHOP
61,DEFU LANE 12,
SINGAPORE 539147



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA204 870 31 58	COVER 1st Lock lower	1B-03G	1 PC	22.00	22.00
GOODS RECEIVED IN GOOD ORDER AND CONDITION.					TOTAL 22.00
*GOODS SOLD ARE NOT RETURNABLE.					ADD GST 7% 1.54
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE					AMOUNT DUE 23.54
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.					

SIGN & COMPANY'S STAMP
DATE
ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

Exclusive Distributor

HDK

Stockists



For MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018 Sendback Est	24 Oct 2018 10:18 S\$22,775.05	24 Oct 2018 10:29 Edit Adj Rpt	S\$13,669.83 Edit Estimates	S\$13,669.83 View Rpt		Pending for Survey Report Cancel Case
Supp #1	01 Nov 2018 12:34	21 Nov 2018 15:21 S\$2,471.68	21 Nov 2018 15:21			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TAM KUM CHEONG, ID: S1676507D, Tel: +6590262032, Email: paul@prmes.com.sg		
Vehicle Reg. No.:	SGW166B	Date of Loss:	23/10/2018 08:00 - :59 [62 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / 18/18/18/VP05/021049	Policy/Cover Note No.:	Z18VP05017540 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/11/2018]		
Driver/Custodian:	TAM KUM CHEONG (54 / Male), NRIC: S1676507D, Tel: +6590262032 Email: paul@prmes.com.sg		
Adj Asg. Remarks:	SURVEY & REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- LONPAC_HQ (26/10/2018): Alert - Adj Mandate Approved (S\$20000.00) - SGW166B - Claim Handler: Gerald Poh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGW166B (18/18/18/VP05/021049)

OD

Oct 23 2018 8:00AM

[TAM KUM CHEONG]

Kan Fook Sing Motor Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	24/10/18 10:18	Repairer Estimates		Load HTM	
2	21/11/18 15:21	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/10/18 13:37	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/10/18 13:25	General View		Load JPG	☒
2	25/10/18 13:25	General View		Load JPG	☒
3	25/10/18 13:25	General View		Load JPG	☒
4	25/10/18 13:25	General View		Load JPG	☒
5	25/10/18 13:25	General View		Load JPG	☒
6	25/10/18 13:25	General View		Load JPG	☒
7	25/10/18 13:25	General View		Load JPG	☒
8	25/10/18 13:25	General View		Load JPG	☒
9	25/10/18 13:25	General View		Load JPG	☒
10	25/10/18 13:25	General View		Load JPG	☒
11	25/10/18 13:25	General View		Load JPG	☒
12	25/10/18 13:25	General View		Load JPG	☒
13	25/10/18 13:25	General View		Load JPG	☒
14	25/10/18 13:25	General View		Load JPG	☒
15	25/10/18 13:25	General View		Load JPG	☒
16	25/10/18 13:25	General View		Load JPG	☒
17	25/10/18 13:25	General View		Load JPG	☒
18	25/10/18 13:25	General View		Load JPG	☒
19	25/10/18 13:25	General View		Load JPG	☒
20	25/10/18 13:25	General View		Load JPG	☒
21	25/10/18 13:25	General View		Load JPG	☒
22	25/10/18 13:25	General View		Load JPG	☒
23	25/10/18 13:25	General View		Load JPG	☒
24	25/10/18 13:25	General View		Load JPG	☒
25	25/10/18 13:25	General View		Load JPG	☒
26	25/10/18 13:25	General View		Load JPG	☒
27	25/10/18 13:25	General View		Load JPG	☒
28	25/10/18 13:25	General View		Load JPG	☒
29	25/10/18 13:25	General View		Load JPG	☒
30	25/10/18 13:25	General View		Load JPG	☒
31	25/10/18 13:25	General View		Load JPG	☒
32	25/10/18 13:25	General View		Load JPG	☒
33	25/10/18 13:25	General View		Load JPG	☒
34	25/10/18 13:25	General View		Load JPG	☒
35	25/10/18 13:25	General View		Load JPG	☒
36	25/10/18 13:25	General View		Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
37	25/10/18 13:25	General View	 Load JPG	☒
38	25/10/18 13:25	General View	 Load JPG	☒
39	25/10/18 13:25	General View	 Load JPG	☒
40	25/10/18 13:25	General View	 Load JPG	☒
41	25/10/18 13:25	General View	 Load JPG	☒
42	25/10/18 13:25	General View	 Load JPG	☒
43	25/10/18 13:25	General View	 Load JPG	☒
44	25/10/18 13:25	General View	 Load JPG	☒
45	25/10/18 13:25	General View	 Load JPG	☒
46	25/10/18 13:25	General View	 Load JPG	☒
47	25/10/18 13:25	General View	 Load JPG	☒
48	25/10/18 13:25	General View	 Load JPG	☒
49	25/10/18 13:25	General View	 Load JPG	☒
50	25/10/18 13:25	General View	 Load JPG	☒
51	25/10/18 13:25	General View	 Load JPG	☒
52	25/10/18 13:25	General View	 Load JPG	☒
53	25/10/18 13:25	General View	 Load JPG	☒
54	25/10/18 13:25	General View	 Load JPG	☒
55	25/10/18 13:25	General View	 Load JPG	☒
56	25/10/18 13:25	General View	 Load JPG	☒
57	25/10/18 13:25	General View	 Load JPG	☒
58	25/10/18 13:25	General View	 Load JPG	☒
59	25/10/18 13:25	General View	 Load JPG	☒
60	25/10/18 13:25	General View	 Load JPG	☒
61	25/10/18 13:25	General View	 Load JPG	☒
62	25/10/18 13:25	General View	 Load JPG	☒
63	25/10/18 13:25	General View	 Load JPG	☒
64	25/10/18 13:25	General View	 Load JPG	☒
65	25/10/18 13:25	General View	 Load JPG	☒
66	25/10/18 13:25	General View	 Load JPG	☒
67	25/10/18 13:25	General View	 Load JPG	☒
68	25/10/18 13:25	General View	 Load JPG	☒
69	25/10/18 13:25	General View	 Load JPG	☒
70	25/10/18 13:25	General View	 Load JPG	☒
71	25/10/18 13:25	General View	 Load JPG	☒
72	25/10/18 13:25	General View	 Load JPG	☒
73	25/10/18 13:25	General View	 Load JPG	☒
74	25/10/18 13:25	Odometer Reading	 Load JPG	☒
75	25/10/18 13:25	Chassis Number	 Load JPG	☒
76	25/10/18 13:25	General View	 Load JPG	☒
77	25/10/18 13:25	General View	 Load JPG	☒
78	25/10/18 13:25	General View	 Load JPG	☒
79	25/10/18 13:25	General View	 Load JPG	☒
80	25/10/18 13:25	General View	 Load JPG	☒
81	25/10/18 13:25	General View	 Load JPG	☒
82	25/10/18 13:25	General View	 Load JPG	☒
83	25/10/18 13:25	General View	 Load JPG	☒
84	25/10/18 13:25	General View	 Load JPG	☒
85	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
86	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
87	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
88	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
89	16/09/19 14:00	Dismantled Parts	 Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
90	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
91	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
92	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
93	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
94	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
95	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
96	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
97	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
98	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
99	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
100	16/09/19 14:00	Dismantled Parts	 Load JPG	☒
101	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
102	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
103	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
104	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
105	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
106	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
107	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
108	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
109	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
110	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
111	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
112	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
113	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
114	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
115	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
116	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
117	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
118	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
119	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
120	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
121	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
122	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
123	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
124	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
125	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
126	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
127	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
128	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
129	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
130	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
131	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
132	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
133	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
134	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
135	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
136	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
137	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
138	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
139	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
140	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
141	16/09/19 14:01	Dismantled Parts	 Load JPG	☒
142	16/09/19 14:01	Dismantled Parts	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
143	16/09/19 14:01	Dismantled Parts	Load JPG	☒
144	16/09/19 14:01	Dismantled Parts	Load JPG	☒
145	16/09/19 14:01	After Repair Photo	Load JPG	☒
146	16/09/19 14:01	After Repair Photo	Load JPG	☒
147	16/09/19 14:01	After Repair Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	23/10/18 12:09	E-filed GIA report	Load PDF	
2	16/09/19 14:54	Repairer's Bill	Load PDF	
3	16/09/19 14:54	Signed DV	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 13:26	ESTIMATE	Load PDF	
2	18/09/19 10:59	SUPPLEMENTARY	Load PDF	
3	18/09/19 10:59	PARTS INVOICE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	23/10/18 10:28	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	23/10/18 10:27	Accident Photo	Load JPG	☒
2	23/10/18 10:27	Accident Photo	Load JPG	☒
3	23/10/18 10:27	Accident Photo	Load JPG	☒
4	23/10/18 10:27	Accident Photo	Load JPG	☒
5	23/10/18 10:27	Accident Photo	Load JPG	☒
6	23/10/18 10:27	Accident Photo	Load JPG	☒
7	23/10/18 10:27	Accident Photo	Load JPG	☒
8	23/10/18 10:27	Accident Photo	Load JPG	☒
9	23/10/18 10:27	Accident Photo	Load JPG	☒
10	23/10/18 10:27	Accident Photo	Load JPG	☒
11	23/10/18 10:27	Accident Photo	Load JPG	☒
12	23/10/18 10:27	Accident Photo	Load JPG	☒
13	23/10/18 10:27	Accident Photo	Load JPG	☒
14	23/10/18 10:27	Accident Photo	Load JPG	☒
15	23/10/18 10:27	Accident Photo	Load JPG	☒
16	23/10/18 10:27	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	23/10/18 10:28	Accident Sketch Plan	Load TIF	
2	23/10/18 10:28	Accident Sketch Plan	Load TIF	
3	23/10/18 10:28	insurer's nric & license	Load TIF	
4	23/10/18 10:28	certificate of insurance	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18019346/GQD3S2

Date: 18/09/2019

REFERENCE

Insured/Claimant: TAM KUM CHEONG Policy No: Z18VP05017540
Date of Loss: 23/10/2018 Nature of Claim: OD Claim No: 18/18/18/VP05/021049

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW166B**
Make & Model: MERCEDES-BENZ E250, 2.0 (A) Engine No: 27492030054976
Reg. Date: 23/08/2013 (Man. Year: 2013) Chassis No: WDD2120362A787146
Colour: Silver Odometer: 80502 km
Engine Capacity: 1991 cc
Market Value/New Car Price: S\$97,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 ZR18 Rear Tyre Size: 245/40 ZR18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,426.73	11,379.83	11,046.90	49.26
Miscellaneous Items	30.00	30.00	0.00	0.00
Labour	1,590.00	1,260.00	330.00	20.75
Paintwork Labour	1,200.00	1,000.00	200.00	16.67
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,246.73	13,669.83	11,576.90	45.86
+ GST 7.00/7.00% (S\$)	1,767.27	956.89	810.38	45.85
Nett Amount (S\$)	27,014.00	14,626.72	12,387.28	45.86

INSPECTION

Date of Assignment: 24/10/2018 Present Location: Kan Fook Sing Motor Workshop (Defu)
Date Inspected: 24/10/2018 Inspected At: Kan Fook Sing Motor Workshop (Defu)
Estimated Period of Repair: 7.0 days No. 61 Defu Lane 12
Singapore 539147

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2019)
Parts:	143	MERCEDES-BENZ E250 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGW166B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Buckled	1,150.00 F	*1,150.00 F
2	1		*FRONT BONNET EMBLEM (WCP)	Not Necessary	50.00 F	*- F
3	1		*FRONT BONNET HINGE RH (WCP)	Not Necessary	75.00 F	*- F
4	1		*FRONT BONNET HINGE LH (WCP)	Not Necessary	75.00 F	*- F
5	1		*FRONT BONNET LOCK CENTRE TOP (WCP)	Bent	35.00 F	*35.00 F
6	1		*FRONT BONNET LOCK LOWER LH (WCP)	Bent	36.00 F	*22.00 F
7	1		*FRONT BONNET LOCK LOWER RH (WCP)	Not Necessary	36.00 F	*- F
8	1		*FRONT BONNET HOOK RH (WCP)	Not Necessary	17.00 F	*- F
9	1		*FRONT BONNET HOOK LH (WCP)	Bent	17.00 F	*19.00 F
10	1		*FRONT BONNET STOPPER RH (WCP)	Not Necessary	12.00 F	*- F
11	1		*FRONT BONNET STOPPER LH (WCP)	Not Necessary	12.00 F	*- F
12	1		*FRONT BONNET CABLE (WCP)	Cut	34.00 F	*38.00 F
13	1		*FRONT TOP PANEL (WCP)	Bent	75.00 F	*83.00 F
14	1		*FRONT BRACE PANEL (WCP)	Bent	22.00 F	*18.00 F
15	1		*FRONT HEADLAMP PANEL RH (WCP)	Not Necessary	130.00 F	*- F
16	1		*FRONT HEADLAMP PANEL LH (WCP)	Buckled	130.00 F	*133.00 F
17	1		*FRONT HEADLAMP RH (WCP)	Not Necessary	2,380.00 F	*- F
18	1		*FRONT HEADLAMP LH (WCP)	Cracked	2,380.00 F	*2,420.00 F
19	1		*FRONT HEADLAMP HID BULB (WCP)	Not Necessary	240.00 F	*- F
20	1		*FRONT HEADLAMP HID CONTROL UNIT LH (WCP)	Damaged	435.00 F	*390.00 F
21	1		*FRONT HEADLAMP PANEL STOPPER LH (WCP)	Not Necessary	10.00 F	*- F
22	1		*FRONT GRILLE (WCP)	Not Necessary	590.00 F	*- F
23	1		*FRONT GRILLE EMBLEM (WCP)	Cracked	65.00 F	*70.00 F
24	1		*FRONT GRILLE HANDLE (WCP)	Not Necessary	88.00 F	*- F
25	1		*FRONT GRILLE SURROUND CHROME (WCP)	Cut	168.00 F	*190.00 F
26	1		*FRONT FENDER LH (WCP)	Distorted	520.00 F	*480.00 F
27	1		*FRONT FENDER SHIELD FRT (WCP)	Deformed	98.00 F	*103.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT FENDER SHIELD RR (WCP)	Not Necessary	83.00 F	*- F
29	10		*FRONT FENDER SHIELD CLIP (WCP)	Not Necessary	40.00 F	*- F
30	1		*FRONT FENDER CHROME LH (WCP)	Not Necessary	22.00 F	*- F
31	1		*FRONT BUMPER (WCP)	Distorted	695.00 F	*720.00 F
32	1		*FRONT BUMPER FOAM (WCP)	Cracked	65.00 F	*69.00 F
33	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	255.00 F	*270.00 F
34	1		*FRONT BUMPER REINFORCEMENT BRACKET LH (WCP)	Bent	136.00 F	*147.00 F
35	1		*FRONT BUMPER SIDE CARRIER LH (WCP)	Deformed	32.00 F	*34.00 F
36	1		*FRONT BUMPER LOWER GRILLE (WCP)	Cut	35.00 F	*39.00 F
37	1		*FRONT BUMPER FOGLAMP COVER LH (WCP)	Deformed	24.00 F	*26.00 F
38	1		*FRONT BUMPER SENSOR INNER LH (WCP)	Not Necessary	88.00 F	*- F
39	1		*FRONT BUMPER SENSOR LH (WCP)	Not Necessary	88.00 F	*- F
40	1		*FRONT BUMPER SENSOR RING INNER LH (WCP)	Not Necessary	6.00 F	*- F
41	1		*FRONT BUMPER SENSOR RING LH (WCP)	Not Necessary	6.00 F	*- F
42	1		*FRONT BUMPER SIDE BRACKET LH (WCP)	Not Necessary	26.00 F	*- F
43	1		*FRONT BUMPER TOP RUBBER (WCP)	Not Necessary	22.00 F	*- F
44	1		*FRONT BUMPER TOP BRACKET (WCP)	Not Necessary	100.00 F	*- F
45	1		*AIR CON CONDENSER (WCP)	Bent	630.00 F	*580.00 F
46	1		*AIR CON LIQUID PIPE (WCP)	Not Necessary	110.00 F	*- F
47	1		*AIR CON SUCTION HOSE (WCP)	Not Necessary	110.00 F	*- F
48	1		*AIR DUCT (WCP)	Not Necessary	66.00 F	*- F
49	1		*AIR CLEANER HOSE (WCP)	Deformed	98.00 F	*102.00 F
50	1		*RADIATOR ASSY (WCP)	Bent	670.00 F	*650.00 F
51	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	40.00 F	*- F
52	1		*RADIATOR FAN ASSY (WCP)	Cracked	720.00 F	*700.00 F
53	1		*WASHER TANK (WCP)	Deformed	78.00 F	*83.00 F
54	1		*ABS PUMP ASSY (WCP)	Not Necessary	2,430.00 F	*- F
55	1		*THROTTLE BODY (WCP)	Not Necessary	2,150.00 F	*- F
56	1		*FRONT NUMBER PLATE GARNISH (WCP)	Not Necessary	82.00 F	*- F
Supplementary #1						
57	1		*FRONT GRILLE GARNISH (WCP)	Cracked	95.00 F	*95.00 F
58	1		*FRONT GRILLE GARNISH CHROME LH TOP (WCP)	Cracked	21.00 F	*21.00 F
59	1		*FRONT GRILLE GARNISH CHROME LH LOWER (WCP)	Cracked	21.00 F	*21.00 F
60	1		*FRONT BUMPER CENTRE CARRIER (WCP)	Cracked	47.00 F	*47.00 F
61	1		*FRONT BUMPER REINFORCEMENT TOP BRACKET LH (WCP)	Cracked	62.00 F	*62.00 F
62	1		*FRONT BUMPER REINFORCEMENT SIDE BRACKET LH (WCP)	Cracked	29.00 F	*29.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
63	1		*FRONT BUMPER TOP BEAM (WCP)	Cracked	133.00 F	*133.00 F
64	10		*RIVET (WCP)	Necessary	20.00 F	*20.00 F
65	1		*WASHER TANK MOTOR (WCP)	Damaged	9.00 F	*9.00 F
66	1		*WASHER TANK BUSH (WCP)	Necessary	5.50 F	*5.50 F
67	1		*RADIATOR TOP GARNISH (WCP)	Cracked	21.00 F	*21.00 F
68	1		*RADIATOR LOWER GARNISH (WCP)	Cracked	44.00 F	*44.00 F
69	1		*RADIATOR TOP BRACKET RH (WCP)	Bent	13.00 F	*13.00 F
70	1		*RADIATOR TOP BRACKET LH (WCP)	Bent	13.00 F	*13.00 F
71	1		*RADIATOR TOP BUSH RH (WCP)	Necessary	7.00 F	*7.00 F
72	1		*RADIATOR TOP BUSH LH (WCP)	Necessary	7.00 F	*7.00 F
73	1		*INTERCOOLER (WCP)	Cracked	530.00 F	*530.00 F
74	1		*FRONT HEADLAMP HID CONTROL UNIT LH (WCP)	Repeated	390.00 F	*- F
75	1		*A/C PRESSURE SWITCH (WCP)	Missing	58.00 F	*58.00 F
76	1		*FRONT GRILLE MESH BASE (WCP)	Cracked	98.00 F	*98.00 F
77	1		*FRONT BONNET SPRING RH (WCP)	Missing	9.00 F	*9.00 F
78	1		*FRONT BONNET SPRING LH (WCP)	Missing	9.00 F	*9.00 F
79	1		*FRONT SUPPORT TOP COVER (WCP)	Broken	73.00 F	*73.00 F

F=Franchise part.

Sub Total (\$\$)	19,501.50	9,895.50
+ Margin on L,N Items 15.00/15.00% (\$\$)	2,925.23	1,484.33
Total Parts (\$\$)	22,426.73	11,379.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRONT NUMBER PLATE (CUT)	30.00	30.00
Sub Total (\$\$)			30.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	1,200.00	1,000.00
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	30.00	30.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	80.00	80.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	980.00	850.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
5	TO PERFORM SPECIALIST JOB TO CALIBRATE HEADLAMP CONTROL UNIT	New	500.00	300.00
Gross Labour Cost (\$\$)			2,790.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >