

Singapore Tampin

REF: MS167 CC3/MSH18019382/T11602

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SHA 4086M
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

<input checked="" type="checkbox"/>	
N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : **Yes** or No
 GIA / PR Seen: _____ Consistent? : **Yes** or No
 Est. Repairs: _____ days Res.: **Yes** or No
 Lum Sum: _____ % 3 Val.: **Yes** or No
 CA / REV / REP. / 24 HRS WP
 Date: _____ Person Contacted: _____
 Vehicle: **IN / OUT**

Veh No: SMB1541J Yr Regn: 2014 Dec.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MAN NL32WF c.c. 60518
 Colour: Mulh A/C: Insured / Std / NI / NA
 Sp. Reading: 267715 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMAA22722E7002426
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 275/70R22.5
 R: h~ (D)
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Firezza
 Front 6 mm R/Bal. 6 mm
 Rear 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 19/10/1805pm
 Survey held at SMART
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
Frnt N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMB1541J - CL/TPD18000516/Zn SHA 4086M - CC3/ATN12002821/H151321
	DOA: 190817 DOA: 2102012

26/10 @ 8:55am - revert GIA and Estimate to Kiu Shi via email
lump sum \$15500 - (red: 2829.50, 33%)

RECEIVED 16 JAN 2019

[Signature]
16/1/2019

Date/Time, File Pass to? 15/1/2019
 : Preli. Report
 : Final Report
 Date/Time, File Return to? _____

Days Of Repair: 3
 Resurvey No. of Trip: 1

Report Format: TP
 Lump Sum / I.B.I. (\$) 51500

Add Fee:

<input type="checkbox"/>	Site Insp (\$)	
<input type="checkbox"/>	Interview (\$)	
<input type="checkbox"/>	Tech. Invs (\$)	
<input type="checkbox"/>	Weekend (\$)	

Survey Fee: 150
 Transportation: _____
 Photos _____
 Others 10
 TOTAL 160

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 26 October 2018 8:55 AM
To: 'xiushi_pang@sg.msig-asia.com'
Cc: SUR; KKLau; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD, DOA: 16/10/2018, SMB 1541J (TP VEHICLE), SGA 4076M (OI VEHICLE)
Attachments: SMB 1541J ESTIMATE.pdf; SMB 1541J GIA REPORT.pdf

Dear XiuShi,

Please be informed that we had inspected the vehicle **SMB 1541J** at **SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705**.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly provide us the claim reference number for our necessary action

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/10/2018 09:00
Date Of Accident	16/10/2018 09:25
Exact Location Of Accident	JALAN EUNOS JUNCTION WITH SIMS AVE EAST
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMB1541J
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	MAN
Model	MAN A22
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	
Driver	
Name of Driver	CHONG CHE KONG
NRIC No	G2689012N
Date Of Birth	10/09/1985
Occupation	OUTDOOR
Date Of Driving Pass	14/09/2015
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	10

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along Jalan Eunon on the left most lane heading towards the junction of Sims Ave East. As my bus was approaching the traffic light junction, I braked to reduce speed as the traffic light ahead was red. Suddenly, a pte car (SGA4086M) which was stationary on the middle filtered left abruptly and cut into my path. I swerved a sharp right to avoid collision but the distance was too close hence my bus collided onto the rear portion of the pte car. Due to the impact, the car surged onto the kerb at the traffic light junction and collided onto the safety bollard and a cyclist. The cyclist was not injured but his bicycle was damaged.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGA4086M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



[Handwritten Signature]



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FIN No.: S8340325Z

SMRT Accident Vehicle Repair Breakdown


SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 19/10/2018

User ID : TanAhLeong

Section A - Accident Details

Registration Number	SMB1541J
Case Reference Number	BUS/10/18/1026
Registration Date	12/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Chong Che Kong
Type of Accident	Head to Rear
Accident Date and Time	16/10/2018 9:25 AM
Accident Reported Date and Time	16/10/2018 1:45 PM
Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1541J - FRONT RIGHT PORTION SGA4086M (TP) - REAR PORTION. INSURED WITH MSIG
Prepared Date and Time	19/10/2018 11:06 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,855.00	\$0.00
Total Spray Cost	\$1,048.00	\$0.00
Total Spare Part Cost	\$4,891.35	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$7,794.35	\$0.00
Temp Sum Total	\$0.00	\$0.00
Number of Repair Days	4	3
Prepared / Adjusted By	Tan Ah Leong	3329.50
ARC / Surveyor Sign Off Date		
Signature	x	x
Remarks		

Tan Ah Leong 97495769
 Resurvey before paint.
 suv@lkkauto.com
 WP
 19/10/18 @ 5pm.

Section C - Quotation and Accident Case Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



SMRT Accident Vehicle Repair Breakdown

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 19/10/2018

User ID : TanAhLeong

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,855.00	1590
Total Labour	1,855.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,048.00	900
Total Spray Painting & Panel Beating	1,048.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	Estimator Approved	Surveyor Approved
010153			FRONT HEADLAMP PANEL LH	1	Replace 682.29	LMR ✓
010304			HEADLAMP FRONT LH	1	Replace 1122.52	AMR ✓
010306			FRONT AUX HEADLAMP FLASHER LH	1	Replace 633.08	AMR ✓
010154			FRONT FLAP	1	Replace 1308.16	AMR ✓
005301			SMRT LOGO FRONT	1	Replace \$15	AMR ✓

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	ARC Check	Surveyor Check
-------------	---------	--------------	-----------	----------	-----------	----------------

LKX Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications allowed
 • Subsequent work must be resurveyed and is subject to the applicable terms and conditions



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	


Date Generated : 14/01/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1541J
Case Reference Number	BUS/10/18/1026
Registration Date	12/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Chong Che Kong
Type of Accident	Head to Rear
Accident Date and Time	16/10/2018 9:25 AM
Accident Reported Date and Time	16/10/2018 1:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098374
Special Instruction to ARC,if any	SMB1541J - FRONT RIGHT PORTION SGA4086M (TP) - REAR PORTION. INSURED WITH MSIG
Prepared Date and Time	19/10/2018 11:06 AM
Chassis Number	WMAA22ZZ2E7002426
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,855.00	\$1,590.00
Total Spray Cost	\$1,048.00	\$900.00
Total Spare Part Cost	\$3,056.84	\$3,056.84
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,959.84	\$5,546.84
Lump Sum Total	\$5,950.00	\$5,550.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Internal Surveyor Team	Taufikh
ARC / Surveyor Sign Off Date	19/10/2018 11:57 AM	
Signature	x	x
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel


[Handwritten signatures and dates]
22/12/11 11:45
[Signature]
[Signature]

We declare the foregoing particulars are true in every respect.

Declaration

I was at Upper Thompson Road. I wanted to park. When I saw a car coming out of a lot ~~to the left~~ I reversed. Knocked into a Volkswagen screws behind me!

Describe Circumstances of the Accident



Sketch Plan

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available abroad.

I reversed

IMPORTANT NOTICE

SKETCH PLAN



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/01/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,855.00	\$1,590.00
Total Labour	\$1,855.00	\$1,590.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,048.00	\$900.00
Total Spray Painting & Panel Beating	\$1,048.00	\$900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153			FRONT HEADLAMP PANEL LH	1.00	\$974.70	30.00	\$682.29	Replace	Replace
6010304			HEADLAMP FRONT LH	1.00	\$1,603.60	30.00	\$1,122.52	Replace	Replace
6010306			FRONT AUX HEADLAMP FLASHER LH	1.00	\$904.40	30.00	\$633.08	Replace	Replace
6010154			FRONT FLAP	1.00	\$1,868.80	30.00	\$1,308.16	Replace	Replace
4005301			SMRT LOGO FRONT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
Total					\$5,426.50		\$3,821.05		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Oct 2018		16 Jan 2019 09:05 Edit Adj Rpt	S\$6,311.05 Edit Estimates	S\$6,311.05 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	MAVIS SIM PECK HONG , ID: S0118821F, Tel: +6594592952, Email: MAVISSIM.88@GMAIL.COM								
Main Claimant:	SMRT BUSES LTD , Co. Reg. No.: 198202292D								
Vehicle Reg. No.:	SMB1541J	Date of Loss:	16/10/2018 09:00 - :59 [46 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 573910	Policy/Cover Note No.:	B27916652TMP (Third Party Only) Coverage: 17/05/2018 - 16/05/2019						
Vehicle Reg. No. (Insured):	SGA4086M	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 17/01/2019]								
Driver/Custodian (Insured):	MAVIS SIM PECK HONG (70 / Male), NRIC: S0118821F, Tel: +6594592952								
Adj Asg. Remarks:	direct survey done								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB1541J (573910)**
[SGA4086M]
TP
SMRT BUSES LTD
Oct 16 2018 9:00AM
[MAVIS SIM PECK HONG]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/19 09:04	Accident Statement Addm. #1 <small>From:SC - Reg. No: SGA4086M, Claimant: MAVIS SIM PECK HONG</small>	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
2	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
3	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
4	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
5	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
6	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
7	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
8	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
9	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
10	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
11	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
12	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
13	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
14	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
15	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
16	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
17	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
18	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
19	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
20	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
21	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
22	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
23	16/01/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
24	16/01/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	16/01/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	16/01/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	16/01/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	16/01/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/19 09:04	SMB1541J e-file report <small>From:SC - Reg. No: SGA4086M, Claimant: MAVIS SIM PECK HONG</small>	Load PDF	<input type="checkbox"/>
2	16/01/19 09:04	SMB 1541J ESTIMATE	Load PDF	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
3	16/01/19 09:10	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Direct survey done	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18019382/T1TBE2
Date: 22/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27916652TMP
Claimant Vehicle No : SMB1541J	Insured Vehicle No :	SGA4086M
Date of Loss: 16/10/2018	Nature of Claim:	TP
		Claim No: 573910

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1541J	Engine No:	50338711733876
Make & Model:	MAN NL320F (A22), 10.5 D ABS TURBO (A)	Chassis No:	WMAA22ZZ2E7002426
Reg. Date:	12/12/2014 (Man. Year: 2014)	Odometer:	267715 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6/6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,426.50	3,821.05	1,605.45	29.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,903.00	2,490.00	413.00	14.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	8,329.50	6,311.05	2,018.45	24.23

INSPECTION

Date of Assignment:	16/01/2019	
Date Inspected:	19/10/2018	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 22 Jan 2019)
Parts:	N/A MAN NL320F (A22) 10.5 D ABS TURBO (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB1541J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT HEADLAMP PANEL LH	Cracked	974.70 F	*974.70 FL	
2	1		*HEADLAMP FRONT LH	Cracked	1,603.60 F	*1,603.60 FL	
3	1		*FRONT AUX HEADLAMP FLASHER LH	Cracked	904.40 F	*904.40 FL	
4	1		*FRONT FLAP	Cracked	1,868.80 F	*1,868.80 FL	
5	1		*SMRT LOGO FRONT	Necessary	75.00 FS	*75.00 FS	
					Sub Total (S\$)	5,426.50	5,426.50
					- List Item Discount on L Items 0.00/30.00% (S\$)	0.00	1,605.45
					Total Parts (S\$)	5,426.50	3,821.05

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,855.00	1,590.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	1,048.00	900.00
			Gross Labour Cost (S\$)	2,903.00
				2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >